



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Aisa Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Pte Ltd

Steel C LKK

8391 8813

with previous

22/3/19 5-48

3 days

L/S

By A/L M

Vehicle number	FBG617K
Make / Model	HONDA/ CBR 600'
Chassis number	JH2PC40C9AK301600
Accident date	18 March 2019
Reference	1903-34

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1 SET	FRONT MIRROR LH / CUT	210.00 ✓
1	CLUTCH LEVER / OT	290.00 ✓
1	BAR END X N/A	580.00
1	LH FOOTREST X N/A	450.00
1	LH SIGNAL LAMP / CUT	340.00 ✓
1	ENGINE COVER X / CUT N/A	880.00
1	HANDLE BAR BALANCER LH / CUT	410.00 ✓
1	GP RACING ENGINE COVER LH X / CUT N/A	780.00
1	PADDOCK STAND BOBBIN X N/A	470.00
1	AXLE SLIDER X N/A	520.00
1	HEADLAMP COWLING RH X N/A	415.00
1	HEADLAMP COWLING LH X N/A	415.00
1	SWING ARM CARBIN COVER X N/A	400.00
1	UPPER COWLING LH / CUT	670.00 ✓
1	UPPER COWLING INNER GUIDE X N/A	300.00
1	LOWER COWLING LH X / CUT	590.00 ✓
1	REAR SEAT COWLING LH / CUT	550.00 ✓
1	HANDLEBAR (LHS) / OT	450.00 ✓
1	HANDLEBAR (RHS) X N/A	450.00
1	FRONT LH FORK ASSY X N/A	750.00
1	FRONT RH FORK ASSY X N/A	750.00
1	STEERING HEADCROWM X N/A	550.00
1	STEERING STEM UNDERBRACKET X N/A	319.00
1	STEERING STEM BEARING X N/A	290.00
1	REAR PLATE GUARD / MIS	150.00 ✓
		11979.00
Less 10 %		1197.90
Subtotal		10781.10
Balance B/F		10781.10
1	REAR EXHAUST ASSY X N/A	2200.00
1	REAER NUMBER PLATE / OT	80.00 30
Subtotal		2280.00
Balance C/F		13061.10

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	13061.10
REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS		
AND CHECK WIRING AND LIGHTNING SYSTEM		60.00 30
TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING		500.00 200
TO REMOVE/REFIT, REPLACE FRONT FORK TUDES		459.00 X
SPRAY PAINTING		600.00 200
	Subtotal	1619.00
	Grand total	14680.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: