

7/20/2019

ASS. REC. BY:

REF: CS3/124/9005182/9cd307 Special Instruction:

SW/Veq/v

GA

ASSIGNMENT (Office)

From (Person):

Chin Lee Yng

of

AIG

Date/Time:

21/3/19 @ 3:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 5803M

Insured:

8KX7178T

at Workshop n/s:

Verve Motorworkz

Tel:

9144 4476

of

25/401 Bukit Rd 4 #03-32

Policy No:

0999994432

Claim No:

965759298986

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:56am 22/3/19

Person Contacted:

Kenneth

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Insp: 03-39
	SJU 5803M - MA / INC 130/1351 / r	D O A - 22/6/2013
	SKX 7178T - X.	
	Dismantle: 25/3/2019	
	After repair: 26/3/2019	

PRS
AL

REF: AIG

24450

ASSIGNMENT

62019)

From:

Date: 22/3/2019

Veh No:

SJU 5803M

Yr Regn:

16 Dec 2003

Estimated Cost:

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No:

SJU 5803M

Make:

Honda Civic 2.0 c.c 1998

at Workshop m/s

Verve Motorworkz

Colour

white

A/C: Insured / Std / NI / NA

of

25 kaki Bkt Rd 4 #03-39

Sp. Reading

193442

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

JHMFD 26409S 200942

Policy No.

C/No:

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Kenneth @ 9144 4476

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:


225/45 ZR17

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habibead

Bal. or Market Value:

\$ 22k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

D.O.I.

2203-19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

w/s

4:15pm

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 AUG 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

180

Date/Time, File Return to?

Transportation:

S + RS, SI

Photos

Others

TOTAL

19

191

Report Format :

DAR

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019 Edit Reg		22 Mar 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	POPULAR RENT A CAR PTE LTD, Co. Reg. No.: 199608195Z		
Main Claimant:	WONG WEI SHENG, ID: S8727445D		
Vehicle Reg. No.:	SJU5803M	Date of Loss:	19/03/2019 20:00 - :59
Claim Type:	TP / 9657592989SG	Policy/Cover Note No.:	0999994432 (Comprehensive)
Vehicle Reg. No. (Insured):	SKX7178T	Policy No. (Claimant):	
		Excess:	
Repairer:	Verve Motorworkz Pte. Ltd (HQ) 25 Kaki Bukit Road 4, #03-32/39 Synergy@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (26/03/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 21/3/2019 3:17:34 PM
Attachments:  SJU5803M vs SKX7178T.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Charles Hoon [mailto:charles@aplp.com.sg]
Sent: Thursday, March 21, 2019 2:53 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Nur Ardilah Ramli; Mithoosingh, Aashweenjeetkaur
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX7178T AND SJU5803M ON 19/03/2019

WITHOUT PREJUDICE

Dear Yinrul,

Our client's vehicle can be inspected at:

Verve Motorworkz
25 Kaki Bukit Road 4
#03-32 Synergy@KB
Singapore 417800
Contact Person: Kenneth (91444476)

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Please note our new office address as of 1st March 2019.

**50 Chin Swee Road,
#07-01 Thong Chai Building, Singapore 169874**
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899

Regards,

Charles Hoon

A P Law Practice

50 Chin Swee Road #07-01 Thong Chai Building S169874

T: 6955 8899 F: 6900 9899 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Schedule of Surveyor's Attendance for Conducting PRS

This document indicates that the 3rd party surveyor has inspected the vehicle as follows :

Workshop : ORION Autoclinic
 Vehicle No. : SJU 5803M
 Date of Accident : _____
 Name of TP Insurer Co. : _____
 Surveyor's Firm & Name : Lkt - Eyo Biang
 Contact No. : 82880282 / 67418434
 Date of Vehicle Send In : _____

1st PRS Conducted.

Date & Time of Inspection : 22/3/19
 Require of Resurvey Hidden/Check Items : YES / NO

Signature / Name L

2nd PRS Conduct Hidden/Check Damages Items.

Date & Time Informed Surveyor : 25/3/19 5:15pm Steve Chen CLKK (By Repairer)
 Date & Time of Inspection : _____
 Require of Resurvey After Repair : YES / NO
 Remarks : _____

Signature / Name Steve

3rd PRS Conduct After Repairs.

Date & Time Informed Surveyor : Eyo Biang (By Repairer) L
 Date & Time of Inspection : 26/3/19 ← P/s sign

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	7445D
Vehicle No.:	SJU5803M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L 5AT
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	K20Z24500940
Chassis No.:	JHMF26409S200942
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$27,684.00
Original Registration Date:	16 Dec 2009
First Registration Date:	16 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$27,684.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	\$13,842.00
COE Expiry Date:	15 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,003.00
COE Rebate Amount:	\$1,375.00
Total Rebate Amount:	\$15,217.00

The information contained herein is correct as at 24 Mar 2019

OK

► Civic Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Civic 2.0A	\$19,800	-	14-May-2009	1,998 cc	155,000 km	STI Auto Trading	Available
Good For COE Renewal 5 Or 10 Years. Loan Can Be Arrange And Trade In Are Welcome. Office No. - 64892855 Richard - 96712965							
Honda Civic 2.0A Si	\$20,800	\$8,950 /yr	18-Dec-2009	1,998 cc	-	Auto Nexus Pte Ltd	Available
Calling All I-Vtec Lovers! Well Oiled And Maintained 2.0 Civic By Car Enthusiast! Fitted With Legal Expensive Mods For Smoother Driving! Reluctant Sales Due To Expansion Of Family! Selling Cheap! Call... Office No. - 67433722 Henry - 87400320 Kelvin - 90707779							
Honda Civic 2.0A Si	\$21,800	\$10,850 /yr	15-Dec-2009	1,998 cc	170,000 km	Dart Alliance Automobile Pte Ltd	Available
Calling All I-Vtec Lovers! Well Oiled And Maintained 2.0 Civic By Car Enthusiast! Fitted With Legal Expensive Mods For Smoother Driving! Reluctant Sales Due To Expansion Of Family! 5/ 10 Years COE Ren... Office No. - 63140662 Arthur - 96806027 Daniel - 82127773 Desmond - 87873632							
Honda Civic 2.0M Si	\$23,800	\$13,060 /yr	21-Dec-2009	1,998 cc	162,000 km	The Driven Dealership Pte Ltd	Available
Best Condition In The Market. 100% Accident Free With No Repairs Needed. Tip Top Condition. Office No. - 67444484 Cash - 82489900							
Honda Civic 2.0A	\$24,800	\$14,150 /yr	03-Dec-2009	1,998 cc	-	Hong Wei Vehicle Pte Ltd	Available
Well Maintained And In Good Condition. Ideal For Short-Term Drive As Well As COE Renewal. So Hurry Come And View, Test Drive Now! Make An Appointment With Any Of Hong Wei Vehicle Salespersons Now! Office No. - 64647339 KC Woon - 91399839 Jason Ho - 96896816							
Honda Civic Type R 2.0M 3DR \$24,888	-	-	29-Jun-2009	1,998 cc	188,000 km	The Driven Dealership Pte Ltd	Available
100% Stock. Immaculate Condition. Good For COE Renewal. Very Well Maintained And Taken Care Of. Fully Serviced By Kah Motor Throughout Use. Many Wear And Tear Parts Already Replaced. Office No. - 67444484 Cash - 82489900							
Honda Civic 1.8A VTi-S	\$25,500	\$14,730 /yr	26-Dec-2009	1,799 cc	155,000 km		Available
Best Buy! Quality Pre-Owned At A Affordable And Reasonable Price! Well Maintained And Regularly Serviced! Straight Chassis. No Leaks! Interior Leather Well Maintained! Office No. - - Mikey - 92994969							
Honda Civic 1.6A VTi (New 5-yr COE)	\$29,666	\$5,930 /yr	16-Jan-2009	1,595 cc	121,208 km	Creative Auto	Available
Price Neg, Accident-Free, Beautiful Leather Interior, Extremely Well Maintained, Wear And Tear Fully Replaced, 90% Loan At 3.18%, View Anytime Till 11 PM Daily, Please Call To Arrange Viewing. Office No. - - Andychev - 93392128 Tony Chia - 97460421 Terence Leow - 90290899							
Honda Civic 1.6A VTi (New 5-yr COE)	\$31,888	\$6,370 /yr	15-May-2009	1,595 cc	-	SG Auto Pte Ltd	Available
Yet Another Beautiful And Well Maintained Car! High Loan Or Trade In Avail! Lowest Int Rates In Town Only 3.18%! Try Out Our Latest V.T.A.C Loan Services! Approval Almost Immediate! Hurry Down For A N... Office No. - 68484844 Jamme - 98179689 Koh - 92475893							

Honda Civic 1.8A VTI-S (COE till 01/2024) \$32,766 \$6,810 /yr 14-Jan-2009 1,799 cc 103,163 km Creative Auto **Available**

Loan Available, No Repairs Needed, Good Interior And Exterior Condition, Smooth Engine And Gear Box, Call Now For Viewing!

Office No. - -

Yang - 87480430 | Alex Tan - 97556887 | Terence Leow - 90290899

Honda Civic 1.8A VTI-S (New 5-yr COE) \$32,800 \$6,550 /yr 25-Jun-2009 1,799 cc - D&L Auto Trading **Available**

Guaranteed Accident Free, High OMV \$28K, Beautiful Leather Interior, Extremely Well Maintained, Wear & Tear Fully Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After ...

Office No. - 62960188

Darren Low - 96236322

Honda Civic 1.6A VTI (New 5-yr COE) \$32,800 \$6,550 /yr 01-Apr-2009 1,595 cc - Car World Automobile **Available**

Interest Rate At 3.88% Monthly Of \$681)2 Owners Car, New Paint, New Leather, New 5 Years COE, Showroom Condition Guarantee, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Preowned Car Ar...

Office No. - 64712822

Thomas Hii - 88383233 | Vincent Lim - 96338877 | Alfred Koh - 94567818 | Ambrose Koh - 97912121

Honda Civic 1.8A VTI-S (New 5-yr COE) \$32,800 \$6,550 /yr 28-Apr-2009 1,799 cc - 88 Motor Trading **Available**

Full Loan Available At \$700 Plus, We Can Help To Conver To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...

Office No. - 62911187

Rayner Ho - 96811390 | Jeremy - 97625070 | Ben - 90913551 | Lek - 87555787

Honda Civic 1.6A VTI-S (COE till 02/2024) \$32,800 \$6,650 /yr 27-Feb-2009 1,595 cc 110,000 km SmartCars Boutique Pte Ltd **Available**

Superbly Well Maintained By 1 Owner Only. 100% Accident-Free. Gearbox And Engine Still In Excellent State, Quite Undercarriage. No Further Repairs Needed. STA Or VICOM Evaluation Are Welcome, Wear And...

Office No. - 67410182

Jimmy Choo - 97913903 | Gary - 98883009

Honda Civic 1.6A VTI (New 5-yr COE) \$32,800 \$6,550 /yr 06-May-2009 1,595 cc 129,000 km House De Carz Trading Pte Ltd **Available**

Well Maintained. With Low Mthly From \$600 No Repairs Needed. Price Negotiable. Loan & Trade-in Available. Call Us Now To Arrange For A Viewing!

Office No. - -

Casper - 93855920 | Nick - 97911515 | Adrian - 93888488

Honda Civic 1.8A (New 5-yr COE) \$32,800 \$6,550 /yr 02-Mar-2009 1,799 cc - Next Drive **Available**

Affordable Monthly From \$700 Only! Warranty Packages Available! Excellent Condition, Extremely Well Maintained By Previous Owner! Bank Loan/In-House Loan Available! Nothing Can Go Wrong With The All T...

Office No. - -

Ray - 87880819

Honda Civic 1.6A VTI (New 5-yr COE) \$32,800 \$6,550 /yr 02-Dec-2009 1,595 cc 98,000 km D&L Auto Trading **Available**

100% Guaranteed Accident Free, Well Maintained, Wear And Tear Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, Viewing After Lunch Till 7PM Mon To Fri.

Office No. - 62960188

Darren Low - 96236322 | Charles Low - 83175978

Honda Civic 1.6A VTI (New 5-yr COE) \$32,900 \$6,570 /yr 25-Mar-2009 1,595 cc 110,487 km Car Elegance **Available**

The Most Popular Black Civic For Sale! New Facelift! Genuine Price With No Hidden Cost! 100% Loan Available! Very Low Mileage. Smooth Engine And Gearbox. Come And Test Drive To Believe!

Office No. - -

Andy Ng - 97934799

Honda Civic 1.6A VTI (COE till 02/2024) \$33,300 \$6,750 /yr 27-Feb-2009 1,595 cc - Prime Motor & Leasing **Available**

Elegant Silver, One Owner Only, Low Mileage Done, Spacious Sedan, Low Maintenance Cost, Very Well Maintained, Flexible In-House Loan Packages Available.

Office No. - 64440088

Mark - 84995146 | Andy - 91086443 | Jordan - 91168032 | Pauline - 97810269

Honda Civic 1.8A (New 5-yr COE) **\$33,588** \$6,710 /yr 20-Mar-2009 1,799 cc 162,732 km ABS Auto Capital Pte Ltd **Available**

We Are The COE Specialist. No Gimmicks, Honest Dealing, Car In Very Good Condition. Full Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Showroo...

Office No. - 64753423

Roy - 83158315 | Ken - 91196006 | Kenny - 98259995 | Alex - 82298229

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

MVA319037024 / VAC - Kaki Bukit
 ENTRY DATE & TIME: 20/03/2019 15:43
 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/03/2019 15:43
Date Of Accident	19/03/2019 20:20
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU5803M
Insured/Policyholder	
Name Of Registered Owner	WONG WEI SHENG
NRIC No	S8727445D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93823381
Alternative Phone No	OTHERS-93823381
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC 2.0L 5AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100770255
Cover Note Number	
Driver	
Name of Driver	WONG WEI SHENG
NRIC No	S8727445D
Date Of Birth	05/09/1987
Occupation	INDOOR
Date Of Driving Pass	28/07/2010
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93823381
Fax Number	
Contact Number	OTHERS-93823381
EEmail Address	NOEMAIL

Address BLK 210A #16-164 COMPASSVALE LANE
 Postcode 541210
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190320/7012;

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKX7178T
 Vehicle Make/Model/Colour TOYOTA VIOS E GRADE 1.5 A/T
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver HONG ZIQIANG
 NRIC/Passport Number S8313651J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	WONG WEI SHENG
Approximate Age	31
Injuries Sustain	
Injured person in which vehicle?	SJU5803M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 210A #16-164 COMPASSVALE LANE
Postcode	541210

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

20 MAR 2019

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
21 KAKI BUKIT AVE 4
Reporting Centre
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN

REFER TO POLICE REPORT NO T/20190370/7017

20 MAR 2019

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Singapore 119993
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vacbb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190320/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No. T/20190320/7012

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2019 14:54		Vide Report No.:		Station Diary No.:	
Informant Details					
Name of Informant: WONG WEI SHENG			Address: APT BLK 210A COMPASSVALE LANE #16-164 SINGAPORE 541210		
ID Type / ID No.: NRIC NO / S8727445D			Contact No.:		Mobile: 93823381
Nationality: SINGAPORE CITIZEN			Email: weisheng87@gmail.com		
Sex: Male	Age: 31	Date of Birth: 05/09/1987	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/03/2019 20:20	Type of Location: Straight Road
Location: UPPER SERANGOON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU5803M	Car	HONDA	CIVIC 2.0L SAT	White	Slightly Damaged	0
SKX7178T	Car	TOYOTA	Altis	Silver	Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
SJU5803M	NTUC Income Insurance Co-Operative Limited	5100770255	17/05/2018	15/06/2019	

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190320/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20190320/7012

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WONG WEI SHENG	ID No.	S8727445D
Related Vehicle	SJU5803M (Car)	Contact No.	93823381
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	20/03/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

Whilst stationary at the traffic junction, suddenly a vehicle bearing registration no. SKX7178T collided onto my rear portion.

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190320/7012

3 of 3

Report No. T/20190320/7012

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NP168

Signature Of Informant:
The Identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
20/03/2019 14:54

Classification Of Case:

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
* (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (✓)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DL	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	MC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DL	/ 2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	MM	/	
1159	993327	Rear End Panel	Repair	X	
1160	993339	Rear End Panel Top Garnish	DL	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BT	/	
1171	991328	Bootlid Emblem	MC	/ 4	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	SR	/	
1176	992899	Bootlid Lamp RH	SR	/	
1177	995243	Bootlid Lock	BT	/	
1178	990377	Bootlid Rubber	twi	/	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: GU5803M

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

20/12/2017




































...CLAIM SUBFOLDER...(Pending for Survey Report)










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	POPULAR RENT A CAR PTE LTD , Co. Reg. No.: 199608195Z								
Main Claimant:	WONG WEI SHENG , ID: S8727445D								
Vehicle Reg. No.:	SJU5803M	Date of Loss:	19/03/2019 20:00 - :59 [111 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9657592989SG	Policy/Cover Note No.:	0999994432 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX7178T	Policy No. (Claimant):							
		Excess:							
Repairer:	Verve Motorworkz Pte. Ltd (HQ) 25 Kaki Bukit Road 4, #03-32/39 Synergy@KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU5803M (9657592989SG)
[SKX7178T]
TP
WONG WEI SHENG
Mar 19 2019 8:00PM
[POPULAR RENT A CAR PTE LTD]
Verve Motorworkz Pte. Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
2	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
3	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
4	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
5	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
6	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
7	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
8	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
9	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
10	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
11	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
12	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
13	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
14	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
15	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
16	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
17	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
18	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
19	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
20	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
21	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
22	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
23	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
24	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
25	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
26	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
27	25/03/19 14:49	General View														Load JPG	<input checked="" type="checkbox"/>	
28	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
29	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
32	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	19/06/19 12:13	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
36	19/06/19 12:14	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
37	19/06/19 12:14	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 12:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	19/06/19 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/03/19 15:19	OI GIA REPORT	 Load PDF	
2	12/04/19 10:45	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005182/GCD3E2

Date: 23/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994432

Claimant Vehicle No : SJU5803M

Insured Vehicle No : SKX7178T

Date of Loss: 19/03/2019

Nature of Claim: TP

Claim No: 9657592989SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU5803M

Make & Model: HONDA CIVIC, 2.0 L (A)

Engine No: K20Z24500940

Reg. Date: 16/12/2009 (Man. Year: 2009)

Chassis No: JHMF26409S200942

Colour: White

Odometer: 193442 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: Habilead 6 mm

Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 22/03/2019 Inspected At:

Verve Motorworkz Pte. Ltd (HQ)
25 Kaki Bukit Road 4, #03-32/39
Synergy@KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
9	1		*BOOTLID	Bent	0.00 F	*- F
10	4		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
11	1		*BOOTLID LAMP LH	Scratched	0.00 F	*- F
12	1		*BOOTLID LAMP RH	Scratched	0.00 F	*- F
13	1		*BOOTLID LOCK	Bent	0.00 F	*- F
14	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >