

12/17/2013

ASS. REC. BY:

REF:

REF: 123A1619005206 Ged302 Special Instruction:

SUNVADY

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of AIG Date/Time: 22/3/2019

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 6959T Insured: SMG 469DK
070-0000

at Workshop no/s Perfect Motor Tel: 5741 5338

of 51 Dehu Lane 9

Policy No: 1800185348 Claim No: 48315160459

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 183 2001

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time _____ Person Contacted: _____ Vehicle IN/OUT _____

Date/Time	Action/Instruction (X) Estimate
	SLM6A59J-NA/AIG19004986/K4 DOA: 18/3/2019
	SMG7692 R-X.
	After repair: 29/3/2019

*** Error Report (Send) ***

Send job resulted in error.

Job No.	2380
Address	64153727
Name	
Start Time	20/03 03:31 PM
Call Length	00'47
Sheets	0
Result	NG

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
梁 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
林
06 CATHERINE C. LIM
18 DIRECTOR
LLS (HONS) SINGAPORE - 法律硕士
M.B.A. (BUSINESS LAW) - 商业硕士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SMG 7692R
Our Ref: CL/190343/1/NRR.sg

20 March 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
75 Selegie Way
#07-16
Singapore 079120
Attn: Motor Claims Department

Tan Siew Lin
Blk 201 Bukit Batok Street 21
#06-168
Singapore 650201

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

ACCIDENT INVOLVING SLM 6959J / SMG 7692R ON 18.03.2019 ALONG T2 ARRIVAL DRIVE

We are instructed by Neo R And R Pte Ltd to notify you of a road traffic accident involving our client's vehicle No. SLM 6959J and vehicle No. SMG 7692R driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeframe, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Perfect Motor
3 Defu Lane 12
Singapore 539112

Reminder NIMA

via fax: 6415 3727 & By Hand

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C. LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系-律師
M.B.A. (BUSINESS LAW) - 商业系-碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SMG 7692R
Our Ref: CL/190343/T/NRR.sg

20 March 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Tan Seow Lin
Blk 201 Bukit Batok Street 21
#06-168
Singapore 650201

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

ACCIDENT INVOLVING SLM 6959J / SMG 7692R ON 18.03.2019 ALONG T2 ARRIVAL DRIVE

We are instructed by Neo R And R Pte Ltd to notify you of a road traffic accident involving our client's vehicle No. SLM 6959J and vehicle No. SMG 7692R driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Perfect Motor
3 Defu lane 12
Singapore 539112

Contact: 8299 8628 Ah Soon

Yours faithfully


cc: clients

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6086E
Vehicle Details	
Vehicle No.:	SLM6959J
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2NR8702014
Chassis No.:	NSP1707065891
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,522.00
Original Registration Date:	06 Apr 2017
First Registration Date:	06 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$9,522.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Apr 2027
PARF Rebate Amount:	\$7,141.00
Intended COE Rebate Details	
COE Expiry Date:	05 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$40,563.00
Total Rebate Amount:	\$47,704.00

The information contained herein is correct as at 04 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/03/2019 16:47
Date Of Accident	18/03/2019 23:00
Exact Location Of Accident	T2 ARRIVAL DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM6959J
Insured/Policyholder	
Name Of Registered Owner	NEO R & R PTE LTD
Co Reg No	201026086E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96790493
Alternative Phone No	OFFICE-96790493
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994579
Cover Note Number	
Driver	
Name of Driver	TAN ZHEN HUI
NRIC No	S8235200G
Date Of Birth	23/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	29/06/2005
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96790493
Fax Number	
Contact Number	OTHERS-96790493
EMail Address	NOEMAIL

Address	BLK 637C PUNGGOL DRIVE #06-401
Postcode	823637
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20190319/7004

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG7692R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SEOW LIN
NRIC/Passport Number	S1230819A
Contact Number	96275957
Address	
Postcode	
Insurance Company Name	

Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN ZHEN HUI
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLM6959J
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls Refer to the Police Report -
T/20190319/7004

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20190319/7004

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190319/7004

CONTINUATION OF REPORT

Driver			
Name	TAN ZHEN HUI	ID No.	S8235200G
Related Vehicle	SLM6959J (Car)	Contact No.	96790493
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/03/2019	Date Discharge	19/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the stated time and date , i was stationary at the stated venue waiting for the traffic light to turn green. Suddenly , i felt an impact from the rear. I alighted and realised vehicle bearing carplate number (SMG7692R) had collided onto my vehicle rear portion causing damages to my vehicle. After the accident , i felt pain on my neck , shoulder and lower back thus i seek medical attention at intemedical clinic and was given 3 days mc.

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(0) (3)Check (7)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NGC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RM	/	
1159	993327	Rear End Panel	Repair		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Re	/	
1182	991328	Tailgate Emblem	NGC	/	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NGC	/	
1196	994607	Tailgate Glass Sealant	NGC	/	
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLM 6959J

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	Repair		
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

ORIGINAL COPY




































...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2019 Edit Reg		22 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN SEOW LIN , ID: S1230819A									
Main Claimant: NEO R AND R PTE LTD , Co. Reg. No.: N/A									
Vehicle Reg. No.: SLM6959J		Date of Loss: 18/03/2019 23:00 - :59 [23 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4831516099SG		Policy/Cover Note No.: 1800155348 (Comprehensive)							
Vehicle Reg. No. (Insured): SMG7692R		Policy No. (Claimant):							
		Excess:							
Repairer: Perfect Motor (HQ) No. 51 Defu Lane 9, Defu Industrial Estate, 539277 Defu Lane - Tel: 83549009									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM6959J (4831516099SG)
[SMG7692R]
TP
NEO R AND R PTE LTD
Mar 18 2019 11:05PM
[TAN SEOW LIN]
Perfect Motor

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View In Browser	
Photos/Images											3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
2	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
3	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
4	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
5	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
6	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
7	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
8	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
9	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
10	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
11	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
12	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
13	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
14	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
15	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
16	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
17	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
18	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
19	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
20	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
21	25/03/19 14:29	General View										Load JPG	<input checked="" type="checkbox"/>	
22	25/03/19 14:29	General View										Load PDF		
23	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
24	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
25	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
26	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
27	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
28	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
29	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
30	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
31	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
32	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
33	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
34	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
35	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
36	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
37	04/06/19 11:41	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/03/19 15:10	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005206/GCD3E2

Date: 04/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800155348
 Claimant Vehicle No: SLM6959J Insured Vehicle No: SMG7692R
 Date of Loss: 18/03/2019 Nature of Claim: TP Claim No: 4831516099SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM6959J
 Make & Model: TOYOTA SIENTA, 1.5 X CVT (A) Engine No: 2NR8702014
 Reg. Date: 06/04/2017 (Man. Year: 2016) Chassis No: NSP1707065891
 Colour: Black Odometer: 0 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/03/2019
 Date Inspected: 22/03/2019 Inspected At: Perfect Motor (HQ)
 No. 51 Defu Lane 9, Defu Industrial Estate
 Singapore 539277
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*TAILGATE	Buckled	0.00 F	*- F
6	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
7	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
8	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
9	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >