

Your Ref: 1957517170SG

Date: 25th Mar 2019

Our Ref : CS3/AIG18007413/Gtd3e2-1

Liu Bo Wen2, Chua Chu Kang Grove,
#06-01,
Singapore 688238

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFG 7000X
INSURED VEHICLE: SKP 9697R
ACCIDENT DATE: 18/04/2018**

We thank you for your instruction on 18/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFG 7000X from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicle SKP 9697R.
- c) Colour damaged vehicle photographs of SFG 7000X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFG 7000X
Make & Model	: Volvo S60 T4
Year of Registration	: 2013
Chassis Number	: YV1FS48HBD2233341
Engine Capacity	: 1596 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.