

CS/FCI 19005215 / KVd3ⁿ²

Call/Vendor

Kenneth

ASSIGNMENT (Office)

CWS

From/Person

Henry Kao

at

FCI

Date/Time

10:22am @ 2/3/19

Estimated Cost

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MVTC

To Inspect Vehicle No.

SKL 9588T

Insured

SHA 8850K

at Workshop no.

Wei Tee Motor

Tel

84569830

of

Blk 9 Sin Ming Ind Est #01-32

Policy No.

Claim No.

D19001972MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

16/03/2019

CA / REV / REP / REV 24 HRS

(wp)

25/3/2019

H.O.D. Endorsement

Date/Time

10:33am @ 2/3/19

Person Contacted

Karen

Vehicle IN

(OUT)

Date/Time

Action/Instruction

() Estimate

SKL 9588T-X

SHA 8850K - CC3/CTE 19004036 / FI fa3

D.O.A - 02/03/2019

26/3/19

Email preli revised to FCI

REF: FCI

ASSIGNMENT

From:

Date:

25/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKL 9588T

at Workshop m/s

Wei Lee Motor

of

Blk 9 Sin Ming Ind Est #01-32

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

813/c

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKL 9588T

Yr Regn:

10, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A/P/S

c.c.

1598

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

206072

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053 888106157557

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1613/1P

D.O.I.

25/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/3

11 Pm

8/600 - email

Confirmed with Karen (Recd 996.85, 389)

@459pm

mv: \$13K (EST)

LTA: \$9743

NV: \$3257

RECEIVED 27 MAR 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

26/3 - typist

Days Of Repair:

3

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

CWS

Lump Sum / I.B.I. (\$

1600k

110

50

50

14

224



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001972MFSH

Our ref: CS/FCI19005215/Kvd3

Date : 26/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKL 9588T


We thank for your instruction on 22/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/3/2019 at the premises of M/s WEI LEE MOTOR WORKS and have the following to report:-

Workshop Estimate Amount	: S\$2,596.85
Revised Estimate Amount	: S\$1,600.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	20-03-2019	Our Ref No. D19001972MFSH
Accident Date	16-03-2019	Claim Type. Third Party
Insured Vehicle	SHA8850K	Third Party Vehicle. SKL9588T
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 March 2019 5:42 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001972MFSH/1, SKL 9588T
Attachments: SKL 9588T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKL 9588T
Date of survey: 25/3/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 22 March 2019 12:18 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001972MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer arrange on 25/03/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 22 March 2019 10:22 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19001972MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SKL9588T
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	3ZZ4939468
Chassis No.:	MR053ZEE106157557
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	06 Oct 2009
First Registration Date:	06 Oct 2009
Transfer Count:	3
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Oct 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	05 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,589.00
COE Rebate Amount:	\$817.00
Total Rebate Amount:	\$9,743.00

The information contained herein is correct as at 26 Mar 2019

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

20, MAR 2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SHA8850K
Accident involving vehicle no: SKL9588T/SHA8850K
DOA:16/03/2019 AT 8 Dampsey Road

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKL9588T
To supply—

Description	Qty	Amount
Headlamp,Rh	1	481.90
Front fender,Rh	1	602.40
Fender cowlng,Rh	1	156.00
Cowlng clip		42.00
Front bumper	1	423.60
Bumper retainer	1	51.90
Bumper clip		38.00
Parts		1,795.80
Parts less 25%		448.95
		1,346.85

To remove damaged parts and attachments

Repair/reshape dented areas.

Replace/align all parts into position.

To spray paint

700.00
550.00

2,596.85

Not withstanding
C/Sump & 1600L
Purvey After Paint
3day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005215/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8850K	Veh. Inspected	SKL 9588T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001972MFSH	Excess (\$)	0.00	
Assign From	HENRY	Assign Date	22/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106157557	Colour	METALLIC PEARL WHITE	
Odometer	206072	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	7 mm	
L/H Front Tyre	195/65 R15	MICHELIN	7 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	7 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2019	Inspection Date	25/03/2019	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 9588T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP,RH	CRACKED	481.90	481.90
1	FRONT FENDER,RH	BUCKLED	602.40	602.40
1	FENDER COWLING,RH	SERVICEABLE	156.00	-
1	COWLING CLIP	NECESSARY	42.00	42.00
1	FRONT BUMPER	BUCKLED / CRACKED	423.60	423.60
1	BUMPER RETAINER	DISTORTED	51.90	51.90
1	BUMPER CLIP	NECESSARY	38.00	38.00
	LESS 25% DISCOUNT		-448.95	-409.95
			1,346.85	1,229.85
	LABOUR			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR/RESHAPE DENTED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION.		700.00	400.00
	TO SPRAY PAINT.		550.00	400.00
			1,250.00	800.00
	GRAND TOTAL		2,596.85	2,029.85
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/FCI19005215/Kvd3n2

MARKET VALUE: \$13,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,743.00=NETT VALUE: \$3,257.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.