

Page 001

ASSIGNMENT

REF: CS3/AIG19005219/ECd307

Call Vexor

STEV2

ASSIGNMENT (Office)

From (Person)

Chin lee Ying

AIG

Date/Time 21/3/19 @ 5:29pm

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SKP 3452U

Insured

SFX 1530H

at Workshop n/a

JDMotorsports

Tel:

9237 3644

of 25/keki Bld Rd 4 # 06-38 Synergy

Policy No.

1800136989

Claim No.

9618245764SG

Sum Insured

Excess

Make of Veh.

D.O.A.

16/03/19

(Client's Record)

25/3/19

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time: 22/3/19 @ 2:49pm

Person Contacted

Ronnie

Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	SKP 3452U -X
	SFX 1530H - CS/msg 11004767/ Rb n
	Dismantle: 25/3/2019
	After repair: 28/3/2019.

D.O.A - 10/3/2011

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 21/3/2019 5:29:37 PM

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Thursday, March 21, 2019 4:00 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; jd.motorsports@outlook.com; Ronnie Tay (wei_845@outlook.com)

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFX1530H AND SKP3452U ON 16/03/2019

Without Prejudice

Save As To Cost

Dear Mdm,

We refer to your email dated even date.

Our client regret to reject your list of surveyors and append below our client's list of surveyors for your consideration.

- | | |
|-------------|---------------------|
| 1. Mr Bok | - Prudent Adjusters |
| 2. Kelvin | - KAAS |
| 3. Terrence | - KAAS |

If your end is not agreeable with the above list of surveyors , kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : JD Motorsports Pte Ltd
25 Kaki Bukit Road 4
#06-38 Synergy@KB
Singapore 417800
Contact Person : Mr Ronnie : 9237 3644

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3806J
Vehicle Details	
Vehicle No.:	SKP3452U
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	A520I093N46B20BE
Chassis No.:	WBANT12040CX29033
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$46,209.00
Original Registration Date:	29 Feb 2008
First Registration Date:	29 Feb 2008
Transfer Count:	3
Actual ARF Paid:	\$50,830.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,578.00
COE Rebate Amount:	\$45,156.00
Total Rebate Amount:	\$45,156.00

The information contained herein is correct as at 25 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 11:56
Date Of Accident	16/03/2019 08:25
Exact Location Of Accident	SEASONS PARK CONDOMINIUM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP3452U
Insured/Policyholder	
Name Of Registered Owner	WANG LIANG
NRIC No	S8363806J
Email Address	VINCENT0WANG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96345679
Alternative Phone No	OFFICE-96345679

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3062151802
Cover Note Number	

Driver

Name of Driver	WANG LIANG
NRIC No	S8363806J
Date Of Birth	30/01/1983
Occupation	INDOOR
Date Of Driving Pass	30/06/2005
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96345679
Fax Number	
Contact Number	OFFICE-96345679
Email Address	VINCENT0WANG@HOTMAIL.COM

Address	495 YIO CHU KANG ROAD #03-01
Postcode	787080
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN & POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFX1530H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of fault by the driver or the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available to all interested parties
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to the report being made available aforesaid


8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident. All insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers". The Insurers are regulated by the Monetary Authority of Singapore and any relevant government agency authority, such as the Data Protection Commission of Singapore.
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) investigating the accident and/or my claims
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries from me
- (iv) administering my claims (including the mailing of correspondence, statements, notices, receipts, notices to me which could involve disclosure of certain personal data about me to bring about the settlement of the claims, the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims to achieve the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' agents, law firms, etc, are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes.
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to the relevant carrier's legal representatives (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims; regulators, law enforcement and government agencies as reasonably required for the purposes stated;
 - (ii) for complying with requirements under any regulations, laws or court orders


 Policyholder's Signature
 Date & Time
 Mar 18. 2019
 9:50 AM


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Car City Auto Centre Pte Ltd
 Name: 
 Saly
 5184 Z

SKETCH PLAN

Van A → SKP 3452 W
Van B → SFX 1530H



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report

You have been advised by Worksafe that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time

[Signature]
Driver's Signature
If driver is not the policyholder
Date & Time

Mar 18. 2019



[Signature]
Date & Time
7 8 4 2



**SINGAPORE
POLICE FORCE**



F/20190317/2090

1 of 2

POLICE REPORT (NP299)

Report No. F/20190317/2090

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No 1800-4849999

Date/Time Report Made 17/03/2019 20:58	Vide Report No.	Station Diary No. 56
Name Of Informant WANG LIANG	Address 495 YIO CHU KANG ROAD #03-01 Seasons Park Condominium SINGAPORE 787080	
ID Type / ID No NRIC NO / S8363806J	Contact No. Home/Office Mobile 96345679	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation ENGINEER	Sex Male	Age 36
Institution/School Name	Date of Birth 30/01/1983	Race Chinese
Date/Time Of Incident 16/03/2019 08:25 - 16/03/2019 09:30	Location Of Incident 495 YIO CHU KANG ROAD SEASONS PARK SINGAPORE 787080 level 1 of MSCP, parking lot number 47	

Brief details.

On 15/03/2019 at about 9.15pm at the location of incident, I parked my car (BMW 520, White, SKP3452U) at my residence. Thereafter, I went home. On 16/03/2019 at about 9.30am, I returned to my car and discovered fresh damages (scratch and damage to the parking sensor) on the right side of the front bumper. I sought help from the Condominium Management office to view the CCTV footages and discovered that on 16/03/20019 at 8.25am, one of the resident's car (Mercedes Benz E200, black,

Signature Of Officer Recording The Report:

F / SI BALA MURUGAN S/O KALIAPPAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
17/03/2019 20:58

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Sr Staff Sgt MOHAMMED SYAZWAN BIN ABDULLAH
Contact No.: 64849999

Classification Of Case:

Authentication Stamp



Signature:

Singapore Police Force

SM 085



**SINGAPORE
POLICE FORCE**



F/20190317/2090

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190317/2090

SFX1530H, owner: Monika Verma) drove out the car from the parking lot 48. After coming out, the said car stopped for some time and drove off. On 16/03/2019 at about 2.30pm, the Management office contacted the owner and I corresponded with her. On the same day at about 3pm, she acknowledged the accident and we agreed for insurance claim. I am lodging this report for my record and for insurance claim.

Subjects Involved			
Defendant			
Person Name	Monika Verma		
ID Type	NRIC NO	ID No	S6872333G
Gender	Female	Address	Seasons Park Condominium SINGAPORE
Mobile No	91834844		

Signature Of Officer Recording The Report:

F / SI BALA MURUGAN S/O KALIAPPAN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Sr Staff Sgt MOHAMMED SYAZWAN BIN ABDULLAH
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
17/03/2019 20:58

Classification Of Case:



Signature:

SN 085

Vehicle No.

SKP 345201

MAC	INC	Item	Cost	Qty
1071	992205	Fuse Box		
1072	994011	Relay Box		
1073	995053	Wiper Washer Tank		
1074	995052	Wiper Washer Tank Motor		
1075	990159	Alternator Assy		
1076	990160	Alternator Belt		
1077	992688	Power Steering Pump		
1078	992669	Power Steering Belt		
1079	994431	Power Steering Cooler Pipe		
1080	992692	Power Steering Hose		
1081	990010	ABS Pump Control Unit		
1082	990427	Brake Master Pump Assy		
1083	990403	Brake Booster Pump Assy		
1084	991005	Engine Top Cover		
1085	991011	Engine Under Cover		
1086	990946	Engine Mounting		
1087	990949	Engine Mounting Frt		
1088	990950	Engine Mounting LH		
1089	990952	Engine Mounting RH		
1090	990951	Engine Mounting Rear		
1091	992234	Gear Box Mounting		
1092	991520	Frt LH Chassis Member		
1093	991520	Frt RH Chassis Member		
1094	990728	Frt Vertical Cross Member		
1095	991863	Frt Lower Cross Member		
1096	995070	Frt LH Fender		
1097	995072	Frt LH Fender Inner Panel		
1098	995147	Frt LH Fender Lamp		
1099	995148	Frt LH Fender Protector		
1100	991740	Frt LH Fender Inner Shield		
1101	995179	Frt LH Mudflap		
1102	995170	Frt LH Wheel Rim		
1103	994025	Frt LH Rim Cover		
1104	995065	Frt LH Tyre		
1105	995071	Frt RH Fender		
1106	991739	Frt RH Fender Inner Panel		
1107	991744	Frt RH Fender Lamp		
1108	991752	Frt RH Fender Protector		
1109	991740	Frt RH Fender Inner Shield		
1110	991834	Frt RH Mudflap		
1111	992087	Frt RH Wheel Rim		
1112	994025	Frt RH Rim Cover		
1113	995065	Frt RH Tyre		
1114	992093	Frt Windscreen Glass		
1115	992117	Frt Windscreen Rubber		
1116	992108	Frt Windscreen Moulding		
1117	992093	Frt Windscreen Sealant		
1118	991019	ERP Bracket		
1119	991020	ERP Unit		
1120	992140	Frt Wiper Arm		
1121	992142	Frt Wiper Blade		
1122	995045	Wiper Panel Garnish		
1123	991126	Firewall Panel		
1124	990753	Dashboard Assy		
1125	992382	Glove Box Cover		
1126	992281	Glove Box Compartment		
1127	994433	Steering Wheel Airbag		
1128	994435	Steering Wheel Airbag Sensor		
1129	990749	Dashboard Airbag		
1130	990750	Dashboard Airbag Sensor		
1131	990029	Airbag Control Unit		
1132	990864	Frt Driver Seat		
1133	991933	Frt FH Seat Belt Assy		
1134	991899	Frt Passenger Seat		
1135	991423	Frt LH Seat Belt Assy		
1136	990547	Anchor		

RH Headlap washer pump

RR ✓

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI






































CLAIM SUBFOLDER TRACKING









































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DINESH VERMA , ID: S2601346A									
Main Claimant: UNKNOWN									
Vehicle Reg. No.: SKP3452U		Date of Loss: 16/03/2019 00:00 - :59 [132 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7892315781SG		Policy/Cover Note No.: 1800136989 (Comprehensive)							
Vehicle Reg. No. (Insured): SFX1530H		Policy No. (Claimant):							
		Excess:							
Repairer: Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 02/04/2019]									
Claimant's Solicitor: HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/03/2019): No OI GIA Report AIG_SG (26/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP3452U (7892315781SG)
[SFX1530H]
TP
UNKNOWN
Mar 16 2019 12:00AM
[DINESH VERMA]
Jd Motorsports Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>	
Photos/Images						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
2	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
3	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
4	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
5	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
6	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
7	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
8	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
9	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
10	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
11	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
12	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
13	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
14	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
15	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
16	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
17	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
18	26/03/19 08:29	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
19	26/03/19 08:29	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
20	26/03/19 08:29	General View		Load JPG	<input checked="" type="checkbox"/>		
21	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
22	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
23	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
24	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
25	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
26	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
27	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
28	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
29	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
30	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
31	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
32	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
33	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
34	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
35	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
36	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
37	26/03/19 08:29	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	26/03/19 08:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	02/04/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005218/ECD3E2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800136989

Claimant Vehicle No: SKP3452U

Insured Vehicle No: SFX1530H

Date of Loss: 16/03/2019

Nature of Claim: TP

Claim No: 7892315781SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP3452U

Make & Model: BMW 520I, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)

Engine No: A520I093N46B20BE

Reg. Date: 29/02/2008 (Man. Year: 2007)

Chassis No: WBANT12040CX29033

Colour: White

Odometer: 103561 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 25/03/2019 Inspected At:

Jd Motorsports Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4, #06-38
SYNERGY@KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SENSOR	Broken	0.00 F	*- F
4	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
5	1		*RH HEADLAMP WASHER PUMP	Broken	0.00 F	*- F
Total Parts (S\$)						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >