

22/03/2019

ASS. REC. BY:

REF: CS3/FCI 19005226 / BC d30 Special Instruction:

Surveyor: [Signature]ASSIGNMENT (Office)

CWS

From (Person): SITHARA of FCI Date/Time: 22.3.2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBC 1425 L Insured: SHD 8531Rat Workshop m/s MTA AUTO SOLUTIONS Tel: 82658352of 25 KAKI Bukit Road 4 Synergy @ KB #07-47

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21.3.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22.3.19. 1:34 pm Person Contacted: Ah Wai Vehicle IN OUT

Date/Time	Action/Instruction	Estimate (X)
	GBC 1425 L - NA / INV 19005121 / h4	D.O.A. : 21 / 3 / 2019
	SHD 8531R - NA / INC 19005121 / h4	D.O.A. : 21 / 3 / 2019

Girrajor

REF: PC1

B3425C

## ASSIGNMENT

From: Date: 27.3.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 1425L

at Workshop m/s MTA Auto Solutions

of 25 kaki Bukit Road 4 # 07-47

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wp"

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBC 1425L Yr Regn: 15 July 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT Fiorino C.C. 1248

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 209801 km T/Radio: Insured / Std / NI / NA

Eng/No: 199A2000

C/No: ZFA22500000015698

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14 84H

R: 175/70 R14 84H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 21/03/2019 D.O.I. 29/3/2019

Survey held at MTA Auto Solutions 1154AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 23,000/2

PV 14,348/2

NV 8,652/2

3/4/2019

Team

29/3/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

S + RS, SI

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

190

**MOTOR SURVEY ASSIGNMENT**

Date	21-03-2019	Our Ref No. D19001993MFSH
Accident Date	21-03-2019	Claim Type. Third Party
Insured Vehicle	SHD8531R	Third Party Vehicle. GBC1425L
Survey Location	25 KAKI BUKIT ROAD 4SYNERGY @ KB #07-47	
Contact Person.	AH WAI	
Contact No.	82658352/ 82658352	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

P: Ah Wai  
V: in today 6.30.  
E: x  
T: 1.38pm  
Anytime. (Monday)

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

PRS X

Cc : Workshop	MTA AUTO SOLUTIONS PTE LTD	Attention. NIL
Cc : TP Solicitor	RIAZ LLC	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	3425C
<b>Vehicle Details</b>	
Vehicle No.:	GBC1425L
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	FIAT
Vehicle Model:	FIORINO 1.3MJTD (225.2L20)
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	199A20002606302
Chassis No.:	ZFA22500000015698
Maximum Power Output:	-
Open Market Value:	\$19,748.00
Original Registration Date:	15 Jul 2008
First Registration Date:	15 Jul 2008
Transfer Count:	5
Actual ARF Paid:	\$988.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jun 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,859.00
COE Rebate Amount:	\$14,348.00
<b>Total Rebate Amount:</b>	<b>\$14,348.00</b>
<b>Message</b>	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 28 Mar 2019

OK

MV. - \$23,000  
 PV - \$14,348  
 NV - \$8652.00

Dep - \$4.5K/yr.  
 \$375/mth.

  
 28/03/2018.



## ANNOUNCING Autolink Holdings as sgCarMart Premium Dealer 2019

# AUTOLINK HOLDINGS

### Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

### New 5 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A Low Interest @ Gv  
Finance. 2 Years Warranty.  
\$2500 Down Monthly From \$63  
GV Credit Pte Ltd StarAd

**Lake View  
Credit Pte Ltd**
[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)
[7 vehicles](#)

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	FIORINO		Any	Any	Any	Any	Any	Any	Available
	Fiat	Fiorino 1.3JTD (COE till 01/2024)	\$21,800	\$4,520 /yr	21-Jan-2009	1,248 cc	88,541 km	Van	Available
<b>Fuel Type:</b> Diesel 1.3 Auto, Vehicle In Stock Condition, Selling Cheap, Call Now Don't Miss. Posted: 26-Mar-2019 Tags: 2009 Fiat Fiorino, 2009 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									
	Fiat	Fiorino Cargo 1.3MTA Multijet Glaze	\$60,900	\$7,210 /yr	04-Sep-2017	1,248 cc	20,000 km	Van	Available
<b>Fuel Type:</b> Diesel This Is The 3rd Personal Vehicle Use For Administrative Use. Posted: 26-Feb-2019 Tags: 2017 Fiat Fiorino, 2017 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									
	Fiat	Fiorino Cargo 1.3MTA Multijet Glaze	\$52,800	\$5,410 /yr	28-Dec-2018	1,248 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Fiorino Cargo Is The Van Made For The City Where It Is Known For Its Unmistakable Car-like Style And New Anterior Looks, Now Even More Appealing Especially For Those Who Wish To Get A Vehicle For Work... QiFei Auto Pte Ltd Posted: 09-Mar-2019 Tags: 2018 Fiat Fiorino, 2018 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									
	Fiat	Fiorino Cargo 1.3MTA Multijet Glaze	\$52,800	\$5,370 /yr	22-Jan-2019	1,248 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Possibly The Best Small Auto Diesel Van In Its Class! Combines A Commercial Vehicle Soul With A Car Look And Great Features. Very Functional, Good Load Capacity And Very Low Running Cost. 100% Loan, H... Net Link Partners Pte Ltd Posted: 25-Mar-2019 Tags: 2019 Fiat Fiorino, 2019 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									
<b>New Fiat Fiorino - Very van-tastic!</b> What the Fiat? The vans from the Italian marquee seem to be getting better and better each year... <a href="#">Read this article</a>									
	Fiat	Fiorino Cargo 1.3MTA Multijet Glaze	\$51,900	\$5,250 /yr	14-Feb-2019	1,248 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Exclusive Leather Combi Seats. Solar Film, Full Insulation. GPS. BlackVue Front Recording Camera. Reverse Camera. Warranty 5 Years Up To 160000km. Call Now For More Details! Bell Auto Pte Ltd Posted: 24-Feb-2019 Tags: 2019 Fiat Fiorino, 2019 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									
	Fiat	Fiorino Cargo 1.3MTA Multijet Glaze	\$52,800	\$5,310 /yr	04-Mar-2019	1,248 cc	135 km	Van	Available
<b>Fuel Type:</b> Diesel Possibly The Best Small Auto Diesel Van In Its Class! Combines A Commercial Vehicle Soul With A Car Look And Great Features. With Front Recording Camera. Very Functional. Warranty 3 Years Up To 60,000... Posted: 05-Mar-2019 Tags: 2019 Fiat Fiorino, 2019 fiat fiorino, Fiat Fiorino, fiat fiorino, Fiat, Fiorino, fiorino, Used Fiat									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/03/2019 13:41
Date Of Accident	21/03/2019 12:10
Exact Location Of Accident	OUTSIDE 69 LOYANG DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBC1425L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	H&H AUTO SERVICING
Co Reg No	53293425C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82658352
<b>Vehicle Particulars</b>	
Manufacturer	FIAT
Model	FIORINO 1.3MJTD (225.2L20)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5096927851-01
Cover Note Number	-
<b>Driver</b>	
Name of Driver	NG KIN KOK
NRIC No	S0018906E
Date Of Birth	05/02/1949
Occupation	OUTDOOR
Date Of Driving Pass	09/02/1998
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81179261
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 492F TAMPINES ST 45 #12-702
Postcode	526492
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY VEH WAS PARKED OUTSIDE 69 LOYANG DRIVE, EVERYTHING WAS INTACT, WHILE I STAND OUTSIDE SOMEWHERE NEARBY MY VEH, SUDDENLY I HEARD A BANG SOUND, I WENT TO MY VEH AND I SAW THE TAXI HAD REVERSING HIT ONTO MY VEH RIGHT FRONT PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD8531R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOU CHOK WHONG
NRIC/Passport Number	S1581281H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) in complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Accident Sketch Plan

## SKETCH PLAN

67 Luyang Drive

A = GBC 1425L  
B = SHD 8531R

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to statement

## DECLARATION

I/We declare the following particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

G:\MSAC Sketch\IP\IPForm\ipf\_03

2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**PRE-REPAIR INSPECTION REPORT**

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI19005226/Bcd3e2

Date: 22-04-2019



Code: FCI2

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

Insured Veh.	SHD 8531R	Veh. Inspected	GBC 1425L
Policy No.		Coverage (\$)	0.00
Claim No.	D19001993MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	22/03/2019


**2. Vehicle Particulars & Condition**

Make & Model	FIAT FIORINO	c.c	1248
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ZFA22500000015698	Colour	BLUE
Odometer	209801 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	5 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	5 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	5 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE BODY STRUCTURE AFFECTED DUE TO COLLISION.	
--	---

**5. General Information**

Accident Date	21/03/2019	Inspect Date / Time	27/03/2019 ( 11:54 AM )
Survey held at	MTA SOLUTION-25 KB ROAD 4 SYNERGY @ KB #07-47		
Repairer	-		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE:\$23,000.00
--

Report Ref No. CS3/FCI19005226/Bcd3e2

**Inspected By**

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.