

FORM 100

ASS. REC. BY:

REF

CS3/MSC18023287/11vd 3⁰⁷

of Instruction

From (Person)

Mentmen Fievel F00

ASSIGNMENT (Office)

of MS1G

Date/Time: 20/03/2019

Estimated Cost

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

GBF1548A

Insured:

XD2509G

at Workshop m/s

Precision Motorworks

Tel:

8742 7247

of

68 kaki Bukit Ave 6 # 01-02

Policy No

528949814 MKC

Claim No:

580261

Sum Insured

Excess:

Make of Veh:
(Client's Record)

D.O.A

26/12/18

CA / REV / REF. / REV 24 HRS

kup

31121100 Muminey

Date/Time

5:06pm @ 28/12/18

Person Contacted

John

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

GBF1548A - X

XD2509G - CA/AIG11004103/WI

DIA: 01/03/2019

Dismantle: 2/1/2019

28/3/19

Sumat h/s 8900 R/L (Ref 5500, 3890)

RECEIVED 28 MAR 2019

28/3/2019

Do Not Finalise


REF: MSIG

ASSIGNMENT

From: Date: 3/12/18
 Estimated Cost:
 OD ☒ WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: GBF 15489
 at Workshop m/s: Precision Motorworks
 at: 68 kaki Bukit Ave 6 # 01-02
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bail. or Market Value: 53
 IDAC Accident Rpt: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 6 days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

42500

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBF 15489 Yt Regn: 7116
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CM /
 Make: Toyota Dyna CC 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 128253 T/Radio: Insured / Std / NI / NA
 Eng/No:
 Ctno: JTFAT35460K206625
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195/75R15.
 R: 155R12
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 28/1/18 D.O.I. 31/12/18
 Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 No settlement; LRA 14919 resurvey done on 7-1-19
 7 yrs 7m. 10-11k.

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format: PRE.

Lump Sum / I.B.I: (\$)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

Y... \$ + RS... \$1

j. Photos

i. Others

i. i.

Total

100

10

130

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Thursday, 21 March 2019 11:37 AM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: Report Send Back Alerts - GBF1548A (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report- CS3/MSG18023287/UCD3E2

20 Mar 2019 14:22	Ins Send Back Adj Rpt	Paper reinspection
20 Mar 2019 14:22	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2019/03/22
20 Mar 2019 14:22	Adj Mandate Set	Maintained.

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6742 9588 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Wednesday, 20 March 2019 2:40 PM
To: account@lkkauto.com
Subject: Report Send Back Alerts - GBF1548A (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Report No: 0139-19-PM

08 March 2019

ACCIDENT VEHICLE SURVEY REPORT

United Wooden Case & Packing Enterprise (S)
c/o Precision Motorworks
68 Kaki Bukit Ave 6 ARK @ KB #01-02
Singapore 417896

VEHICLE INFORMATION:

Vehicle Reg No.:	GBF1548A	Odometer:	128236km
Make & Model:	Toyota Dyna	Colour:	White
Chassis number:	JTFAT35Y60K206625	Date of accident:	26/12/2018
Year of Regn.:	18/07/2016	Date inspected:	27/12/2018
Repairer at:	Precision Motorworks	Date inspected (After Repair):	07/01/2019
	68 Kaki Bukit Ave 6 ARK @ KB #01-02		
	Singapore 417896		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	3mm/Bridgestone	3mm/Bridgestone	195/75R15
Rear: x2	3mm/Bridgestone	3mm/Bridgestone	155R12

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0139-19-PM

Vehicle No: GBF1548A

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Tailgate	1	buckled <i>Buc</i>	1,712.85	1,712.85 ✓
Tailgate sticker "Toyota"	1	necessary <i>nee</i>	192.62	192.62 ✓
Tailgate hinges	4	bent <i>bent</i>	318.40	318.40 ✓
Rear sidegate lock RH/LH	2	bent <i>bent</i>	242.60	242.60 ✓
Rear sidegate RH	1	buckled <i>Buc</i>	2,117.80	2,117.80 ✓
Rear end panel sticker "Dyna"	1	necessary <i>nee</i>	19.02	19.02 ✓
Rear tail lamp RH/LH <i>251.4 N/SAA can't see dye</i>	2	fractured/cracked <i>of/bent</i>	502.80	502.80 <i>120</i>
<i>201.3</i> Rear tail lamp bracket RH/LH <i>N/SAA</i>	2	bent <i>0.5 bent</i>	402.60	402.60 <i>120</i>
Rear tailgate stopper rubber RH/LH	2	deformed <i>De</i>	144.80	144.80 ✓
Rear tailgate stopper bracket RH/LH	2	bent <i>Bent</i>	200.60	200.60 ✓
Rear number plate lamp <i>can't see dye</i>	1	fractured <i>fr</i>	86.00	86.00 <i>X</i>
Rear number plate bracket	1	bent <i>Bent</i>	273.70	273.70 ✓
Front cabin rear panel	1	repair <i>r</i>	691.00	0.00 <i>X</i>
Rear windscreen glass rubber	1	necessary <i>nee</i>	75.00	75.00 <i>X</i>
Chassis outrigger RH/LH	8	distorted	960.00	960.00 <i>X</i>
Rear cargo carrier floor panel	1	buckled <i>Buc</i>	5,754.00	5,754.00 ✓
Rear cargo carrier floor panel cross structure beam	6	bent <i>complete</i>	1,200.00	1,200.00 <i>X</i>
Front door rear pillar panel	1	buckled <i>r</i>	388.10	388.10 <i>X</i>
Subtotal before discount			15,281.89	14,590.89
Percentage discount 0% and 25%			0.00	3,647.72
Sub-total 1			15,281.89	10,943.17
Tailgate sticker '70km/h'	1	necessary <i>nee</i>	10.00	10.00 ✓
Reverse sensor	1	shorted <i>shorted</i>	350.00	300.00 <i>200</i>
Rear number plate	1	bent <i>Bent</i>	25.00	25.00 <i>15</i>
Subtotal before discount			385.00	335.00
Percentage discount 0% and 0%			0.00	0.00
Sub-total 2			385.00	335.00
Parts-total			15,666.89	11,278.17

11429.09

225

PAR Automotive Consultancy


LABOUR

1. To straighten and panel beating front cabinet rear panel, rear chassis frame member and rear frame members. To cut/weld front door LH rear pillar panel. To remove and refit above parts.	3,000.00	2,500.00 ¹⁰⁰⁰
2. To putty, re-spray painting and polish affected areas.	2,000.00	1,600.00 ¹⁰⁰⁰
3. To check and rectify wiring system.	120.00	80.00 ³⁰
4. To rust proof affected areas.	150.00	120.00 ⁸⁰
5. To provide lifting equipment to remove and refit rear cargo carrier floor panel.	500.00	500.00 ²⁵⁰
Labour total	5,770.00	4,800.00
Parts & Labour total	21,436.89	16,078.17

Results of inspection of the accident vehicle are as shown above. ²⁴¹⁰

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : **\$14,400.00**
and the recommended number of working days for the repairs is : **14**


B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2018 17:56
Date Of Accident	26/12/2018 08:55
Exact Location Of Accident	TUAS SOUTH AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF1548A
Insured/Policyholder	
Name Of Registered Owner	UNITED WOODEN CASE & PACKING ENTERPRISE (S)
Co Reg No	200204250D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800079452
Cover Note Number	

Driver

Name of Driver	LIM SWEE TECK
NRIC No	S0228427H
Date Of Birth	31/05/1953
Occupation	OUTDOOR
Date Of Driving Pass	12/12/1973
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82034090
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 193 BUKIT BATOK WEST AVE 6 #20-69
Postcode	650193
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20181226/2053.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD2509G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMALINGAM MUTHUMANI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM SWEE TECK

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBF1548A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NAIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181226/2053

1 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20181226/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/12/2018 13:33		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: LIM SWEE TECK			Address: APT BLK 193 BUKIT BATOK WEST AVENUE 6 #20-69 SINGAPORE 650193		
ID Type / ID No.: NRIC NO / S0228427H			Contact No.: Home/Office: Mobile: 82034090		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 31/05/1953	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/12/2018 09:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TUAS SOUTH AVENUE 3 TUAS SOUTH AVENUE 5 At the junction between Tuas South Avenue 3 and Tuas South Avenue 5				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF1548A	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181226/2053

2 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20181226/2053

CONTINUATION OF REPORT

Driver			
Name	LIM SWEE TECK	ID No.	S0228427H
Related Vehicle	GBF1548A (Lorry)	Contact No.	82034090
Hospital/Clinic	C & K FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/12/2018	Date Discharge	26/12/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 26/12/2018 at about 0930hrs, I was driving my lorry bearing registration number - GBF1548A along Tuas South Avenue 3. As I was approaching the junction between Tuas South Avenue 3 and Tuas South Avenue 5, the traffic light had turned red and I stopped my vehicle. While I was waiting for the light to turn green, a trailer truck collided onto the rear of my lorry. The impact caused my lorry to be pushed forward and into the middle of the junction. The plastic cover for my lorry had fallen off and items that I had placed inside the lorry were thrown around as a result of the impact.

I felt a pain on my lower back and on the back of my neck and I was feeling disoriented. I exited the vehicle and saw that the rear of my lorry was damaged and heavily dented. I had as well noticed that the front of the trailer truck was dented and the bumper had fallen off and there were large dents. I immediately called my boss to inform him of what had happened. My boss told me he will be coming down to my scene and he will be calling for Traffic Police.

Traffic police had arrived at the scene and had attended to me and the trailer truck driver. My boss had come down to the scene and had taken pictures of the damages and exchanged particulars.

The driver of the trailer truck approached me and apologised to me for colliding into my lorry. As I was feeling pain on my lower back and on the back of my neck area, I decided to visit a clinic to see a doctor.

On 26/12/2018 at about 1200hrs, I had gone to C&K Family Clinic and was given 7 days MC from 26/12/2018 to 01/01/2018.

I wish to add that my lorry's in-car camera was damaged as a result of the collision, hence, I was unable to view the in-car camera footage. I was advised to lodge a Traffic Accident report by Traffic Police. I am now lodging this report under the instruction of Traffic Police and for insurance claiming purposes.



**SINGAPORE
POLICE FORCE**



T/20181226/2053

3 of 3

Report No. T/20181226/2053

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 JONATHAN LIM ZI XUAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt YUS MASTARI I KHAZALI Contact No: 65476214
Authentication Stamp

Signature Of Informant:
Date/Time: 26/12/2018 13:33
Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0228427H



Name

LIM SWEE TECK

Race

CHINESE

Date of birth


31-05-1953

Sex

M

Country of birth

SINGAPORE



12/12/1973



486327H

IDENTITY CARD NO. S0228427H




Date of issue

06-11-2010

Address

APT. BLK 193 BUKIT BATOK WEST AVENUE 8
#20-09
SINGAPORE 650193





POLICY SCHEDULE

COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Policy No. : 1800079452

Period of Insurance : 18 Jul 2018 to 17 Jul 2019

Issued Date : 11 Jul 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : UNITED WOODEN CASE & PACKING ENTERPRISE (S)
 Address : 103 TUAS VIEW WALK 1
 WESTLINK TECHPARK
 SINGAPORE 637728
 Occupation/Nature of Business : Manufacturing/ Engineering

ABOUT THE VEHICLE

Registration No. : GBF1548A Engine Capacity/Tonnage : 1.7 Tonnage
 Chassis No. : JTFAT35Y60K206625 Engine No. : 1KD2626548
 Seating Capacity : 2 First Year of Registration : 2016 Body Type : Lorry
 Make/Model : TOYOTA DYNA 150 1.7 ton [Lorry]
 Hire Purchase Company/Employer's Loan : MERCEDES BENZ FINANCE CO LTD

ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No
 Driver Restriction : NA Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

- a) Any person who is driving on the Policyholder's order or with their permission.
 b) This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

- 1) Use in connection with the Policyholder's business.
 2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business.
 3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing; and b) use whilst towing a trailer except the towing of anyone disabled using a mechanically propelled vehicle. c) use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Key Replacement Cover - \$800, Strike, Riots and Civil Commotions, Dealer (First 3 years from original registration) + AIG Authorized Workshops, In-Car Camera Excess Waiver, Act of God

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

PREMIUM

Premium : \$ 1,205.10
 GST (7%) : \$ 84.36

Total : \$ 1,289.46

Your Premium includes the following discount(s):

No Claim Discount - 15%

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





UNITED WOODEN CASE AND PACKING ENTERPRISE (S) PTE. LTD.
1 BUKIT BATOK CRESCENT
#06-22 WCEGA PLAZA
(S) 658064
COMPANY NO : 200204250D
PAX : 2

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2018 09:01
Date Of Accident	26/12/2018 09:00
Exact Location Of Accident	JUNCTION TUAS SOUTH AVE 3 & TUAS SOUTH AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD2509G
Insured/Policyholder	
Name Of Registered Owner	KIM SOON LEE PTE LTD
Co Reg No	200304459N
Email Address	PAULINEKIMSOONLEE@GMAIL.COM

Mobile Phone No	
Alternative Phone No	Office-67412222

Vehicle Particulars

Manufacturer	HINO
Model	SH1EEKA-12.9 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	REPORTING ONLY
--	----------------

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S 28949814 MKC
Cover Note Number	08/05/2018 TO 07/05/2019

Driver

Name of Driver	RAMALINGAM MUTHUMANI
NRIC No	G6634837M
Date Of Birth	07/06/1984
Occupation	OUTDOOR
Date Of Driving Pass	28/08/2013
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86150019

Fax Number
Contact Number
EMail Address NOEMAIL
Address 200 BEDOK SOUTH AVE 1, SINGAPORE 469331
Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER WITH ATTACH.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF1548A
Vehicle Make/Model/Colour TOYOTA DYNA

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver LIM SWEE TECK

NRIC/Passport Number S0228427H

Contact Number 82034090

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Tuas South ave 3



Tas South
ave 4

A - XD25096

B - GBF1548A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

upon approaching the traffic light junction of tuas south ave 3. The light turned to yellow & the lorry GBF1548A jam brake in front. I car behind him immediately applied my brake, but still hit onto the rear of his lorry.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
 Tel: +65 6827 7000 Fax: +65 6827 7000
 Co Reg No 200417212G GST Reg No 20-0-112212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.E.300
 Goods Carrying Vehicle - Sch 1

COMMERCIAL VEHICLE
 Comprehensive

Certificate No. S 20949814 MKC

Excess: SGD1,000

1. Index Mark and Registration Number of Vehicle
 XD2509G

2. Name of Policyholder
 Kim Soon Lee Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 09/05/2018

4. Date of Expiry of Insurance
 07/05/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 Use for social domestic and pleasure purposes.
 The Policy does not cover
 (1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.
 (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers


 for Chief Executive Officer

FCY2201803291332

driver's work permit & license

S PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
KIM SOON LEE PTE. LTD.

Name
RAMALINGAM MUTHUMANI

S Pass No.
O 34982405

Sector
MANUFACTURING

K0287368

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G 6634837 M**

Name:
RAMALINGAM MUTHUMANI

Birth Date: **07 Jun 1984**

Issue Date: **05 Sep 2016**

Valid Till: **04/09/2021**

driver's work permit & license

VISIT PASS
Immigration Regulations

Name
RAMALINGAM MUTHUMANI

File
G6634837M

Date of Birth: **07-06-1984** Sex: **M**

Nationality
INDIAN

MULTIPLE JOURNEY VISA ISSUED

Download SGWorkPass App to check status

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS[ES]

		EFFECTIVE DATE
Class 3	Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	03 Sep 2011
Class 4	Motor vehicles which are constructed to carry load or passengers and the unladen weight $> 2500\text{kg}$ Motor vehicles which are not constructed to carry load or passengers and the unladen weight $\leq 7250\text{kg}$	26 Aug 2013

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2018		28 Dec 2018 15:42 Edit Adj Rpt	S\$8,900.00 Edit Estimates	S\$8,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KIM SOON LEE PTE LTD , Co. Reg. No.: 200304459N, Email: PAULINEKIMSOONLEE@GMAIL.COM								
Main Claimant:	UNITED WOODEN CASE & PACKING ENTERPRISE (S) , Co. Reg. No.: 200204250D								
Vehicle Reg. No.:	GBF1548A	Date of Loss:	26/12/2018 09:00 - :59 [29 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 580261	Policy/Cover Note No.:	S28949814MKC (Comprehensive) Coverage: 08/05/2018 - 07/05/2019						
Vehicle Reg. No. (Insured):	XD2509G	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Precision Motorworks Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB, 417896 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/03/2019]								
Driver/Custodian (Insured):	RAMALINGAM MUTHUMANI (34 / Male) , NRIC: G6634837M, Tel: +6586150019 Email:								
Adj Asg. Remarks:	LIABILITY 100% Please contact MR JOHN @ 8742 7247 to arrange for survey								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> MSIG_SG (20/03/2019): Report Send Back Alerts - GBF1548A (TP) 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF1548A (580261)

[XD2509G]



































TP



















































UNITED WOODEN CASE & PACKING ENTERPRISE (S)














































Dec 26 2018 9:00AM

[KIM SOON LEE PTE LTD]

Precision Motorworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/18 18:04	Accident Statement From: SC - Reg. No: XD2509G, Claimant: KIM SOON LEE PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
58	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	02/01/19 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/18 18:04	TPD GBF1548A GIA REPORT <small>From: SC - Reg. No: XD2509G, Claimant: KIM SOON LEE PTE LTD</small>	 Load PDF	
2	27/12/18 18:09	TPD GBF1548A - PRI	 Load PDF	
3	28/12/18 15:29	Reject email to TP lawyer & appoint LKK AUTO	 Load PDF	
4	20/03/19 11:10	Survey Report	 Load PDF	
5	20/03/19 11:11	Survey Photos	 Load PDF	
6	20/03/19 11:12	Survey Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 12:13	PRS Invoice	 Load PDF	
2	29/03/19 12:13	Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18023287/UVD3E2-1

Date: 29/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S28949814MKC

Claimant Vehicle
No: GBF1548A

Insured Vehicle No: XD2509G

Date of Loss: 26/12/2018

Nature of Claim: TP

Claim No: 580261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF1548A

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2626546

Reg. Date: 18/07/2016 (Man. Year: 2016)

Chassis No: JTFAT35Y60K206625

Colour: Silver

Odometer: 128253 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,666.89	8,796.82	6,870.07	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	2,360.00	3,410.00	59.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,436.89	11,156.82	10,280.07	47.96
Approved Total (Overridden) (S\$)		8,900.00		
(S\$)	21,436.89	8,900.00	12,536.89	58.48
+ GST 7.00/7.00% (S\$)	1,500.58	623.00	877.58	58.48
Nett Amount (S\$)	22,937.47	9,523.00	13,414.47	58.48

INSPECTION

Date of Assignment: 28/12/2018

Date Inspected: 31/12/2018 Inspected At:

Precision Motorworks Pte Ltd (HQ)
68 KAKI BUKIT AVENUE 6 #01-02
ARK@KB
Singapore 417896

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Mar 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF1548A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,712.85 F	*1,712.85 FL
2	1		*TAILGATE STICKER TOYOTA	Necessary	192.62 F	*192.62 FL
3	4		*TAILGATE HINGES	Bent	318.40 F	*318.40 FL
4	2		*REAR SIDEGATE LOCK RH/LH	Bent	242.60 F	*242.60 FL
5	1		*REAR SIDEGATE RH	Buckled	2,117.80 F	*2,117.80 FL
6	1		*REAR END PANEL STICKER DYNA	Necessary	19.02 F	*19.02 FL
7	1		*REAR TAIL LAMP RH/LH	N/S Not Necessary / O/SCracked	502.80 F	*251.40 FL
8	1		*REAR TAIL LAMP BRACKET RH/LH	N/S Not Necessary / O/S Bent	402.60 F	*201.30 FL
9	2		*REAR TAILGATE STOPPER RUBBER RH/LH	Deformed	144.80 F	*144.80 FL
10	2		*REAR TAILGATE STOPPER BRACKET RH/LH	Bent	200.60 F	*200.60 FL
11	1		*REAR NUMBER PLATE BRACKET	Bent	273.70 F	*273.70 FL
12	1		*FRONT CABIN REAR PANEL	Repair	691.00 F	*-FL
13	1		*REAR WINDSCREEN GLASS RUBBER	Not Necessary	75.00 F	*-FL
14	1		*REAR CARGO CARRIER FLOOR PANEL }	Buckled	5,754.00 F	*5,754.00 FL
15	8		*CHASSIS OUTRIGGER RH/LH }		960.00 F	*-FL
16	6		*REAR CARGO CARRIER FLOOR PANEL CROSS STRUCTURE BEAM }		1,200.00 F	*-FL
17	1		*FRONT DOOR REAR PILLAR PANEL	Repair	388.10 F	*-FL
18	1		*TAILGATE STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
19	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Bent	25.00 FS	*15.00 FS
21	1		*REAR NUMBER PLATE LAMP	Not Necessary	86.00 F	*-FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,666.89	11,654.09
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,857.27
Total Parts (\$\$)	15,666.89	8,796.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING FRONT CABINET REAR PANEL, REAR CHASSIS FRAME MEMBER AND REAR FRAME MEMBERS. TO CUT / WELD FRONT DOOR LH REAR PILLAR PANEL. TO REMOVE AND REFIT ABOVE PARTS	New	3,000.00	1,000.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	2,000.00	1,000.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	120.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	150.00	80.00
5	TO PROVIDE LIFTING EQUIPEMENT TO REMOVE AND REFIT REAR CARGO CARRIER FLOOR PANEL	New	500.00	250.00
Gross Labour Cost (S\$)			5,770.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >