

REF: CS/ICS 19005257 / Utd 352

Special Instruction:

un run Surveyor

Surveyor

Marcus

ASSIGNMENT (Office)

Date/Time:

22/3/19 @ 6.07pm

From (Person):

crystabelle tan

or

ICS

Bill to:

Estimated Cost:

OD / FT / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 1174K

Insured:

SGN 2052E

at Workshop m/s

QuonDe Motor

Tel:

96709191

of

1 Kalki Bukit Ave 6 # 01-67

Policy No:

Claim No:

DMPC 1900077H/JG

Excess:

Sum Insured:

D.O.A.

22/03/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

9:33am @ 22/3/19

Person Contacted:

Jennifer

H.O.D. Reimbursement

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJW 1174K - X
	SGN 2052E - X ...

(08/11/13) wef

REF:

SLIC

ASS. REC. BY: Marcus

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 7509

vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

2-3-2020

ref 1049 / rental company per month 1500 x 11 = 16500

9/4/19 2/5 x 10,000 confirm with Jennifer (Red: 11513.65, 53%)

Veh No:

5JW1174K

Yr Regn:

3/3/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

KIA cerato ex forte c.c

1591

Colour

blue

A/C: Insured / Std / NI / NA

Sp. Reading

sooty flap

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAFU411MA 5188574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/3/19

D.O.I.

25/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; R/L

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 APR 2019

Date/Time, File Pass to?

1) 104 TYP184

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I.: (\$ 10,000)

Days Of Repair:

16

Resurvey No. of Trip:

1

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

10

## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Friday, 22 March 2019 6:07 PM  
**To:** assignments  
**Cc:** Janice Goh Siew Geok (ECICS, Claims)  
**Subject:** RE: Pre-Repair Inspection - SGN2052E - Ref : DMPC1900077H/JG  
**Attachments:** SAS2572316 (2).PDF

Dear LKK

Enclosed OI SAS.

NOTE: This case is handle by Janice Goh.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** ECICS Claims  
**Sent:** Friday, 22 March, 2019 6:04 PM  
**To:** assignments  
**Cc:** ECICS Claims; Janice Goh Siew Geok (ECICS, Claims); Jennifer Pang  
**Subject:** RE: Pre-Repair Inspection - SGN2052E - Ref : DMPC1900077H/JG

Dear LKK

Refer to below email and arrange survey.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Jennifer Pang [mailto:quanv3@yahoo.com.sg]  
**Sent:** Friday, 22 March, 2019 5:58 PM

**To:** ECICS Claims

**Subject:** Re: Pre-Repair Inspection - SGN2052E - Ref : DMPC1900077H/JG

Dear Crystabelle Tan,

We refer to the above email.

Kindly arrange your panel surveyor, M/s. LKK Auto Consultants to survey our client's vehicle SJW1174K soonest possible.

Thank you.

Regards,  
Quan De Motor Trading  
Jennifer

On Friday, 22 March 2019, 5:54:29 pm GMT+8, ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)> wrote:

Dear Jennifer

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Jennifer Pang [mailto:[quanv3@yahoo.com.sg](mailto:quanv3@yahoo.com.sg)]

**Sent:** Friday, 22 March, 2019 4:15 PM

**To:** ECICS Claims

**Subject:** Pre-Repair Inspection

Hi All,

Accident on 22/03/2019 involving vehicles SJW1174K, SGN2052E, SMD2538C, SLK350P & SHD7068T along PIE towards Changi

Kindly arrange for pre-repair inspection for vehicle SJW1174K as we are claiming against your insured vehicle SGN2052E.

Quan De Motor Trading

1 Kaki Bukit Avenue 6

#01-67 Autobay, (417883)

Contact: Ms. Jennifer (Hp: 96709191)

Regards,

Quan De Motor Trading

Jennifer

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

MSME19037989 / SME Motor Pto Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 22/03/2019 16:56  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 22/03/2019 16:56  
 Date Of Accident 22/03/2019 11:00  
 Exact Location Of Accident PIE TWDS CHANGI (THOMSON FLYOVER)  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SJW1174K  
 Insured/Policyholder  
 Name Of Registered Owner EAZI CAR LEASING & MARKETING PTE LTD  
 Co Reg No 200715161E  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-NOPHONE

**Vehicle Particulars**

Manufacturer KIA  
 Model CERATO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company ERGO INSURANCE PTE. LTD.  
 Type Of Coverage THIRD PARTY  
 Fleet Policy NO  
 Policy Number DMFG19003100  
 Cover Note Number

**Driver**

Name of Driver CHEW KAI SHENG  
 NRIC No S9345981D  
 Date Of Birth 03/12/1993  
 Occupation INDOOR  
 Date Of Driving Pass 05/10/2018  
 Driving Experience 0 YEAR AND 5 MONTH  
 Gender MALE  
 Mobile Number (LOCAL) +65-97676474  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address BLK 443C BUKIT BAKO WEST AVE 8 #02-793  
 Postcode 653443  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) Involved in the accident 5  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

FIRST CAR JAMMED BRAKE SUDDENLY DUE TO A CAR IN FRONT OF HIS CAR BRAKED. SECOND CAR BRAKED AND FOLLOWED BY ALL THE CARS BEHIND ALSO JAMMED BRAKE. I ALSO MANAGED TO BRAKE IN TIME BEHIND THE THIRD VEHICLE (TAXI) WITHOUT HITTING HIM. SUDDENLY, VEHICLE B (SGN2052E) TRAVELLING AT HIGH SPEED COULD NOT BRAKE IN TIME AND HIT ONTO THE REAR OF MY VEHICLE AND THE GREAT IMPACT CAUSED MY VEHICLE TO LOSE CONTROL AND HIT ONTO THE RAILING AT THE RIGHT AND ALSO HIT ONTO THE RIGHT SIDE OF TAXI IN FRONT OF ME. IT WAS A CHAIN COLLISION INVOLVING 5 VEHICLES.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGN2052E  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage



No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMD2538C  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE C  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLK350P  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE D  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SHD7068T  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE E  
Vehicle Category TAXI  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

braked.

First car jammed brake suddenly due to a car in front of his car. Second car braked & followed by all the cars behind also jammed brake & I also managed to brake in time behind the 3rd vehicle (taxi) without hitting him. Suddenly, vehicle (B) - SGH 2052E travelled by high speed could not brake in time & hit onto the rear of my vehicle & the great impact caused my vehicle to lose control & hit onto the railing on the right & also hit onto the ~~front~~ right side of the taxi in front of me. It was a chain collision involving 5 vehicles.

## DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5161E

### Vehicle Details

Vehicle No.:	SJW1174K
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9H352976
Chassis No.:	KNAFU411MA5188574
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$11,245.00
Original Registration Date:	03 Mar 2010
First Registration Date:	03 Mar 2010
Transfer Count:	3
Actual ARF Paid:	\$11,245.00 5622

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2020
PARF Rebate Amount:	\$5,622.00

### Intended COE Rebate Details

COE Expiry Date:	02 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,340.00
COE Rebate Amount:	\$1,887.00
<b>Total Rebate Amount:</b>	<b>\$7,509.00</b>

The information contained herein is correct as at 25 Mar 2019

OK

Cerato Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home » Used Cars » ValueCars Auto Traders » Kia Cerato Forte 1.6A EX

## Kia Cerato Forte 1.6A EX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

<b>Price</b>	\$16,500		
<b>Depreciation</b>	\$10,040 /yr <small>View models with similar depre</small>	<b>Reg Date</b>	21-Apr-2010 (1yr 26days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b>	2010
<b>Road Tax</b>	\$738 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$9,335 as of today (change)	<b>OMV</b>	\$11,430
<b>COE</b>	\$28,389	<b>ARF</b>	\$11,430
<b>Engine Cap</b>	1,591 cc	<b>Power</b>	92.7 kW (124 bhp)
<b>Curb Weight</b>	1,251 kg	<b>No. of Owners</b>	2
<b>Type of Vehicle</b>	Mid-Sized Sedan		

### Features

Powerful And Responsive 1.6L 4 Cylinders 16 Valves DOHC Engine, Smooth 4 Speed Auto. View specs of the Kia Cerato Forte (2009-2013)

### Accessories

Bodykit And Sports Rims, Factory Fitted Audio System, Reverse Sensors.

### Description

Loan Available, This 4 Dr Kia Forte EX 1.6A In Its Original Condition! Durable Ride And Hassle Free Kia Forte 1.6A! Very Well Taken Care By Seller! Easy To Maintain Korean Ride! Best Quality 2nd Hand Car! Popular Among COE Renewable Car! Come View And We Discuss Further! Thanks!

### Category

PARF Car

### Status

Available

### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 23-Mar-2019 | Last Updated on: 24-Mar-2019

Upfront Payment  
Compare

» more Financial Info



Location Map

Price Chart

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report error

More Actions

### Seller Information

#### Company

ValueCars Auto Traders

» dealer's pricelist

» 48 vehs sold | 15 vehs available

#### Address

61 Ubi Avenue 2 #02-06

Search cars nearby this location



Cerato

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

Home » Used Cars » DSC Motor LLP » Kia Cerato Forte 1.6A SX

## Kia Cerato Forte 1.6A SX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$15,000**Depreciation** \$8,270 /yr  
View models with similar depre**Reg Date** 03-Mar-2010  
(11mths 6days COE left)**Mileage** N.A.**Manufactured** 2009**Road Tax** \$738 /yr**Transmission** Auto**Dereg Value** \$9,143 as of today (change)**OMV** \$14,464**COE** \$20,340**ARF** \$14,464**Engine Cap** 1,591 cc**Power** 92.7 kW (124 bhp)**Curb Weight** 1,251 kg**No. of Owners** 2**Type of Vehicle** Mid-Sized Sedan

## Features

4 Cylinder Inline 16 Valves DOHC Engine Producing 124bhp Mated To 5 Speed Steptronic. ABS, Knockdown Rear Seats, Keyless Entry/Start/Stop. View specs of the Kia Cerato Forte (2009-2013)

## Accessories

Leather Seats, Built In Audio With AUX/USB/Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film, Fog Lights.

## Description

Modern And Stylish Family Sedan. Convenience Keyless Entry, Factory Fitted Leather Seat And Original Stock Condition. Well Maintained, Neat And Clean Interior, Light On Fuel And Yet Reliable. New Tax Till Sept 19. Call Now!

## Category

PARF Car

## Status

Available

## Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started


Posted on: 16-Mar-2019 | Last Updated on: 23-Mar-2019

Compare



## Price Chart

## Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

## Company

DSC Motor LLP

\* dealer's pricelist

\* 10 vehs sold | 3 vehs available

## Address

24 Sin Ming Lane #02-105D

Search cars nearby this location

## Location

Midview City

## Contact Person(s)

Serene

81120002

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



No Card



Cerato

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Miracle Automobile Pte Ltd » Kia Cerato Forte 1.6A SX

## Kia Cerato Forte 1.6A SX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

<b>Price</b>	\$21,800		
<b>Depreciation</b>	\$11,630 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	29-Jun-2010 (1yr 3mths 3days COE left)
<b>Mileage</b>	145,000 km (16.6k /yr)	<b>Manufactured</b>	2009
<b>Road Tax</b>	\$738 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$11,800 as of today (change)	<b>OMV</b>	\$14,218
<b>COE</b>	\$31,510	<b>ARF</b>	\$14,218
<b>Engine Cap</b>	1,591 cc	<b>Power</b>	92.7 kW (124 bhp)
<b>Curb Weight</b>	1,251 kg	<b>No. of Owners</b>	2
<b>Type of Vehicle</b>	Mid-Sized Sedan		



## Features

1.6L DOHC Engine, SRS Airbags, Multi Function Steering Control, Auto Climatic Aircon Control, Keyless Start, Reverse Sensors. [View specs of the Kia Cerato Forte \(2009-2013\)](#)

## Accessories

Sports Rims, Factory Fitted Audio System, Solar Film, Upholstery Leather Seats.

## Description

Full Agent Services. Immaculate Condition, No Repair Require. New Paint Work. 10% Down Available! Don't Miss!

## Category

PARF Car

## Status

Available

## Resources



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



## Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

Posted on: 27-Jan-2019 | Last Updated on: 27-Jan-2019

## Upfront Payment

[\\* more Financial info](#)


## Transfer Fee

\$25

[Compare](#)

## Price Chart

## Summary



[Click on the point to view the vehicle](#)

[Shortlist](#)

[Compare](#)

[Add note](#)

[Report Error](#)

[More Actions](#)

## Seller Information

## Company

Miracle Automobile Pte Ltd

\* dealer's pricelist

\* 2 vehs sold | 1 vehs available

## Address

24 Leng Kee Road #05-09

[Search cars nearby this location](#)

## Location

Leng Kee Autopoint

## Office No

97125719



SUPREME

CLICK HERE OR CALL  
64

Kia Cerato

Price Range ▼

Depreciation ▼

2010 ▼

Vehicle Type ▼



Home » Used Cars » 360 VR Cars » Kia Cerato Forte 1.6A SX

## Kia Cerato Forte 1.6A SX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

## 360° VR Cars

Price \$19,500

Depreciation ⓘ

\$10,060 /yr

View models with similar depre

Reg Date

29-Jun-2010

(1yr 2mths 19days COE left)

Mileage

N.A.

Manufactured ⓘ

2010

Road Tax ⓘ

\$738 /yr

Transmission

Auto

Dereg Value ⓘ

\$11,778 as of today (change)

OMV ⓘ

\$14,414

COE ⓘ

\$31,510

ARF ⓘ

\$14,414

Engine Cap

1,591 cc

Power

92.7 kW (124 bhp)

Curb Weight ⓘ

1,251 kg

No. of Owners ⓘ

3

Type of Vehicle

Mid-Sized Sedan

## Features

4 Cylinder Inline 16 Valves DOHC Engine Producing 124bhp Mated To 5 Speed Steptronic. ABS, Knockdown Rear Seats, Keyless Entry/Start/Stop. View Specs View specs of the Kia Cerato Forte (2009-2013)

## Accessories


Leather Seats, Built In Audio With AUX/USB/Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film, Fog Lights.

## Description

Very Well Maintained Car, Original Mileage, Silver Exterior With Leather Interior, Owned This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price! Trade In And Flexible Loan Available, Viewing Strictly By Appointment Only.


## Categor

PAF Compare



Location Map

Price Chart



Click on the point to view



Sumat to insurance.

**QUAN DE MOTOR TRADING**

1 KAKI BUKIT AVENUE 6, #01067

AUTOBAY, SINGAPORE 417883

HP: 96709191 FAX: 66840767

ECICS Limited  
 10 Eunos Road 8, #09-04  
 Singapore Post Centre  
 Singapore 408600  
 Attn: Motor Claims Department

Date: 25 March 2019

**Accident on 22/03/2019 involving vehicles SJW1174K, SGN2052E, SMD2538C,  
 SLK350P, SHD7068T along PIE towards Changi**

**Estimate cost of repair to vehicle SJW1174K Kia Cerato EX Forte 1.6L A**

1 pc.	bootlid	Blue	\$	673.50	✓
1 pc.	bootlid outer handle	Buttline	\$	265.00	✓
1 pc.	bootlid rear logo	new	\$	45.00	✓
1 pc.	bootlid "CERATO" emblem	new	\$	48.00	✓
1 pc.	bootlid "FORTE" emblem	new	\$	40.00	✓
1 pc.	bootlid "C&C" logo	new	\$	42.00	✓
1 pc.	bootlid inner lock	twi/gm	\$	105.00	✓
1 pc.	bootlid inner trim	Trim	\$	188.20	✓
1 pc.	bootlid weatherstrip	twi	\$	161.00	✓
2 pcs.	bootlid hinges @\$105.00	new	\$	210.00	X
2 pcs.	bootlid reflectors @\$265.00	new	\$	530.00	✓
1 pc.	bootlid license lamp	new	\$	45.00	X
1 pc.	rear bumper	new	\$	601.00	✓
1 pc.	rear bumper sponge	new	\$	165.00	✓
1 pc.	rear bumper reinforcement	new	\$	366.00	✓
2 pcs.	rear bumper side holders @\$35.00	new	\$	70.00	✓
2 pcs.	rear bumper brackets @\$145.00	new	\$	290.00	✓
5 pcs.	rear bumper reinforcement brackets @\$22.00	twi	\$	110.00	✓
1 pc.	rear bumper lower skirting	new	\$	148.00	✓
2 pcs.	taillamps @\$385.00	new	\$	770.00	✓
1 pc.	rear end panel	Body	\$	481.00	✓
1 pc.	rear end panel top garnish	twi	\$	173.00	✓
1 pc.	rear floor panel	crushed	\$	971.00	✓
1 pc.	rear floor panel top board	Wagon/cor	\$	298.00	✓
2 pcs.	rear fenders @\$966.00	new	\$	1,932.00	W C
2 pcs.	rear fender inner trims @\$184.00	new	\$	368.00	W C
2 pcs.	rear fender splash shields @\$48.00	new	\$	96.00	W C
1 pc.	rear air vent	new	\$	45.00	✓
1 pc.	rear windscreen moulding	new	\$	68.30	✓
1 pc.	rear exhaust	new	\$	791.00	X
				<b>\$ 10,096.00</b>	

not Authorized  
 Mark  
 25/3/19  
 Singapore  
 2/s \$10,000/  
 16 day.

		Bal c/f	\$ 10,096.00	
1 pc.	bonnet	Buc	\$ 698.00	✓
2 pcs.	bonnet hinges @\$65.00	11	\$ 130.00	X
1 pc.	bonnet rubber	ser	\$ 35.00	✓
1 pc.	front bumper	D-5	\$ 698.00	✓
1 pc.	front bumper reinforcement	ser	\$ 288.00	✓
1 pc.	front bumper side holder	ser	\$ 45.00	✓
1 set	front bumper clips	ser	\$ 40.00	✓
1 pc.	front bumper fog lamp cover	Tom	\$ 62.00	✓
1 pc.	front bumper fog lamp	cm	\$ 305.00	✓
1 pc.	front bumper centre grille	11	\$ 188.00	X
1 pc.	front fender	Buc	\$ 422.00	✓
1 pc.	front fender inner shield	Tom	\$ 185.00	✓
1 pc.	headlamp assy 165	Sno	\$ 735.00	✓
1 pc.	front support panel	cm	\$ 645.00	✓
1 pc.	front door	n	\$ 899.00	X
1 pc.	battery tray	cm	\$ 49.50	✓
			\$ 15,520.50	
		Less 10%	\$ 1,552.05	12059.5
			\$ 13,968.45	10853.55

**S. Nett Items:**

1 pc.	front tyre LP 160	pur	\$ 300.00	50% 905.2
1 pc.	front license plate w/holder	17	\$ 50.00	X
1 set	rear reverse sensor	shnd	\$ 280.00	200
1 set	rear floor panel insulator	ser	\$ 250.00	100
1 pc.	rear windscreen sealant	ser	\$ 45.00	40

**Labour Charges:**

Towing	\$ 100.00	60
To check wiring	\$ 100.00	30
To remove & reinstall reverse sensor	\$ 100.00	50
To remove & reinstall rear windscreen	\$ 150.00	120
To remove & reinstall petrol tank	\$ 100.00	60
To remove & refix seat cushion, upholstery	\$ 150.00	80
To conduct wheel alignment	\$ 120.00	60
To spray rust proofing	\$ 100.00	✓
Labour for panel beating, welding and renew parts	\$ 3,200.00	2200
Spray painting	\$ 2,500.00	1800

Total: \$ 21,513.45

LKK Auto Consultants hence notify the Repalrer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repalrer

Signature

Date

15843.55

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019 10:23 <a href="#">Edit Reg</a>		22 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$10,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$10,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: EMAIL@YAHOO.COM		
Main Claimant:	-		
Vehicle Reg. No.:	<b>SJW1174K</b>	Date of Loss:	22/03/2019 18:00 - :59 [108 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / DMPC1900077H/JG</b>	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	<b>SGN2052E</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Quan De Motor Trading ()</b> BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883, 417883 Kaki Bukit - Tel:		
Handling Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Janice Goh</b> - 6303 0182]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 03/04/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJW1174K (DMPC1900077H/JG)**  
**[SGN2052E]**




































**TP**
















































**-**

**Mar 22 2019 6:00PM**







































**[-]**



**Quan De Motor Trading**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser ▼</a>	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
74	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
75	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
76	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
77	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
78	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
79	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
80	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
81	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
82	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
83	10/04/19 11:14	General View	Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
85	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
86	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
87	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
88	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
89	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
90	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
91	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
92	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
93	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
94	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
95	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
96	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
97	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
98	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
99	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
100	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
101	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
102	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
103	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
104	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
105	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
106	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
107	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
108	10/04/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
109	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	10/04/19 11:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS19005257/UTD3S2  
**Date:** 25/04/2019

## REFERENCE

Handling Insurer: ECICS Limited Policy No:  
**Claimant Vehicle No :** SJW1174K **Insured Vehicle No :** SGN2052E  
 Date of Loss: 22/03/2019 Nature of Claim: TP Claim No: DMPC1900077H/JG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJW1174K**  
 Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FC9H352976  
 Reg. Date: 03/03/2010 (Man. Year: 2009) Chassis No: KNAFU411MA5188574  
 Colour: Blue Odometer: 0 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm  
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,893.45	11,283.55	3,609.90	24.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,620.00	4,560.00	2,060.00	31.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,513.45</b>	<b>15,843.55</b>	<b>5,669.90</b>	<b>26.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>21,513.45</b>	<b>10,000.00</b>	<b>11,513.45</b>	<b>53.52</b>

## INSPECTION

Date of Assignment: 22/03/2019  
 Date Inspected: 25/03/2019 Inspected At: Quan De Motor Trading  
 BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY  
 SINGAPORE 417883  
 Singapore 417883  
 Estimated Period of Repair: 16.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2019)
<b>Parts:</b>	143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW1174K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Buckled	673.50 FL	*673.50 FL
2	1	*BOOTLID OUTER HANDLE	Bent / Cracked	265.00 FL	*265.00 FL
3	1	*BOOTLID REAR LOGO	Necessary	45.00 FL	*45.00 FL
4	1	*BOOTLID CERATO EMBLEM	Necessary	48.00 FL	*48.00 FL
5	1	*BOOTLID FORTE EMBLEM	Necessary	40.00 FL	*40.00 FL
6	1	*BOOTLID C&C LOGO	Necessary	42.00 FL	*42.00 FL
7	1	*BOOTLID INNER LOCK	Twisted / Jammed	105.00 FL	*105.00 FL
8	1	*BOOTLID INNER TRIM	Torn	188.20 FL	*188.20 FL
9	1	*BOOTLID WEATHERSTRIP	Twisted	161.00 FL	*161.00 FL
10	2	*BOOTLID HINGES	Repair	210.00 FL	*- FL
11	2	*BOOTLID REFLECTORS	Cracked	530.00 FL	*530.00 FL
12	1	*BOOTLID LICENCE LAMP	Not Necessary	45.00 FL	*- FL
13	1	*REAR BUMPER	Distorted	601.00 FL	*601.00 FL
14	1	*REAR BUMPER SPONGE	Distorted	165.00 FL	*165.00 FL
15	1	*REAR BUMPER REINFORCEMENT	Distorted	366.00 FL	*366.00 FL
16	2	*REAR BUMPER SIDE HOLDERS	Bent	70.00 FL	*70.00 FL
17	2	*REAR BUMPER BRACKETS	Bent	290.00 FL	*290.00 FL
18	5	*REAR BUMPER REINFORCEMENT BRACKETS	Twisted / Cracked	110.00 FL	*110.00 FL
19	1	*REAR BUMPER LOWER SKIRTING	Distorted	148.00 FL	*148.00 FL
20	2	*TAILLAMPS	Cracked	770.00 FL	*770.00 FL
21	1	*REAR END PANEL	Badly Dented	481.00 FL	*481.00 FL
22	1	*REAR END PANEL TOP GARNISH	Twisted	173.00 FL	*173.00 FL
23	1	*REAR FLOOR PANEL	Crumpled	971.00 FL	*971.00 FL
24	1	*REAR FLOOR PANEL TOP BOARD	Warped / Cracked	298.00 FL	*298.00 FL
25	1	*REAR FENDERS	N/s Badly Dented	1,932.00 FL	*966.00 FL
26	1	*REAR FENDER INNER TRIMS	N/s Deformed / Torn	368.00 FL	*184.00 FL
27	1	*REAR FENDER SPLASH SHIELDS	N/s Torn	96.00 FL	*48.00 FL
28	1	*REAR AIR VENT	Cracked	45.00 FL	*45.00 FL
29	1	*REAR WINDSCREEN MOULDING	Necessary	68.30 FL	*68.30 FL
30	1	*REAR EXHAUST	Not Necessary	791.00 FL	*- FL
31	1	*BONNET	Buckled	698.00 FL	*698.00 FL
32	2	*BONNET HINGES	Not Necessary	130.00 FL	*- FL
33	1	*BONNET RUBBER	Necessary	35.00 FL	*35.00 FL
34	1	*FRONT BUMPER	Distorted	698.00 FL	*698.00 FL
35	1	*FRONT BUMPER REINFORCEMENT	Bent	288.00 FL	*288.00 FL
36	1	*FRONT BUMPER SIDE HOLDER	Bent	45.00 FL	*45.00 FL
37	1	*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
38	1	*FRONT BUMPER FOG LAMP COVER	Torn	62.00 FL	*62.00 FL
39	1	*FRONT BUMPER FOG LAMP	Cracked	305.00 FL	*305.00 FL
40	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	188.00 FL	*- FL
41	1	*FRONT FENDER	Buckled	422.00 FL	*422.00 FL
42	1	*FRONT FENDER INNER SHIELD	Torn	185.00 FL	*185.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*HEADLAMP ASSY N/S	Broken	735.00 FL	*735.00 FL
44	1		*FRONT SUPPORT PANEL	Cracked	645.00 FL	*645.00 FL
45	1		*FRONT DOOR	Repair	899.00 FL	*- FL
46	1		*BATTERY TRAY	Cracked	49.50 FL	*49.50 FL
47	1		*FRONT TYRE (LOCAL PURCHASE) (@ \$180.00 DISC 50%)	Punctured	300.00 FS	*90.00 FS
48	1		*FRONT LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
49	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
50	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	250.00 FS	*100.00 FS
51	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,445.50</b>	<b>12,489.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,552.05</b>	<b>1,205.95</b>

<b>Total Parts (\$\$)</b>	<b>14,893.45</b>	<b>11,283.55</b>
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING.	New	100.00	60.00
2	TO CHECK WIRING.	New	100.00	30.00
3	TO REMOVE & REINSTALL REVERSE SENSOR.	New	100.00	50.00
4	TO REMOVE & REINSTALL REAR WINDSCREEN.	New	150.00	120.00
5	TO REMOVE & REINSTALL PETROL TANK.	New	100.00	60.00
6	TO REMOVE & REFIX SEAT CUSHION, UPHOLSTERY.	New	150.00	80.00
7	TO CONDUCT WHEEL ALIGNMENT.	New	120.00	60.00
8	TO SPRAY RUST PROOFING.	New	100.00	100.00
9	LABOUR FOR PANEL BEATING, WELDING AND RENEW PARTS.	New	3,200.00	2,200.00
10	SPRAY PAINTING.	New	2,500.00	1,800.00
Gross Labour Cost (\$\$)			6,620.00	4,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >