

ASS. REC. BY:

REP: CS/PC1 19005258/Gqd 302

Special Instruction:

Surveyor

Call

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

PEI

Date/Time:

23/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFU 18229

Insured:

SHA 9956H

at Workshop n/a

Lsoon Auto

Tel:

648 2153

of

No. 10 Amk Ind. park 2A #03-18

Policy No:

Claim No:

D19001988 MRSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

2/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:30am @ 28/3/19

Person Contacted:

Mrs. Lee

Vehicle (IN) (OUT)

(IN) (OUT)

Date/Time

Action/Instruction (✓) Estimate

SFU 18229 - X

SHA 9956H - CS/PC1 18022167 / Uqd 3n2 D.O.A - 02/12/2018

08/4/19 @ 11:00am

Estan revised to Henry Kao by email.

09/4/19

Submit prelim. report. - According to XRS, WWSY will not
Analyse. with him. & ask him submit PRS.

MOTOR SURVEY ASSIGNMENT

Date	21-03-2019	Our Ref No. D19001988MFSH
Accident Date	21-03-2019	Claim Type. Third Party
Insured Vehicle	SHA9956H	Third Party Vehicle. SFU1822G
Survey Location	NO.10 ANG MO KIO INDUSTRIAL PARK 2A #03-18 AMK AUTOPOINT	
Contact Person.	MRS LEE	
Contact No.	64821513/ 0	Fax No. 65562590
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	L SOON AUTO SERVICES	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Elaine Toh

From: Elaine Toh <Elainetoh@visionlawllc.com>
Sent: Friday, 22 March, 2019 2:46 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'
Subject: RE: Our Ref: Pre-Repairs Assessment Request for SFU1822G - accident involving with SHA9956H

Importance: High

Our Ref: SFU 1822 G (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of 21 March 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **MA CHIN FOOK – LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

L SOON AUTO SERVICES
No. 10 Ang Mo Kio Industrial Park 2A
#03-18 AMK Autopoint
Singapore 568047

Contact : **Mrs Lee @ 64821513 (To call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,
 Elaine Toh
 Vision Law LLC
 Tel: 65342811 (Ext. 122)
 Fax: 65356802



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
 Thank you.

Appointed surveyor :
 (Name & Signature)

Guo Qiang
LKK

Date & Time of Inspection :

25/3/19.

cc: SFU 1822 G – By fax: 65562590 only

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 21 March, 2019 6:56 PM
To: Elainetoh@visionlawllc.com
Cc: Henry Kao Cai Jie; CWS Motor Claims
Subject: Our Ref: Pre-Repairs Assessment Request for SFU1822G - accident involving with SHA9956H

Without Prejudice

Dear Sirs,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 8 April 2019 11:25 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001988MFSH/1
Attachments: CSFCI19005258Gqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SFU 1822G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 25 March 2019 10:28 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001988MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 March 2019 4:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001988MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001988MFSH
Our Ref: CS/FCI19005258/Gqd3

Date: 08 April 2019

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SFU 1822G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/03/2019 at the premises of M/s L SOON AUTO . and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 22,631.28</u> .
Revised Estimate Amount	: <u>S\$ 5,484.00</u> .
"Check" Items Amount	: <u>S\$ 11,453.84</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:
The vehicle sustained damages
at the front portion.



Yours faithfully

Guo Qiang
Automotive Assessor

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5890I
Vehicle Details	
Vehicle No.:	SFU1822G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	SUBARU
Vehicle Model:	BRZ 2.0 6AT ABS D/AIRBAG RWD 2DR HID
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	FA20G929450
Chassis No.:	JF1ZC6K72DG002947
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$22,283.00
Original Registration Date:	29 Nov 2014
First Registration Date:	29 Nov 2014
Transfer Count:	2
Actual ARF Paid:	\$23,197.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2024
PARF Rebate Amount:	\$17,397.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$73,900.00
COE Rebate Amount:	\$41,344.00
Total Rebate Amount:	\$58,741.00

The information contained herein is correct as at 26 Mar 2019

OK

▶ Subaru BRZ Used Vehicle List (1 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Subaru BRZ	\$68,000	\$11,680 /yr	31-Dec-2013	1,998 cc	80,000 km	Monster Motors Pte Ltd	Availal

Cheapest Depreciation Guaranteed. Full Agent Serviced With Records. Awesome Condition. Unbeatable Handling With The Corners. Definitely Fun And Sporty Car To Own. Loan And Trade-in Available. Call U...

Office No. - -

Austin - 87512137 | Low - 96538664

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/03/2019 17:04
Date Of Accident	21/03/2019 13:35
Exact Location Of Accident	CLAYMORE ROAD INFRONT OF ETONHOUSE INT SCHOOL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU1822G
Insured/Policyholder	
Name Of Registered Owner	FOO JOON AIK JOSEPH
NRIC No	S1795890I
Email Address	FOOJFA@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96810831
Alternative Phone No	OTHERS-96810831

Vehicle Particulars

Manufacturer	SUBARU
Model	BRZ-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA361828/1
Cover Note Number	05/06/2018 - 04/06/2019

Driver

Name of Driver	FOO JOON AIK JOSEPH
NRIC No	S1795890I
Date Of Birth	08/06/1967
Occupation	INDOOR
Date Of Driving Pass	18/06/2012
Driving Experience	6 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96810831
Fax Number	
Contact Number	OTHERS-96810831
Email Address	FOOJFA@YAHOO.COM.SG

Address	BLK 35 LORONG 5 TOA PAYOH #12-329
Postcode	310035
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWN WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA9956H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MR TAN
NRIC/Passport Number	S7327570I
Contact Number	93895721
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	FOO JOON AIK JOSEPH
Approximate Age	
Injuries Sustain	NECK & SHOULDER
Injured person in which vehicle?	SFU1822G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 21/03/2019 Time: 13.35 Location: towards claymore Road towards American club.
 My Vehicle A: SFU 1822G Vehicle B: SHA 9956H Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/3 Thursday at 1:30pm. I drive out from Orchard Towers carpark. I was driving towards claymore Road towards American club. When I was turning a slight bend along claymore Road near Etonhouse school. Suddenly a yellow taxi comfort. SHA 9956H. drive out to turn right. I apply my emergency brake but his taxi already 3/4 body turning towards me and hence ~~my~~ ~~the~~ car had a impact on the taxi's driver front side. I feel pain on my neck and shoulder on the impact of the accident.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop : L Soon Auto services.
 Email address : L_Soon@ymail.com
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Officer's Signature
 Name:
 NRIC/FIN No.:

AHLIM MOTOR COMPANY

L Soon Auto Services
 No.10 Ang Mo Kio Industrial Park 2A
 #03-18 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6482 1513 Fax: 6556 2590

SFU1822G Subaru BRZ

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy / bc.	\$ 2,800.00
2	2	Front bumper bracket ?	\$ 182.00
3	2	Front bumper retainer X NN	\$ 188.00
4	1	Front bumper reinforcement ?	\$ 323.00
5	1	Front bumper sponge ?	\$ 195.00
6	1	Front bumper top beam ?	\$ 295.00
7	1	Front bumper left nozzle ?	\$ 148.30
8	1	Front bumper right nozzle X NN	\$ 148.30
9	1	Front bumper left nozzle cover - Mis.	\$ 73.50
10	1	Front bumper right nozzle cover X NN	\$ 73.50
11	1	Front left headlamp ?	\$ 2,260.30
12	1	Front right headlamp ?	\$ 2,260.30
13	1	Front left headlamp lower bracket ?	\$ 52.70
14	1	Front right headlamp lower bracket ?	\$ 52.70
15	1	Front left fog lamp ?	\$ 380.00
16	1	Front right fog lamp X NN	\$ 380.00
17	1	Front left fog lamp cover ?	\$ 85.00
18	1	Front right fog lamp cover X NN	\$ 85.00
19	1	Front lower grille assy ?	\$ 368.00
20	1	Front bumper emblem / bc.	\$ 148.00
21	1	Front bonnet assy / Buc.	\$ 1,828.00
22	1	Front bonnet insulator / bc.	\$ 179.00
23	2	Front bonnet hinges X NN	\$ 166.00
24	2	Front bonnet rubber stopper X NN	\$ 38.00
25	1	Front bonnet lock / BT	\$ 189.00
26	1	Front bonnet lock catch X NN	\$ 68.00
27	1	Front support panel assy ?	\$ 1,065.00
28	1	Front left fender assy X	\$ 985.00
29	1	Front right fender assy X repair.	\$ 985.00
30	1	Front air con condenser with dryer assy ?	\$ 1,023.00
31	1	Front air con condenser fan blade with motor assy ?	\$ 448.00
32	1	Front air-con discharge pipe ?	\$ 288.00
33	1	Front air-con suction pipe ?	\$ 278.00
34	1	Front air duct ?	\$ 275.00
35	1	Front air intake box assy ?	\$ 450.00
36	1	Front radiator assy ?	\$ 1,085.00
37	1	Front radiator fan blade with motor complete assy ?	\$ 448.00
38	1set	Front radiator hose X NN	\$ 125.00
39	1	Front wiper tank ?	\$ 105.00
			\$ 20,526.60
Less 20%			\$ 4,105.32
			<u>\$ 16,421.28</u>

L Soon Auto Services
 No.10 Ang Mo Kio Industrial Park 2A
 #03-18 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6482 1513 Fax: 6556 2590

SFU1822G Subaru BRZ

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Front bumper clips / <i>NEC</i>	\$ 50.00
2	1	Front bumper lower spoiler ? <i>(new & old take photos After repair)</i>	\$ 1,200.00
3	10	Front bumper lower spoiler clips <i>new</i>	\$ 50.00
4	1	Front bumper lower spoiler sealant <i>new</i>	\$ 80.00
5	6	Front lower grille clips ?	\$ 20.00
6	10	Front bonnet insulator clips <i>new</i>	\$ 30.00
7	2	Front radiator coolant ?	\$ 80.00
8	1	Front air con gas ?	\$ 80.00
9	1set	Front LED lamp <i>X NN</i>	\$ 650.00
10	1	Front no plate with garnish <i>URA</i>	\$ 120.00
			<hr/>
			\$ 2,360.00
		Total parts	\$ 17,328.80

L Soon Auto Services
 No.10 Ang Mo Kio Industrial Park 2A
 #03-18 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6482 1513 Fax: 6556 2590

SFU1822G Subaru BRZ

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,600.00	Uae
2	To putty and spray painting front portion.	\$ 1,600.00	Suo
3	To check wiring and focus front headlamp.	\$ 50.00	3o
4	To remove and install front bonnet lock mechanism.	\$ 80.00	X
5	To remove and install air con system to facilitate the repair and refill gas.	\$ 150.00	?
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 150.00	?
7	To apply anti rust proofing to front affected area.	\$ 120.00	?
8	Towing service.	\$ 100.00	So.
Total labour :		\$ 3,850.00	

4 Days.

Lumpsua Repair.

After repair photos.

Guo Qiang - 82880282

25/3/19.

Total parts : \$ 18,781.28
 Total labour : \$ 3,850.00
Total repair cost : \$ 22,631.28

LIA Auto Condition hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005258/Gqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-05-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9956H	Veh. Inspected	SFU 1822G
Policy No.		Coverage (\$)	0.00
Claim No.	D19001988MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	23/03/2019
2. Vehicle Particulars & Condition			
Make & Model	SUBARU BRZ	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JF1ZC6K72DG002947	Colour	BLUE
Odometer	83458	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	AUSTONE	6 mm
L/H Front Tyre	225/45 R17	AUSTONE	6 mm
R/H Rear Tyre	225/45 R17	AUSTONE	6 mm
L/H Rear Tyre	225/45 R17	AUSTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/03/2019	Inspection Date	25/03/2019
Survey held at	L SOON AUTO SERVICES 10 ANG MO KIO INDUSTRIAL PARK 2A #03-18 AMK AUTO POINT SINGAPORE 568407		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFU 1822G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSY	DEFORMED	2,800.00	2,800.00
2	FRONT BUMPER BRACKET	* CHECK	182.00	-
2	FRONT BUMPER RETAINER	NOT NECESSARY	188.00	-
1	FRONT BUMPER REINFORCEMENT	* CHECK	323.00	-
1	FRONT BUMPER SPONGE	* CHECK	195.00	-
1	FRONT BUMPER TOP BEAM	* CHECK	295.00	-
1	FRONT BUMPER LEFT NOZZLE	* CHECK	148.30	-
1	FRONT BUMPER RIGHT NOZZLE	NOT NECESSARY	148.30	-
1	FRONT BUMPER LEFT NOZZLE COVER	MISSING	73.50	73.50
1	FRONT BUMPER RIGHT NOZZLE COVER	NOT NECESSARY	73.50	-
1	FRONT LEFT HEADLAMP	* CHECK	2,260.30	-
1	FRONT RIGHT HEADLAMP	* CHECK	2,260.30	-
1	FRONT LEFT HEADLAMP LOWER BRACKET	* CHECK	52.70	-
1	FRONT RIGHT HEADLAMP LOWER BRACKET	* CHECK	52.70	-
1	FRONT LEFT FOG LAMP	* CHECK	380.00	-
1	FRONT RIGHT FOG LAMP	NOT NECESSARY	380.00	-
1	FRONT LEFT FOG LAMP COVER	* CHECK	85.00	-
1	FRONT RIGHT FOG LAMP COVER	NOT NECESSARY	85.00	-
1	FRONT LOWER GRILLE ASSY	* CHECK	368.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	148.00	148.00
1	FRONT BONNET ASSY	BUCKLED	1,828.00	1,828.00
1	FRONT BONNET INSULATOR	DEFORMED	179.00	179.00
2	FRONT BONNET HINGES	NOT NECESSARY	166.00	-
2	FRONT BONNET RUBBER STOPPER	NOT NECESSARY	38.00	-
1	FRONT BONNET LOCK	BENT	189.00	189.00
1	FRONT BONNET LOCK CATCH	NOT NECESSARY	68.00	-
1	FRONT SUPPORT PANEL ASSY	* CHECK	1,065.00	-
1	FRONT LEFT FENDER ASSY	TO REPAIR SEE LABOUR	985.00	-
1	FRONT RIGHT FENDER ASSY	TO REPAIR SEE LABOUR	985.00	-

Report Ref No. CS/FC119005258/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT AIR CON CONDENSER WITH DRYER ASSY	* CHECK	1,023.00	-
1	FRONT AIR CON CONDENSER FAN BLADE WITH MOTOR ASSY	* CHECK	448.00	-
1	FRONT AIR-CON DISCHARGE PIPE	* CHECK	288.00	-
1	FRONT AIR-CON SUCTION PIPE	* CHECK	278.00	-
1	FRONT AIR DUCT	* CHECK	275.00	-
1	FRONT AIR INTAKE BOX ASSY	* CHECK	450.00	-
1	FRONT RADIATOR ASSY	* CHECK	1,085.00	-
1	FRONT RADIATOR FAN BLADE WITH MOTOR COMPLETE ASSY	* CHECK	448.00	-
1	SET FRONT RADIATOR HOSE	NOT NECESSARY	125.00	-
1	FRONT WIPER TANK	* CHECK	105.00	-
	LESS 20% DISCOUNT		-4,105.32	-1,043.50
			16,421.28	4,174.00
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SPOILER (SN)	* CHECK	1,200.00	-
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	80.00	80.00
6	FRONT LOWER GRILLE CLIPS (SN)	* CHECK	20.00	-
10	FRONT BONNET INSULATOR CLIPS (SN)	NECESSARY	30.00	30.00
2	FRONT RADIATOR COOLANT (SN)	* CHECK	80.00	-
1	FRONT AIR CON GAS (SN)	* CHECK	80.00	-
1	SET FRONT LED LAMP (SN)	NOT NECESSARY	650.00	-
1	FRONT NO PLATE WITH GARNISH (SN)	CRACKED	120.00	120.00
			2,360.00	330.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT LEFT FENDER ASSY AND FRONT RIGHT FENDER ASSY.		1,600.00	400.00
	TO PUTTY AND SPRAY PAINTING FRONT PORTION.		1,600.00	500.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	30.00

Report Ref No. CS/FCI19005258/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.	* CHECK	150.00	-
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	* CHECK	150.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.	* CHECK	120.00	-
	TOWING SERVICE.		100.00	50.00
			3,850.00	980.00
	GRAND TOTAL		22,631.28	5,484.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$11,453.84 NETT)			5,484.00

Report Ref No. CS/FCI19005258/Gqd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.