

ASS. REP. BY

REF: CS/CTI19005262/Gcd307

Special Instruction

SAIS/evj/01

GQ

ASSIGNMENT (Office)

From (Person)

Chong Ben gen

of

CTI

Date/Time

28/3/19 @ 11:25 am

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SJA 1789C

Insured

GBB 3896C

at Workshop no.

Wei Car Spray

Tel

9 638 3306

of

Blk 1017, Yishun Ind. park A #01-242

Policy No.

DMCVSN30153718033

Claim No.

8NM18D05671000 :

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 01/12/2018

CA / REV / REP. / REV 24 HRS

Date/Time

12:27 pm @ 28/3/19

Person Contacted

Ahwei

Vehicle

IN/OUT

H.O.D. Endorsement

Date/Time

Action/Instruction (X) Estimate

GBB 3896C - CCF / AIG13002607 / C2W2

D.O.A - 29/1/2019

SJA 1789C - X

Dismantle: 28/3/2019

After repair: 28/3/2019

Surveyor: PRS

REF: CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Wei Car Spray

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIA789C Yr Regn: Nov / 07

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Impreza c.c. 1597

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 176440 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF16D5KJ3 7G072330

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45Z R17

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 25-03-19

Survey held at W/S 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

683 38460

RECEIVED 03 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PRS

Lump Sum / I.B.I. (\$) _____

190

190

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 25 March 2019 11:25 AM
To: Accident@kscgp.com
Cc: assignments
Subject: RE: RE:2nd Notice - Pre-Repair Survey YR REF:SNM18D05671-GBB3896C Our ref: SJA1789C/WE/ms/mt
Attachments: Template 2nd PRS (reject).pdf

SAVE AS TO COSTS

Dear Sir,

We refer to your email below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Monday, 25 March, 2019 11:22 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE:2nd Notice - Pre-Repair Survey YR REF:SNM18D05671-GBB3896C Our ref: SJA1789C/WE/ms/mt

Dear Sirs,

We refer to your email below of even date.

Please see enclosed our 2nd Notice to conduct Pre-Repair Survey. Our client is not agreeable to appointing your proposed surveyor as a Single Joint Expert.

The workshop details are as follows :
Wei Car Spray Painting Pte Ltd

Block 1017 Yishun Industrial Park A

#01-242

Singapore 768759

Contact Person : Ah Wei / 9638 3306

Thank you.

Regards,
May Teo
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Chong Boon Sen [<mailto:boonsen.chong@sg.entaiping.com>]

To: Accident@kscgp.com

Sent: Mon, 25 Mar 2019 03:09:11 +0000

Subject:

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Regards,
Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, 25 March, 2019 10:53 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM18D05671-GBB3896C - 1st Notice to conduct Pre-Repair Survey: Your ref: SJA1789C/WE/ms/mt

Dear Sir

There was no surveyors indicated in your previous email below.

Thank you.

Regards,

May Teo

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

To: Accident@kscgp.com

Sent: Mon, 25 Mar 2019 01:16:37 +0000

Subject:

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Friday, 22 March 2019 5:21 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: 1st Notice to conduct Pre-Repair Survey: Your ref: GBB 3896C Our ref: SJA1789C/WE/ms/mt

Dear Sirs

We refer to the above matter.

Please find enclosed herein the 1st Notice to conduct Pre-Repair Survey, for your immediate attention and necessary action.

Thank you.

Regards,
May Teo
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are

susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Your Ref : SNM18D05671-GBB3896C

Our Ref : SJA 1789C/WE/ms/mt

Date : 25 March 2019

Fax : 6538 3708

Tel : 3152 0981

Email : accident@kscgp.com

China Taiping Insurance (Singapore) Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 1 DECEMBER 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 25 March 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Billy Loh	Ajax Inspection Services
2.	Foo Philip	Precision Appraisal Services
3.	Ronald Ng	Precision Appraisal Services
4.	Lee Kok Weng	Lee Automobile Appraisals Services
5.	Leslie Lim	Premier Appraisal Services
6.	Ng Kong Beng, Patrick	Carlink Consultancy
7.	Andrew How	Prominent Appraiser Services Pte Ltd
8.	Gan Song Sing, Roger	ROG Associates
9.	Dennis Yap	Pal's Appraiser Pte Ltd
10.	Michael Yap	Mc-Coy Appraiser Pte Ltd
11.	Nicky Seah	Absolute Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Wei Car Spray Painting Pte Ltd
Block 1017 Yishun Industrial Park A
#01-242
Singapore 768759
Contact Person/Mobile nos. : Ah Wei / 9638 3306

Yours faithfully,

MT

> [Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Road Tax Payable

Vehicle Details			
Vehicle No.:	SJA1789C		
Vehicle Type:	P10 - Passenger Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	SUBARU		
Vehicle Model:	IMPREZA 5MT		
Chassis No.:	JF1GD5KJ37G072330		
Propellant:	Petrol		
Engine No.:	EJ16D138871		
Engine Capacity:	1597 cc		
Maximum Power Output:	70.0 kW (93 bhp)		
Maximum Laden Weight:	1730 kg		
Unladen Weight:	1260 kg		
Year Of Manufacture:	2007		
Original Registration Date:	29 Nov 2007		
Lifespan Expiry Date:	-		
COE Category:	A - Car (1600cc & below)		
PQP Paid:	\$20,997.00		
COE Expiry Date:	28 Nov 2022		
Road Tax Expiry Date:	28 May 2019		
Inspection Due Date:	28 Nov 2019		
Intended Transfer Date:	02 Apr 2019		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 28 May 2019. You may renew the road tax from 28 Feb 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 28 May 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 29 May 2019 to 28 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	446.00	-	446.00
Total Amount Payable:			471.00
Amount Payable (From 29 May 2019 to 28 May 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	928.00	-	928.00
Total Amount Payable:			953.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0238F
Vehicle Details	
Vehicle No.:	SJA1789C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 5MT
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	EJ16D138871
Chassis No.:	JF1GD5KJ37G072330
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$9,914.00
Original Registration Date:	29 Nov 2007
First Registration Date:	29 Nov 2007
Transfer Count:	1
Actual ARF Paid:	\$10,906.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$15,351.00
Total Rebate Amount:	\$15,351.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Apr 2019

OK

MEAM18156526 / Elite AM Pte Ltd - HQ
 ENTRY DATE & TIME: 03/12/2018 19:00
 SUBMITTED BY: Christy Hang Pek Chin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/12/2018 19:00
 Date Of Accident 01/12/2018 22:00
 Exact Location Of Accident BLK546A WLANDS DR16 DECK 2A MULTI STOREY CARPARK
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJA1789C
Insured/Policyholder
 Name Of Registered Owner A KUMARRAN
 NRIC No S9210238F
 Email Address ICENUVA@GMAIL.COM
 Mobile Phone No (LOCAL) +65-97550426
 Alternative Phone No Others-97550426

Vehicle Particulars

Manufacturer SUBARU
 Model IMPREZA 5MT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA285643/1
 Cover Note Number

Driver

Name of Driver A KUMARRAN
 NRIC No S9210238F
 Date Of Birth 17/03/1992
 Occupation INDOOR
 Date Of Driving Pass 05/04/2011
 Driving Experience 7 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97550426

Fax Number	
Contact Number	OTHERS-97550426
EMail Address	ICENUVA@GMAIL.COM
Address	BLK 330 YISHUN RING ROAD #03-1444
Postcode	760330
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT : T/20181202/2094

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

03/12/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan & Describe Circumstances Of The Accident

B: "6C
unknown

Refer Police Report : T/2018/202/2094

I/We declare the foregoing particulars are true in every respect.

Date & Time: 03/12/18

Date & Time:

NRIC/FIN No.:

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_viewersmart&noimgviewer=1&ftype=2&docid=40615268&c... 5/21



**SINGAPORE
POLICE FORCE**



T/20181202/2094

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20181202/2094

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/12/2018 21:58		Vide Report No.:		Station Diary No.: 206
Name of Informant: A KUMARRAN		Address: APT BLK 330 YISHUN RING ROAD #03-1444 SINGAPORE 760330		
ID Type / ID No.: NRIC NO / S9210238F		Contact No.: Home/Office: Mobile: 97550426		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 26	Date of Birth: 17/03/1992	Type of Informant: Vehicle Owner	
Race: Indian		Language: English	Institution / School Name:	
Occupation: LECTURER		Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 01/12/2018 22:00	Type of Location: Car Park
Location: Along Road 1 WOODLANDS DRIVE 16 At the multi storey carpark of Block 546A Woodlands Drive 16 Deck 2A (Unknown lot number)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

SJA1789C	Car	SUBARU	Impreza 5MT	Grey	Slightly Damaged	0
----------	-----	--------	-------------	------	------------------	---

SJA1789C	AXA INSURANCE SINGAPORE PTE LTD	GA285643	29/11/2018	28/11/2019
----------	---------------------------------	----------	------------	------------



**SINGAPORE
POLICE FORCE**



T/20181202/2094

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20181202/2094

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	A KUMARRAN	ID No.	S9210238F
Related Vehicle	SJA1789C (Car)	Contact No.	97550426
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/12/2018 at about 2145hrs, I parked and secured my vehicle SJA1789C (grey Subaru Impreza 5MT) at the multi-storey carpark of Block 546A Woodlands Drive 16 Deck 2A (Unknown lot number) and left.

On 01/12/2018 at about 2245hrs, I went back to retrieve my vehicle and did not noticed anything. On 02/12/2018 at about 1400hrs, I came back to retrieve my vehicle and discovered that the left headlight of my vehicle was cracked, the front left bumper and bonnet of my vehicle were damaged. As there were vehicle cameras installed on my vehicle, I went home to check the footages and discovered that the incident took place on 01/12/2018 at about 2200hrs. There was a lorry driver who was driving an unknown lorry was parking his lorry on the left of my vehicle, subsequently the lorry collided on my vehicle's front left.

The said driver who was a male Chinese subject aged about 50s, came out from his lorry to check on my vehicle's damages; thereafter went to my vehicle's rear before going back to his vehicle to park on an empty lot on the left, two lots away from my vehicle.

As the lighting at the multi-storey carpark was poor, I only managed to make out that the last 2 suffix of the vehicle number of the lorry as '6C'.

There were no notes left behind on my vehicle to inform my about the accident and the said multi-storey carpark is controlled by gantry. This is the first time such an incident happened and I had yet to inform my insurance company about the incident.

**SINGAPORE
POLICE FORCE**

T/20181202/2094

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20181202/2094

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt LAU JIXIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2018 21:58
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	Signature: Singapore Police Force

Owner's IC & Driving Licence



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/66783/2018
Date : 11 March 2019

A Kumarran
Blk 330 Yishun Ring Road
#03-1444
Singapore 760330

Dear Sir / Madam,

**TRAFFIC ACCIDENT INVOLVING SJA1789C AND GBB3896C ALONG WOODLANDS
DRIVE 16 ON 01/12/2018 AT ABOUT 2200 HRS**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of GBB3896C had committed the following offences:

- (i) Careless Driving under Rule 29 of the Road Traffic Rules;
- (ii) Failing to stop after an accident under Section 84(1) of the Road Traffic Act Chapter 276;
- (iii) Failing to report an accident within 24 Hours under Section 84(2) of the Road Traffic Act Chapter 276.

Action has been initiated against the driver for the said offences.

3. If you have any clarification, you may contact the Investigation Officer, SSS Esther Chong at office number: 6547 6368.

4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : SAS2515112 Vehicle Registration No : SJA17896
 Name(as shown in NRIC): A KUMARRAN
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 NRIC/Passport No : S9210238F
 Address : Block 330, YISHUN RING ROAD, #03-1244, SINGAPORE 760330
 Contact (Tel) : 97550426 (H/P) : -
 (Email) : ICENUVA@GMAIL.COM
 Date of Accident : 1/12/2013 Time of Accident : 1200 22'00
 Place of Accident : Block 546A WILANDS DRIVE DECK 2A MULTI-STOREY CARPARK
 Insurance Company : AXA INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Following investigation by the traffic police, it was discovered that the other
vehicle involved in the accident was GBB39161. Please refer to police report
attached.


 Signature of Vehicle Owner / Driver

Date: 21/3/2014

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
 Operating Hours : Monday to Friday 9am to 5pm

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019		26 Mar 2019 13:54 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: A KUMARRAN , ID: S9210238F									
Vehicle Reg. No.: SJA1789C		Date of Loss: 01/12/2018 22:00 - :59 [132 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05671C02		Policy/Cover Note No.: DMCVSN30153718033							
Vehicle Reg. No. (Insured): GBB3896C		Policy No. (Claimant): GA285643/1							
		Excess: S\$0.00							
Repairer: Wei Car Spray Painting (HQ) 1017 YISHUN INDUSTRIAL PARK A #01-242, 768759 Yishun - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents










***SJA1789C (SNM18D05671C02)**
[GBB3896C]
TP
A KUMARRAN
Dec 1 2018 10:00PM
[-]
Wei Car Spray Painting

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 19:35	Video - Accident [Linked Accident Report Documents]	Load AVI	
2	03/12/18 19:35	Video - Accident [Linked Accident Report Documents]	Load AVI	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 20:00	Accident Statement	Load HTM	
2	21/03/19 10:28	Addendum Sheet	Load TIF	
3	21/03/19 10:30	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 19:56	Damage 1 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	03/12/18 19:56	Damage 2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	03/12/18 19:56	Damage 3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	03/12/18 19:56	Damage 4 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	03/12/18 19:56	Damage 5 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	03/12/18 19:56	Damage 6 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	03/12/18 19:56	Damage 7 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	03/12/18 19:56	Damage 8 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	03/12/18 19:56	Damage 9 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	03/12/18 19:56	ODOMETER READING [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	03/12/18 19:56	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
2	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
3	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/04/19 16:14	General View	Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)		Thumbnail	Print
12	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
18	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
19	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
20	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
21	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
22	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
23	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
24	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
25	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
26	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
27	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
28	02/04/19 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
29	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
30	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
31	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
34	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
35	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
36	02/04/19 16:14	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
38	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
41	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
42	02/04/19 16:14	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/03/19 13:54	prs contact		Load PDF	
No	Finalized On	Elite AM Pte Ltd (HQ)		Thumbnail	Print
1	03/12/18 19:45	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	03/12/18 19:45	Accident Sketch Plan & Describe Circumstances Of The Accident [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	03/12/18 19:45	Certificate Of Insurance [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	03/12/18 19:45	Police Report Pg 1 [Linked Accident Report Documents]		Load TIF	
5	03/12/18 19:45	Police Report Pg 2 [Linked Accident Report Documents]		Load TIF	
6	03/12/18 19:45	Police Report Pg 3 [Linked Accident Report Documents]		Load TIF	
7	03/12/18 19:45	Owner's IC & Driving Licence [Linked Accident Report Documents]		Load TIF	
8	21/03/19 10:29	POLICE REPORT ACCIDENT OUTCOME [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 19:35	Video - Accident	 Load AVI	
2	03/12/18 19:35	Video - Accident	 Load AVI	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 20:00	Accident Statement	 Load HTM	
2	21/03/19 10:28	Addendum Sheet	 Load TIF	
3	21/03/19 10:30	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 19:56	Damage 1	 Load JPG	<input checked="" type="checkbox"/>
2	03/12/18 19:56	Damage 2	 Load JPG	<input checked="" type="checkbox"/>
3	03/12/18 19:56	Damage 3	 Load JPG	<input checked="" type="checkbox"/>
4	03/12/18 19:56	Damage 4	 Load JPG	<input checked="" type="checkbox"/>
5	03/12/18 19:56	Damage 5	 Load JPG	<input checked="" type="checkbox"/>
6	03/12/18 19:56	Damage 6	 Load JPG	<input checked="" type="checkbox"/>
7	03/12/18 19:56	Damage 7	 Load JPG	<input checked="" type="checkbox"/>
8	03/12/18 19:56	Damage 8	 Load JPG	<input checked="" type="checkbox"/>
9	03/12/18 19:56	Damage 9	 Load JPG	<input checked="" type="checkbox"/>
10	03/12/18 19:56	ODOMETER READING	 Load JPG	<input checked="" type="checkbox"/>
11	03/12/18 19:56	CHASSIS NUMBER	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 19:45	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	03/12/18 19:45	Accident Sketch Plan & Describe Circumstances Of The Accident	 Load JPG	<input checked="" type="checkbox"/>
3	03/12/18 19:45	Certificate Of Insurance	 Load JPG	<input checked="" type="checkbox"/>
4	03/12/18 19:45	Police Report Pg 1	 Load TIF	
5	03/12/18 19:45	Police Report Pg 2	 Load TIF	
6	03/12/18 19:45	Police Report Pg 3	 Load TIF	
7	03/12/18 19:45	Owner's IC & Driving Licence	 Load TIF	
8	21/03/19 10:29	POLICE REPORT ACCIDENT OUTCOME	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19005262/GCD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30153718033

Claimant Vehicle
No: SJA1789CInsured Vehicle
No: GBB3896C

Date of Loss: 01/12/2018

Nature of Claim: TP

Claim
No: SNM18D05671C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJA1789C

Make & Model: SUBARU IMPREZA, 1.6 4D (A)

Engine No: EJ16D138871

Reg. Date: 29/11/2007 (Man. Year: 2007)

Chassis No: JF1GD5KJ37G072330

Colour: Grey

Odometer: 176440 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/03/2019

Date Inspected: 25/03/2019 Inspected At:

Wei Car Spray Painting (HQ)
1017 YISHUN INDUSTRIAL PARK A #01-
242
Singapore 768759

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Apr 2019)

Parts: 143 SUBARU IMPREZA 1.6 4D (A)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJA1789C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >