

Company
ASS. P.C. REF.

REF CS/1CS19005265 / Utd3m2

Sub Vpn

Marcus

ASSIGNMENT (Office)

From (Person)

Desmond Lee

of

ICS

Date/Time

25/3/19 @ 11:55am

Estimated Cost

Bill to

OD / TP / VS / TP RES / OD RES / EVA / INV / MY / US

To Inspect Vehicle No

SKD 85211

Insured

SJE 2266S

at Workshop no

Fastech Auto

Tel

6746 5405

of

1 Kalei Blet Ave 6 #01-01-46

Policy No

Claim No

Sum Insured

Excess

Make of Veh
(Client's Record)

D.O.A. 23/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Enforcement

Date/Time

12:33pm 25/3/19

Person Contacted

Jason

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate

SKD 85211 - NA / INC 19005242 / 24

D.O.A - 23/3/2019

SJE 2266S - NA / MSG 10000303 / P1

D.O.A - 05/1/2010

(08/11/13) wef

REF:

SCIC

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have G.A 1yrs. contr. nett (226)

24/4/19 4/5 @ 13,200 confirmed with the. Cred: 27139.10 (67%)

RECEIVED 25 APR 2019

Date/Time, File Pass to?

1) 25/4 Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I: (\$ 13,200)

350

10

360

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Monday, 25 March 2019 11:58 AM
To: assignments; Nancy Lam
Cc: ECICS Claims
Subject: RE: REQUEST FOR PRS SKD8521J // our insured veh: SJE 2266S // DOA: 23.03.19

Dear Nancy

We are appointing LKK for the PRI.

Hi LKK

Please assist with the PRI.

Thank you.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: ECICS Claims
Sent: Monday, 25 March 2019 10:26 AM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: ECICS Claims
Subject: FW: REQUEST FOR PRS SKD 8521J

Hi Desmond

Please assist.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice_goh@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, 25 March 2019 9:49 AM
To: ECICS Claims
Subject: REQUEST FOR PRS SKD 8521J

Hi Sir

My client claiming your insured SJE 2266S.

Please kindly arrange PRS for SKD 8521J.

Date of accident 23.03.2019

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



Elantra Price Range Depreciation 2012 Vehicle Type Submit

Advanced Search

Home » Used Cars » 007 » Hyundai Elantra 1.6A

Hyundai Elantra 1.6A

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$36,998		
Depreciation	\$10,140 /yr View models with similar depre	Reg Date	01-Mar-2012 (2yrs 11mths 3days COE left)
Mileage	N.A.	Manufactured	2012
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$22,814 as of today (change)	OMV	\$14,495
COE	\$48,112	ARF	\$14,495
Engine Cap	1,591 cc	Power	95.6 kW (128 bhp)
Curb Weight	1,267 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

Powerful And Responsive 16L DOHC, 6 Speed, Dual VVT Engine Producing 128 BHP, ABS, Auto Rain Sensor And Headlights, 6 SRS Airbags. View specs of the Hyundai Elantra (2011-2014)

Accessories

Sunroof, Electric Leather Seats, Sports Rims, Reverse Camera, Keyless Entry/Push Start, Pioneer DVD System, Fog Lamps, Cruise Control.

Description

Be Our Next Happy Buyer To Own This Well Kept Vehicle At Most Reasonable And Affordable Price! Flexible Bank/In House Loan Up To 80%! Regular Servicing Done, Tip Top Conditions! Viewing Via Appointment Only! Why Wait? Call Our Professional And Friendly Staffs For A No Obligations Discussion. Thank You.

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Shortlist Compare Add note
Report Error More Actions

Seller Information

Company	007 * dealer's pricelist * 20 vehs sold 29 vehs available	
Address	421 Tagore Industrial Avenue #02-09 Search cars nearby this location	
Location	Tagore 8	
Office No	65700770	
Contact Person (s)	Mr Tay Kenny Goh Ian Chan Tom Tan	85353544 98334449 81180118 85002727



DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT www.scamalert.sg





[Advanced Search](#)

[Home](#) » [Used Cars](#) » [Car Search](#) » [Hyundai Elantra 1.6A Elite](#)

Hyundai Elantra 1.6A Elite

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[CONSIGNMENT](#)


Price \$36,800

Depreciation \$10,520 /yr
View models with similar depre

Reg Date 14-Jan-2012
(2yrs 9mths 19days COE left)

Mileage 171,000 km (23.8k /yr)

Manufactured 2011

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$22,734 as of today (change)

OMV \$14,488

COE \$50,001

ARF \$14,488

Engine Cap 1,591 cc

Power 95.6 kW (128 bhp)

Curb Weight 1,267 kg

No. of Owners 2

Type of Vehicle Mid-Sized Sedan

Features

Smooth And Reliable 4 Cylinders Inline 16 Valve Dual CVVT Engine, 6 Speed Auto Transmission, ABS, Steering Control, Remote Boot Release, Rear Aircon. View specs of the Hyundai Elantra (2011-2014)

Accessories

Factory Fitted Audio System Embedded With USB, AUX And BT, All Round Sensors, Electric Leather Seats, Fog Lamps, Sports Rims, Door Visors.

Description

Consignment Unit Call To View And Test Drive Now!

Category

PARF Car, Consignment Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » [List of owner consignment cars](#)
- » [List of consignment agents](#)


[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Company	Car Search	
	» dealer's pricelist	
	» 64 vehs sold 153 vehs available	
Address	18 Sin Ming Lane #04-02	
	Search cars nearby this location	
Location	Midview City	
Office No	62620728	
Contact Person(s)	Ken	93388994
	Justin	91827511
	Kelvin	97593539
	Rachel	91126538

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7759Z

Vehicle Details

Vehicle No.: SKD8521J

Vehicle to be Exported: No

Intended Deregistration Date: 25 Mar 2019

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: G4FGBU445980

Chassis No.: KMHDH41CMCU403592

Maximum Power Output: 95.6 kW (128 bhp)

Open Market Value: \$14,579.00

Original Registration Date: 13 Jan 2012

First Registration Date: 13 Jan 2012

Transfer Count: 1

Actual ARF Paid: \$14,579.00 7289.

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Jan 2022

PARF Rebate Amount: \$8,747.00

Intended COE Rebate Details

COE Expiry Date: 12 Jan 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$50,001.00

COE Rebate Amount: \$13,992.00

Total Rebate Amount: \$22,739.00

The information contained herein is correct as at 25 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 10:15
Date Of Accident	23/03/2019 11:25
Exact Location Of Accident	PIE TOWARDS JURONG (BEFORE KALLANG EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD8521J
Insured/Policyholder	
Name Of Registered Owner	TAN KWANG WEN
NRIC No	S1687759Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92378713
Alternative Phone No	OFFICE-92378713

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095406862-01 CLASSIC
Cover Note Number	

Driver

Name of Driver	TAN KWANG WEN
NRIC No	S1687759Z
Date Of Birth	10/08/1965
Occupation	OUTDOOR
Date Of Driving Pass	12/10/2015
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92378713
Fax Number	
Contact Number	OFFICE-92378713
Email Address	NOEMAIL

Address	BLK 8 #05-4104 NORTH BRIDGE ROAD
Postcode	190008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CAIRNHILL NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 GLOUCESTER ROAD , POSTCODE: 210009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2968999 - FAX NO: 63912398
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE2266S
Vehicle Make/Model/Colour	OPEL ASTRA ST 1.0 AT
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMH5516A
Vehicle Make/Model/Colour HYUNDAI AD AVANTE 1.6 GLS (A) S
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN KWANG WEN
Approximate Age
Injuries Sustain SHOULDER, NECK & BACK PAIN
Injured person in which vehicle? SKD8521J
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg


Policyholder's Signature
Date & Time:


25 MAR 2019

GIA/IMC Sketch/PlanForm_V3


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/03/19 at about 1135hrs I was traveling
 along PIE Towards Jurong Before Kallang Exit.
 I was stationary due to front traffic. Suddenly,
 I felt on impact My vehicle was pushed forward
 to hit the front vehicle. I was involvolved in
 a three vehicle ~~front~~ collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

25 MAR 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
 Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190324/2049

Police Station Of Origin:
Cairnhill NPP
9 Gloucester Road #01-03 SINGAPORE
210009
Tel No: 1800-2968999

1 of 4

Report No. T/20190324/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/03/2019 12:55		Vide Report No.:		Station Diary No.: 11
Informant's Particulars				
Name of Informant: TAN KWANG WEN		Address: APT BLK 8 NORTH BRIDGE ROAD #05-4104 SINGAPORE 190008		
ID Type / ID No.: NRIC NO / S1687759Z		Contact No.: Home/Office: Mobile: 92378713		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 53	Date of Birth: 10/08/1965	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Manufacturing engineering technician (general)		Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 23/03/2019 11:25	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY TOWARDS JURONG BEFORE KALLANG EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJE2266S	Car				Seriously Damaged	0
SKD8521J	Car	HYUNDAI	ELANTRA 1.6 AT ABS D/AB 2WD 4DR	Red	Seriously Damaged	2
SMH5516A	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190324/2049

Police Station Of Origin:
Cairnhill NPP
9 Gloucester Road #01-03 SINGAPORE
210009
Tel No: 1800-2968999

2 of 4

Report No. T/20190324/2049

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKD8521J	NTUC Income Insurance Co-Operative Limited	5095406862-01	13/01/2019	12/01/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN KWANG WEN	ID No.	S1687759Z
Related Vehicle	SKD8521J (Car)	Contact No.	92378713
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	23/03/2019	Date Discharge	23/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	TAI CHEE HEAN	ID No.	S9327044D
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ZENG TENG GABRIEL	ID No.	S9902044Z
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190324/2049

Police Station Of Origin:
Cairnhill NPP
9 Gloucester Road #01-03 SINGAPORE
210009
Tel No: 1800-2968999

3 of 4

Report No. T/20190324/2049

CONTINUATION OF REPORT

Brief Details.

On the 23/03/2019 at about 1125hrs I was travelling along PIE on the 1st lane the express lane towards Jurong before Kallang exit when I was hit from the rear by a car SJE2266S, as a result the force pushed my car forward that caused me hit onto the car SMH5516A that was in front of me. IO together with the other drivers alighted from our vehicle and inspected the damages. My car rear bonnet was totally damaged that I had to have it towed away, the car that hit me from the rear also had his vehicle towed as his vehicle was seriously damaged, the front car was not seriously damaged and he picked us up and dropped us off at the workshop that our cars were towed to. I would like to state that I went to Tan Tock Seng Hospital to have a check up as my neck and shoulders were aching and I was given a total of 3 days MC. I would like to state that at the point of the accident my passengers were not injured. That's all.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Cairnhill NPP
9 Gloucester Road #01-03 SINGAPORE
210009
Tel No: 1800-2968999



T/20190324/2049

4 of 4

Report No. T/20190324/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
A /
Sgt 2 ANAND KUMAR S/O SASITARAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
24/03/2019 12:55

Classification Of Case:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
Heli
25/3/19
4/s \$13,200/
12dy.

VEHICLE NO:SKD 8521J

QTY	PARTICULAR		
1 PCS	BOOTLID		\$1,507.30
1 PCS	BOOTLID 'H' LOGO		\$39.90
1 PCS	BOOTLID 'HYUNDAI' EMBLEM		\$48.50
1 PCS	BOOTLID 'ELANTRA' EMBLEM		\$52.20
1 PCS	BOOTLID 'ELITE' EMBLEM		\$50.00
1 PCS	BOOTLID INNER LOCK	135.80	\$291.30
1 PCS	BOOTLID LOCK STRIKER		\$66.80 X
1 PCS	BOOTLID WEATHERSTRIP	115.20	\$311.30
2 PCS	BOOTLID REFLECTORS @\$520.30		\$1,040.60 X
1 PCS	BOOTLID INNER TRIM		\$322.60 X
1 SET	BOOTLID INNER TRIM CLIPS		\$50.00 X
1 PCS	REAR BUMPER	495.40	\$788.20
2 PCS	REAR BUMPER REFLECTORS @\$105.00	68.60	\$210.00 1PC
1 PCS	REAR BUMPER REINFORCEMENT	365	\$485.10
2 PCS	REAR BUMPER REINFORCEMENT STAYS @\$201.00	105	\$402.00 1PC
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50	44.80	\$133.00 1PC
1 SET	REAR BUMPER CLIPS		\$48.00
1 PCS	REAR BUMPER LOWER GARNISH N/S		\$105.60 X
2 PCS	REAR BUMPER SPLASH SHIELDS @\$150.50	120.20	\$301.00 1PC
1 PCS	REAR END PANEL	453.80	\$892.20
1 PCS	REAR END PANEL TOP GARNISH	166.80	\$288.30
1 PCS	REAR END PANEL LOCK SENSOR		\$250.00
1 PCS	REAR FLOOR PANEL	1120.20	\$1,680.30
1 PCS	REAR FLOOR PANEL TOP BOARD	345.50	\$525.40
1 PCS	REAR FLOOR PANEL TOP TOOLS SPONGE	265.00	\$311.20
2 PCS	REAR FENDERS @\$1807.00		\$3,614.00 X
2 PCS	REAR FENDER INNER TRIMS @\$405.00	242.50	\$810.00 1PC
1 PCS	REAR WINDSCREEN MOULDING		\$188.20 X
1 PCS	REAR EXHAUST		\$891.30 X
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00		\$90.00 X
2 PCS	TAILLAMPS @\$685.30	363.80 x 2 = 727.60	\$1,370.60
2 PCS	TAILLAMP HOUSING PANELS @\$295.00	205	\$590.00 1PC
2 PCS	BOOTLID HINGES @\$145.00		\$290.00 X
2 PCS	REAR AIR VENTS @\$45.00		\$90.00 X
1 PCS	FRONT BUMPER	495.60	\$665.30
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00		\$130.00
2 PCS	FRONT BUMPER BRACKETS @\$145.00		\$290.00 X
1 SET	FRONT BUMPER CLIPS		\$50.00
1 PCS	FRONT BUMPER INNER SPONGE	175.20	\$180.50
1 PCS	FRONT BUMPER REINFORCEMENT	382.00	\$515.10
1 PCS	FRONT BUMPER CENTRE GRILLE	229.20	\$239.00
2 PCS	FRONT BUMPER FOG LAMPS @\$385.00		\$770.00 X
1 PCS	FRONT BUMPER LOWER GRILLE CHROME MOULDING		\$245.10 X
1 PCS	FRONT GRILLE	266.50	\$425.50
2 PCS	FRONT GRILLE CHROME MOULDINGS @\$65.00		\$130.00
1 PCS	FRONT GRILLE LOGO		\$38.00

20%

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19005265/UTD3N2

Date: 06/05/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKD8521J	Insured Vehicle No :	SJE2266S
Date of Loss:	23/03/2019	Nature of Claim:	TP
		Claim No:	DMPC1900081H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD8521J	Engine No:	G4FGBU445980
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMCU403592
Reg. Date:	13/01/2012 (Man. Year: 2011)	Odometer:	168130 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	33,639.10	13,706.56	19,932.54	59.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	4,360.00	2,340.00	34.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,339.10	18,066.56	22,272.54	55.21
Approved Total (Overridden) (S\$)		13,200.00		
(S\$)	40,339.10	13,200.00	27,139.10	67.28
+ GST 7.00/7.00% (S\$)	2,823.74	924.00	1,899.74	67.28
Nett Amount (S\$)	43,162.84	14,124.00	29,038.84	67.28

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	25/03/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD8521J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Bent	1,507.30 F	*1,507.30 FL
2	1		*BOOTLID H LOGO	Necessary	39.90 F	*39.90 FL
3	1		*BOOTLID HYUNDAI EMBLEM	Necessary	48.50 F	*48.50 FL
4	1		*BOOTLID ELANTRA EMBLEM	Necessary	52.20 F	*52.20 FL
5	1		*BOOTLID ELITE EMBLEM	Necessary	50.00 F	*50.00 FL
6	1		*BOOTLID INNER LOCK	Twisted	291.30 F	*135.80 FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	66.80 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	311.30 F	*115.20 FL
9	2		*BOOTLID REFLECTORS	Not Necessary	1,040.60 F	*- FL
10	1		*BOOTLID INNER TRIM	Not Necessary	322.60 F	*- FL
11	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
12	1		*REAR BUMPER	Distorted	788.20 F	*495.40 FL
13	1		*REAR BUMPER REFLECTORS	N/s Cracked	210.00 F	*68.60 FL
14	1		*REAR BUMPER REINFORCEMENT	Cracked	485.10 F	*365.00 FL
15	1		*REAR BUMPER REINFORCEMENT STAYS	N/s Bent	402.00 F	*105.00 FL
16	1		*REAR BUMPER SIDE RETAINERS	N/s Bent	133.00 F	*44.80 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
18	1		*REAR BUMPER LOWER GARNISH N/S	Not Necessary	105.60 F	*- FL
19	1		*REAR BUMPER SPLASH SHIELDS	N/s Torn	301.00 F	*120.20 FL
20	1		*REAR END PANEL	Badly Dented	892.20 F	*453.80 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	288.30 F	*166.80 FL
22	1		*REAR END PANEL LOCK SENSOR	Cracked	250.00 F	*250.00 FL
23	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,680.30 F	*1,120.20 FL
24	1		*REAR FLOOR PANEL TOP BOARD	Warped	525.40 F	*345.50 FL
25	1		*REAR FLOOR PANEL TOP TOOLS SPONGE	Torn	311.20 F	*265.00 FL
26	2		*REAR FENDERS	Repair	3,614.00 F	*- FL
27	1		*REAR FENDER INNER TRIMS	N/s	810.00 F	*242.50 FL
				Deformed/Torn		
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	188.20 F	*- FL
29	1		*REAR EXHAUST	Not Necessary	891.30 F	*- FL
30	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
31	2		*TAILLAMPS	Cracked	1,370.60 F	*727.60 FL
32	1		*TAILLAMP HOUSING PANELS	N/s Bent	590.00 F	*205.00 FL
33	2		*BOOTLID HINGES	Not Necessary	290.00 F	*- FL
34	2		*REAR AIR VENTS	Not Necessary	90.00 F	*- FL
35	1		*FRONT BUMPER	Dented/Torn	665.30 F	*495.60 FL
36	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
37	2		*FRONT BUMPER BRACKETS	Not Necessary	290.00 F	*- FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
39	1		*FRONT BUMPER INNER SPONGE	Torn	180.50 F	*175.20 FL
40	1		*FRONT BUMPER REINFORCEMENT	Dented	515.10 F	*382.00 FL
41	1		*FRONT BUMPER CENTRE GRILLE	Twisted	239.00 F	*229.20 FL
42	2		*FRONT BUMPER FOG LAMPS	Not Necessary	770.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Not Necessary	245.10 F	*- FL
44	1		*FRONT GRILLE	Cracked	425.50 F	*266.50 FL
45	2		*FRONT GRILLE CHROME MOULDINGS	Scratched	130.00 F	*130.00 FL
46	1		*FRONT GRILLE LOGO	Necessary	38.00 F	*38.00 FL
47	1		*BONNET	Dented/Buckled	1,361.90 F	*1,184.00 FL
48	2		*BONNET HINGES	Not Necessary	170.00 F	*- FL
49	1		*BONNET INSULATOR	Not Necessary	175.00 F	*- FL
50	1		*SET BONNET INSULATOR CLIPS	Not Necessary	35.00 F	*- FL
51	1		*BONNET LOCK	Twisted	68.50 F	*68.50 FL
52	2		*HEADLAMPS	Cracked	3,530.80 F	*3,512.00 FL
53	2		*HEADLAMP LOWER BRACKETS	Not Necessary	90.00 F	*- FL
54	1		*FRONT SUPPORT PANEL	Bent	994.30 F	*994.30 FL
55	1		*AIRCON CONDENSER	Bent/Punctured	892.10 F	*892.10 FL
56	1		*AIRCON SIDE GARNISH	O/s Torn	70.00 F	*35.00 FL
57	1		*RADIATOR	Bent/Cracked	1,055.20 F	*866.00 FL
58	1		*RADIATOR FAN ASSY	Not Necessary	899.20 F	*- FL
59	1		*RADIATOR TOP HINGE	Not Necessary	42.90 F	*- FL
60	2		*FRONT FENDERS	Not Necessary	912.20 F	*- FL
61	1		*AIR CLEANER BOX TOP	Not Necessary	279.90 F	*- FL
62	1		*AIR CLEANER BOX BOTTOM	Not Necessary	285.50 F	*- FL
63	1		*AIR INTAKE DUCT	Not Necessary	153.20 F	*- FL
64	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
65	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	280.00 FS	*200.00 FS
66	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
67	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
68	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
69	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
70	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,639.10	16,990.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,284.14
Total Parts (\$\$)	33,639.10	13,706.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	120.00	60.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
4	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
8	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
9	TO SPRAY RUST PROOFING	New	150.00	120.00
10	TO REFILL AIR CON GAS	New	150.00	100.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	3,000.00	2,000.00
12	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (S\$)			6,700.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >