

22/03/2019

REF: CS / MSG 19005267 / NSd25

Special Instruction:

ASS. REC. BY:

Surveyor: Ndz

ASSIGNMENT (Office)

From (Person):

Kwok Woon Choo

of

MSG

Date/Time: 25.3.19 9.11a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 4257G

Insured:

at Workshop m/s

Shu Fatt Auto Works

Tel:

62730119

of Block 1009 Bukit Merah Lane 3 # 01-90

Policy No: B28912568MCG

Claim No:

587268

Sum Insured:

Excess:

IBF \$0/-

D.O.A. 26.2.2019

Make of Veh:  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.3.19 11.02a.m

Person Contacted:

Connie

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	Investigation (Fire)
	SJS 4257G - CVI / VAL 19004790 / BS		D.O.A. - 26/4/2019
27/03/19	@ 11:21 a.m. revised IA to Kwok Woon Choo via messenger		
27/03/19	@ 11:23 a.m. mandate requested total loss to Kwok Woon Choo via messenger.		

REF: MS1G

# Investigation (Fire)

## ASSIGNMENT

From: \_\_\_\_\_ Date: 25/03/2019

Veh No: SJS 4257G Yr Regn: 17 AUG 2009

Estimated Cost: \_\_\_\_\_

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SJS 4257G  
at Workshop m/s: Shu Fatt Auto Works  
of: Blk 1009 Blk Merah Lane 3 #01-90

Make: FORD SMAX cc 2,261  
Colour: SILVER A/C: Insured / Std / NI / NA  
Sp. Reading: 165,263 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_  
C/No: L1F05XXGBWS9R18631

Policy No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: TBA \$0/-

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Find cause of fire

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60 R16  
R: 11

Remark: The veh had commenced its repair at the time of inspection.

	<input checked="" type="checkbox"/>
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Bal. or Market Value: ~~22K~~ 16K.

TOYO / YOKO or MIC (F), OWNER

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

Front R/Bal. 5 mm Rear R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 5 mm L/Bal. 6 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 26/2/19 D.O.I. 25/3/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at SHU FATT AUTO

CA / REV REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
engine compartment

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rebate: \$11,362
	Repair Margin: \$4,637
	Total Loss due to uneconomical for repair.
	MV - \$16K
	LTA - \$12,098.00
	Nett - \$3,902.00

RECEIVED 23 APR 2019

Date/Time, File Pass to? 23/04/19  
1) Typist  : Preli. Report  
 : Final Report

Days Of Repair: /  
Resurvey No. of Trip: /

Survey Fee:	200
Transportation:	
S + RS, SI	
Photos	10
Others Free Report	\$190.00
TOTAL:	

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Insp (\$)  
 Weekend (\$)

5001

Report Format: Total Loss  
Lump Sum / I.B.I: (\$)

Signature: [Signature]  
16/4/2019

### ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019 Sendback Est	23 Mar 2019 10:25 <b>S\$9,900.00</b>	25 Mar 2019 09:11 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>SMIT SINGAPORE PTE LTD</b> , Co. Reg. No.: 198501849W, Tel: +6598537818								
Vehicle Reg. No.:	<b>SJS4257G</b>	Date of Loss:	26/02/2019 12:00 - :59 [114 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 587268</b>	Policy/Cover Note No.:	B28912568MCY (Comprehensive) Coverage: 01/04/2018 - 31/03/2019						
		Excess:	S\$0.00						
Repairer:	<b>Shu Fatt Auto Works (HQ)</b> Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Kwok Woon Choo</b> - 6643 1330]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Imm.Advice</b> due 26/03/2019]								
OD Investigation	Yes								
Driver/Custodian:	DE SAVORNIN LOHMAN ALEIDA ELISABETH CATHARNA (40 / Female) , NRIC: G3085222U, Tel: +6598537818 Email: aleidsavlo@hotmail.com								
Adj Asg. Remarks:	TO REVERT AND PENDING FOR INVESTIAGTION (cause of fire).								
<b>ASSOCIATED MAIL RECEIVED</b>									
			View All	Compose Case Mail					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Received Message

This mail is associated with :

**SJS4257G (587268)**  
OD  
Feb 26 2019 12:00PM  
[SMIT SINGAPORE PTE LTD]  
Shu Fatt Auto Works

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 27/03/2019 17:11 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Revoked - SJS4257G - Claim Handler: Kwok Woon Choo

Revoked.

### DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 23 Apr 2019

**Preliminary Advice**

Vehicle No	: SJS4257G	Accident Date	: 26/02/2019
Make	: FORD S-MAX	Policy No.	: B28912568MCY
Assignment Date	: 25/03/2019	Excess	: S\$0.00
Date of Inspection	: 25/03/2019	Est. Duration of Repair	: 0.00
Inspection At	: SHU FATT AUTO WORKS (HQ) BLOCK 1009 BUKIT MERAH LANE 3, #01-90 SINGAPORE 159723		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages engine compartment caught fire.

Repairer's Estimate (Gross)	:S\$	9,900.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	12,098.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,902.00

**Remarks**

( X ) The vehicle is not economical for repair. Vehicle recommended total loss.

( ) The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 27 Mar 2019

**Preliminary Advice**

Vehicle No	: SJS4257G	Accident Date	: 26/02/2019
Make	: FORD S-MAX	Policy No.	: B28912568MCY
Assignment Date	: 25/03/2019	Excess	: S\$0.00
Date of Inspection	: 25/03/2019	Est. Duration of Repair	: -
Inspection At	: Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages engine compartment caught fire.

Repairer's Estimate (Gross)	:S\$	9,900.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	11,362.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,638.00

**Remarks**

( X ) The vehicle is not economical for repair. Vehicle recommended total loss. Pending investigation.

( ) The above survey was conducted on a 'without prejudice' basis.

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report: 27/02/2019 14:52  
 Date Of Accident: 26/02/2019 12:15  
 Exact Location Of Accident: CENTRAL BOULEVARD  
 Country/State of Loss: SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number: SJS4257G  
**Insured/Policyholder**  
 Name Of Registered Owner: SMIT SINGAPORE PTE LTD  
 Co Reg No: unknown 198561849W  
 Email Address: E.C.CHOW@SMIT.COM  
 Mobile Phone No:  
 Alternative Phone No: Office-98537818

**Vehicle Particulars**

Manufacturer: FORD  
 Model: S-MAX  
 Exact Purpose for which vehicle was being used at time of accident: private use  
 Are you claiming under your own insurance policy for repair to your vehicle?: NO  
 If No, Please state action to be taken: REPORTING ONLY  
 Vehicle Category: PRIVATE CAR

**Insurance Company**

Name of Insurance Company: MSIG INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage: COMPREHENSIVE  
 Fleet Policy: NO  
 Policy Number: B28912568MCY  
 Cover Note Number:

**Driver**

Name of Driver: DE SAVORNIN LOHMAN ALEIDA ELISABETH CATHARNA  
 Work Permit No: G3085222U  
 Date Of Birth: 16/02/1979  
 Occupation: INDOOR  
 Date Of Driving Pass: 13/06/2016  
 Driving Experience: 2 YEARS AND 8 MONTHS

*employee's wife*  
 - no fire.  
 - overheating.  
 - vehicle new.  
 - used by employee's wife.  
 - marketing vehicle, party, sales.  
 - did home.  
 - normal servicing.  
 - overhaul done.  
 - normal problems.

Gender	FEMALE
Mobile Number	(LOCAL) +65-98537818
Fax Number	
Contact Number	
E-Mail Address	ALEIDSAVLO@HOTMAIL.COM
Address	35 JALAN KAMPONG CHANTEK
Postcode	588614
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

see attached

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*


Driver's Signature  
(If driver is not the policyholder)

Date & Time:  
27 Feb. 2019, 11AM



Reporting Centre - Personal Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving down the MCE when I had to take a shallow slope and the car started to go slower and slower I checked the dashboard, but there were no lights or other signs there. About 30 seconds later, when I had just arrived on Central Boulevard, the car just didn't accelerate anymore and the wheel became very heavy. That's when the oil signage switched on and smoke came out of the right front of the car. I immediately stopped the car alongside the road and called GGS. The firemen came and cooled the engine with water. They said they believed the oil reservoir was leaking. The car was towed away. This all happened at 12:15 on 26 February 2019.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:  
27 Feb 11 am



Reporting Centre Personnel Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1849W
Vehicle Details	
Vehicle No.:	SJS4257G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	FORD
Vehicle Model:	S-MAX TREND 5DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	9R18631
Chassis No.:	WF0SXXGBWS9R18631
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$22,725.00
Original Registration Date:	17 Aug 2009
First Registration Date:	17 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$22,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2019
PARF Rebate Amount:	\$11,362.00
Intended COE Rebate Details	
COE Expiry Date:	16 Aug 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,890.00
COE Rebate Amount:	\$736.00
<b>Total Rebate Amount:</b>	<b>\$12,098.00</b>

The information contained herein is correct as at 26 Mar 2019

OK

> Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SJS4257G		
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	FORD		
Vehicle Model:	S-MAX TREND 5DR		
Chassis No.:	WF0SXXGBWS9R18631		
Propellant:	Petrol		
Engine No.:	9R18631		
Engine Capacity:	2261 cc		
Maximum Power Output :	118.0 kW ( 158 bhp)		
Maximum Laden Weight :	2430 kg		
Unladen Weight :	1658 kg		
Year Of Manufacture :	2009		
Original Registration Date :	17 Aug 2009		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$18,890.00		
COE Expiry Date :	16 Aug 2019		
Road Tax Expiry Date :	16 Aug 2019		
PARF Eligibility Expiry Date :	16 Aug 2019		
Inspection Due Date :	16 Aug 2020		
Intended Transfer Date :	26 Mar 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

> Back to OneMotoring

### Enquiry on Vehicle Recall - Vehicle Specific

\* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

#### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1849W

#### Vehicle Details

Vehicle Registration number:	SJS4257G
Make:	FORD
Vehicle Model:	S-MAX TREND 5DR
Engine No.:	9R18631
Chassis No.:	WF0SXXGBWS9R18631

#### Recall Details

No Recall Detail records

OK

4 vehicles

Search Ford S-Max

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Ve Ty
Search Selection	Ford S-Max		Any	Any	Any	Any	Any	



**Ford S-Max 2.0A EcoBoost Titanium** \$61,800 \$10,110 /yr 19-Dec-2013 1,999 cc 97,000 km

Drive Home Now. Buy With Added Peace Of Mind From Vantage Pre-Owned. A Member Of The Darby Group. With Our Comprehensive 72 Points Mechanical And Safety Inspection. Finance Arr In Welcomed....

Vantage Pre-Owned

★ Posted: 26-Mar-2019 Tags: 2013 Ford S-Max, 2013 ford s-max, Ford S-Max, ford s-max, Ford, S-Max, s-max, Used Ford



**Ford S-Max 2.0A EcoBoost Titanium** \$65,800 \$9,910 /yr 19-Jun-2014 1,999 cc 83,000 km

Drive Home Now. Buy With Added Peace Of Mind From Vantage Pre-Owned. A Member Of The Darby Group. With Our Comprehensive 72-Points Mechanical And Safety Inspection. Finance Arr In Welcomed....

Vantage Pre-Owned

★ Posted: 24-Mar-2019 Tags: 2014 Ford S-Max, 2014 ford s-max, Ford S-Max, ford s-max, Ford, S-Max, s-max, Used Ford



**Ford S-Max 2.0A EcoBoost Titanium** \$50,888 \$12,880 /yr 23-Mar-2012 1,999 cc 120,000 km

Very Rare Black Performance S-Max. 236 Bhp. Best Family Car For Long Drives. 7 Seaters. Very Spacious Boot.

★ Posted: 20-Mar-2019 Tags: 2012 Ford S-Max, 2012 ford s-max, Ford S-Max, ford s-max, Ford, S-Max, s-max, Used Ford



**Ford S-Max 2.0A EcoBoost Titanium** \$43,600 \$11,000 /yr 15-Dec-2011 1,999 cc 163,000 km

Excellent Condition, Original Mileage & Paintworks, Accident Free, Owner Upgrading To Bigger Repair Needed, Easy Loan / High Trade In Available, Extended Warranty Available, STA Evaluat We...

★ Posted: 27-Jan-2019 Tags: 2011 Ford S-Max, 2011 ford s-max, Ford S-Max, ford s-max, Ford, S-Max, s-max, Used Ford

General view




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



chassis no





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
 6 Raffles Quay #18-00 Singapore 048580  
 Tel (65) 6224 0010 Fax (65) 6224 0030  
 Operating Hours : Monday to Friday, 09:00 - 17:00  
 UEN: S469500286 / GST Reg. No.: M400917735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

**ADDENDUM**

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : M3FA 19027287 Vehicle Registration No: SJS 4257 G  
 Name (as shown in NRIC) : CHOW EWA AEW NRIC/FIN/Passport No : S19178924  
 (\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
 Address : 23 GUL ROAD Singapore (621356)  
 Contact (Tel) : 66684226 Mobile No.: 9698052  
 Email Address : e.c.chow@smi.com.  
 Date of Accident : 26/02/19 Time of Accident : 12.15 pm.  
 Place of Accident : CENTRAL BOULEVARD  
 Insurance Company : MSIA INSURANCE (S) PTE LTD

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

My company will be making 'own damage' claim for  
the breakdown & repair of vehicle against our  
insurance company.

Chew

Policyholder / Driver's Signature  
 Date: 6/3/19.



Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:  
 Date:



Your Broker:



MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Aon Singapore Pte. Ltd.  
2 Shenton Way #26-01  
SGX Centre 1  
Singapore 068804  
T +65. 6221 8222 / F +65. 6224 1700  
Co. Reg. No. 198301525W

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

**MOTORMAX PLUS-COMMERCIAL**  
Comprehensive

Certificate No. B 28912568 MCY

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
SJS4257G

2. Name of Policyholder  
Smit Singapore Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
01/04/2018

4. Date of Expiry of Insurance  
31/03/2019

5. Persons or Classes of Persons entitled to drive\*

Reinder Peek, Celine Grimbergen,

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
Approved Insurers

for Chief Executive Officer

- Claiming OD?

- Policy no - to correct

- Address: 35' Jalan Kompang Chantek (588614)

was driver or employee of the Insurer's company? husband

no of passengers (1) auto driver

**EMPLOYMENT PASS**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer:  
BOVENTALANCE CONSULTING PTE. LTD.

Name:  
DE SAVORNIN LOHMAN ALEXIA ELISABETH CATHARINA

Occupation:  
CONSULTANT

PN  
G3097272U

Date of Application  
09-08-2016

Date of Issue  
11-08-2016

Date of Expiry  
27-10-2018

L7084827

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

03085222U

DE SAVORNIN LOHMAN ALEXIA  
ELISABETH CATHARINA

High Card: 18 Feb 1979


Issue Date: 13 Jun 2016

Valid Till: 12/09/2023

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**  
EFFECTIVE DATE:

Class 1 Motor cars with unladen weight <= 2000kg with <= 7 passengers, exclusive of driver, and other motor vehicles with unladen weight <= 2500kg

NP 426A



**VISIT PASS**

Immigration Regulations


Name:  
DE SAVORNIN LOHMAN ALEXIA ELISABETH CATHARINA



Date of Birth	Sex	Nationality
18-02-1979	F	NETHERLANDS

PN	Date of Issue	Date of Expiry
G3096722U	11-08-2016	27-10-2018

YOU ARE TO SURRENDER THIS CARD IF IT IS DAMAGED OR FALSIFIED, OR WHEN A NEW CARD IS ISSUED TO YOU.





樹發汽車修理廠  
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065  
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	WSK/JW/SF-4257G
Policy No:	B28912568MCY	Date of Loss:	26/02/2019
Vehicle Reg. No.:	SJS4257G	Driveable?	
Driver Age/Info:	40 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	SMIT SINGAPORE PTE LTD	Contact No:	+6598537818
Driver:	DE SAVORNIN LOHMAN ALEIDA ELISABETH CATHARNA		
Make/Model:	FORD S-MAX, 2.3 Trend (A)	Vehicle Reg. Date:	17/08/2009
Vehicle Colour:	Silver	Chassis No:	WF0SXXGBWS9R18631
Engine No:	9R18631		
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	SEE ATTACHED		
Remarks:	VEHICLE WAS TOWED IN.		
Present Location:	SHU FATT AUTO WORKS (HQ)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	9,900.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>9,900.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>693.00</b>
<b>Nett Amount (S\$)</b>	<b>10,593.00</b>

This claim is handled by: PATRICIA KOH



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Shu Fatt Auto Works/SJS4257G/23/03/2019 10:25. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not economical to repair.  
Recommended total loss.

NAZUKK

if

2713719



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20190226/0345	LOCATION OF FIRE:		
FIRE REPORTED ON : 26 February 2019	Along Marina Link		
TIME OF CALL : 12:09:53 hrs	Near lamp post no. 94F		
STATION COVERAGE : Marina Bay Fire Station	Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Ford car (SJS4257G) at the above said location.			
METHOD OF EXTINGUISHMENT: Fire burnt itself out before the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
<b>REPORT CERTIFIED TRUE AND CORRECT BY:</b>			
DANNIES ANG WEITONG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

*This is a computer generated Fire Report. No signature is required.*



## Fire Report Application

Your request for the Fire Report has been confirmed and the amount of SGD170.00 will be deducted from your account. You will receive the report within 8 working days upon completion of investigations. Please quote the following transaction number when making enquiries.

Download Tax Invoice/Receipt

Transaction Number: FR2019032802783

Date/Time: 28/03/2019 14:12

INCIDENT DETAILS						
Date and Time	26/02/2019 12:15					
Location of Fire	CENTRAL BOULEVARD					
Fire Involved	SJS4257G					
REQUESTOR DETAILS						
Requestor Type	Insurance Companies					
Requestor ID Type	Foreign International	Requestor ID	G2706880X			
Name of Applicant	SHIRLEY HIEW					
Company Name	LKK AUTO CONSULTANT PTE LTD					
Company UEN						
Company Reference Number	CS/MSG19005267/NSD3					
CONTACT DETAILS						
Mode of Collection	Email					
Main Contact No.	62563561	Office No.				
Handphone No.		Fax No.	62564315			
Email Address	sur@lkkauto.com					
Address	Block No.	51	Floor No.	01	Unit No.	25
	Street Name	UBI AVE 1				
	Building Name	PAY UBI INDUSTRIAL PARK	Postal Code	408933		
PAYMENT DETAILS						
Payment Mode	Credit/Debit Card					
EP Reference No.	5537537184786440603226					
PSi Reference No.	63aa8e7f-95d1-4e81-9156-a850e65ab906					
Total Fees	SGD170.00					



SINGAPORE CIVIL DEFENCE FORCE  
91 UBI AVENUE 4  
SINGAPORE 408827  
TELEPHONE: 6280 0000  
GST REG NO: MG-8400000-5

## TAX INVOICE/RECEIPT

Name : SHIRLEY HIEW  
Address : 51 UBI AVE 1  
#01-25 PAY UBI INDUSTRIAL PARK  
Singapore 408933

Receipt No : 5537537184786440603226  
Date/Time : 28/03/2019 14:12  
eService ID : FR2019032802783

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2019032802783	170.00	0.00	170.00
					<b>Total Amount (SGD)</b>	<b>170.00</b>

**REMARKS:**

Date and Time [26/02/2019 12:15] - Location of Fire [CENTRAL BOULEVARD]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Mar 2019	23 Mar 2019 10:25 <b>S\$9,900.00</b>	25 Mar 2019 09:11 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>SMIT SINGAPORE PTE LTD</b> , Co. Reg. No.: 198501849W, Tel: +6598537818		
Vehicle Reg. No.:	<b>SJS4257G</b>	Date of Loss:	26/02/2019 12:00 - :59 [114 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / 587268</b>	Policy/Cover Note No.:	B28912568MCY (Comprehensive) Coverage: 01/04/2018 - 31/03/2019
		Excess:	S\$0.00
Repairer:	<b>Shu Fatt Auto Works (HQ)</b> Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Kwok Woon Choo</b> - 6643 1330]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 24/04/2019]		
OD Investigation	<b>Yes</b>		
Driver/Custodian:	DE SAVORNIN LOHMAN ALEIDA ELISABETH CATHARNA (40 / Female), NRIC: G3085222U, Tel: +6598537818 Email: aleidsavlo@hotmail.com		
Adj Asg. Remarks:	TO REVERT AND PENDING FOR INVESTIAGTION (cause of fire).		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG\_SG (27/03/2019): Alert - Adj Mandate Revoked - SJS4257G - Claim Handler: Kwok Woon Choo

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



## Claim Documents

**SJS4257G (587268)**  
**OD**  
**Feb 26 2019 12:00PM**  
**[SMIT SINGAPORE PTE LTD]**  
**Shu Fatt Auto Works**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	04/03/19 11:58	<b>Accident Statement</b>	Load HTM	
2	08/03/19 12:55	<b>Addendum Sheet</b>	Load TIF	
3	08/03/19 12:58	<b>Accident Statement Addm. #1</b>	Load HTM	
4	23/03/19 10:25	<b>Repairer Estimates</b>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/19 11:21	<b>Adjuster Immediate Advice</b>	Load HTM	
2	23/04/19 13:47	<b>Adjuster Immediate Advice</b>	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	04/03/19 11:56	<b>General view</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
2	04/03/19 11:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
3	04/03/19 11:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
4	04/03/19 11:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
5	04/03/19 11:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
6	04/03/19 11:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
7	04/03/19 11:57	<b>chassis no</b> [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
8	23/03/19 10:14	<b>1</b>	Load JPG <input checked="" type="checkbox"/>	
9	23/03/19 10:14	<b>2</b>	Load JPG <input checked="" type="checkbox"/>	
10	23/03/19 10:14	<b>3</b>	Load JPG <input checked="" type="checkbox"/>	
11	23/03/19 10:14	<b>4</b>	Load JPG <input checked="" type="checkbox"/>	
12	23/03/19 10:14	<b>5</b>	Load JPG <input checked="" type="checkbox"/>	
13	23/03/19 10:14	<b>6</b>	Load JPG <input checked="" type="checkbox"/>	
14	23/03/19 10:14	<b>7</b>	Load JPG <input checked="" type="checkbox"/>	
15	23/03/19 10:14	<b>8</b>	Load JPG <input checked="" type="checkbox"/>	
16	23/03/19 10:14	<b>9</b>	Load JPG <input checked="" type="checkbox"/>	
17	23/03/19 10:14	<b>10</b>	Load JPG <input checked="" type="checkbox"/>	
18	23/03/19 10:14	<b>11</b>	Load JPG <input checked="" type="checkbox"/>	
19	23/03/19 10:14	<b>12</b>	Load JPG <input checked="" type="checkbox"/>	
20	23/03/19 10:14	<b>13</b>	Load JPG <input checked="" type="checkbox"/>	
21	23/03/19 10:14	<b>Chassis Number</b>	Load JPG <input checked="" type="checkbox"/>	
22	23/03/19 10:14	<b>Odometer Reading</b>	Load JPG <input checked="" type="checkbox"/>	
23	23/03/19 10:14	<b>tyre make</b>	Load JPG <input checked="" type="checkbox"/>	
24	23/03/19 10:14	<b>tyre make</b>	Load JPG <input checked="" type="checkbox"/>	
25	23/03/19 10:14	<b>tyre size</b>	Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail Print
1	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
2	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
3	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
4	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
5	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
6	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
7	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
8	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
9	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
10	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
11	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
12	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
13	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
14	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
15	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
16	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
17	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
18	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
19	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
20	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
21	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
22	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
23	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
24	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
25	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
26	27/03/19 11:09	General View		Load JPG <input checked="" type="checkbox"/>
27	27/03/19 11:09	Chassis Number		Load JPG <input checked="" type="checkbox"/>
28	27/03/19 11:09	Odometer Reading		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail Print
1	04/03/19 11:54	Sketch Plan [Linked Accident Report Documents]		Load TIF
2	23/03/19 10:25	Certificate of Insurance		Load PDF
3	23/03/19 10:25	Driver's Driving License		Load PDF
4	23/03/19 10:25	parf value enquiry		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/03/19 11:00	ESTIMATE.pdf		Load PDF
2	27/03/19 11:00	SJS 4257G GIA.pdf		Load PDF
3	25/04/19 13:27	INVESTIGATION REPORT		Load PDF
4	25/04/19 13:27	SCDF FIRE REPORT		Load PDF
5	25/04/19 13:36	LTA REBATE		Load PDF

## Linked Accident Report Documents

View 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail Print
1	04/03/19 11:58	Accident Statement		Load HTM
2	08/03/19 12:55	Addendum Sheet		Load TIF
3	08/03/19 12:58	Accident Statement Addm. #1		Load HTM

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	04/03/19 11:56	<b>General view</b>	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 11:56	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 11:56	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 11:56	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 11:56	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 11:56	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 11:57	<b>chassis no</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	04/03/19 11:54	<b>Sketch Plan</b>	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:**  Repairer  Handling Insurer  
 Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG19005267/NSD3S2  
**Date:** 25/04/2019

### REFERENCE

Insured/Claimant:	SMIT SINGAPORE PTE LTD	Policy No:	B28912568MCY	Claim No:	587268
Date of Loss:	26/02/2019	Nature of Claim:	OD		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJS4257G</b>	Engine No:	9R18631
Make & Model:	FORD S-MAX, 2.3 Trend (A)	Chassis No:	WF0SXXGBWS9R18631
Reg. Date:	17/08/2009 (Man. Year: 2009)	Odometer:	165263 km
Colour:	Silver		
Engine Capacity:	2261 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,900.00	0.00	9,900.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,900.00</b>	<b>0.00</b>	<b>9,900.00</b>	<b>100.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>693.00</b>	<b>0.00</b>	<b>693.00</b>	<b>100.00</b>
<b>Nett Amount (S\$)</b>	<b>10,593.00</b>	<b>0.00</b>	<b>10,593.00</b>	<b>100.00</b>

### INSPECTION

Date of Assignment:	25/03/2019	Present Location:	Shu Fatt Auto Works (HQ)
Date Inspected:	25/03/2019	Inspected At:	Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723
Estimated Period of Repair:	0.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$16,000.00
OMV :	\$22,725.00
PARF Rebate (1) :	\$11,362.00
Quota Premium Paid :	\$18,890.00
COE Rebate (2) :	\$736.00
Total Rebate (1) + (2) = :	\$12,098.00

The total amount incurred will be Market Value \$16,000.00 minus Total Rebate \$12,098.00 = \$3,902.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 25 Apr 2019)

**Parts:** M1-MPV      FORD S-MAX 2.3 Trend (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJS4257G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*The repair charges of the abovementioned vehicle is approximately \$9000.00.		9,000.00 F	*- F		
						<b>Sub Total (\$)</b>	<b>9,000.00</b>	<b>0.00</b>
						<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	900.00	0.00
						<b>Total Parts (\$)</b>	<b>9,900.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >