

ASS. REC. BY:

REF: CS/smo19005280/TV d301

Special Instruction:

Surveyor: SteveASSIGNMENT (Office)From (Person): Gnroh Pau Loong of SMO Date/Time: 25.3.19 13:14pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 3788E Insured: YP 8013Eat Workshop m/s My Car Consultant - UBI Tel: 88668832of 53 pang ubi Industrial Park, #01-33Policy No: DIGMPCVE 003732 Claim No: CMTD1901486

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21.3.2019
(Client's Record)CA / REV / REP. / REV 24 HRS "up" H.O.D. Endorsement: _____Date/Time: 25.3.19 2.59pm Person Contacted: Hui Qin Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	GBC 3788E x	
	YP 8013E - NA/INC. 190051721 24	DOA - 21/3/2019
<u>28/3/19</u>	Send preli revised wia merimen	

Steve

REF: SMO

ASSIGNMENT

From:

Date: 26.3.2019

Estimated Cost:

QD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 3788E

at Workshop m/s My Car Consultant
of 53 Paya ubi Industrial Park # 01-33

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GBC 3788E

Yr Regn:

28/07/17

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN NV200

C.C.

1-6

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

33887

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VM29105528

Gen. Cond: (Good) / Fair / Poor / BurntSteering: (Inorder) / Jammed / Leaked / Burnt orBrake: (Inorder) / Jammed / Leaked / Burnt orModi: Nil / S/Rim / (STD A/Rim) or

Tyre Size:

F:

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

(TOYO) / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/3/19

D.O.I.

26/3/19

Survey held at

My Car Consultant

Des. of Damages (Frt) / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 48,000

PV - 33,489

NV - 14,511

17/4/19 Finalize \$8200, 12 days (Red 7821.19, 4910)

RECEIVED 17 APR 2019

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

17/4 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$) 8200p

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

490

10

490

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2019		25 Mar 2019 13:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CO-OPERATE ASSOCIATES PTE LTD, Co. Reg. No.: NA		
Main Claimant:	SPECTRIS PTE LTD, Co. Reg. No.: 198101779G		
Vehicle Reg. No.:	GBC3788E	Date of Loss:	21/03/2019 16:00 - :59
Claim Type:	TP / CMTD1901486	Policy/Cover Note No.:	D18MTPCVE003732 (Comprehensive)
Vehicle Reg. No. (Insured):	YP8013E	Policy No. (Claimant):	
		Excess:	
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel: 88668832 (Hui Qin)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2019]		
Driver/Custodian (Insured):	TAN KIAN TONG (), NRIC: S1115405J, Tel: +6593884596 Email:		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

T. 2.58 p.m
V: PA
P: Hui Qin
E: V

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Wednesday, 10 April 2019 11:30 AM
To: SUR
Subject: FW: Direct Settle ; RE: CMTD1901486/GPL - PRI/ YP8013E & GBG3788E & ETC ACC ON 21.03.19

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]
Sent: Wednesday, 10 April 2019 11:09 AM
To: admin@mycar.sg
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Direct Settle ; RE: CMTD1901486/GPL - PRI/ YP8013E & GBG3788E & ETC ACC ON 21.03.19

Dear Sir / Madam,

With reference to the captioned, we would like to direct settle and please liaise with agreed SJE, M/s LKK AUTO CONSULTANTS for survey / finalisation, thank you.

By copy to M/s LKK AUTO,

Please assist in the above, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

Teo, Grace

From: My Car Consultant <admin@mycar.sg>
Sent: Monday, March 25, 2019 1:09 PM
To: Teo, Grace
Subject: re: CMTD1901486/GPL - PRI/ YP8013E & GBG3788E & ETC ACC ON 21.03.19

WITHOUT PREJUDICE

OUR REF: GBG3788E
YOUR REF: YP8013E

We agree to your list of surveyor.
We propose to use LKK Auto Consultants

Thanks & Regards,

Huiqin

My Car Consultant
53 Paya Ubi Industrial Park #01-33 S(408934)
Tel: 88668832

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 25 March, 2019 12:54 PM
To: admin@mycar.sg; claimsreport <claimsreport@sompo.com.sg>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1901486/GPL - PRI/ YP8013E & GBG3788E & ETC ACC ON 21.03.19

Our Reference : CMTD1901486/GPL
Your Reference: GBG3788E

Without Prejudice

Date: 25/03/2019

EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S MY CAR CONSULTANT

Dear Hui Qin,

ACCIDENT INVOLVING YP8013E & GBG3788E ON 21.03.2019

We refer to your Notice of Accident dated 22/03/2019.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: My Car Consultant [<mailto:admin@mycar.sg>]

Sent: Friday, March 22, 2019 6:55 PM

To: claimsreport; Claims - Motor Survey

Subject: OUR REF: GBG3788E YOUR REF: YP8013E PRE-REPAIR INSPECTION FOR GBG3788E

WITHOUT PREJUDICE

OUR REF: GBG3788E

YOUR REF: YP8013E

Dear Sir/Madam,

**PRE-REPAIR INSPECTION FOR GBG3788E
ACCIDENT INVOLVING GBG3788E AND YP8013E**

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention. Please let us know within two (2) working days

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Thanks & Regards,

Huiqin

My Car Consultant

53 Paya Ubi Industrial Park #01-33 S(408934)

Tel: 88668832



This email has been checked for viruses by AVG antivirus software.
www.avg.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	GNOH PAU LOONG	Date:	28 Mar 2019
-------	----------------	-------	-------------

Preliminary Advice

Insured Vehicle No	: YP8013E	Accident Date	: 21/03/2019
TP Vehicle No	: GBG3788E	Assignment Date	: 25/03/2019
Make	: NISSAN NV200	Est. Duration of Repair	: 12
Date of Inspection	: 26/3/2019		
Inspection At	: MR CAR CONSULANT PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,021.19
Revised Amount	:S\$	9,356.87
Check Items (Estimated)	:S\$	1,624.42
Total	:S\$	10,981.29
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1779G
Vehicle Details	
Vehicle No.:	GBG3788E
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 DX-2 1.6 AUTO
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	HR16088414D
Chassis No.:	VM20105528
Maximum Power Output:	-
Open Market Value:	\$18,028.00
Original Registration Date:	28 Jul 2017
First Registration Date:	28 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$902.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$33,489.00
Total Rebate Amount:	\$33,489.00

The information contained herein is correct as at 28 Mar 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



[Advanced Search](#)
[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Nissan NV200 1.6A](#)

Nissan NV200 1.6A

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWN](#)

Price	\$49,888	Lifespan	26-Jul-2037
Depreciation ⓘ	\$5,990 /yr View models with similar depre	Reg Date	27-Jul-2017 (8yrs 3mths 28days COE left)
Mileage	32,600 km (19.5k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$33,514 as of today (change)	OMV ⓘ	\$18,041
COE ⓘ	\$40,212	ARF ⓘ	\$903
Engine Cap	1,597 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,220 kg		
Type of Vehicle	Van		

Features

16V In-line, 4 Cylinder, DOHC, Petrol. [View specs of the Nissan NV200 \(2011\)](#)

Accessories

Front Recording Camera, Power Side Mirrors.

Description

Compact. Car-Like Cabin, Good Cargo Space. 1 Careful Owner. Pristine Cond! Under Agent Warranty.

Category

Direct Owner Sale

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

[Compare](#)


Price Chart

Summary



Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s) Gabriel Tan

Contact No. 97474090

Enquiry [Contact Seller](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/03/2019 11:05
Date Of Accident	21/03/2019 16:40
Exact Location Of Accident	CTE TWDS CITY BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG3788E
Insured/Policyholder	
Name Of Registered Owner	SPECTRIS PTE LTD
Co Reg No	198101779G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200 DX-2 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101529270
Cover Note Number	

Driver

Name of Driver	LIM POH KIAT (LIN BAOJI)
NRIC No	S7927511E
Date Of Birth	08/09/1979
Occupation	OUTDOOR
Date Of Driving Pass	14/03/2014
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96214539
Fax Number	
Contact Number	OFFICE-96214539
Email Address	NOEMAIL

Address	BLK 250 KIM KEAT LINK #05-101
Postcode	310250
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8013E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GZ8209T
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

YN6751G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LIM POH KIAT (LIN BAOJI)

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

GBG3788E

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Sketch Plan

A: G863788E
B: YP8013E
C: GZ8209T
D: YN6751G

SKETCH PLAN



BLADWEN Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED TIME AND DATE, I WAS ~~DRIVING~~ (G863788E) WAS TRAVELLING AT A SLOW SPEED ALONG THE STATE VENUE ON THE LEFT MOST ~~FA~~ LANE. TRAFFIC WAS SLOW AS IT WAS RAINING HEAVILY. AS THE FRONT VEHICLE APPLIED BRAKES, I ^{FOLLOWED SUIT.} A SUDDENT THERE WAS A HUGE IMPACT FROM MY REAR, CAUSING MY VEHICLE TO PROPEL FORWARD AND COLLIDE ONTO (YN6751G). AFTER ALIGHTING, I REALISED IT WAS A CHAIN COLLISION CAUSED BY (GZ8209T) WHO COLLIDED ONTO (YP8013E) THUS COLLIDING ONTO ME AND FINALLY PUSHING MY VEHICLE FORWARD TO (YN6751G)

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/IN No.:



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Steve CLKK) wil Prejudice 27/3/19 5.00pm

28/3/19

Estimate

12 days
L/S
Ry AF spray

Vehicle: GBG3788E

Make & Model: NISSAN NV200

No.	Particular	Qty	Amount (\$)
List Price			
1	BONNET ✓ DD	1 pc	858.50 /
2	BONNET LOCK ✓ DD	1 pc	68.50 /
3	BONNET HINGE LH/RH@\$36.50 ✓ LH RH - BT	2 pcs	73.00 /
4	FRONT GRILLE ASSY BR ✓	1 pc	300.50 /
5	FRONT GRILLE LOGO ✓ CUT	1 pc	48.50 /
6	FRONT BUMPER ✓ BR	1 pc	513.20 /
7	FRONT BUMPER SIDE PAD LH/RH@\$348.60 RH ✓ LH - BR	2 pcs	697.20 /
8	FRONT BUMPER SIDE RETAINER LH/RH@\$23.00 RH ✓ LH - BR	2 pcs	46.00 /
9	FRONT BUMPER TOW COVER X NN	1 pc	16.90 X
10	FRONT BUMPER SPONGE ✓ BR	1 pc	107.20 /
11	FRONT REINFORCEMENT X NN	1 pc	444.90 X
12	HEADLAMP LH/RH@\$359.80 LH ✓ RH - BR	2 pcs	719.60 /
13	SUPPORT PANEL ✓ DD	1 pc	425.70 /
14	AIRCON CONDENSOR ? / BT	1 pc	681.20 /
15	RADIATOR ? X NN	1 pc	668.30 X
16	RADIATOR COWLING ? X NN	1 pc	102.50 X
17	RADIATOR FAN MOTOR X NN	1 pc	335.40 X
18	REAR BUMPER ✓ BR	1 pc	460.80 /
19	REAR BUMPER SIDE RETAINER LHS & RHS @ \$35.20 LH ✓ RH - BR	2 pcs	70.40 /
20	REAR BUMPER SPONGE ✓ BR	1 pc	88.90 /
21	END PANEL - OUTER ✓ DD	1 pc	168.40 /
22	END PANEL - INNER ✓ DD	1 pc	841.80 572 /
23	END PANEL TOP GARNISH ✓ BR	1 pc	60.00 /
24	SPARE WHEEL CARRIER X NN	1 pc	268.00 X
25	SPARE WHEEL CARRIER HOOK & BOLT X NN	1 pc	78.00 X
26	REAR EXHAUST SILENCER X NN	1 pc	446.40 X
27	REAR EXHAUST MOUNTING X NN	1 pc	12.66 X
28	TAILLAMP LHS & RHS @\$203.4 LH ✓ RH - BR	2 pcs	406.80 /
29	TAILGATE DD ✓	1 pc	1,890.20 /
30	TAIL GATE DAMPER LHS & RHS @\$161.30 X NN	2 pcs	322.60 X
31	REAR FENDER RHS (BODY PANEL) X R	1 pc	1,791.60 X
32	TAILGATE EMBLEM NV200 ✓ NEC	1 pc	67.60 /
33	TAIL GATE EMBLEM LOGO ✓ NEC	1 pc	45.60 /
34	TAIL GATE GARNISH STICKER ✓ NEC	1 pc	30.80 /

35	TAILGATE HANDLE	X N/A	1 pc	351.50 X
36	TAIL GATE NUMBER PLATE LAMP	X N/A	1 pc	54.80 X
37	TAILGATE LOCK	✓ BR	1 pc	228.10 /
38	TAILGATE LOCK CATCH	X N/A	1 pc	30.80 X
39	TAIL GATE WEATHERSTRIP	✓ CR4	1 pc	75.00 /
40	TAILGATE WIPER ARM	X N/A	1 pc	55.00 X
41	TAILGATE WIPER MOTOR	X N/A	1 pc	191.30 X
42	TAILGATE INNER TRIM	✓ TN	1 pc	131.80 /

43. Rear windscreen 868.60 BR /

Total
LESS 30%
Sub-Total cost for parts

9,704.19
 - 30%
 6,792.87 /

14,275.96
- 4,282.79
9,993.17

Part Replacement - Special
Nett Item

1	REAR REVERSE SENSOR	✓ BR	180.00 /
2	REAR WINDSCREEN SEAL	✓ NEC	80.00 /
3	REAR BUMPER CLIP	✓ NEC	25 35.00 /
4	FRONT BUMPER CLIP	✓ NEC	25 35.00 /
5	TOP UP GAS	✓ NEC	40.00 /
6	TOP UP COOLANT	✓ NEC	40.00 /
Sub-Total cost for parts			410.00

390 /

Labour & MISC Charges

1	REMOVE,REFIX REAR WINDSCREEN	100	150.00
2	REMOVE,REFIX REAR INTERIOR UPHOLSTERY , ASSIST REPAIR	30	120.00
3	CHECK REAR ELECTRICAL WIRING	30	60.00
4	SPRAY UNDERCOATING	30	180.00
5	SPRAY PAINTING ACCIDENT AREAS	1200	1,800.00
6	REMOVE , REFIX REAR BOOT ASSY	30	100.00
7	REMOVE,REFIX REVERSE SENSOR	20	80.00
8	PANEL BEAT , REMOVE AND REPLACING FRONT & REAR	1600	2,400.00
9	REMOVE,REFIX RADIATOR & CONDENSOR	30	120.00

Sub-Total Labour

3070 / **5,010.00**

Grand Total

15,413.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10,252.87
 L/S - 8202.99
 = 8209

16,021.19

Steve Chen (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Wednesday, April 17, 2019 12:41 PM
To: Steve Chen (LKK Auto)
Subject: re: GBG3788E Finalize

WITHOUT PREJUDICE

Hi Steve,

I confirm the same for this vehicle:
COR \$8200
Rental 12 Days

Best Regards,

Huiqin

My Car Consultant Pte Ltd
53 Paya Ubi Industrial Park #01-33 S(408934)
Tel: 88668832

From: "Steve Chen (LKK Auto)" <SteveChen@lkkauto.com>
Sent: Thursday, April 11, 2019 9:12 AM
To: "My Car Consultant" <admin@mycar.sg>
Subject: GBG3788E Finalize

Dear Sir,

The above vehicle finalize \$8200 L/S. 12 days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2019		25 Mar 2019 13:14 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case



































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CO-OPERATE ASSOCIATES PTE LTD , Co. Reg. No.: NA								
Main Claimant:	SPECTRIS PTE LTD , Co. Reg. No.: 198101779G								
Vehicle Reg. No.:	GBG3788E	Date of Loss:	21/03/2019 16:00 - :59 [19 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901486	Policy/Cover Note No.:	D18MTPCVE003732 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP8013E	Policy No. (Claimant):							
		Excess:							
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/04/2019]								
Driver/Custodian (Insured):	TAN KIAN TONG (), NRIC: S1115405J, Tel: +6593884596 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



























***GBG3788E (CMTD1901486)**
[YP8013E]
TP
SPECTRIS PTE LTD
Mar 21 2019 4:00PM
[CO-OPERATE ASSOCIATES PTE LTD]
My Car Consultant - Ubi

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print	
1	25/03/19 13:13	Sompo Insurance Singapore Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: YP8013E, Claimant: CO-OPERATE ASSOCIATES PTE LTD	 Load HTM		
1	28/03/19 12:22	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	28/03/19 08:14	General View	 Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/03/19 08:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/19 08:14	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 08:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
82	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	28/03/19 08:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	25/03/19 12:49	Pre-Repair Survey - SAS	 Load PDF	
2	25/03/19 13:14	Pre-Repair Survey - AGREED LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19005280/EVD32E

Date: 09/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE003732
Claimant Vehicle No :	GBG3788E	Insured Vehicle No :	YP8013E
Date of Loss:	21/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3788E			
Make & Model:	NISSAN NV200, 1.6 DX-2 (A)		Engine No:	HR16088414D
Reg. Date:	28/07/2017 (Man. Year: 2016)		Chassis No:	VM20105528
Colour:	Grey		Odometer:	33887 km
Engine Capacity:	1597 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,931.19	7,102.87	3,828.32	35.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,090.00	3,150.00	1,940.00	38.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,021.19	10,252.87	5,768.32	36.00
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	16,021.19	8,200.00	7,821.19	48.82

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	26/03/2019	Inspected At: My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33 Singapore 408934
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 May 2019)	
Parts:	N/A	NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3788E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	858.50 FL	*858.50 FL
2	1		*BONNET LOCK	Dented	68.50 FL	*68.50 FL
3	2		*BONNET HINGE LH / RH	Bent	73.00 FL	*73.00 FL
4	1		*FRONT GRILLE ASSY	Broken	300.50 FL	*300.50 FL
5	1		*FRONT GRILLE LOGO	Cut	48.50 FL	*48.50 FL
6	1		*FRONT BUMPER	Broken	513.20 FL	*513.20 FL
7	2		*FRONT BUMPER SIDE PAD LH / RH	Broken	697.20 FL	*697.20 FL
8	2		*FRONT BUMPER SIDE RETAINER LH / RH	Broken	46.00 FL	*46.00 FL
9	1		*FRONT BUMPER TOW COVER	Not Necessary	16.90 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Broken	107.20 FL	*107.20 FL
11	1		*FRONT REINFORCEMENT	Not Necessary	444.90 FL	*- FL
12	2		*HEADLAMP LH / RH	Broken	719.60 FL	*719.60 FL
13	1		*SUPPORT PANEL	Dented	425.70 FL	*425.70 FL
14	1		*AIRCON CONDENSOR	Bent	681.20 FL	*681.20 FL
15	1		*RADIATOR	Not Necessary	668.30 FL	*- FL
16	1		*RADIATOR COWLING	Not Necessary	102.50 FL	*- FL
17	1		*RADIATOR FAN MOTOR	Not Necessary	335.40 FL	*- FL
18	1		*REAR BUMPER	Broken	460.80 FL	*460.80 FL
19	2		*REAR BUMPER SIDE RETAINER LHS & RHS	Broken	70.40 FL	*70.40 FL
20	1		*REAR BUMPER SPONGE	Broken	88.90 FL	*88.90 FL
21	1		*END PANEL - OUTER	Dented	168.40 FL	*168.40 FL
22	1		*END PANEL - INNER	Dented	841.80 FL	*572.00 FL
23	1		*END PANEL TOP GARNISH	Broken	60.00 FL	*60.00 FL
24	1		*SPARE WHEEL CARRIER	Not Necessary	268.00 FL	*- FL
25	1		*SPARE WHEEL CARRIER HOOK & BOLT	Not Necessary	78.00 FL	*- FL
26	1		*REAR EXHAUST SILENCER	Not Necessary	446.40 FL	*- FL
27	1		*REAR EXHAUST MOUNTING	Not Necessary	12.66 FL	*- FL
28	2		*TAILLAMP LHS & RHS	Broken	406.80 FL	*406.80 FL
29	1		*TAILGATE	Dented	1,890.20 FL	*1,890.20 FL
30	2		*TAIL GATE DAMPER LHS & RHS	Not Necessary	322.60 FL	*- FL
31	1		*REAR FENDER RHS (BODY PANEL)	Repair	1,791.60 FL	*- FL
32	1		*TAILGATE EMBLEM NV200	Necessary	67.60 FL	*67.60 FL
33	1		*TAIL GATE EMBLEM LOGO	Necessary	45.60 FL	*45.60 FL
34	1		*TAIL GATE GARNISH STICKER	Necessary	30.80 FL	*30.80 FL
35	1		*TAILGATE HANDLE	Not Necessary	351.50 FL	*- FL
36	1		*TAIL GATE NUMBER PLATE LAMP	Not Necessary	54.80 FL	*- FL
37	1		*TAILGATE LOCK	Broken	228.10 FL	*228.10 FL
38	1		*TAILGATE LOCK CATCH	Not Necessary	30.80 FL	*- FL
39	1		*TAIL GATE WEATHERSTRIP	Crushed	75.00 FL	*75.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*TAILGATE WIPER ARM	Not Necessary	55.00 FL	*- FL
41	1		*TAILGATE WIPER MOTOR	Not Necessary	191.30 FL	*- FL
42	1		*TAILGATE INNER TRIM	Torn	131.80 FL	*131.80 FL
43	1		*REAR WINDSCREEN	Broken	868.60 FL	*868.60 FL
44	1		*REAR REVERSE SENSOR	Broken	180.00 FS	*180.00 FS
45	1		*REAR WINDSCREEN SEAL	Necessary	80.00 FS	*80.00 FS
46	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*25.00 FS
47	1		*FRONT BUMPER CLIP	Necessary	35.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,474.56	10,014.10
- List Item Discount on L Items 30.00/30.00% (S\$)	4,543.37	2,911.23
Total Parts (S\$)	10,931.19	7,102.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOP UP GAS	New	40.00	40.00
2	TOP UP COOLANT	New	40.00	40.00
3	REMOVE, REFIX REAR WINDSCREEN	New	150.00	100.00
4	REMOVE, REFIX REAR INTERIOR UPHOLSTERY, ASSIST REPAIR	New	120.00	30.00
5	CHECK REAR ELECTRICAL WIRING	New	60.00	30.00
6	SPRAY UNDERCOATING	New	180.00	30.00
7	SPRAY PAINTING ACCIDENT AREAS	New	1,800.00	1,200.00
8	REMOVE, REFIX REAR BOOT ASSY	New	100.00	30.00
9	REMOVE, REFIX REVERSE SENSOR	New	80.00	20.00
10	PANEL BEAT, REMOVE AND REPLACING FRONT & REAR	New	2,400.00	1,600.00
11	REMOVE, REFIX RADIATOR & CONDENSOR	New	120.00	30.00
Gross Labour Cost (S\$)			5,090.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >