Surveyor: Tanfin | REF: QBE

ASSIGNMENT

From: | Date: 26/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 733Y

at Workshop m/s Ventage Automotive

of 305 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: call Melody @ 9278 2710

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted: Vehicle: IN / OUT Melody.

Veh No: SMH 733Y Yr Regn: 2019, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Peugeot 5008 c.c 1598

Colour Bronze A/C: Insured / Std / NI / NA

Sp.Reading 5431 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF3M4SGZWJL009525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	0 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	26/3/19 @ 2:45pm.

Survey held at Vantage Auto

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL