

22/03/2021

ASS. REC. BY:

REF: CS/ICS 19005338/Kt d301 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

Mentem

From (Person): Crystabelle Tan of ICS Date/Time: 26.3.19 16.05pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGU 4151C Insured:

at Workshop m/s chung Hoo motor Tel: 67556142

of BK 1019 # 01-374/382

Policy No: MRC 18A 0024960 Claim No: DMPC 19000 83H/CT

Sum Insured: Excess: \$750.00

Make of Veh: D.O.A 24.3.19

(Client's Record)

CA / (REV) REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 26.3.19 8.29am Person Contacted: Mr Ang Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate	(✓)
	SGU 4151C - X		
28/3	Revert via mentem		
29/3	11:13 approve by Crystabelle Lump sum \$4500		
29/3	inform lefeeda on offer lump sum		
29/3	14:46 mandate request propose lump sum - 10% instead 20%		
29/3	15:29 mandate approved \$5000, Crystabelle Tan		
29/3	inform June, authorise repair lump sum \$5000 inclusive?		

REF: ICS

ASSIGNMENT

From:

Date: 26.3.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGU 4151C

at Workshop m/s Chung Hoe Motor

of BLK 1019 # 01-374/382 (Yishuh)

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: \$750.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$476

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGU 4151C

Yr Regn:

09 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato Forte K3 1591

Colour:

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

29719

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAF-B 411 M14 5664821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

24/3/19

D.O.I.

26/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

OPC

Date / Time

Action / Instruction

If supplementary need get approval again. Excess \$750/-

26/8/19 @ 4800 Confirmed. E fees. (Red: 1076.70; 18%)

RECEIVED 26 AUG 2019

Date/Time. File Pass to?



Prel. Report

26/19 Typist



Final Report

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 4800/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week-end (\$)

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Others

TOTAL

250

11

261



26/8/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Mar 2019 15:38 Sendback Est	25 Mar 2019 15:48 S\$5,832.70	25 Mar 2019 16:05 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	SHEN WEIGUO, ID: S2752240H, Email: shenxing1989@gmail.com		
Vehicle Reg. No.:	SGU4151C	Date of Loss:	24/03/2019 12:00 - :59 [29 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900083H/CT	Policy/Cover Note No.:	MPC18A00249601 (Comprehensive)
		Excess:	S\$750.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2019]		
Driver/Custodian:	SHEN WEIGUO (), NRIC: S2752240H Email: shenxing1989@gmail.com		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SGU4151C (DMPC1900083H/CT)

OD

Mar 24 2019 12:00PM

[SHEN WEIGUO]

Cheng Hoe Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 29/03/2019 15:29 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5000.00) - SGU4151C - Claim Handler: Crystabelle Tan

Approved:5000.00:offer lump sum

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	25 Mar 2019 15:36	Clim Veh Model Changed	(203777) KIA FORTE K3 1.6 (A).	[R] SHARON CHIONG BENG CHOON	
2	25 Mar 2019 15:36	Clim Created	Reg No: SGU4151C. Policy No: MPC18A00249601. Acct Date: 2019/03/24. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: Cheng Hoe Motor Pte Ltd (Yishun)	[R] SHARON CHIONG BENG CHOON	
3	25 Mar 2019 15:48	Clim Submitted	5832.70.	[R] SHARON CHIONG BENG CHOON	
4	25 Mar 2019 16:05	Clim Registration Modified	Excess: -> 750.00.	[I] Crystabelle Tan	
5	25 Mar 2019 16:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj. : JP Knights Pte Ltd.	[I] Crystabelle Tan	
6	25 Mar 2019 16:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/03	[I] Crystabelle Tan	
7	25 Mar 2019 16:05	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Crystabelle Tan	
8	25 Mar 2019 17:07	Assignment 1st Accessed		[A] LEE SU THING	
9	26 Mar 2019 09:23	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] LEE SU THING	
10	27 Mar 2019 16:35	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG	
11	27 Mar 2019 16:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/03	[A] DENISE TAY KWEE CHENG	
12	27 Mar 2019 16:38	Adj Mandate Request	Cur.Req:5641.90:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG	
13	29 Mar 2019 11:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/03. Mandate Remarks: offer lump sum	[I] Crystabelle Tan	
14	29 Mar 2019 11:13	Adj Mandate Set	Approved:4500.00:offer lump sum	[I] Crystabelle Tan	

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2095212	25/03/2019 15:36	Motor	Cheng Hoe Motor Pte Ltd	Cheng Hoe Motor Pte Ltd (Yishun)	SGU4151C		xx.xx
2097986	27/03/2019 16:35	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGU4151C		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 27 Mar 2019

Preliminary Advice

Vehicle No	: SGU4151C	Accident Date	: 24/03/2019
Make	: KIA FORTE K3	Policy No.	: MPC18A00249601
Assignment Date	: 25/03/2019	Excess	: S\$750.00
Date of Inspection	: 26/03/2019	Est. Duration of Repair	: 6.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,832.70
Revised Amount	:S\$	4,967.60
Check Items (Estimated)	:S\$	674.30
Total	:S\$	5,641.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	37,505.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,495.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2240H

Vehicle Details

Vehicle No.: SGU4151C
Vehicle to be Exported: No
Intended Deregistration Date: 25 Mar 2019
Vehicle Make: KIA
Vehicle Model: FORTE K3 1.6A
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: G4FGGH657700
Chassis No.: KNAFZ411MH5664821
Maximum Power Output: 95.3 kW (127 bhp)
Open Market Value: \$16,971.00
Original Registration Date: 29 Sep 2016
First Registration Date: 29 Sep 2016
Transfer Count: 0
Actual ARF Paid: \$16,971.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Sep 2026
PARF Rebate Amount: \$12,728.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$33,000.00
COE Rebate Amount: \$24,777.00
Total Rebate Amount: \$37,505.00

The information contained herein is correct as at 25 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 10:21
Date Of Accident	24/03/2019 12:35
Exact Location Of Accident	YISHUN AVE 1 SLIP RD TWDS SELETAR NORTH LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU4151C
Insured/Policyholder	
Name Of Registered Owner	SHEN WEIGUO
NRIC No	S2752240H
Email Address	SHENXING1989@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81387717
Alternative Phone No	OTHERS-81612875

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3 1.6A
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00249601
Cover Note Number	29/09/18 - 28/09/19

Driver

Name of Driver	SHEN WEIGUO
NRIC No	S2752240H
Date Of Birth	17/11/1965
Occupation	INDOOR
Date Of Driving Pass	01/03/2011
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81387717
Fax Number	(LOCAL) +65-81612875
Contact Number	OTHERS-81612875
Email Address	SHENXING1989@GMAIL.COM

Address	BLK 123 YISHUN ST.11 #11-511
Postcode	760123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DAUGHTER-IN-LAW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Car B in front of me started to move on and I was moving slowly behind it when it made a sudden e-brake that caused me to hit onto its rear due to short notice. No one was injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY122S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SHE KIN SAN @SEH KIN SAN
NRIC/Passport Number	S1302053A
Contact Number	98187568
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

Selekar North Link
←

A: SGU 4151C
B: GY 122S
She Kin San @
Seh Kin San
S1302053A
98187568

Yishun Ave 1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car B in front of me started to move on and I was moving slowly behind it when it made a sudden e-brake that caused me to hit onto its rear due to short notice. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

25/3/19
Name: (YS)
NRIC/FIN No.:

SKETCH PLAN

VEHICLE NO.: SGU 4151C
INSURER : ECICS
DATE & TIME: 24/3/19 @ 12:35pm

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719


Email: chmotor@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MPC18A00249601	Date of Loss:	24/03/2019
Vehicle Reg. No.:	SGU4151C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHEN WEIGUO		
Driver:	SHEN WEIGUO		
Make/Model:	KIA FORTE K3, 1.6 (A)	Vehicle Reg. Date:	29/09/2016
Vehicle Colour:	GREY		
Engine No:	G4FGGH657700	Chassis No:	KNAFZ411MH5664821
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0 6 day,		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		


 Not authorized
 Putting B4 paint
 Ex 8 75d

COST OF CLAIMS	Amount
Parts	3,967.70
Miscellaneous Items	35.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,832.70
+ GST 7.00% (S\$)	408.29
Nett Amount (S\$)	6,240.99

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 25 Mar 2019)

Parts: 143

KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SGU 4151C

OD/ECICS

1/1 B & 480d vol

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	0.00	0.00	Bu *280.00 F ✓
2	1		*1 pc frt bumper sponge	0.00	0.00	CM *45.00 F ✓
3	1		*6 pcs frt bumper clips @2/pc	0.00	0.00	M *12.00 F ✓
4	1		*2 pcs headlamps @650/pc	0.00	0.00	ols m/c m n/c m *1,300.00 F ✓
5	1		*1 pc frt grille	0.00	0.00	n/c *160.00 F ✓
6	1		*1 pc frt grille logo	0.00	0.00	n/c *18.00 F ✓
7	1		*4 pcs frt grille clips @2/pc	0.00	0.00	M *8.00 F ✓
8	1		*1 pc frt grille top cover	0.00	0.00	Sn *28.00 F X
9	1		*1 pc bonnet	0.00	0.00	B *430.00 F ✓
10	1		*2 pcs bonnet hinges @20/pc	0.00	0.00	B *40.00 F ✓
11	1		*1 pc frt support panel	0.00	0.00	CM *280.00 F ✓
12	1		*1 pc air-con condenser	0.00	0.00	Pu *230.00 F ✓
13	1		*1 pc radiator	0.00	0.00	Pu *250.00 F ✓
14	1		*1 pc radiator fan assy	0.00	0.00	Sn *220.00 F X
15	1		*1 pc frt wiper garnish	0.00	0.00	CM *135.00 F ✓
16	1		*1 pc radiator top hose	0.00	0.00	Sn *18.00 F X
17	1		*1 pc air filter housing	0.00	0.00	Sn *70.00 F X
18	1		*1 pc air filter ducting	0.00	0.00	CM *55.00 F 7
19	1		*1 pc bonnet inner lock	0.00	0.00	B *28.00 F ✓

F=Franchise part.

Sub Total (\$\$) 3,607.00
+ Margin on L,N Items 10.00% (\$\$) 360.70
Total Parts (\$\$) 3,967.70

Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc frt number plate	B 35.00 ✓
Sub Total (\$\$)			35.00


Estimates on Labour

No	Particulars	Lab.Type	Amount
1	Remove & refix aircon,check,vacuum & refill gas	New	100.00 ✓
2	Panel beating	New	700 800.00
3	Putty & respray painting	New	800 850.00
4	To application for remove & refix frt opc number plate seal,send for inspection including coupon	New	80.00 80.00 Fo
Gross Labour Cost (\$\$)			1,830.00

Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

(SUPPLEMENTARY)INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MPC18A00249601	Date of Loss:	24/03/2019
Vehicle Reg. No.:	SGU4151C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHEN WEIGUO		
Driver:	SHEN WEIGUO		
Make/Model:	KIA FORTE K3, 1.6 (A)	Vehicle Reg. Date:	29/09/2016
Vehicle Colour:	GREY		
Engine No:	G4FGGH657700	Chassis No:	KNAFZ411MH5664821
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	44.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	44.00
+ GST 7.00% (S\$)	3.08
Nett Amount (S\$)	47.08
+ Previous Estimates (S\$)	6,240.99
Claim Total (S\$)	6,288.07

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Supp 1

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Apr 2019)**Parts:** 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SGU4151C/12/04/2019 16:40**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*2 pcs radiator side garnish	0.00	0.00	CM *28.00 F ✓
2	1		*1 pc air filter end duct	0.00	0.00	CM *12.00 F ✓
Sub Total (S\$)						40.00
+ Margin on L,N Items 10.00% (S\$)						4.00
Total Parts (S\$)						44.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SGU4151C/12/04/2019 16:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SGU4151C/12/04/2019 16:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Mar 2019)

Parts: 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	0.00	0.00	Bu *280.00 F ✓
2	1		*1 pc frt bumper sponge	0.00	0.00	cm *45.00 F ✓
3	1		*6 pcs frt bumper clips @2/pc	0.00	0.00	nc *12.00 F ✓
4	1		*2 pcs headlamps @650/pc	0.00	0.00	ols mjc m n/s cm *1,300.00 F ✓
5	1		*1 pc frt grille	0.00	0.00	my *160.00 F ✓
6	1		*1 pc frt grille logo	0.00	0.00	n/s *18.00 F ✓
7	1		*4 pcs frt grille clips @2/pc	0.00	0.00	nc *8.00 F ✓
8	1		*1 pc frt grille top cover	0.00	0.00	su *28.00 F X
9	1		*1 pc bonnet	0.00	0.00	Bt *430.00 F ✓
10	1		*2 pcs bonnet hinges @20/pc	0.00	0.00	Bt *40.00 F ✓
11	1		*1 pc frt support panel	0.00	0.00	cm *280.00 F ✓
12	1		*1 pc air-con condenser	0.00	0.00	Pr *230.00 F ✓
13	1		*1 pc radiator	0.00	0.00	*250.00 F ?
14	1		*1 pc radiator fan assy	0.00	0.00	*220.00 F ?
15	1		*1 pc frt wiper garnish	0.00	0.00	cm *135.00 F ✓
16	1		*1 pc radiator top hose	0.00	0.00	*18.00 F ?
17	1		*1 pc air filter housing	0.00	0.00	*70.00 F ?
18	1		*1 pc air filter ducting	0.00	0.00	*55.00 F ?
19	1		*1 pc bonnet inner lock	0.00	0.00	Bt *28.00 F ✓
Sub Total (\$\$)						3,607.00
+ Margin on L,N Items 10.00% (\$\$)						360.70
Total Parts (\$\$)						3,967.70

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc frt number plate	Bt 35.00 ✓
Sub Total (\$\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	Remove & refix aircon,check,vacuum & refill gas	New	100.00 ✓
2	Panel beating	New	700 800.00
3	Putty & respray painting	New	800 850.00
4	To application for remove & refix frt opc number plate seal,send for inspection including coupon	New	80.00 70
Gross Labour Cost (\$\$)			1,830.00

Cheng Hoe Motor Pte Ltd/SGU4151C/25/03/2019 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Mar 2019 15:38	25 Mar 2019 15:48	25 Mar 2019 16:05	S\$4,800.00	S\$4,800.00		Pending for Survey Report
	Sendback Est	S\$5,832.70	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	12 Apr 2019 16:38	12 Apr 2019 16:40	12 Apr 2019 16:40			(Combined)	Combined with Main
		S\$44.00					Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SHEN WEIGUO , ID: S2752240H, Email: shenxing1989@gmail.com									
Vehicle Reg. No.: SGU4151C		Date of Loss: 24/03/2019 12:00 - :59 [29 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DMPC1900083H/CT		Policy/Cover Note No.: MPC18A00249601 (Comprehensive)							
		Excess: S\$750.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/04/2019]									
Driver/Custodian: SHEN WEIGUO (), NRIC: S2752240H Email: shenxing1989@gmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> ECICS (29/03/2019): Alert - Adj Mandate Approved (S\$5000.00) - SGU4151C - Claim Handler: Crystabelle... ECICS (29/03/2019): Alert - Adj Mandate Approved (S\$4500.00) - SGU4151C - Claim Handler: Crystabelle... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





































SGU4151C (DMPC1900083H/CT)

OD

Mar 24 2019 12:00PM

[SHEN WEIGUO]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View In Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	25/03/19 15:48	Repairer Estimates		Load HTM	<input type="checkbox"/>
2	12/04/19 16:40	Repairer Estimates Suppl. #1		Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/03/19 16:37	Adjuster Immediate Advice		Load HTM	<input type="checkbox"/>
2	29/03/19 14:45	Adjuster Immediate Advice		Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
2	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
3	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
4	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
5	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
6	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
7	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
8	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
9	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
10	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
11	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
12	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
13	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
14	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
15	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
16	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
17	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
18	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
19	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
20	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
21	27/03/19 16:32	General View		Load JPG	<input checked="" type="checkbox"/>
22	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	26/08/19 10:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
33	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/08/19 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	25/03/19 15:47	GIA REPORT	 Load PDF	
2	25/03/19 15:47	IC & DL	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 10:56	ESTIMATE	 Load PDF	
2	06/09/19 12:22	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19005338/KTD3E2

Date: 09/09/2019

REFERENCE

Insured/Claimant: SHEN WEIGUO Policy No: MPC18A00249601
Date of Loss: 24/03/2019 Nature of Claim: OD Claim No: DMPC1900083H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU4151C**
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH657700
Reg. Date: 29/09/2016 (Man. Year: 2016) Chassis No: KNAFZ411MH5664821
Colour: Metallic Grey Odometer: 29719 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$47,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Nexen 3 mm Rear Left Side: Nexen 3 mm
Front Right Side: Nexen 3 mm Rear Right Side: Nexen 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,011.70	3,642.10	369.60	9.21
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,830.00	1,670.00	160.00	8.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,876.70	5,347.10	529.60	9.01
Approved Total (Overridden) (S\$)		4,800.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	5,876.70	4,050.00	1,826.70	31.08
+ GST 7.00/7.00% (S\$)	411.37	283.50	127.87	31.08
Nett Amount (S\$)	6,288.07	4,333.50	1,954.57	31.08

INSPECTION

Date of Assignment: 25/03/2019 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 26/03/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2019)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU4151C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc frt bumper (WCP)	Buckled	280.00 F	*280.00 F
2	1		*1 pc frt bumper sponge (WCP)	Cracked	45.00 F	*45.00 F
3	1		*6 pcs frt bumper clips @2/pc (WCP)	Necessary	12.00 F	*12.00 F
4	1		*2 pcs headlamps @650/pc (WCP)	O/S Mtg Cracked / N/S Cracked	1,300.00 F	*1,300.00 F
5	1		*1 pc frt grille (WCP)	Missing	160.00 F	*160.00 F
6	1		*1 pc frt grille logo (WCP)	Missing	18.00 F	*18.00 F
7	1		*4 pcs frt grille clips @2/pc (WCP)	Necessary	8.00 F	*8.00 F
8	1		*1 pc frt grille top cover (WCP)	Serviceable	28.00 F	*- F
9	1		*1 pc bonnet (WCP)	Bent	430.00 F	*430.00 F
10	1		*2 pcs bonnet hinges @20/pc (WCP)	Bent	40.00 F	*40.00 F
11	1		*1 pc frt support panel (WCP)	Cracked	280.00 F	*280.00 F
12	1		*1 pc air-con condenser (WCP)	Punctured	230.00 F	*230.00 F
13	1		*1 pc radiator (WCP)	Punctured	250.00 F	*250.00 F
14	1		*1 pc radiator fan assy (WCP)	Serviceable	220.00 F	*- F
15	1		*1 pc frt wiper garnish (WCP)	Cracked	135.00 F	*135.00 F
16	1		*1 pc radiator top hose (WCP)	Serviceable	18.00 F	*- F
17	1		*1 pc air filter housing (WCP)	Serviceable	70.00 F	*- F
18	1		*1 pc air filter ducting (WCP)	Cracked	55.00 F	*55.00 F
19	1		*1 pc bonnet inner lock (WCP)	Bent	28.00 F	*28.00 F
Supplementary #1						
20	1		*2 pcs radiator side garnish (WCP)	Cracked	28.00 F	*28.00 F
21	1		*1 pc air filter end duct (WCP)	Cracked	12.00 F	*12.00 F

F=Franchise part.

Sub Total (S\$)	3,647.00	3,311.00
+ Margin on L,N Items 10.00/10.00% (S\$)	364.70	331.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					4,011.70	3,642.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc frt number plate (BENT)	35.00	35.00
Sub Total (S\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & refix aircon,check,vacuum & refill gas	New	100.00	100.00
2	Panel beating	New	800.00	700.00
3	Putty & respray painting	New	850.00	800.00
4	To application for remove & refix frt opc number plate seal,send for inspection including coupon	New	80.00	70.00
Gross Labour Cost (S\$)			1,830.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >