

22/03/2019

ASS. REC. BY:

REF: (S/CT1/19005339/TI+ds)

Special Instruction:

Surveyor: TAUHID

mhm mhm

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping

of CT1

Date/Time: 25.3.2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 9BG 1330E

Insured: Ym 3877C

at Workshop m/s Sin shung Engineering

Tel: 68639595

of 3 Tech Park crescent, Tuen Tech Park

Policy No: DMCVSN 303863/8000

Claim No: SNM190201295C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 25.3.19 5.46 p.m

Person Contacted: Susan

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	9BG 1330E - NA/INC 19000645/24
	Ym 3877C - X

D.O.A. - 10/01/2019


Signature: *Tan Jiah*

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT
Susan

Veh No: *6BG1330E* Yr Reg: *2017, June*
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Toyota Dyna* C.C. *2982*
 Colour: *White* A/C: Insured / Std / NI / NA
 Sp. Reading: *43023* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *K032318027875*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *195/R15*
 R: *185/R13(D)*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: *Hubb* Rear: *BS*
 R/Bal: *6* mm R/Bal: *6/6* mm
 L/Bal: *6* mm L/Bal: *6/6* mm
 D.O.A. _____ D.O.I. *18/4/19*
 Survey held at: *Sin Sheng*
 Des. of Damages: Frt / Rear / O/S / N/S / D/C / Rooftop or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

22/4 3.25pm - No photos upload.

21/5 458 4850, 4 days email to Susan confirm (Red: 2167 03, 30%)

RECEIVED 28 JUN 2019

Date/Time, File Pass to?

11/28/16 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.J. (\$) *4850/-*



Preli. Report



Final Report

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S / R / S / S

☐ Photos

☐ Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Mar 2019		25 Mar 2019 17:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOK KEONG LANDSCAPE PTE LTD , Co. Reg. No.: 200512433R								
Main Claimant:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBG1330E	Date of Loss:	21/03/2019 19:00 - :59 [21 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201295C02	Policy/Cover Note No.:	DMCVSN30386318000 (Comprehensive) Coverage: 15/06/2018 - 14/06/2019						
Vehicle Reg. No. (Insured):	YM3877C	Policy No. (Claimant):	29090793						
		Excess:	S\$0.00						
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2019]								
Driver/Custodian (Insured):	KARUPPIAH THIRUNAVUKKARASU (33 / Male), NRIC: G8078999N Email:								
Adj Asg. Remarks:	please assign for Mr Chua Wei Jie to conduct TP survey for SJE. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

P. Susan

V out

E V

T: 5:42 PM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/03/2019 22:27
Date Of Accident	21/03/2019 19:10
Exact Location Of Accident	ALONG PORTSDOWN FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG1330E
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29090793
Cover Note Number	

Driver

Name of Driver	CHOO LIANG TECK
NRIC No	S1298628I
Date Of Birth	29/04/1958
Occupation	OUTDOOR
Date Of Driving Pass	10/04/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96360992
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002822

Date : 18/04/2019

Vehicle Num. : GBG1330E

Make/Model : TOYOTA KODY 231-2016

Chassis/Eng# : KODY2318027875/1KD2677824

Accident Date : 21/03/2019

Claim No. :

Reference : YM3877C

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE	bt ✓	2,345.60
2.	1	SIDE GATE, LHS	bt ✓	2,745.50
3.	1	'L' LOCK	bt ✓	195.20
4.	1	REAR LAMP	ent ✓	265.58
5.	1	REFLECTOR	ny x	69.50
6.	1	REAR LAMP BRACKET	bt ✓	172.20
7.	1	REAR END PANEL	Rx	458.20
8.	1	RUBBER STOPPER	wt ✓	75.20
9.	1	RUBBER STOPPER BRACKET	bt ✓	169.20
10.	1	DYNA MARK	nt ✓	45.20
List TotalS\$:			6013.68	6,541.38
25.00% Discount S\$:				1,635.35
			4510.26	4,906.03
NETT ITEMS :				
1.	1	70km/h Sticker	nt ✓	20.00
2.	1	13 PAX STICKER	nt ✓	20.00
3.	1	ALUMINIUM CHEQUERED PLATE	bt ✓	750.00 400
Nett Total S\$:				790.00
10.00% Discount S\$:				79.00 440
				711.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002822

Date : 18/04/2019

Vehicle Num. : GBG1330E

Make/Model : TOYOTA KDY 231-2016

Chassis/Eng# : KDY2318027875/1KD2677824

Accident Date : 21/03/2019

Claim No. :

Reference : YM3877C

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

750.00 600

SPRAY PAINTING

650.00 550

LOSS OF USE : 6 DAYS @ \$ 120/DAY

Labour Total S\$:

1,400.00 1150.

4510.26.

440

1150

6160.26.

4/584 850 * 4 days.

Total S\$: 7,017.03

1096.03.

Susan

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

wp

18/4/19. @ 345pm

lump sum

Resurvey after repair

4 days.

sure lkk auto. com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2019		25 Mar 2019 17:06 Edit Adj Rpt	S\$4,850.00 Edit Estimates	S\$4,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOK KEONG LANDSCAPE PTE LTD , Co. Reg. No.: 200512433R		
Main Claimant:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBG1330E	Date of Loss:	21/03/2019 19:00 - :59 [21 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201295C02	Policy/Cover Note No.:	DMCVSN30386318000 (Comprehensive) Coverage: 15/06/2018 - 14/06/2019
Vehicle Reg. No. (Insured):	YM3877C	Policy No. (Claimant):	29090793
		Excess:	S\$0.00
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/04/2019]		
Driver/Custodian (Insured):	KARUPPIAH THIRUNAVUKKARASU (33 / Male) , NRIC: G8078999N Email:		
Adj Asg. Remarks:	please assign for Mr Chua Wei Jie to conduct TP survey for SJE. thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG1330E (SNM19D201295C02)
[YM3877C]

TP

GOLDBELL LEASING PTE LTD
Mar 21 2019 7:00PM
[KOK KEONG LANDSCAPE PTE LTD]
Sin Sheng Engineering Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Sin Sheng Engineering Services (HQ)		Thumbnail	Print
1	22/03/19 16:54	Accident Statement	1	Load HTM	
2	22/03/19 23:05	Addendum Sheet	1	Load JPG	<input checked="" type="checkbox"/>
3	22/03/19 23:09	Accident Statement Addm. #1	1	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	28/06/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Sheng Engineering Services (HQ)	Thumbnail	Print
31	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
32	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
33	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
34	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
35	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
36	28/06/19 11:06	General View	Load JPG	<input checked="" type="checkbox"/>
37	28/06/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	28/06/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	28/06/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/03/19 17:01	PRI	Load PDF	
2	25/03/19 17:01	INSND YM3877C GIA REPORT	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Sin Sheng Engineering Services (HQ)	Thumbnail	Print	
1	22/03/19 16:54	Accident Statement	Load HTM		
2	22/03/19 23:05	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>	
3	22/03/19 23:09	Accident Statement Addm. #1	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sin Sheng Engineering Services (HQ)	Thumbnail	Print	
1	22/03/19 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
2	22/03/19 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
3	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
4	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
5	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
6	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
7	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
8	22/03/19 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
9	22/03/19 16:53	Driving License	Load JPG	<input checked="" type="checkbox"/>	
10	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
11	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
12	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
13	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
14	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
15	22/03/19 23:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sin Sheng Engineering Services (HQ)	Thumbnail	Print	
1	22/03/19 11:29	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>	
2	22/03/19 11:29	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT19005339/TITD3S2
Date: 02/07/2019REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30386318000
Claimant Vehicle No :	GBG1330E	Insured Vehicle No :	YM3877C
Date of Loss:	21/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201295C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG1330E	Engine No:	1KD2677824
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318027875
Reg. Date:	06/06/2017 (Man. Year: 2016)	Odometer:	43023 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/R15	Rear Tyre Size:	185/R13(D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,696.03	4,950.26	745.77	13.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,150.00	250.00	17.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,096.03	6,100.26	995.77	14.03
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	7,096.03	4,850.00	2,246.03	31.65
+ GST 7.00/7.00% (S\$)	496.72	339.50	157.22	31.65
Nett Amount (S\$)	7,592.75	5,189.50	2,403.25	31.65

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	18/04/2019	Inspected At: Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jul 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1330E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,345.60 FL	*2,345.60 FL
2	1		*SIDE GATE,LHS	Bent	2,745.50 FL	*2,745.50 FL
3	1		*L LOCK	Bent	195.20 FL	*195.20 FL
4	1		*REAR LAMP	Cut	265.58 FL	*265.58 FL
5	1		*REFLECTOR	Not Necessary	69.50 FL	*- FL
6	1		*REAR LAMP BRACKET	Bent	172.20 FL	*172.20 FL
7	1		*REAR END PANEL	Repair	458.20 FL	*- FL
8	1		*RUBBER STOPPER	Cut	75.20 FL	*75.20 FL
9	1		*RUBBER STOPPER BRACKET	Bent	169.20 FL	*169.20 FL
10	1		*DYNA MARK	Necessary	45.20 FL	*45.20 FL
11	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
12	1		*13 PAX STICKER	Necessary	20.00 FS	*20.00 FS
13	1		*ALUMINIUM CHEQUERED PLATE	Bent	750.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,331.38	6,453.68
- List Item Discount on L Items 25.00/25.00% (S\$)	1,635.35	1,503.42
Total Parts (S\$)	5,696.03	4,950.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT/REPAIR REAR BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS	New	750.00	600.00
2	SPRAY PAINTING	New	650.00	550.00
Gross Labour Cost (S\$)			1,400.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >