

ASS. REC. BY

REF CS3/AIG18022127/GSD3

per of instructions

Surveyor
Merrin

Guo Qiang

ASSIGNMENT (Office)

Lee Ming yao

AIG

Date/Time: 26/3/2019

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 6954C

Insured:

SKR 4596X

at Workshop no/

Autonwerke Automotive

Tel:

94743434

of

8 koki Bkt Ave 4 # 05-01/02

Policy no:

2100402541

Claim No:

0944026289SG

Sum Insured:

Excess:

Make of Veh
(Client's Record)

D.O.A

30/11/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10.56am @ 10/12/18

Person Contacted:

Merrin

Vehicle:

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLL 6954C - X
	SKR 4596X - X
	Dismantle: 13/12/2018
	\$12600 . 8 Days.
	(87.700/- red - 38%)

16/4/2019

PRS
Xcel

REF AIG

C4107W

ASSIGNMENT

(-2028)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / CD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at Workshop with: **Auto werke Auto**
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: **\$82k**
 IDAC Accident Report, Consistent? : Yes or No
 GIA / PR Seen, Consistent? : Yes or No
 Est. Repairs: **10** days Res: Yes or No
 Lump Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: **SLL6954C** Reg: **22 Jan 200**
 Type: Motor / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Velfire cc 3456**
 Colour: **white** A/C: Insured / Std / NI / NA
 Sp. Reading: **255653** T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: **67H 2080 15900**
 Gen. Cont: **Good** / Fair / Poor / Burrit
 Steering: **In** / Jammed / Leaked / Burnt or
 Brake: **In** / Jammed / Leaked / Burnt or
 Mod: Nil / 5/Rim / STD / Rim or
 Tyre Size F: **235/50 R18**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FALKEN**
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: _____ D.O.I: **10-12-18**
 Survey held at: **W/S** **12:45pm**
 Des. of Damages: **Fr** / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
\$10k - \$12k

Consent: File Pass to / : Prol. Report
 : Final Report

Days Of Repair: **8**
 Resurvey No. of Trip: **1**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Title (\$)
 Workshop (\$)

Survey Fee
 Transportation

Report Format: **DAR**
 Lump Sum / LB.I. (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 4107W

Vehicle Details

Vehicle No.: SL14934C
Vehicle to be Exported: No
Intended Deregistration Date: 19 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: VELLFIRE 3.5Z G-EDITION A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 2GR0607763
Chassis No.: GGH208015900
Maximum Power Output: 206.0 kW (276 bhp)
Open Market Value: \$53,614.00
Original Registration Date: 22 Jan 2009
First Registration Date: 22 Jan 2009
Transfer Count: 2
Actual ARF Paid: \$53,614.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2028
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$31,553.00
COE Rebate Amount: \$30,603.00
Total Rebate Amount: \$30,603.00

The information contained herein is correct as at 16 Apr 2019

OK

▶ Vellfire Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Toyota Vellfire 3.5A Z (COE till 09/2028)	\$89,800	\$9,490 /yr	05-Jan-2009	3,456 cc	-	Car Search	Availal

Consignment Unit, Call Us Now To Arrange Viewing.

Office No. - 62620728

Ken - 93388994 | Rachel - 91126538 | Justin - 91827511 | Athrun Lee - 87425361

Toyota Vellfire 3.5A Z G-Edition (COE till 01/2029)	\$82,888	\$8,510 /yr	08-Jan-2009	3,456 cc	-	Ethicarz Pte Ltd	Availal
--	-----------------	--------------------	-------------	----------	---	------------------	---------

Very Well Maintained, Very Clean & New! Spacious MPV, 18" New Sports Rims, Pioneer Audio Set, Dual Power Sliding Doors, Middle Row Elec Seats, Dual Sunroof, Keyless Access And Engine Starting Cruise...

Office No. - 82282044 / 63844404

Sk Ng - 97563519

Toyota Vellfire 3.5A Z (New 10-yr COE)	\$75,800	\$7,570 /yr	06-Apr-2009	3,456 cc	86,000 km	Straits Euro Motors Pte Ltd	Availal
---	-----------------	--------------------	-------------	----------	-----------	-----------------------------	---------

100% Loan, Immediate Approval! 1 Owner Unit With Low Mileage! Beautifully Maintained By Previous Owner. High Demanding Unit Spacious Yet Comfortable Suits Big Families. Accident Free. STA/VICOM Inspec...

Office No. - 64562277 / 64592277

Candy - 90101312 | Alan Tan - 97541899 | Ms Wingz - 86166068 | Jordan Yep - 81936407

Toyota Vellfire 3.5A X (New 10-yr COE)	\$89,800	\$8,970 /yr	09-Sep-2009	3,456 cc	108,000 km	SG Car Choice Pte Ltd	Availal
---	-----------------	--------------------	-------------	----------	------------	-----------------------	---------

Ideal For Short Term Drive/ Renewal COE 5/10 Year! Low Depreciation! High Loan Are Available At Low Interest Rate! Warranty & Servicing Can Be Arranged For An Added Peace Of Mind! High Trade-In Are We...

Office No. - 63974080

Robin - 98181222 | Tommy - 81252285 | Trev - 92727377

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Nivitha (LKK Auto)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Tuesday, 26 March 2019 10:54 AM
To: Jerdine
Cc: 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM; jiamin.mak@alt.sg; vincent@alt.sg; 'Allister Lim'
Subject: RE: [URGENT] RE: Our ref: 09440262895G-003; Your ref: ALINS.2018.12901(PD).jw

Without Prejudice

Hi Jerdine,

We will appoint LKK to conduct a paper survey.

Will revert after.

By copy to LKK Team,

Kindly assist to conduct paper survey. Supporting documents will be sent in follow up email.

Thank You.

Regards,
Lee Ming Yao
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1769
MingYao.Lee@AIG.com | www.aig.sg



Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jerdine [mailto:jerline.wang@alt.sg]
Sent: 25 March 2019 15:40
To: Kesaval, Jaclyn-M <Jaclyn-M.Kesaval@aig.com>
Cc: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM; jiamin.mak@alt.sg; vincent@alt.sg; 'Allister Lim' <allister@alt.sg>

Subject: [URGENT] RE: Our ref: 0944026289SG-003; Your ref: AL.INS.2018.12901(PD).jw
Importance: High

URGENT REMINDER

Dear Jaclyn,

May we hear from you urgently pls?

Best Regards,

Jerdine

For and on behalf of
Allister Lim

ALLISTER LIM & THRUMURGAN ADVOCATES & SOLICITORS

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6438 3303
DID: 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Jerdine <jerdine.wang@alt.sg>
Sent: Friday, 15 March 2019 12:35 PM
To: 'Kesaval, Jaclyn-M' <Jaclyn-M.Kesaval@aig.com>
Cc: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>; 'jiamin.mak@alt.sg' <jiamin.mak@alt.sg>; 'vincent@alt.sg' <vincent@alt.sg>; 'Allister Lim' <allister@alt.sg>
Subject: RE: Our ref: 0944026289SG-003; Your ref: AL.INS.2018.12901(PD).jw
Importance: High

WITHOUT PREJUDICE

Dear Jaclyn,

We refer to your earlier of 9 Jan 2019.

We have tried numerous attempts to arrange for a RI with our client but he is always unavailable.

Accordingly, we understand that a post-repair was conducted on 21 Dec 2018 by LKK.

To move things forward, we suggest a paper resurvey.

Kindly let us hear from you soonest.

Thank you.

Best Regards,

Jerdine

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6438 3303
DID: 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Kesaval, Jaclyn-M <Jaclyn-M.Kesaval@aig.com>
Sent: Wednesday, 9 January 2019 12:04 PM
To: mail@alt.sg; jerdine.wang@alt.sg
Cc: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM
Subject: Our ref: 0944026289SG-003; Your ref: AL.INS.2018.12901(PD).jw

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Jerdine,

We refer to your letter of demand dated 3 Jan 2019.

We would like to call for a physical re-inspection of your client's vehicle.

Kindly let us have a date **1 week** in advance.

Thank you.

Kind regards,
Jaclyn

Jaclyn M K
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1953

Jaclyn-M.Kesaval@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



24 HRS HOTLINE: 8455 5669

PHOTOCOPY No. 13193



Date : 30/11/18

Autowork Automotive

RECEIVED

Vehicle No : SLL 6954C Model : Vellfire 03 DEC 2018

Address : Bayfront ave n/red Time Start : 1530

Remarks : DS-01 Premier K.B Time End : 1550 BY: (A)

Phone No : 96911133

Change Tyres / Jump Start Accident Use Car Carrier Lock

Basement / Multi Carpark Low Body Kit / Low Spoiler Open Door

Using King Dolly Dismantle Brake / Shaft Crane Up / Winch Out

AMOUNT \$ 602

Received By: [Signature] for 24 hour Recovery Serv

PHOTOCOPY No. 13193

V.Z AUTOMOTIVE PTE LTD

PHOTOCOPY

8 Kaki Bukit Avenue 4 Premier @ Kaki Bukit #05-01/02 Singapore 415875
Tel: +65 6282 4292 / +65 8558 0000

REPAIR INVOICE

Repair Invoice Details

Repair Invoice No: VZ2019-0101

Date: 2 JAN 2019

Customer Details

SLL6954C KINGEVER PTE LTD

S.No	Item	Description	Accident Date	Qty	Rate (SGD)	Amount (SGD)
1.	LUMP SUM REPAIR BASIS AS RECOMMENDED & AGREED WITH SURVEYOR		30/11/2018	1	\$20,300.00	\$20,300.00

Sub Total (SGD) \$20,300.00

Total (SGD) \$20,300.00

Amount in words:

Twenty Thousand Three Hundred Singapore Dollar (SGD) Only

For V.Z AUTOMOTIVE PTE LTD



Authorized Signatory
Billed by: Anna
(vzauto@iova.com.sg)

PHOTOCOPY

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: Winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

Our Ref: WG/TP/2018-449
Invoice No: TPNZ/2018-449
Vehicle No: SLL6954C
Attn: KINGEVER PTE LTD
Company: V.Z AUTOMOTIVE PTE LTD
Address: Blk 1, Kaki Bukit 6, #02-02 . SINGAPORE 417883

Date 30 December 2018

Invoice

Surveyor Fee:	S\$630
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$121/- (@ \$1 per photo, total 121 photos)
Total:	S\$851

Surveyor:
Signature:
Date:

Winsongkk
30 December 2018



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 8063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S. KINGEVER PTE LTD
C/O V.Z. AUTOMOTIVE PTE LTD
Blk 1, Kaki Bukit 6, #02-02
SINGAPORE 417883

Date : 30 December 2018
Our Ref : WG/TP/2018-449

REFERENCE PARTICULARS

Date of Accident : 30 November 2018
Date of Inspection : 03 December 2018

Type of Inspection : Third Party Claim
Date of Re-Insps : 13 December 2018

VEHICLE PARTICULARS

Registration No : SLL1994C
Make : TOYOTA
Model : VELLFIRE 3.5Z G-ELETRON A
Year : 2008

Engine No : 2GR0607763
Chassis No : GGJH208015900
Odometer : 255653km
Colour : White

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Servicable
Hand Brake : Servicable

General Body Work : Good
Steering : Servicable
Lightings : Servicable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near Side	Falken	205-50R18	5mm
Front Off side	Falken	205-50R18	5mm
Rear Near side	Falken	205-50R18	5mm
Rear Off side	Falken	205-50R18	5mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$20,300.00** nett at lump sum basis (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Twenty-five (25) working days.

Enclosed One hundred and twenty-one (121) photographs depicting damage to the vehicle.

Inspection conducted at : V.Z. AUTOMOTIVE PTE LTD
Blk 1, Kaki Bukit 6, #02-02, SINGAPORE 417883

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO: SLL6954C
 MODEL: VELLFIRE 3.5Z G-EDITION A

Our Ref: WG/TP/2018-448

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED
	PC/SET	CONDITION	QUOTATION	QUOTATION
1 FRONT BONNET	1	DENTED	\$ 935.00	\$ 935.00
2 FRONT BONNET HINGE	2	BENT	\$ 156.00	\$ 156.00
3 FRONT BONNET DAMPER	2	JAMMED	\$ 143.00	\$ 143.00
4 FRONT GRILLE ASSY	1	CRACKED	\$ 755.00	\$ 755.00
5 FRONT GRILLE EMBLEM	1	NECESSARY	\$ 80.00	\$ 80.00
6 FRONT HEADLAMP	2	CRACKED	\$ 4,678.00	\$ 4,678.00
7 FRONT HEADLAMP CENTRE GRILLE LH	1	CRACKED	\$ 267.00	\$ 267.00
8 FRONT HEADLAMP CENTRE GRILLE RH	1	CRACKED	\$ 267.00	\$ 267.00
9 FRONT BUMPER	1	CRACKED	\$ 785.00	\$ 785.00
10 FRONT BUMPER RETAINER	2	NECESSARY	\$ 115.00	\$ 115.00
11 FRONT FOG LAMP	2	CRACKED	\$ 690.00	\$ 690.00
12 FRONT FOG LAMP COVER	2	CRACKED	\$ 354.00	\$ 354.00
13 TOW COVER	1	MISSING	\$ 35.00	\$ 35.00
14 FRONT LOWER GRILLE	1	CRACKED	\$ 309.00	\$ 309.00
15 SUPPORT PANEL	1	DENTED	\$ 1,417.00	\$ 1,417.00
16 FRONT LH CHASSIS	1	DENTED	\$ 2,690.00	\$ 2,690.00
17 FRONT LH CHASSIS BRACKET	1	DEBTD	\$ 225.00	\$ 225.00
18 FRONT LH WHEEL HOUSE	1	DENTED	\$ 900.00	\$ 900.00
19 FRONT LH FENDER	1	DENTED	\$ 1,050.00	\$ 1,050.00
20 FRONT RH FENDER	1	REPAIR	\$ 1,050.00	\$ 1,050.00
21 FRONT LH FENDER INNER SHIELD	1	DEFORMED	\$ 180.00	\$ 180.00
22 ADRCON CONDENSER	1	BENT	\$ 1,600.00	\$ 1,600.00
23 CONDENSER COWLING	1	CRACKED	\$ 395.00	\$ 395.00
24 CONDENSER MOTOR	1	MALFUNCTION	\$ 640.00	\$ 640.00
25 RADIATOR	1	PUNCTURED	\$ 2,065.00	\$ 2,065.00
26 RADIATOR COWLING	1	CRACKED	\$ 395.00	\$ 395.00
27 RADIATOR MOTOR	1	MALFUNCTION	\$ 540.00	\$ 540.00
28 ADRCON PIPE	1	BENT	\$ 874.00	\$ 874.00
29 DISCHARGE PIPE	1	BENT	\$ 417.00	\$ 417.00
30 ENGINE MOUNTING	1	CRACKED	\$ 355.00	\$ 355.00
31 FRONT BUMPER UNDERCOVER	1	CRACKED	\$ 320.00	\$ 320.00
32 FRONT SUPPORT PANEL TOP GARNISH	1	DEFORMED	\$ 149.00	\$ 149.00
33 FRONT CROSS MEMBER	1	BENT	\$ 1,904.00	\$ 1,904.00
34 AIR DUCT	1	CRACKED	\$ 190.00	\$ 190.00
35 SPARE TANK	1	DEFORMED	\$ 435.00	\$ 435.00
36 WASHER TANK	1	DEFORMED	\$ 220.00	\$ 220.00
			\$ 27,560.00	\$ 26,510.00
			Less 25%	\$ 6,890.00
				\$ 20,620.00
				\$ 19,892.50
				\$ 17,242.12
				\$ 12,971.65
B) SNETT ITEM				
37 FRONT NUMBER PLATE	1	BENT	\$ 80.00	\$ 70.00
38 FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00
39 FRONT FENDER INNER SHIELD CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
40 COOLANT	1 BOT	NECESSARY	\$ 60.00	\$ 50.00
41 FRONT SENSOR	1 SET	MALFUNCTION	\$ 400.00	\$ 300.00
			\$ 630.00	\$ 490.00
Parts Total:			\$ 21,300.00	\$ 20,372.50
C) LABOUR CHARGES & MISC				
42 CHECK FRONT WIRING AND LIGHTING SYSTEM			\$ 70.00	\$ 60.00
43 REMOVE, RENEW CONDENSER AND TOP UP GAS			\$ 150.00	\$ 130.00
44 REMOVE, RENEW RADIATOR AND TOP UP COOLANT			\$ 150.00	\$ 130.00
45 REMOVE AND REFIT FRONT DASHBOARD			\$ 700.00	\$ 600.00
46 CHECK FRONT WHEEL ALIGNMENT			\$ 150.00	\$ 130.00
47 MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT			\$ 600.00	\$ 500.00
48 PANEL BEATING ON AFFECTED AREAS			\$ 2,400.00	\$ 1,800.00
49 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,600.00	\$ 1,500.00
50 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00
			\$ 5,970.00	\$ 4,980.00
Labour Total:			\$ 5,970.00	\$ 4,980.00
Total Parts and Labour:			\$ 27,270.00	\$ 25,352.50
FINAL LUMP SUM ADJUSTMENT				\$ 20,300.00

15741.65
 20% = 12600

POINT OF IMPACT

The impact was confined to the front portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$20,300.00 net** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,
WG APPRAISAL SERVICES

Winston Goh
Automotive Appraiser



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 13:29
Date Of Accident	30/11/2018 14:40
Exact Location Of Accident	BAYFRONT AVE X CENTRAL BLVD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6954C
Insured/Policyholder	
Name Of Registered Owner	KINGEVER PTE. LTD.
Co Reg No	201504107W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88091708

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092168347-01
Cover Note Number	

Driver

Name of Driver	CHEN YICHAO
Passport No/FIN	G1211729P
Date Of Birth	04/03/1991
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2018
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98698777
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 668B JURONG WEST ST 64 #04-110
 Postcode 642668
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR4596X
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to void/late policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


[Handwritten Signature]
Driver's Signature
(Driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BAYFRONT AVE & CENTRAL BLVD JUNCTION
 VEH A: SLL 6954C
 VEH B: SKR 4596X

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE & TIME, I VEH A (SLL 6954C) WAS WAITING AT THE JUNCTION OF BAYFRONT AVE & CENTRAL BLVD FOR THE TRAFFIC LIGHT TO TURN GREEN & MOVE TOWARD MBS. AS THE TRAFFIC LIGHT TURN GREEN I MOVE OFF, JUST WHEN I MOVE OFF AT A VERY SLOW SPEED, AS I JUST PICK UP, VEH B (SKR 4596X) DID A RIGHT TURN ON THE OFF LANE INTO CENTRAL BLVD, AS VEH B DIDNT TURN ON GREEN ARROW, VEH B HIT ONTO MY FRONT & DAMAGE MY VEH WHOLE FRONT PORTION MAKING MY VEH UNABLE TO START PICS BADLY DAMAGE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 16:57
Date Of Accident	30/11/2018 14:30
Exact Location Of Accident	BAYFRONT AVE TO CENTRAL BLVD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR4596X
Insured/Policyholder	
Name Of Registered Owner	WONG YONG MEI
NRIC No	S7517439Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93659425
Alternative Phone No	OTHERS-93659425

Vehicle Particulars

Manufacturer	VOLVO
Model	S60-1.6 D2 (A)

Exact Purpose for which vehicle was being used at time of accident	SOCIAL
--	--------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100402541-03
Cover Note Number	

Driver

Name of Driver	TAN KHAI YANG
NRIC No	S7822766D
Date Of Birth	15/08/1978
Occupation	INDOOR
Date Of Driving Pass	21/09/1998
Driving Experience	20 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93659425
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	80 MOUNT SINAI DRIVE #02-02
Postcode	277125
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6954C
Vehicle Make/Model/Colour	TOYOTA VELLFIRE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN YI CHAO
NRIC/Passport Number	
Contact Number	98698777
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre Personnel & Time



Describe Circumstance of the Accident

Around 2:30pm, I was driving along Rayfront Ave turning ~~to~~ right onto Central Boulevard.

I slowed down at the cross junction as the light was red.

Upon green light, I checked that there was no vehicle coming straight and took a right turn.

While I was turning right, a white vehicle hit my vehicle on the left side spinning my car to face the other direction against traffic.

No one was injured and no government property was damaged.

IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Handwritten Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Corps Personnel



CERTIFICATE OF INSURANCE

WEARNES AUTO PROTECTOR (VOLVO) PRIVATE VEHICLE

Name of Policyholder	: WONG YONG MEI (HUANG RONGMEI)	Vehicle No.	: SKR4596X
Period of Insurance	: 10 Feb 2018 To 09 Feb 2019	Policy No.	: 2100402541-03
Engine No.	: D4162T3J40661	Endorsement No.	:
Chassis No.	: YV1FS84ABF2356140	Issued Date	: 10 Jan 2018

ABOUT THE COVER

Make/Model	: VOLVO S60 D2	Sum Insured	: Market Value	First Year of Registration	: 2015
Engine Capacity/Tonnage	: 1,580.00 CC	Off Peak Car	: No	Insuring with COE/PARF	: Yes
Driver Restriction	: NA				

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's behalf or with their permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDE") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use

Use only for social, domestic, and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, auto-racing, reliability trial or speed testing, the carriage of goods other than samples, connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188) and Section 35 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WONG YONG MEI (HUANG RONGMEI) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Western Automotive Pte Ltd, Add: 245 Alorazha Road Singapore 130535 6404600 62780550

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503485718

WEARNES AUTOMOTIVE - RL (V)
 45 LENG KEE ROAD
 SINGAPORE 169103

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

00964.0

Accident Sketch Plan

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7517439Z



Name
WONG YONG MEI
(HUANG RONGMEI)
黄荣美
Race
CHINESE
Date of birth
13-08-1979
Sex
F
Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7822766D





Name
TAN KHAI YANG
(CHEN KAIYANG)
陈凯扬
Race
CHINESE
Date of birth
15-08-1978
Sex
M
Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S7822766D
Name
TAN KHAI YANG
(CHEN KAIYANG)
Date of Birth: 15 Aug 1978
Issue Date: 05 Nov 2008



NRIC No. S7517439Z
Date of issue
08-08-2008

80 MOUNT SINAI DRIVE #02-02
SINGAPORE 277125
NRIC No. S7517439Z Date: 30/10/2011 No. 8843302



80 MOUNT SINAI DRIVE #02-02
SINGAPORE 277125
NRIC No. S7822766D Date: 30/10/2011 No. 8843302
SINGAPORE 257710

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms

ISSUE DATE

21 Sep 1991



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorized Reporting Centre ("ARC") after filling.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorized Driver.
4. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT


Date and Time of Accident	Date: 30/11/2018 Time: 1430hrs.
Exact Location of Accident	Beiyang Rd to Central Blvd.
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	CKR 4596X
INSURED / POLICYHOLDER (OWN VEHICLE)	
Name of Registered Owner (See Insurance Cert.)	Wong Yong Mei
Personal Identification - NRIC (Singaporean/PR)	8751 F 4392
- FIN/Passport Number	
- Not Applicable	
VEHICLE PARTICULARS (OWN VEHICLE)	
Vehicle Make / Model	Manufacturer <u>Volvo</u> Model <u>S60</u>
Type of Vehicle*	<input checked="" type="checkbox"/> Saloon <input type="checkbox"/> MPV <input type="checkbox"/> CRV <input type="checkbox"/> Van <input type="checkbox"/> Lorry <input type="checkbox"/> Bus <input type="checkbox"/> Micycle <input type="checkbox"/> Others
Exact Purpose for which vehicle was being used at time of accident	<u>Social</u>
Are you claiming under your own insurance policy for repair to your vehicle?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No (If No, Pls select <input type="checkbox"/> Third Party <input type="checkbox"/> Reporting)
Vehicle Category*	<input checked="" type="checkbox"/> Private <input type="checkbox"/> Commercial <input type="checkbox"/> Motorcycle
INSURANCE COMPANY (OWN VEHICLE)	
Name of Insurance Company*	<u>Aty</u>
Type of Policy	<input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire & Theft <input type="checkbox"/> TP Only
Fleet Policy	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Policy Number	2100 402541-03
Motor CI	
DRIVER	<input type="checkbox"/> Same as Insured above
Name of Driver	<u>Tan Khai Yang</u>
Personal Identification - NRIC (Singaporean/PR)	<u>S7822766D</u>
- FIN/Passport Number	
Date of Birth	<u>15</u> day <u>03</u> month <u>1978</u> year
Driving Date Pass	<u>31</u> day <u>09</u> month <u>1996</u> year
Year of Driving Experience	Year(s) _____ Month(s) <u>12</u>
Occupation	<input checked="" type="checkbox"/> Indoor <input type="checkbox"/> Outdoor
Gender	<input checked="" type="checkbox"/> Male <input type="checkbox"/> Female
Contact Number / Mobile Phone / Fax No.	<u>9365 9425</u>

Page 1

Accident Sketch Plan

Address of Driver	80 Mount Sinai Drive #02-02	Postcode (277125)
Email Address	wette_new@yahoo.com.sg	
Was driver an employee of the Insured's Company?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
If No, Relationship of the Driver with the Insured	Spouse	
Vehicle Registration Number of Driver's Own	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		
Insurance Company of Driver's Own Vehicle (if applicable)		
GENERAL INFORMATION OF THE ACCIDENT		
Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	Junction (Front to Side)	
Weather Conditions	<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others	
Road Surface	<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others	
OTHER INFORMATION		
Was any foreign vehicle involved in this accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any body injured in the accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any other vehicle or property damaged?	<input checked="" type="radio"/> Yes <input type="radio"/> No	
Was there any video captured by Car Camera?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Number of Passengers (Including Driver)	01	
DETAILS OF POLICE ACTION		
Was the Accident reported to the Police?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, please state which Police Station.)	
Police Station Name		
Police Station Address		
Police Station Contact	Tel No.	Fax No.
Was notice of intended Prosecution given?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, against whom?)	
DETAILS OF OTHER VEHICLE / PROPERTY 1		
Vehicle Registration Number	SLL6957C	
Vehicle Maker/ Model/ Colour	Toyota Vellfire	
Details of Properties		
Name of Driver	Chen Chen Yi Chao	
Personal Identification - NRIC (Singaporean/PR) - FIN/Passport Number		
Contact Number	9869 8937	
Address		
Name of Insurance Company		
Nature of Damage		
No. of Passenger (Including Driver)		

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MWPA18156392 Vehicle Registration No: SKR 4516X
Name (as shown in NRIC) : Wong Yung Mei NRIC/FIN/Passport No : 87517439Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 30th Nov 2018 Time of Accident : 1430hrs
Place of Accident : Bayfront Ave to Central Blvd
Insurance Company: Ath Asia Pacific Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Please amend owner's name to Wong Yung Mei.

[Signature]
Policyholder / Driver's Signature
Date: _____

[Signature]
Reporting Centre Personnel's Signature
Name: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18022127/Gsd3e2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-04-2019	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKR 4596X	Veh. Inspected	SLL 6954C
Policy No.	2100402541-03	Coverage (\$)	0.00
Claim No.	0944026289SG-003	Excess (\$)	0.00
Assign From	LEE MING YAO	Assign Date	26/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VELLFIRE	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GGH208015900	Colour	WHITE
Odometer	255653	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	FALKEN	6 mm
L/H Front Tyre	235/50 R18	FALKEN	6 mm
R/H Rear Tyre	235/50 R18	FALKEN	6 mm
L/H Rear Tyre	235/50 R18	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/11/2018	Inspection Date	10/12/2018
Survey held at	AUTOWERKE AUTOMOTIVE PL 8 KAKI BUKIT AVENUE 4 #05-01 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6954C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DENTED	935.00	560.00
2	FRONT BONNET HINGE	BENT	156.00	156.00
2	FRONT BONNET DAMPER	NOT NECESSARY	143.00	-
1	FRONT GRILLE ASSY	CRACKED	755.00	755.00
1	FRONT GRILLE EMBLEM	NECESSARY	80.00	80.00
2	FRONT HEADLAMP	CRACKED	4,678.00	4,678.00
1	FRONT HEADLAMP CENTRE GRILLE LH	CRACKED	267.00	140.00
1	FRONT HEADLAMP CENTRE GRILLE RH	CRACKED	267.00	140.00
1	FRONT BUMPER	CRACKED	785.00	785.00
2	FRONT BUMPER RETAINER	NECESSARY	115.00	78.00
2	FRONT FOG LAMP	CRACKED	690.00	560.00
2	FRONT FOG LAMP COVER	CRACKED	334.00	334.00
1	TOW COVER	MISSING	35.00	35.00
1	FRONT LOWER GRILLE	CRACKED	309.00	278.00
1	SUPPORT PANEL	DENTED	1,417.00	985.20
1	FRONT LH CHASSIS	TO REPAIR SEE LABOUR	2,690.00	-
1	FRONT LH CHASSIS BRACKET	TO REPAIR SEE LABOUR	225.00	-
1	FRONT LH WHEEL HOUSE	TO REPAIR SEE LABOUR	900.00	-
1	FRONT LH FENDER	DENTED	1,050.00	670.00
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	1,050.00	-
1	FRONT LH FENDER INNER SHIELD	DEFORMED	180.00	180.00
1	AIRCON CONDENSER	BENT	1,600.00	1,600.00
1	CONDENSER COWLING	NOT NECESSARY	395.00	-
1	CONDENSER MOTOR	NOT NECESSARY	640.00	-
1	RADIATOR	PUNCTURE	2,065.00	945.00
1	RADIATOR COWLING	CRACKED	395.00	395.00
1	RADIATOR MOTOR	MALFUNCTION	540.00	540.00
1	AIRCON PIPE	NOT NECESSARY	874.00	-

Report Ref No. CS3/AIG18022127/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DISCHARGE PIPE	NOT NECESSARY	417.00	-
1	ENGINE MOUNTING	CRACKED	355.00	355.00
1	FRONT BUMPER UNDERCOVER	CRACKED	320.00	320.00
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	149.00	149.00
1	FRONT CROSS MEMBER	BENT	1,904.00	1,904.00
1	AIR DUCT	CRACKED	190.00	190.00
1	SPARE TANK	DEFORMED	435.00	210.00
1	WASHER TANK	DEFORMED	220.00	220.00
	LESS 25% DISCOUNT		-6,890.00	-4,310.55
			20,670.00	12,931.65
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	80.00	40.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	40.00	20.00
1	BOT COOLANT (SN)	NECESSARY	60.00	30.00
1	SET FRONT SENSOR (SN)	MALFUNCTION	400.00	200.00
			630.00	320.00
	LABOUR			
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		70.00	30.00
	REMOVE, RENEW CONDENSER AND TOP UP GAS.		150.00	60.00
	REMOVE, RENEW RADIATOR AND TOP UP COOLANT.		150.00	60.00
	REMOVE AND REFIT FRONT DASHBOARD.	NOT NECESSARY	700.00	-
	CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00
	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT.	NOT NECESSARY	600.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT LH CHASSIS, FRONT LH CHASSIS BRACKET, FRONT LH WHEEL HOUSE AND FRONT RH FENDER.		2,400.00	1,000.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	1,200.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	80.00
			5,970.00	2,490.00
GRAND TOTAL			27,270.00	15,741.65



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,600.00
---	--	--	-----------

Report Ref No. CS3/AIG18022127/Gsd3e2-1

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.