

INSURANCE

INS. CASE OWNER

CC6 / AIG1900 5380, A P 63 / 11

LKK IDAC

Surveyor: Adrian

DOI: ASSIGNMENT 25/7/19

Date / Time: 25/7/19

Registered in Meritex: 26/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.: SME 1539B

Claim No.: 305729688554

Name of Insured: WH WEE KIEW

Policy No.: 1800110411

Insured Tel No.: _____ HP: _____

Make / Model: MERCEDES

Excess Sec II :SS _____ D.O.A: 17/7/19

Place of Accident: 38 TMS SIMPANG

Is driver the owner? (YES / NO) Nature of Accident: _____

If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SLT 24494



INSRS: _____
WSP: Hua
Tel: man
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

Reject Case
 Reason: Shen
 Approved by: Yes
 Date: 22/08/19

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % 0 (Agreed / Assessed) BOLA S/N No.: 13 If NO or B 28, Ass. Lia: _____

Repair Cost: \$S _____ TP or (single) Loge

Loss of Rental (LOR): \$S (_____ days)

Loss of Use (LOU): \$S (S x _____ days)

Loss of Income (LOI): \$S (S x _____ days)

LOR only LOU only LOR + LOI LOR + LO [Tick only one]

GIA/LTA Search: \$S _____

Medical: \$S _____

Disbursement: \$S (e.g. Tow/ Independent) _____

Legal Cost: \$S _____

Total: \$S _____ Global Sum \$S: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S _____ Name 1: _____

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

WORK SENT
26/7/19

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SLT34497 Yr Regn: 2017 / Oct.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Elantra cc 1591
 Colour: Red AC: Insured / Std / Nil / NA
 Sp. Reading 25879 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: KMHDBA1CMJUS60999
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 25/03/19
 Survey held at Hua Meng
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Front 24/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPAIG.</u>
	<u>43: 91,800 (RID) = 2,437.36 51%</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:					
1)	2)	IN	OUT	Basic & Add.	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>					
3)	4)			___ S + RS, ___ \$						
5)	6)			Photos						
Prel. Report:				Others						
Final Report:				TOTAL						

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

THAM SOUK FUN
BLK 505 WOODLANDS DRIVE 14
#06-68
S 730505

TPAIG.
Xico Tony.

Date :15.04.2019
Vehicle no :SLT 3449 Y
Make/Model :HYUNDAI ELANTRA
Accident date :17.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper Torn	1	\$ 487.6 ✓
2	Front bumper side holder @ \$41.80 LHM	2	\$ 83.6 41.80
3	Front bumper fog lamp garnish 2122	1	\$ 105.4 +
4	Front bumper clips (1set) der	1	\$ 70.30
5	Front LH fender Pys	1	\$ 573.9 +
6	Front LH fender inner shield xcm	1	\$ 83.4 +
7	Front LH head lamp cruled	1	\$ 1317.8 ✓
			\$ 2721.7
		Less 20% Disc	\$ 544.34
		Total	\$ 2177.36

Labour Cost

1	Remove,replace & repair consistent to the accident		\$ 2000 300
2	Respray painting	760	\$ 980 450
3	Tuff kote		\$ 150 +
4	Wiring	100 A0	\$ 200
		Total	\$ 2050
		Grand Total	\$ 4227.36

total 2237.76.

L/S: 1.8K.
0.3Days

1.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 22 August 2019 12:51 PM
To: Hua Meng
Subject: ACCIDENT INVOLVING SLT 3449Y AND SME 1539B ON 17/03/2019
Attachments: OI SKETCH PLAN.pdf

Your Ref: SLT 3449Y
Our Ref: CC6/AIG19005380/Aeb3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SLT 3449Y AND SME 1539B ON 17/03/2019

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client changed lane and collided with our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-8051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAuto)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Thursday, 22 August 2019 11:09 AM
To: Asher Sng (LKKAuto)
Subject: FW: Your ref: 3557296885SG (Our ref: CC6/AIG19005380/Agb3) *** ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019 ***

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Asher,


Noted that you are taking over this case.

Fyi.

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Loh, Chee-Heng
Sent: Thursday, 22 August 2019 11:05 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: RE: Your ref: 3557296885SG (Our ref: CC6/AIG19005380/Agb3) *** ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019 ***

Dear Cecilia,

You may proceed to reject TPPD claim as TPV was changing lane.

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]
Sent: Thursday, 6 June 2019 6:13 PM
To: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Subject: [EXTERNAL] RE: Your ref: 35572968855G (Our ref: CC6/AIG19005380/Agb3) *** ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019 ***

This message is from an external sender; be cautious with links and attachments.

Dear Chee Heng,

Ya I have seen the AVF. I also able to see that TPV trying to change the lane as well.

Kindly give us your instruction if we able to reject TP claim. Thank you.

Best Regards,
Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]
Sent: Tuesday, 4 June 2019 11:38 AM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: RE: Your ref: 3557296885SG (Our ref: CC6/AIG19005380/Agb3) *** ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019 ***

Dear Cecilia,

OI's workshop, C&C/Yik, forwarded TP video footage and OI's photo, uploaded into Merimen. Yik will try to forward OI's video footage.

TP video footage seemed to show TPV changing lane.

Thank you.

Best regards,

Loh Chee Heng

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881

Chee-Heng.Loh@aig.com | www.aig.sg

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]

Sent: Friday, 31 May 2019 4:27 PM

To: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>

Subject: [EXTERNAL] Your ref: 3557296885SG (Our ref: CC6/AIG19005380/Agb3) *** ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019 ***

This message is from an external sender; be cautious with links and attachments.

Dear Chee Heng,

ACCIDENT INVOLVING SME 1539B & SLT 3449Y ON 17/03/2019

We refer to the above matter.

Third party driver reported that he was driving straight on his lane, suddenly our insured change into his lane and lead to the collision.

Our insured driver reported that he was going straight on his lane and third party trying to squeeze into his lane and resulted the collision.

We have ask for AVF from TP but to no avail. Kindly let us know if OI did submit his AVF to your end.

Please let us have your comments/ instruction if we may proceed to settle the matter at best or else advise further instruction.

Thank you.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 29.05.2019

Attn: Motor Claims Dept

ACCIDENT ON 17.03.2019 INVOLVING VEHICLE SLT 3449 Y & SME 1539 B ALONG
MALAYSIA CHECKPOINT TWDS SINGAPORE

With regards to the above, we are writing on behalf of the registered owner of vehicle SLT 3449 Y which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SME 1539 B. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair cost	\$	1,800.00
2) Loss of use - \$150 X 03 days	\$	450.00
3) LTA search	\$	7.49
Total	\$	2,257.49

We hereby enclosed herewith the following documents for your consideration of the above claim.

- | | |
|------------------------------------|--|
| a) Final Repair Bill Of SLT 3449 Y | c) LTA SEARCH |
| b) GIA report | d) Owner / Driver NRIC & Driving License |

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
KAKI BUKIT AVE 6 #01-34 SINGAPORE 417883
TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,

HUA MENG SPRAY PAINTING WORKSHOP



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 27/5/2019

VEHICLE NO :SLT 3449 Y
MAKE / MODEL :HYUNDAI ELANTRA
NAME :THAM SOUK FUN
ADDRESS :BLK 505 WOODLANDS DRIVE 14
#06-68
S 730505

FINAL REPAIR BILL FOR VEHICLE NO:SLT 3449 Y

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMPSUM REPAIR)

\$ 1,800.00

SINGAPORE DOLLARS:ONE THOUSAND AND EIGHT HUNDRED ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 16:58
Date Of Accident	17/03/2019 22:30
Exact Location Of Accident	MALAYSIA CHECKPOINT TWDS SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3449Y
Insured/Policyholder	
Name Of Registered Owner	THAM SOUK FUN
NRIC No	S1379772B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82339061
Alternative Phone No	OFFICE-82339061

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2023195
Cover Note Number	

Driver

Name of Driver	SEAH WEI TING
NRIC No	S8839423B
Date Of Birth	10/10/1988
Occupation	INDOOR
Date Of Driving Pass	24/09/2007
Driving Experience	11 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93360851
Fax Number	
Contact Number	
E-Mail Address	ICEJEAN88@HOTMAIL.COM

Address BLK 505 WOODLANDS DRIVE 14 #06-68
 Postcode 730505
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : THAM SOUK FUN
 GENDER: : FEMALE
 Passenger 2
 NAME: : SEAH WEI EN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I AM TRAVELLING STRAIGHT ON MY LANE. VEHICLE B TRY TO CHANGE INTO OUR LANE AND HIT ONTO MY LEFT PORTION. I HAVE STOP MY VEHICLE. HOWEVER, VEHICLE B CAME TOO CLOSE TO MY VEHICLE AND CONTINUED, THUS DAMAGING MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME1539B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIH No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am travelling straight on my lane. Vehicle B try to change into our lane and hit onto my left portion. I have stop my vehicle, however vehicle B came too close to my vehicle and continued, thus damaging my vehicle.

h

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2019 Edit Reg		25 Mar 2019 00:00 Edit Adj Rpt	\$1,800.00 Edit Estimates	\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LOH WEE KIEN , ID: S7130215F								
Main Claimant:	THAM SOUK FUN , ID: S1379772B								
Vehicle Reg. No.:	SLT3449Y	Date of Loss:	17/03/2019 21:00 - :59 [16 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3557296885SG	Policy/Cover Note No.:	1800110411 (Comprehensive)						
Vehicle Reg. No. (Insured):	SME1539B	Policy No. (Claimant):	P2023195						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/04/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT3449Y (3557296885SG)**
[SME1539B]
TP
THAM SOUK FUN
Mar 17 2019 9:00PM
[LOH WEE KIEN]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	04/06/19 11:07	TP video											Load WMV				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
2	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
3	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
4	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
5	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
6	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
7	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
8	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
9	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
10	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
11	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
12	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
13	22/05/19 10:41	General View											Load JPG	<input checked="" type="checkbox"/>			
14	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
15	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
16	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
17	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
18	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
19	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
20	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
21	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
22	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
23	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
24	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
25	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
26	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
27	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
28	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
29	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
30	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
31	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
32	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
33	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
34	22/05/19 10:41	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	22/05/19 10:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	22/05/19 10:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	22/05/19 10:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	22/05/19 10:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	22/05/19 10:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/19 15:19	TP GIA REPORT	 Load PDF	
2	22/05/19 11:01	TP ESTIMATE	 Load PDF	
3	22/08/19 12:18	APPROVAL TO REJECT TP CLAIM	 Load PDF	
4	22/08/19 12:52	EMAIL WSP TO REJECT TP CLAIM	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/03/19 15:18	OI GIA REPORT	 Load PDF	
2	04/06/19 11:28	OI-photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6258-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19005380/AEB3Q2

Date: 29/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800110411
Claimant Vehicle No : SLT3449Y **Insured Vehicle No :** SME1539B
 Date of Loss: 17/03/2019 Nature of Claim: TP Claim No: 3557296885SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT3449Y**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU687293
 Reg. Date: 26/10/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU560999
 Colour: Red Odometer: 25879 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,177.36	1,501.76	675.60	31.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	790.00	1,360.00	63.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,327.36	2,291.76	2,035.60	47.04
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	4,327.36	1,800.00	2,527.36	58.40
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/03/2019
 Date Inspected: 25/03/2019 Inspected At: Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	487.60 FL	*487.60 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/S Necessary	83.60 FL	*41.80 FL
3	1		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	105.40 FL	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
5	1		*FRONT LH FENDER	Repair	573.90 FL	*- FL
6	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	83.40 FL	*- FL
7	1		*FRONT LH HEAD LAMP	Cracked	1,317.80 FL	*1,317.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,721.70	1,877.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	544.34	375.44
Total Parts (\$\$)	2,177.36	1,501.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	300.00
2	RESPRAY PAINTING	New	900.00	450.00
3	TUFF KOTE	New	150.00	0.00
4	WIRING	New	100.00	40.00
Gross Labour Cost (S\$)			2,150.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >