

AE REC. BY:

REF: CS/CT1/1005345/69/d3

Special Instruction:

Survey: GA

ASSIGNMENT (Office)

From (Person): Ong chin kiat of CT1 Date/Time: 26.3.19 15:37 p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: FBB676R Insured: YM 8837K

at Workshop m/s Tong Aik Motor Supply Tel: 63379912
of 87 short street # 01-02/03

Policy No: DMCVSN/153026/8033 Claim No: SNM14D201260C02

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 19.3.2019
27.3.2019

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 26.3.19 3:57 p.m Person Contacted: madan soh Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	FBB676R - X	(Nearby little Indra)
	YM 8837K - X	

6d.

REF: C11

1950 i

(-2021)

ASSIGNMENT

From:

Date: 27.3.2019

Veh No:

FBR 676R

Yr Regn:

28 Feb 2001

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FBR 676R

Make:

Piaggio PX 200E

C.C.

198

at Workshop m/s

Tong BIK motor supply

Colour:

Black

A/C:

Insured / Std / NI / NA

of

89 shaft strat # 01-02/03

Sp. Reading:

57294

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

VSXIT600 8990

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

3.50-10

R:

11

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS, DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

\$ 2000

Front

Rear

IDAC Accident Report:

Consistent?: Yes or No

R/Bal.

4

mm

R/Bal.

4

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

D.O.I.

27-03-19

Lump Sum:

%

3 Val.: Yes or No

Survey held at

w/s

4pm

CA / REV / REP. / 24 HRS

"wp"

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Please scan estimate email to w/s

Finalized \$1500 with ~~at~~ total soh

[Signature]
28/3/19.

RECEIVED 9 APR 2019

Date/Time File Pass to?

Preli. Report

Days Of Repair: 4

1) *[Signature]*

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

Transportation

Add Fee:

Site Insp (\$)

) \$ - RS - SI

Interview (\$)

) Photos

Tech. Invs (\$)

) Others

Weekend (\$)

)

Report Format:

[Handwritten]

Lump Sum / L.P.A. (\$) *[Handwritten]*

1500

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019		26 Mar 2019 15:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIN HWA DEE FOODSTUFF INDUSTRIES PTE LTD , Co. Reg. No.: 198101291M								
Main Claimant:	TEO JUN KAI (ZHANG JUNKAI) , ID: S8811950I								
Vehicle Reg. No.:	FBB676R	Date of Loss:	19/03/2019 14:00 - :59 [216 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201260C02	Policy/Cover Note No.:	DMCVSN15302618033 (Comprehensive) Coverage: 18/07/2018 - 17/07/2019						
Vehicle Reg. No. (Insured):	YM8837K	Policy No. (Claimant):	MC/00502365						
		Excess:	\$0.00						
Repairer:	Tong Aik Motor Supply Co (HQ) 89 Short Street #01-02/03, 188216 Jalan Besar - Tel: 6337-9912								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2019]								
Driver/Custodian (Insured):	LIM KEE CHOI (62 / Male) , NRIC: S1182502H Email:								
Adj Asg. Remarks:	kindly assign Quo Qiang for the SJE. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 10:06
Date Of Accident	19/03/2019 14:10
Exact Location Of Accident	MIDDLE ROAD BEFORE BEACH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBB676R
Insured/Policyholder	
Name Of Registered Owner	TEO JUN KAI (ZHANG JUNKAI)
NRIC No	S88119501
Email Address	JAY.TJK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90068495
Alternative Phone No	OTHERS-90068495

Vehicle Particulars

Manufacturer	VESPA
Model	PX200E-198CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MC/00502365
Cover Note Number	

Driver

Name of Driver	TEO JUN KAI (ZHANG JUNKAI)
NRIC No	S88119501
Date Of Birth	12/04/1988
Occupation	INDOOR
Date Of Driving Pass	18/11/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90068495
Fax Number	
Contact Number	OTHERS-90068495
Email Address	JAY.TJK@GMAIL.COM

Address: BLK 40 TELOK BLANGAH RISE #12-389
SINGAPORE

Postcode: 090040

Was driver an employee of the Insured's Company: NO

If No, Relationship of the Driver with the Insured: OWNER

Vehicle Registration Number of Driver's Own Vehicle: -

Vehicle: -

Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: COLLISION - CHANGE/CROSS LANE

Weather Conditions: CLEAR

Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident?: NO

Number of vehicles (including own vehicle) involved in the accident: 2

Was any body injured in the Accident?: YES

Was any injured conveyed to hospital by ambulance?: NO

Was any other material or property damaged?: YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.: NO

Number of Passengers (Including Driver): 1

Details of Police Action

Was the accident reported to the police?: YES

If Yes, Please state which Police Station

Police Station Name: TRAFFIC POLICE DIVISION HQ

Police Station Address: ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact: TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?: NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?: YES

Was there any video captured by Car Camera?: NO

Was there any audio recorded?: NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: YM8837K

Vehicle Make/Model/Colour:

Details Of Properties:

Vehicle Category: COMMERCIAL VEHICLE

Name of Driver: LIM KEE CHOI

NRIC/Passport Number: S1182502H

Contact Number: 96288906

Address:

Postcode:

Insurance Company Name:

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TEO JUN KAI (ZHANG JUNKAI)
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FBB676R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:
 19/11/2015
 4:17 PM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While travelling down middle road towards beach ~~road~~, the other party made a left turn towards the small road. While attempting to turn the other party did not notice the motorcycle beside and the side of the lorry hit the motorcycle before the turn was completed.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 19/7/2019
 4 PM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190319/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190319/7017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/03/2019 20:58	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: TEO JUN KAI		Address: APT BLK 40 TELOK BLANGAH RISE #12-389 SINGAPORE 090040	
ID Type / ID No.: NRIC NO / S88119501		Contact No.:	Mobile: 90068495
Nationality: SINGAPORE CITIZEN		Email: jay.tjk@gmail.com	
Sex: Male	Age: 30	Date of Birth: 12/04/1988	Type of Informant: Rider
Race: Chinese		Language: English	Institution / School Name:
Occupation: Management executive		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/03/2019 14:10	Type of Location: Straight Road
Location: MIDDLE ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Pedestrian Crossing	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB676R	Motorcycle	PIAGGIO	PX 200E	Black		0
YM8837K	Lorry					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBB676R	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00502365	28/08/2018	27/08/2019



**SINGAPORE
POLICE FORCE**



T/20190319/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190319/7017

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TEO JUN KAJ	ID No.	S8811950I
Related Vehicle	FBB676R (Motorcycle)	Contact No.	90068495
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/03/2019	Date Discharge	19/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Lim Kee Choi	ID No.	S1182502H
Related Vehicle	YM8837K (Lorry)	Contact No.	96288906
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

While traveling straight on middle road towards beach road, My motorcycle was on the left most lane. The other driver, a delivery lorry while attempting to access the service road on the left attempt to make a left turn, which cause the left side of the lorry to impact my motorcycle subsequently pinned the motorcycle under the side of the lorry. Rider sustain injury to the leg, 3 days MC was provided by doctor. No ambulance was called.



**SINGAPORE
POLICE FORCE**



T/20190319/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3
Report No. T/20190319/7017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NF166

Signature Of Informant:
This identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
19/03/2019 20:58

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1950I
Vehicle Details	
Vehicle No.:	FBB676R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	PX 200E
Primary Colour:	Black
Manufacturing Year:	2000
Engine No.:	VSE1M410585
Chassis No.:	VSX1T6008990
Maximum Power Output:	-
Open Market Value:	\$2,516.00
Original Registration Date:	28 Feb 2001
First Registration Date:	28 Feb 2001
Transfer Count:	7
Actual ARF Paid:	\$378.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,567.00
COE Rebate Amount:	\$300.00
Total Rebate Amount:	\$300.00
Message	

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

Bike model

Type

Any



Price From

Any



Price To

Any



Class

Any



MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▾



[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/11885/\)](#)[+ ADD TO SHORTLIST](#)[like 0](#)[Share](#)[SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/PIAGGIO-PIAGGIO-X8-200/11885/\)](#)

Piaggio X8 200

Listing Type	Free Ad
Brand	Piaggio (/listing/usedbike/brand/piaggio/)
Model	Piaggio X8 200 (/listing/usedbike/model/piaggio-x8-200/)
Engine Capacity	198cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	12/08/2004
COE Expiry Date	11/08/2024 (5 years 4 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Scooters (/listing/usedbike/model/motorcycle-for-sale/scooters/)

Price: ^{SGD}\$3800

DETAILS

Piaggio X8 200 for sale due to driving. Seldom ride. Usually park under shelter carpark. Excellent condition. Well taken care. Great fuel efficiency. Lots of storage space able to fit 4 helmet. Best bike for your daily commutes. COE renewable. Exterior: 9/10 (See to believe). Engine: 8/10. Replaced new: High End Bridgestone Tyre made in Japan (front and back), Water pump (whole set including casing with full Kit), Radiator Fan, Regulator rectifier, Belting and roller, Air Filter, Brake pad (front and back), Carburetor Kit, Battery, Main stand and side stand, Rear swing arm. Had changed mostly parts that are costly so next owner can ride with worried free. Servicing: Radiator cooler water with flush. Carburetor servicing, Engine oil (Used only fully synthetic), Oil filter and spark plug change every 3000km. Wash every fortnight and make sure wax everytime after washed.


Accessories

Koso temperature gauge. Racing brake line. Front twin spotlights.

Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



TONG AIK MOTORS SUPPLY CO

89, Short Street, #01-02/03
Golden Wall Centre
Singapore 188216

Tel: 63379912 / 63370201 Fax: 63379246
E-mail: vescom100@hotmail.com

the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 Any item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Rep. on 25 March 2019
 Signature: [Signature]

To: China Tailoring Ins. (S) Pte Ltd

Attention: Motor Claim Dept. email: claimsdept@csq.entaiping.com

Re: Scooter FBB 676 R with your insured vehicle #18837F

Quotations To Repair Scooter FBB 676 R

1) Change 1 pc Front steering Fork arm	\$ 78.50	1883.7
2) Change 1 pc Front midguard, Blue	\$ 95.00	20% 1500
3) Change 1 set Front Fork Bearing w/ cone	\$ 68.00	4 Days
4) Change 1 pc Flywheel cover - BT	\$ 38.50	Improm repair
5) Change 1 pc RH side cover - Blue	\$ 125.00	After repair photos
6) Change 1 set Flooroil set - Cut	\$ 78.00	One Comp.
7) Change 1 set Rear signal RH / L	\$ 48.50	27/3/19
	1238.00	
	1238.00	
	1114.20	
8) Knock RH side cover, RH floorboard edge	180.00	100
9) Jack body Alignment & stopper	150.00	80
10) Transport to IDAC	80.00	35
11) Labour charges	280.00	180
12) Spray whole scooter	800.00	300
	\$ 2604.20	695
13) Change 1 pc Fork link cover / m/s	22.50	
14) Change 1 Horn Emblem / m/s	6.00	
	\$ 2632.70	74.5
15) Change 1 pc front shield / Cut	28.00	
	2660.70	
16) 2 pc Front sticker plate #18/2 - m/s	18.00	
Remarks: Any unforeseen parts damaged in process of repair, another supplementary quotation will be advised.		2678.70

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019		26 Mar 2019 15:37 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	SIN HWA DEE FOODSTUFF INDUSTRIES PTE LTD , Co. Reg. No.: 198101291M								
Main Claimant:	TEO JUN KAI (ZHANG JUNKAI) , ID: S88119501								
Vehicle Reg. No.:	FBB676R	Date of Loss:	19/03/2019 14:00 - :59 [216 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201260C02	Policy/Cover Note No.:	DMCVSN15302618033 (Comprehensive) Coverage: 18/07/2018 - 17/07/2019						
Vehicle Reg. No. (Insured):	YM8837K	Policy No. (Claimant):	MC/00502365						
		Excess:	S\$0.00						
Repairer:	Tong Aik Motor Supply Co (HQ) 89 Short Street #01-02/03, 188216 Jalan Besar - Tel: 6337-9912								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/04/2019]								
Driver/Custodian (Insured):	LIM KEE CHOI (62 / Male) , NRIC: S1182502H Email:								
Adj Asg. Remarks:	kindly assign Quo Qiang for the SJE. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBB676R (SNM19D201260C02)
[YM8837K]

TP

TEO JUN KAI (ZHANG JUNKAI)

Mar 19 2019 2:00PM

[SIN HWA DEE FOODSTUFF INDUSTRIES PTE LTD]

Tong Aik Motor Supply Co

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	1 per page ▼	<input checked="" type="checkbox"/>
1	20/03/19 10:34	Accident Statement	 Thumbnail	Print
			Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	<input checked="" type="checkbox"/>
1	05/04/19 10:15	General View	 Thumbnail	Print
2	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/04/19 10:15	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
33	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
34	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
35	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
36	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
37	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
38	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
39	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
40	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
41	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
42	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
43	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
44	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
45	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
46	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
47	05/04/19 10:15	General View		<input checked="" type="checkbox"/>
48	05/04/19 10:16	Odometer Reading		<input checked="" type="checkbox"/>
49	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
50	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
51	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
52	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
53	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
54	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
55	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
56	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
57	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
58	05/04/19 10:16	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/03/19 14:37	Estimate		<input checked="" type="checkbox"/>
2	26/03/19 14:37	INSD YM8837K GIA report		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	20/03/19 10:34	Accident Statement		<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
2	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
3	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
4	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
5	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
6	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
7	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>
8	20/03/19 10:11	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
9	20/03/19 10:11	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	20/03/19 10:11	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	20/03/19 10:11	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	20/03/19 10:28	Sketch Plan		Load TIF
2	20/03/19 10:28	Sketch Plan #2		Load TIF
3	20/03/19 10:28	Accident Sketch Plan		Load TIF
4	20/03/19 10:28	Accident Sketch Plan		Load TIF
5	20/03/19 10:28	Accident Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005395/GQD3S2

Date: 06/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN15302618033		
Claimant Vehicle No :	FBB676R	Insured Vehicle No :	YM8837K		
Date of Loss:	19/03/2019	Nature of Claim:	TP	Claim No:	SNM19D201260C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBB676R		Engine No:	VSE1M410585
Make & Model:	VESPA PX200E, 198cc		Chassis No:	VSX1T6008990
Reg. Date:	28/02/2001 (Man. Year: 2000)		Odometer:	57294 km
Colour:	Black			
Engine Capacity:	198 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	3.50-10	Rear Tyre Size:	3.50-10
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,188.70	1,188.70	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	695.00	795.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,678.70	1,883.70	795.00	29.68
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	2,678.70	1,500.00	1,178.70	44.00

INSPECTION

Date of Assignment:	26/03/2019		
Date Inspected:	27/03/2019	Inspected At:	Tong Aik Motor Supply Co (HQ) 89 Short Street #01-02/03 Singapore 188216
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 06 May 2019)	
Parts:	N/A	VESPA PX200E 198cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB676R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT STEERING FORK ASSY	Bent	785.00 FL	*785.00 FL
2	1		*FRONT MUDGUARD	Buckled	95.00 FL	*95.00 FL
3	1		*SET FRONT FORK BEARING W/CORE	Necessary	68.00 FL	*68.00 FL
4	1		*71Y WHEEL COVER	Bent	38.50 FL	*38.50 FL
5	1		*RH SIDE SIDE COWL	Buckled	125.00 FL	*125.00 FL
6	1		*SET FLOOR RAIL NET	Cut	78.00 FL	*78.00 FL
7	1		*SET REAR SIGNAL RH	Cracked	48.50 FL	*48.50 FL
8	1		*FORK LINK COVER	Missing	22.50 FS	*22.50 FS
9	1		*HORN EMBLEM	Missing	6.00 FS	*6.00 FS
10	1		*FRT SHIELD BEADING	Cut	28.00 FS	*28.00 FS
11	2		*FRONT STICKER PLATE	Necessary	18.00 FS	*18.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,312.50	1,312.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	123.80	123.80
Total Parts (\$\$)	1,188.70	1,188.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCK RH SIDE COWL, RH FLOORBOARD EDGE.	New	180.00	100.00
2	JACK BODY ALIGNMENT & STOPPER.	New	150.00	80.00
3	TRANSPORT TO IDAC.	New	80.00	35.00
4	LABOUR CHARGES.	New	280.00	180.00
5	SPRAY WHOLE SCOOTER.	New	800.00	300.00
Gross Labour Cost (S\$)			1,490.00	695.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >