Surveyor: Steve | REF:

ASSIGNMENT

From | Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Date / Time | Action / Instruction

Veh No SKN 757S H Yr Regn. 30/11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 730 cc 1998

Colour Grey A/C Insured / Std / NI / NA

Sp.Reading 3787 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA7E 02000 BR 95989

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim. / STD A/Rim or

Tyre Size: F: 245/50 R18

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	21/3/19	D.O.I.	29/3/19

Survey held at Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + R: $

) Photos

) Other

) ..

TOTAL

Add Fee: ☐ : Site Insp ($

☐ : Interview ($

☐ : Tech Invs ($

☐ : Weekend ($

Report Format :

Lump Sum / I.B.I: ($