

ASSIGNMENT

From:

Date: 27.3.2019

Veh No:

SDE 3195C

Yr Regn:

6/10/06

Estimated Cost

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SDE 3195C

Make:

Honda Civic

C.C

1339

at Workshop n/s

MOVA

Colour:

Silver

A/C: Insured / Std / NI / NA

of 15 Fan Yuong Road

Sp. Reading:

166328

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

JHMFO362065203475

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / R/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195/65R15

R: "

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

3

mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

3

mm

Est. Repairs: days Res.: Yes or No

D.O.A.

22/3/19

D.O.I.

27/3/19

Lum Sum: % 3 Val.: Yes or No

Survey held at

MOVA, Fan Yng Rd

CA / REV / REP. / 24 HRS "WP"

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front RIR

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 17,000

PV - 13,125

NV - 3875

Finalize \$2100, 4 days

C \$ 1,366.16 Red - 39%

[Signature]

8/4/2019

Date/Time, File Pass to?

09/04/19
Tyat

: Preli. Report

: Final Report

Date/Time, File Return to?

3)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee: : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.L: (\$ 2,100/- 1/5)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2019		28 Mar 2019 08:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	SUNITI NAWEED NAQVI, ID: S6882876G		
Vehicle Reg. No.:	SDE3195C	Date of Loss:	22/03/2019 13:00 - :59
Claim Type:	TP / SNM19D201335C02	Policy/Cover Note No.:	DMPCSN30556018000
Vehicle Reg. No. (Insured):	SLZ7551B	Policy No. (Claimant):	5072512312-03
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/04/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Shirley Hiew (LKK Auto)

From: Billy <billy@mova.com.sg>
Sent: Tuesday, 9 April 2019 10:01 AM
To: 'Steve Chen (LKK Auto)'
Cc: 'Jia Yu'
Subject: RE: SDE3195C
Attachments: SDE3195C Honda Civic 2006.pdf

Hi Sir,

Confirm thank You.

Best Regard's
Billy Liaw

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: 09 April 2019 09:34
To: Billy
Subject: SDE3195C

Dear Billy,

We have come out with the finalize \$2100. 4 days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Billy [mailto:billy@mova.com.sg]
Sent: Friday, April 05, 2019 2:36 PM
To: Steve Chen (LKK Auto)
Subject: Re:SDE3195C

Hi Sir,

Attach with Finalization report, Please advice. Thank You.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd
Tel: +65 62623377
Fax: +65 62643151



Connect with us on  

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/03/2019 16:00
Date Of Accident	22/03/2019 13:30
Exact Location Of Accident	UWCSEA CAR PARK, 1207 DOVER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDE3195C
Insured/Policyholder	
Name Of Registered Owner	SUNITI NAWEED NAQVI
NRIC No	S6882876G
Email Address	S.AND.N.NAQVI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98297656
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC IMA A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5072512312-03
Cover Note Number	

Driver

Name of Driver	SUNITI NAWEED NAQVI
NRIC No	S6882876G
Date Of Birth	08/01/1968
Occupation	INDOOR
Date Of Driving Pass	16/06/2005
Driving Experience	13 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98297656
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	S.AND.N.NAQVI@GMAIL.COM

Address	BLK 7 BRIGHT HILL DRIVE #25-07
Postcode	579599
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ7551B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DALIA FELDHEIM
NRIC/Passport Number	
Contact Number	91382803
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SDE 3195C	ACCIDENT DATE & TIME: 22/03/2019 1:30pm
CONTACT NUMBER: +65 98297656	E-MAIL ADDRESS: s.and.n.nagvi@gmail.com
LOCATION: UWCSEA Carpark, 1207 Dover Road.	

Another car hit my parked car in the UWCSEA Dover Road Carpark. The other party left a note with their contact details as the car was not occupied when it was hit (parked & stationary in lot # 85).

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

Please state:

Claim Own Policy Claim Third Party Claim OD/TP at other workshop Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Sumiti Nagvi

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2876G
Vehicle Details	
Vehicle No.:	SDE3195C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC IMA A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	LDA21029973
Chassis No.:	JHMF36206S203475
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$26,781.00
Original Registration Date:	06 Oct 2006
First Registration Date:	06 Oct 2006
Transfer Count:	2
Actual ARF Paid:	\$18,748.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Oct 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,054.00
COE Rebate Amount:	\$13,125.00
Total Rebate Amount:	\$13,125.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Mar 2019

OK



MCF HANGOUT
UNDISCOVER TASMANIA WITH JETABOUT HOLIDAYS

SATURDAY, 6 APRIL 2019

ENJOY ONE-DAY EXCLUSIVE PACKAGE DEALS + LUCKY DRAW!

Tasmania
JETABOUT
HOLIDAYS

REGISTER NOW - IT'S



Advanced
Search

Home » Used Cars » Boeki Auto & Marine » Honda Civic 1.8A VTi-S (COE till 08/2021)

Honda Civic 1.8A VTi-S (COE till 08/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



BOEKI AUTO & MARINE



Price \$17,800

Depreciation \$7,320 /yr

Reg Date 22-Sep-2006
(2yrs 5mths 3days COE left)

Mileage 175,000 km (14k /yr)

Manufactured 2006

Road Tax \$1,271 /yr

Transmission Auto

Dereg Value \$13,235 as of today (change)

OMV \$21,245

COE \$27,232

ARF \$23,370

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight 1,219 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Honda Civic (2006-2012)

Description

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare

valuation - Free



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Boeki Auto & Marine » dealer's pricelist » 131 vehs sold 44 vehs availat
Address	49 Sungei Kadut Loop Search cars nearby this location
Office No	67555005
Contact Person(s)	BOEKI 82180:

Shirley

Stone (LKR) with the judge 27/3/19 12.00pm
L/S 4 days
Ry AF Spray Page # :- 1



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/03/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Veh # :- SDE3195C
Veh Model :- HONDA CIVIC IMA A
Estimate# :- CK418911
Claim # :-
ACC. Date :- 22/03/19
Terms :- C.O.D Days
Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	HEADLAMP ASSY RH / CUT	1	PC	921.00 921.00 ✓
2.	HEADLAMP LOWER BRACKET RH / BT	1	PC	29.10 29.10 ✓
3.	RADIATOR GRILLE X	1	PC	84.60 84.60 X
4.	RADIATOR GRILLE CHROME MOULDING X	1	PC	182.40 182.40 X
5.	RADIATOR GRILLE 'H' LOGO X	1	PC	23.40 23.40 X
6.	FRONT BUMPER / TN	1	PC	638.00 638.00 ✓
7.	FRONT BUMPER REINFORCEMENT / DD	1	PC	218.80 218.80 ✓
8.	FRONT BUMPER RETAINER RH & LH LH / RH - OR	2	PCS	12.20 ✓ 24.40
9.	FRONT BUMPER CLIPS / N/C	10	PCS	3.90 39.00 ✓
10.	FOG LAMP RH - CHECK ?	1	PC	
11.	FOG LAMP GARNISH RH - CHECK ?	1	PC	
12.	FRONT FENDER RH / DD	1	PC	537.50 537.50 ✓
13.	FRONT FENDER COWLING RH X / NN	1	PC	94.80 94.80 X
14.	FRONT FENDER COWLING CLIPS X / NN	10	PCS	3.50 35.00 X
15.	TOP GARNISH CLIPS X / NN	10	PCS	3.90 39.00 X
16.	TOP GARNISH X / NN	1	PC	65.70 65.70 X
LIST TOTAL S\$				2395.60 2,932.70
20% DISCOUNT S\$				479.12 -586.54
				1) 1916.48 2,346.16
SPECIAL NET ITEMS :				
1.	FRONT NUMBER PLATE X	1	PC	40.00 40.00
SPECIAL NET TOTAL S\$				40.00
LABOUR :				
TO KNOCK AND STRAIGHTEN SUPPORT PANEL, FRONT FENDER RH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION				400 500.00
SPRAY PAINT FRONT FENDER RH, SUPPORT PANEL, FRONT BUMPER				400 550.00
CHECK WIRING AND FOCUS HEADLIGHT				30.00
LABOUR TOTAL S\$				2) 830.00 1,080.00



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/03/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 134427

Veh # :- SDE3195C

Veh Model :- HONDA CIVIC IMA A

Estimate# :- CK418911

Claim # :-

ACC. Date :- 22/03/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,466.16

GST @ 7 % 242.63

AMOUNT DUE S\$ 3,708.79

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PARTS 1916.48
 2) LABOUR 830.00
 2146.48
 - 549.30 less 25%
 1597.18

Lump sum \$ 2200.00
 Please advice.
 Thank You
 BILLY LIAW.

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Steve (LKK) with for justice 27/3/19 12:00pm
L/S 4 days
Ry AE spray

Estimate

26/03/2019

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909.

Attention :- **XA017**

Page # :- 1
 Veh # :- SDE3195C
 Veh Model :- HONDA CIVIC IMA A
 Estimate# :- CK418911
 Claim # :-
 ACC. Date :- 22/03/19
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	HEADLAMP ASSY RH / CUT	1	PC	921.00	790.40 / 921.00
2.	HEADLAMP LOWER BRACKET RH / BT	1	PC	29.10	29.10 /
3.	RADIATOR GRILLE X N/A	1	PC	84.60	84.60 X
4.	RADIATOR GRILLE CHROME MOULDING X N/A	1	PC	182.40	182.40 X
5.	RADIATOR GRILLE 'H' LOGO X N/A	1	PC	23.40	23.40 X
6.	FRONT BUMPER / TN	1	PC	638.00	638.00 /
7.	FRONT BUMPER REINFORCEMENT / DD	1	PC	218.80	218.80 /
8.	FRONT BUMPER RETAINER RH & LH LH - RH - OR	2	PCS	12.20	24.40 /
9.	FRONT BUMPER CLIPS / N/A	10	PCS	3.90	30 / 39.00
10.	FOG LAMP RH - CHECK	1	PC		
11.	FOG LAMP GARNISH RH - CHECK	1	PC		
12.	FRONT FENDER RH / DD	1	PC	537.50	537.50 /
13.	FRONT FENDER COWLING RH X N/A	1	PC	94.80	94.80 X
14.	FRONT FENDER COWLING CLIPS X N/A	10	PCS	3.50	35.00 X
15.	TOP GARNISH CLIPS X N/A	10	PCS	3.90	39.00 X
16.	TOP GARNISH X N/A	1	PC	65.70	65.70 X

LIST TOTAL S\$

2,932.70

20% DISCOUNT S\$

2268.20
 - 20%
 1814.56

-586.54

2,346.16

SPECIAL NET ITEMS :

1.	FRONT NUMBER PLATE X N/A	1	PC	40.00	40.00 X
----	--------------------------	---	----	-------	---------

SPECIAL NET TOTAL S\$

40.00

LABOUR :

TO KNOCK AND STRAIGHTEN SUPPORT PANEL, FRONT FENDER RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION

400 500.00

SPRAY PAINT FRONT FENDER RH, SUPPORT PANEL, FRONT BUMPER

400 550.00

CHECK WIRING AND FOCUS HEADLIGHT

30.00

LABOUR TOTAL S\$

830 1,080.00

P+L - 2644.56

L/S - 2115.64

= 2100

Estimate

26/03/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- **XA017**

Page # :- 1 134427
Veh # :- SDE3195C
Veh Model :- HONDA CIVIC IMA A
Estimate# :- CK418911
Claim # :-
ACC. Date :- 22/03/19
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/05/06/94
Singapore 159722
Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S	
AMOUNT S\$	3,466.16
GST @ 7 %	242.63
AMOUNT DUE S\$	3,708.79

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2019		28 Mar 2019 08:26 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	SUNITI NAWED NAQVI , ID: S6882876G		
Vehicle Reg. No.:	SDE3195C	Date of Loss:	22/03/2019 13:00 - :59 [149 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201335C02	Policy/Cover Note No.:	DMPCSN30556018000
Vehicle Reg. No. (Insured):	SLZ7551B	Policy No. (Claimant):	5072512312-03
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/04/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDE3195C (SNM19D201335C02)
[SLZ7551B]**

**TP
SUNITI NAWEED NAQVI
Mar 22 2019 1:00PM**

**[-]
Mova Automotive Pte Ltd**

Upload Documents Upload Photos Compose New Letter			View View in Browser ▾
Assessment Reports			1 per page <input type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail <input type="checkbox"/>
1	22/03/19 17:06	Accident Statement	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page <input type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail <input type="checkbox"/>
1	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
2	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
3	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
4	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
5	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
6	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
7	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
8	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
9	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
10	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
11	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
12	22/03/19 17:03	Accident Photo [Linked Accident Report Documents]	<input checked="" type="checkbox"/> Load JPG
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
2	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
3	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
4	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
5	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
6	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
7	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
8	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
9	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
10	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
11	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
12	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
13	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
14	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG
15	28/03/19 08:55	General View	<input checked="" type="checkbox"/> Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
16	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/03/19 08:55	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
21	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/03/19 08:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
24	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/03/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/04/19 10:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
29	08/04/19 10:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/03/19 08:27	pri contact	 Load PDF	

No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/03/19 17:03	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View In Browser
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	1 per page	<input checked="" type="checkbox"/>
1	22/03/19 17:06	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	22/03/19 17:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/03/19 17:03	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19005415/ESD3S2

Date: 06/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30556018000	
Claimant Vehicle No :	SDE3195C	Insured Vehicle No :	SLZ7551B	
Date of Loss:	22/03/2019	Nature of Claim:	TP	Claim No: SNM19D201335C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDE3195C	Engine No:	LDA21029973
Make & Model:	HONDA CIVIC, 1.3 IMA (A)	Chassis No:	JHMF36206S203475
Reg. Date:	06/10/2006 (Man. Year: 2006)	Odometer:	166328 km
Colour:	Silver		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,386.16	1,814.56	571.60	23.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	830.00	250.00	23.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,466.16	2,644.56	821.60	23.70
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,466.16	2,100.00	1,366.16	39.41
+ GST 7.00/7.00% (S\$)	242.63	147.00	95.63	39.41
Nett Amount (S\$)	3,708.79	2,247.00	1,461.79	39.41

INSPECTION

Date of Assignment:	28/03/2019		
Date Inspected:	27/03/2019	Inspected At:	Mova Automotive Pte Ltd 15 FAN YONG ROAD SINGAPORE 629792
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 May 2019)**Parts:** 143 HONDA CIVIC 1.3 IMA (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SDE3195C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Cut	921.00 FL	*790.40 FL
2	1		*HEADLAMP LOWER BRACKET RH	Bent	29.10 FL	*29.10 FL
3	1		*RADIATOR GRILLE	Not Necessary	84.60 FL	*- FL
4	1		*RADIATOR GRILLE CHROME MOULDING	Not Necessary	182.40 FL	*- FL
5	1		*RADIATOR GRILLE H LOGO	Not Necessary	23.40 FL	*- FL
6	1		*FRONT BUMPER	Torn	638.00 FL	*638.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	218.80 FL	*218.80 FL
8	2		*FRONT BUMPER RETAINER RH & LH	Broken	24.40 FL	*24.40 FL
9	10		*FRONT BUMPER CLIPS	Necessary	39.00 FL	*30.00 FL
10	1		*FOG LAMP RH (NPA)	Not Necessary	0.00 FL	*- FL
11	1		*FOG LAMP GARNISH RH (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*FRONT FENDER RH	Dented	537.50 FL	*537.50 FL
13	1		*FRONT FENDER COWLING RH	Not Necessary	94.80 FL	*- FL
14	10		*FRONT FENDER COWLING CLIPS	Not Necessary	35.00 FL	*- FL
15	10		*TOP GARNISH CLIPS	Not Necessary	39.00 FL	*- FL
16	1		*TOP GARNISH	Not Necessary	65.70 FL	*- FL
17	1		*FRONT NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	2,972.70	2,268.20
- List Item Discount on L Items 20.00/20.00% (S\$)	586.54	453.64
Total Parts (S\$)	2,386.16	1,814.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN SUPPORT PANEL, FRONT FENDER RH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION.	New	500.00	400.00
2	SPRAY PAINT FRONT FENDER RH, SUPPORT PANEL, FRONT BUMPER.	New	550.00	400.00
3	CHECK WIRING AND FOCUS HEADLIGHT.	New	30.00	30.00
Gross Labour Cost (\$\$)			1,080.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >