

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672


Date Generated : 26/03/2019
User ID : ZhiYangPhua

Section A - Accident Details				
Registration Number	SHD6130C			
Case Reference Number	TAX/03/19/2100			
Registration Date	6/5/2016			
Company Type	SMRT Taxis Pte Ltd			
Make	TOYOTA			
Model	PRIUS			
Name of Driver	LIM POO LEP			
Type of Accident	Head to Rear			
Accident Date and Time	20/3/2019 12:05 PM			
Accident Reported Date and Time	21/3/2019 9:28 AM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle Issued?	No			
Job Card Number	24100691			
Special Instruction to ARC, if any	TP			
Prepared Date and Time	21/3/2019 2:04 PM			
Chassis Number				
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	pair Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$338.00	\$200.00			
Total Spray Cost	\$558.00	\$200.00			
Total Spare Part Cost	\$1,475.24	\$476.03			
Total Other Cost	\$260.00	\$40.00			
TOTAL COST	\$2,631.24	\$916.03			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	3.0	2.0			
Prepared / Adjusted By	Tuck Foo Kok	Hwee jie			
ARC / Surveyor Sign Off Date	21/03/2019 2:18 PM	22/03/2019 2:50 PM			
Signature	a	0			
Remarks		P/P REPAIR,PHOTO BEFORE PAINT.			

Section	on C - Quotation and Accident Invoice Details	
Quotation Number	Invoice Number	
Quotation Date	Invoice Date	
Invoice Amount	Prepared Date	





Toyota Prius



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 26/03/2019

User ID : ZhiYangPhua

			Sectio	n D - Detai	ls of Repair Es	timates			
art 1 - Labour	Works								
Job Scope			Quotation fro	m AR		1	Adjusted by Surveyor, if applicable		
TO REPAIR REAR PORTION			\$338.00				\$200.00		
otal Labour	RPORTION			***************************************				\$200.00	
A Per Central Const	Deletine 9 Day	nel Beating Relate	ed Works						
Part 2 - Spray	Painting & Pai	let beautily Relate						Adjusted by Surveyor	if applicable
Job Scope			Quotation from ARC						
TO RESPRAY R	EAR BUMPER			\$378.00				\$200.00	
TO RESPRAY B				\$180.00				\$0.00	
Total Spray Pai	nting & Panel B	eating		\$558.00				\$200.00	
Part 3 - Other	Costs - Accide	nt and Accident	Repair Related Expens	е	A PROPERTY.				Manuffeeble
Job Scope			Same Consult	Quotation fro	om ARC			Adjusted by Surveyor	, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION				\$80.00				\$20.00	
		SENSOR SYSTEM	А	\$120.00				\$20.00	
		02,100,10,0		\$60.00				\$0.00	
TO WASH AND VACUUM Total Other Costs				\$260.00				\$40.00	
	Parts / Materia	al lisane							
Part Number	Portion		Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
r are realined.		22/22 /7005	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52159- 47905 52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023- 12240	BUMPER	0.00	\$205.70	0.00	\$0.00	Replace	Check
		32020 12240	REINFORCEMENT						
		52016- 47030	ARM SUB-ASSY, RR	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015- 47050	BUMPER LH ARM SUB-ASSY, RR	0.00	\$139.60	0.00	\$0.00	Replace	Check
		32013-47030	BUMPER RH		0457.40	0.00	\$0.00	Replace	Check
		89997- 30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00			
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace Not Given
		76891- 47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
		52576- 47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	
		52575- 47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
			RETAINER RIVINT		\$1,761.01		\$476.03		
Tabl	_								
Total	Parte / Materi	al Usage After Si	urveyor Signed off	Teleponia.			Marie II		
1.0000	Parts / Materi	al Usage After Su	urveyor Signed off	Quantity	List Price \$	Discount (%)	Final Price (\$	ARC Check	Surveyor Check

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: