

22/03/2019

ASS. REC. BY:

REF: CS3/C7119005438/1cd357

Special Instruction:

Surveyor: Hwei Jie

## ASSIGNMENT (Office)

Minimun

From (Person): Elaine Cheong

of CTI

Date/Time: 26.3.2019 16:42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 7530R

Insured: GBE 2485X

at Workshop m/s Oscarma Global Automotive

Tel: 9117 0086

of 71 Woodland Avenue 10 #02-07

Policy No: DMCVSN 4275318011

Claim No: SNM19D201309102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20.3.2019

CA / REV / REP. / REV 24 HRS

"WP"

(After lunch)

H.O.D. Endorsement:

Date/Time: 27.3.19 9.50am

Person Contacted:

Xiao Xiang

Vehicle (IN) OUT

| Date/Time | Action/Instruction   | Estimate (X) |
|-----------|----------------------|--------------|
|           | SMD 7530 R - X       |              |
|           | GBE 2485 - X         |              |
|           | Dismantle: 28/3/2019 |              |
|           |                      |              |
|           |                      |              |
|           |                      |              |

Surveyor Huei Jie

## ASSIGNMENT

From: \_\_\_\_\_ Date: 27.3.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMD 7530Rat Workshop m/s Oscarma Global Automotiveof 71 Woodland Ave 10 #02-07

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: After lunch

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"WP"

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMD 7530R Yr Regn: 31 Aug 2018Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 12844 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BN24A8J0242364Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/3/19

Survey held at

OscarmaDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/3/19

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

Range: \$3000 - \$4000  
4 days.

RECEIVED 03 APR 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 25 Mar 2019 |               | 26 Mar 2019<br>16:42<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

LEOW YU WOEI, ID: S7115061E

Vehicle Reg. No.:

SMD7530R

Date of Loss:

20/03/2019 14:00 - :59

Claim Type:

TP / SNM19D201309C02

Policy/Cover Note No.:

DMCVSN17275318011

Vehicle Reg. No. (Insured):

GBE2485X

Policy No. (Claimant):

1800103958

Excess:

S\$450.00

Repairer:

Oscarma Global Automotive (HQ) 71 Woodlands Avenue 10, #02-07 Woodlands Industrial Xchange, 737743 Woodlands - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2019]

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The later acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving purposes. Copies of this report will, for a fee, be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report: 21/03/2019 16:19  
Date Of Accident: 20/03/2019 14:35  
Exact Location Of Accident: JALAN AHMAD IBRAHIM TOWARDS TUAS  
Country/State Of Loss: SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number: SMD7530R  
**Insured/Policyholder**  
Name Of Registered Owner: LEOW YU WOEI  
NRIC No: S7115061E  
Email Address: YOJANJAN@YAHOO.COM  
Mobile Phone No: (LOCAL) +65-97990679  
Alternative Phone No: OFFICE-97990679  
**Vehicle Particulars**  
Manufacturer: MAZDA  
Model: 3-1.5 DELUXE SKYACTIV HB (A)  
Exact Purpose for which vehicle was being used at time of accident: PRIVATE USE  
Are you claiming under your own insurance policy for repair of your vehicle? NO  
If No, Please state action to be taken: THIRD PARTY  
Vehicle Category: PRIVATE CAR  
**Insurance Company**  
Name of Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.  
Type Of Coverage: COMPREHENSIVE  
Fleet Policy: NO  
Policy Number: 1800103958  
Cover Note Number:  
**Driver**  
Name of Driver: LEOW YU WOEI  
NRIC No: S7115061E  
Date Of Birth: 29/04/1971  
Occupation: INDOOR  
Date Of Driving Pass: 11/10/2005  
Driving Experience: 13 YEARS AND 5 MONTHS  
Gender: FEMALE  
Mobile Number: (LOCAL) +65-97990679  
Fax Number:  
Contact Number: OFFICE-97990679  
Email Address: YOJANJAN@YAHOO.COM

|                                                     |                                |
|-----------------------------------------------------|--------------------------------|
| Address:                                            | 85 PHENG GECK AVENUE<br>#17-11 |
| Postcode:                                           | 348271                         |
| Was driver an employee of the Insured's Company     | NO                             |
| If No, Relationship of the Driver with the Insured  | OWNER                          |
| Vehicle Registration Number of Driver's Own Vehicle | -                              |
| Insurance Company of Driver's Own Vehicle           | -                              |

#### General Information of the Accident

|                    |                               |
|--------------------|-------------------------------|
| Type Of Accident   | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR                         |
| Road Surface       | DRY                           |

#### Other Information

|                                                                                           |     |
|-------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                        | NO  |
| Number of vehicles (including own vehicle) involved in accident                           | 2   |
| Was anyone injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                        |     |
| Was any other material or property damaged?                                               | YES |
| I have been approached by unknown person(s) soliciting for my accident claims assistance. | NO  |
| Number of passengers (Including Driver)                                                   | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes Please state which Police Station  |    |
| Was notice of Intended Prosecution given? | NO |
| If Yes, agency whom?                      |    |

#### Circumstances of Accident

ON 20/3/2015 2:35 PM, I WAS TRAVELLING ON LANE 1 ON JALAN AHMAD IBRAHIM TOWARDS TUAS. WHILE DRIVING, GBE 2485X MOVED FROM LANE 2 TO LANE 1 AND SIDE SWIPED MY VEHICLE SMD 7530 R WHEN I WAS ALONGSIDE. I WAS UNABLE TO STOP AND I WAS ENTERING THE SLIPS ROAD WHICH LEADS TO AVE (TOWARDS TUAS) AND IT IS NOT ALLOWED TO STOP THERE. I WAS THEREFORE UNABLE TO TAKE PICTURE & THE ACCIDENT SCENE OR EXCHANGE PARTICULARS WITH DRIVER GBE 7530 R. HOWEVER, I HAVE FRONT AND REAR CAMERA WHICH CAPTURED THE INCIDENT. THE WEATHER WAS CLEAR AND THE ROAD WAS DRY

#### Attachment(s)

|                                             |     |
|---------------------------------------------|-----|
| Are good photos available for attachment?   | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded?               | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1


|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | GBE2485X           |
| Vehicle Make/Model/Colour   |                    |
| Details Of Properties       |                    |
| Vehicle Category            | COMMERCIAL VEHICLE |
| Name of Owner               |                    |
| NRIC/Passport Number        |                    |
| Contact Number              |                    |
| Address                     |                    |
| Postcode                    |                    |
| Insurance Company Name      |                    |

100  
100  
100

Nature Of Damage  
No. Of Passenger (including Driver)

# Sketch Plan

SKETCH PLAN



## 1. CIRCUMSTANCES OF THE ACCIDENT

On 20/02/2019 at 2:55 pm, I was travelling in Lane 1 on Jalan Ahmad Ibrahim towards Tuas while driving. CIBE 2465Y moved from Lane 2 to Lane 1 and CIBE 2465Y collided my vehicle SMD7530R. I was driving along the road. I was unable to stop as I was driving fast and while I was in AVE (towards Tuas) and it is not allowed to stop there. I was therefore unable to take picture of the accident. I only managed to take picture with my phone. I have attached the rear camera which captured the accident. The weather was clear and road was dry.

## 2. DECLARATION

I declare the foregoing particulars are true in every respect.

Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name

NRIC/ID No.



## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Report correctly the details of the accident to speed up the claims process.
2. Form must be completed by the Policyholder and/or the Authorised Driver.
3. Report provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. Insurance acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. The reporting may be referred to the Police for investigation.
6. Report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by third parties.
7. Submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of report being made available aforesaid.
8. Under the Personal Data Protection Act (PDPA)
  - a. I understand, acknowledge, agree and consent that:
    - i. Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
      - i. processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - ii. investigating the accident and/or my claims;
      - iii. carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - iv. administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
      - v. complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
    - ii. Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - iii. Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
    - iv. Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
    - v. Information so collected under (d) above may be shared / disclosed:
      - i. to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, investigations, law enforcement and government agencies as reasonably required for the purposes stated, or
      - ii. complying with requirements under any regulations, laws or court orders

Signature

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                    |
|-------------------------------------|------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                    |
| Owner ID Type:                      | Singapore NRIC                     |
| Owner ID:                           | 5061E                              |
| <b>Vehicle Details</b>              |                                    |
| Vehicle No.:                        | SMD7530R                           |
| Vehicle to be Exported:             | No                                 |
| Intended Deregistration Date:       | 28 Mar 2019                        |
| Vehicle Make:                       | MAZDA                              |
| Vehicle Model:                      | MAZDA3 HATCHBACK 1.5 AT DELUXE EU6 |
| Primary Colour:                     | Blue                               |
| Manufacturing Year:                 | 2018                               |
| Engine No.:                         | P520537395                         |
| Chassis No.:                        | JM6BN24A8J0242364                  |
| Maximum Power Output:               | 88.0 kW (118 bhp)                  |
| Open Market Value:                  | \$18,294.00                        |
| Original Registration Date:         | 31 Aug 2018                        |
| First Registration Date:            | 31 Aug 2018                        |
| Transfer Count:                     | 0                                  |
| Actual ARF Paid:                    | \$18,294.00                        |
| <b>Intended PARF Rebate Details</b> |                                    |
| PARF Eligibility:                   | Yes                                |
| PARF Eligibility Expiry Date:       | 30 Aug 2028                        |
| PARF Rebate Amount:                 | \$13,720.00                        |
| <b>Intended COE Rebate Details</b>  |                                    |
| COE Expiry Date:                    | 30 Aug 2028                        |
| COE Category:                       | E - Open - all except motorcycle   |
| COE Period(Years):                  | 10                                 |
| QP Paid:                            | \$32,809.00                        |
| COE Rebate Amount:                  | \$30,809.00                        |
| <b>Total Rebate Amount:</b>         | <b>\$44,529.00</b>                 |

The information contained herein is correct as at 28 Mar 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |                                                   |                                                  |                                            |            |                                                                 |
|--------------------------|-------------|---------------|---------------------------------------------------|--------------------------------------------------|--------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                                      | Adj Rpt                                          | Adj Submitted                              | Ins Auth'd | Status                                                          |
| Main                     | 25 Mar 2019 |               | 26 Mar 2019 16:42<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |                                                                                                                                |                        |                                                                             |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|
| Insured:                    | -, Co. Reg. No.: -                                                                                                             |                        |                                                                             |
| Main Claimant:              | <b>LEOW YU WOEL</b> , ID: S7115061E                                                                                            |                        |                                                                             |
| Vehicle Reg. No.:           | <b>SMD7530R</b>                                                                                                                | Date of Loss:          | 20/03/2019 14:00 - :59<br>[6 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / SNM19D201309C02</b>                                                                                                    | Policy/Cover Note No.: | DMCVSN17275318011                                                           |
| Vehicle Reg. No. (Insured): | <b>GBE2485X</b>                                                                                                                | Policy No. (Claimant): | 1800103958                                                                  |
|                             |                                                                                                                                | Excess:                | S\$450.00                                                                   |
| Repairer:                   | <b>Oscarma Global Automotive (HQ)</b> 71 Woodlands Avenue 10, #02-07 Woodlands Industrial Xchange, 737743 Woodlands - Tel:     |                        |                                                                             |
| Handling Insurer:           | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]              |                        |                                                                             |
| Claimant's Insurer:         | <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000                                                           |                        |                                                                             |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 04/04/2019] |                        |                                                                             |

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.



## Claim Documents

**\*SMD7530R (SNM19D201309C02)**  
**[GBE2485X]**

**TP**

**LEOW YU WOEI**

**Mar 20 2019 2:00PM**

**[-]**

**Oscarma Global Automotive**

| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> |                 |                                                                  | <b>View</b> <a href="#">View in Browser</a> |                                     |
|---------------------------------------------------------------------------------------------------|-----------------|------------------------------------------------------------------|---------------------------------------------|-------------------------------------|
| <b>Video</b>                                                                                      |                 |                                                                  | 1 per page                                  | <input checked="" type="checkbox"/> |
| No                                                                                                | Finalized On    | Premium Autocare Centre (Benoi)                                  | Thumbnail                                   | Print                               |
| 1                                                                                                 | 21/03/19 17:29  | <b>Video - Accident</b><br>[Linked Accident Report Documents]    | Load MP4                                    | <input type="checkbox"/>            |
| 2                                                                                                 | 21/03/19 17:30  | <b>Video - Accident</b><br>[Linked Accident Report Documents]    | Load MP4                                    | <input type="checkbox"/>            |
|                                                                                                   |                 |                                                                  |                                             |                                     |
| <b>Assessment Reports</b>                                                                         |                 |                                                                  | 1 per page                                  | <input checked="" type="checkbox"/> |
| No                                                                                                | Finalized On    | Premium Autocare Centre (Benoi)                                  | Thumbnail                                   | Print                               |
| 1                                                                                                 | 21/03/19 17:32  | <b>Accident Statement</b>                                        | Load HTM                                    | <input type="checkbox"/>            |
|                                                                                                   |                 |                                                                  |                                             |                                     |
| <b>Photos/Images</b>                                                                              |                 |                                                                  | 3 per page                                  | <input checked="" type="checkbox"/> |
| No                                                                                                | Finalized On    | Premium Autocare Centre (Benoi)                                  | Thumbnail                                   | Print                               |
| 1                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 2                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 3                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 4                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 5                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 6                                                                                                 | 21/03/19 17:08  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 7                                                                                                 | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 8                                                                                                 | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 9                                                                                                 | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 10                                                                                                | 21/03/19 17:09  | <b>Identification Card</b><br>[Linked Accident Report Documents] | Load JPG                                    | <input checked="" type="checkbox"/> |
| 11                                                                                                | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 12                                                                                                | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 13                                                                                                | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| 14                                                                                                | 21/03/19 17:09  | <b>Accident Photo</b><br>[Linked Accident Report Documents]      | Load JPG                                    | <input checked="" type="checkbox"/> |
| No                                                                                                | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                | Thumbnail                                   | Print                               |
| 1                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 2                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 3                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 4                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 5                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 6                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |
| 7                                                                                                 | 28/03/19 11:31  | <b>General View</b>                                              | Load JPG                                    | <input checked="" type="checkbox"/> |

| Video |                |                                 | 1 per page ▾                                                                                   | <input checked="" type="checkbox"/> |
|-------|----------------|---------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Premium Autocare Centre (Benoi) | Thumbnail                                                                                      | Print                               |
| 8     | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 9     | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 10    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 11    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 12    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 13    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 14    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 15    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 16    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 17    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 18    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 19    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 20    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 21    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 22    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 23    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 24    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 25    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 26    | 28/03/19 11:31 | General View                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 27    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 28    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 29    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 30    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 31    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 32    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 33    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 34    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 35    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 36    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 37    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 38    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 39    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 40    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 41    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 42    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 43    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 44    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 45    | 29/03/19 09:30 | Dismantled Parts                |  Load JPG | <input checked="" type="checkbox"/> |
| 46    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 47    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 48    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 49    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 50    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 51    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 52    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 53    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 54    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |
| 55    | 08/04/19 09:38 | Photo After Spray               |  Load JPG | <input checked="" type="checkbox"/> |

| Video         |                |                                                      | 1 per page ▼ | ✓     |
|---------------|----------------|------------------------------------------------------|--------------|-------|
| No            | Finalized On   | Premium Autocare Centre (Benoi)                      | Thumbnail    | Print |
| 56            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| 57            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| 58            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| 59            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| 60            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| 61            | 08/04/19 09:38 | Photo After Spray                                    | 1 Load JPG   | ✓     |
| Documentation |                |                                                      | 1 per page ▼ | ✓     |
| No            | Finalized On   | China Taiping Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail    | Print |
| 1             | 26/03/19 16:42 | PRS - SMD7530R                                       | 1 Load PDF   |       |
| No            | Finalized On   | Premium Autocare Centre (Benoi)                      | Thumbnail    | Print |
| 1             | 21/03/19 16:55 | Sketch Plan<br>[Linked Accident Report Documents]    | 1 Load JPG   | ✓     |
| 2             | 21/03/19 16:55 | Sketch Plan #2<br>[Linked Accident Report Documents] | 1 Load JPG   | ✓     |

## Linked Accident Report Documents

| Video              |                |                                 | 1 per page ▼ | ✓     |
|--------------------|----------------|---------------------------------|--------------|-------|
| No                 | Finalized On   | Premium Autocare Centre (Benoi) | Thumbnail    | Print |
| 1                  | 21/03/19 17:29 | Video - Accident                | 1 Load MP4   |       |
| 2                  | 21/03/19 17:30 | Video - Accident                | 1 Load MP4   |       |
| Assessment Reports |                |                                 | 1 per page ▼ | ✓     |
| No                 | Finalized On   | Premium Autocare Centre (Benoi) | Thumbnail    | Print |
| 1                  | 21/03/19 17:32 | Accident Statement              | 1 Load HTM   |       |
| Photos/Images      |                |                                 | 3 per page ▼ | ✓     |
| No                 | Finalized On   | Premium Autocare Centre (Benoi) | Thumbnail    | Print |
| 1                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 2                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 3                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 4                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 5                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 6                  | 21/03/19 17:08 | Accident Photo                  | 1 Load JPG   | ✓     |
| 7                  | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 8                  | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 9                  | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 10                 | 21/03/19 17:09 | Identification Card             | 1 Load JPG   | ✓     |
| 11                 | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 12                 | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 13                 | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| 14                 | 21/03/19 17:09 | Accident Photo                  | 1 Load JPG   | ✓     |
| Documentation      |                |                                 | 1 per page ▼ | ✓     |
| No                 | Finalized On   | Premium Autocare Centre (Benoi) | Thumbnail    | Print |
| 1                  | 21/03/19 16:55 | Sketch Plan                     | 1 Load JPG   | ✓     |
| 2                  | 21/03/19 16:55 | Sketch Plan #2                  | 1 Load JPG   | ✓     |

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19005438/JCD3S2  
Date: 09/04/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN17275318011

Claimant Vehicle No: SMD7530R Insured Vehicle No: GBE2485X

Date of Loss: 20/03/2019 Nature of Claim: TP Claim No: SNM19D201309C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMD7530R

Make & Model: MAZDA 3, 1.5 Deluxe SkyActiv HB (A) Engine No: P520537395

Reg. Date: 31/08/2018 (Man. Year: 2018) Chassis No: JM6BN24A8J0242364

Colour: Blue Odometer: 12844 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 26/03/2019

Date Inspected: 27/03/2019 Inspected At: Oscarma Global Automotive (HQ)  
71 Woodlands Avenue 10, #02-07 Woodlands  
Industrial Xchange  
Singapore 737743

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 09 Apr 2019)

**Parts:** 144      MAZDA 3 1.5 Deluxe SkyActiv HB (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMD7530R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

< END OF ESTIMATES >