

22/03/2019

ASS. REC. BY:

REF: CS/TM19005440/KLS93ⁿ²

Special Instruction:

Surveyor: KOLIN

Mehmet

ASSIGNMENT (Office)

From (Person): Pion Gan Bee Song of Tokio Marine Insurance Date/Time: 26.3.2019 11.46 a.m

Estimated Cost: Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 4583 H

Insured: SMC 443 K

at Workshop m/s Comfort Delgro Engineering

Tel: 6214 8300 (6214 8315/19)

of 59 Loyang Drive

Policy No: M7103677

Claim No: M1901959

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.3.2019

CA / REV / REP. / REV 24 HRS "wup"

H.O.D. Endorsement:

Date/Time: 27.3.19 9.46 A.m

Person Contacted: Zumari

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	(✓)
	SHA 4583 H - NS/INC 18019161/KLSbn		
	SMC - 443 K - X		

D.O.A. - 20/10/2019

Inspector: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / HS / TP RES / OD RES / EVA / INV / MY
To inspect Vehicle No: _____
at Workshop no: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____
DIAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Cum Sum: _____ % J Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA 45834 Yr Regn: 23 Dec 2016
Type: M. Car / M. Cycle / Bus / Van / Lorry / T. / Prime Mover /
Truck / Trailer or
Make: Toyota Prius cc 1798
Colour: Blue A/C: Ins / Std / NI / NA
Sp. Reading: 3 57 439 T/Radio: Ins / Std / NI / NA
Eng/No: _____
C/No: JTDKB3F9403539116
Gen. Cond: Good / FA / Poor / Burnt
Steering: Ins / Jammed / Leaked / Burnt or
Brake: Ins / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Went / NA
Front Rear
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. 25/3/19 D.O.I. 25/3/19
Survey field at C.D.G.E (Loyang)
Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooltop or
Rear w/s
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/3/19	Control P/P \$1,639.70 / 2 bps. (\$ 2,949.20 Red - 64%)

RECEIVED 28 MAR 2019

Date/Time, File Pass to? 28/03/19
1) Typist ☒ : Final Report
Date/Time, File Return to? _____

Days Of Repair: 2
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Insp (\$ _____)

Survey Fee:	
Transportation:	250
S + RS:	10
Photos:	
Other:	260

Report by: _____
\$1,639.70 P/P

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2019 09:33 Sendback Est	26 Mar 2019 09:40 S\$2,899.30	26 Mar 2019 11:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA4583H	Date of Loss:	23/03/2019 11:00 - :59 [27 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1901959	Policy/Cover Note No.:	MT103677 (Comprehensive) Coverage: 25/06/2018 - 24/06/2019						
Vehicle Reg. No. (Insured):	SMC443K	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2019]								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 07:55
Date Of Accident	23/03/2019 11:45
Exact Location Of Accident	ALONG BALMORAL RD TOWARDS STEVENS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4583H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	NG LEE KIA
NRIC No	S1317235H
Date Of Birth	31/12/1958
Occupation	OUTDOOR
Date Of Driving Pass	21/07/1981
Driving Experience	37 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96622233
Fax Number	
Contact Number	
Email Address	NGLEEKIA@HOTMAIL.COM

Address	466 14-1530 HOUGANG AVENUE 8
Postcode	530466
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MARINE PARADE NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC443K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAMIAN
NRIC/Passport Number	
Contact Number	96686824
Address	
Postcode	
Insurance Company Name	

Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1


Name NG LEE KIA
Approximate Age 60
Injuries Sustain NECK,BACK
Injured person in which vehicle? SHA4583H
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name MDM TAN
Approximate Age
Injuries Sustain HEAD PAIN
Injured person in which vehicle? SHA4583H
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Police Report Attached. (.)

T/20190324/2027

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)

Olivia Wendy

Reporting Centre Personnel's Signature
 Date

Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190324/2027

1 of 4

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20190324/2027

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/03/2019 10:06	Vide Report No.:	Station Diary No.: 27
--	------------------	--------------------------

Informant's Particulars

Name of Informant: NG LEE KIA			Address: APT BLK 466 HOUGANG AVENUE 8 #14-1530 SINGAPORE 530466	
ID Type / ID No.: NRIC NO / S1317235H			Contact No.: Home/Office: Mobile: 96622233	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 60	Date of Birth: 31/12/1958	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:	

General information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/03/2019 11:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BALMORAL ROAD STEVENS ROAD junction of balmoral road and stevens road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA4583H	taxi				Slightly Damaged	1
SMC443K	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999



T/20190324/2027

2 of 4

Report No. T/20190324/2027

CONTINUATION OF REPORT

Driver			
Name	NG LEE KIA		ID No. S1317235H
Related Vehicle	SHA4583H (taxi)		Contact No. 96622233
Hospital/Clinic	C&K Family Clinic		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	24/03/2019		Date Discharge 24/03/2019
No. of Days granted Medical Leave	07	Degree of Injury Slight	
Driver			
Name	DAMIAN		ID No. NIL
Related Vehicle	SMC443K (Car)		Contact No. 96686824
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury NIL	

Brief Details.

On 23/03/2019 at about 11am, while I was driving my taxi bearing registration number SHA4583H along the junction of Balmoral Road and Stevens Road, I was involved in a traffic accident with another car (SMC443K). During that time, I had one passenger (Mdm Tan, Hp no: 961616650) with me at the back of the taxi.

Before the collision happened, my taxi was at the said location waiting for the lights to turn green. I would like to state that my intention was to go straight towards Henderson Road. When the lights turned green, I turned my steering wheel a bit to the right as I wanted to avoid the car in front and go straight to Henderson Road. All of a sudden, I felt an impact coming from the rear of my taxi.

I was surprised and I then realised that a car had hit the rear of my taxi. I then make a check to my passenger and she told me that he was feeling some pains on his head. I then alighted from my taxi to a check. There was a dent on the center portion of my taxi rear bumper. I then exchanged particulars with the other driver. I wanted to call for the ambulance, however traffic was very heavy and I was unable to do so. The passenger told me that she will be going to see the doctor to check for her injuries.

On 24/03/2019, I went to the clinic to see the doctor as I felt some pains on the back of my neck and also my back area. I was then given 7 days of medical leave.

Sketch Plan Pg. 4



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999



T/20190324/2027

4 of 4

Report No. T/20190324/2027

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Staff Sgt MUHAMMAD FARHAN BIN
SAFARUAN

Signature Of Interpreter:

Not applicable .

Officer In Charge Of Case:

TP / AEIT /
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH





Contact No: 65476204





Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
24/03/2019 10:06

Classification Of Case:





COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA4583H

DATE: 25. Mar. 2019

MAKE : TOYOTA

MODEL : PRIUS

DOA: 23. Mar. 2019

TOKIO

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper			\$458.60
1	Rear Bumper Beam			\$318.80
1	Rear Bumper Sponge			\$143.40
10	Rear Bumper Clips		\$2.20	\$22.00
1	Rear Bumper Undercover			\$552.60
1	Rear End Panel			\$602.10
	Rear Spare Tyre Panel			\$667.70
2	Rear Bumper Side Retainer		\$112.70	\$225.40
1	Rear Exhaust			\$1,163.40
SUB TOTAL				\$4,154.00
LESS 20% 25%				\$830.80
DISCOUNTED TOTAL				\$3,323.20
1	Reverse Sensor			\$135.70
1	Rear Bumper Rubber Mat			\$50.00
Labour Charge				\$185.70
1	Panel Beating			\$500.00
1	Spray Painting Charge			\$300.00
1	Remove/refix reverse sensor			\$80.00
1	Tuff Kote			\$80.00
1	Remove/refix Rear Exhaust			\$120.00
TOTAL LABOUR				\$1,080.00
ESTIMATE TOTAL				\$4,588.90
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer
Signature:
Date:

Kahin 14/4/19
25/3/19
2 days.
PIP
After Repair phh

Larry Ng

Nett
Nett

200
200
30
X 2
X 2

COMFORTDELGRO

Date/Time: 25.03.2019 09:52 Page : 1

Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JO NO.: 305280487


CUSTOMER
COMFORT TRANSPORTATION PTE LTD VARS
7010045
CUSTOMER NO. 383 SIN MING DRIVE
ADDRESS Singapore SINGAPORE 575717
65508755
(R) (P)
SCOUT CARD NO.

REGN NO.: SHA4583H	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)	DATE/TIME IN 23.03.2019 13:05
YR OF MANUF 23.12.2016	TARGET DATE
CHASSIS CODE JTDKB3FU403539136	COMPLETION DATE/TIME

Accident Date: 23.03.2019
NATURE: 3P 23.03.2019

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
	TOKIO - Rear	
	LRR/Kalin -	



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Knowledge Slip
e:
lo.:
le No.: SHA4583H LARRY
Larry Ng
e of Service Advisor
Signature/Date
a returned to Service Reception upon collection

Exit Pass
Vehicle No.: SHA4583H
Name of Service Advisor
Date
To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg No: 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/03/2019
Vehicle Reg. No.:	SHA4583H	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	NG LEE KIA		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	23/12/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRR971576	Chassis No:	JTDKB3FU403539136
Odometer:	357439 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	SEE POLICE REPORT.		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,929.30
Miscellaneous Items	10.00
Labour	960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,899.30
+ GST 7.00% (S\$)	202.95
Nett Amount (S\$)	3,102.25

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Mar 2019)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA4583H/26/03/2019 09:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*458.60 FL CLC
2	1		*REAR BUMPER BEAM	20.00	0.00	*318.80 FL Bnt
3	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL nlc
4	1		*REAR BUMPER UNDERCOVER	20.00	0.00	*552.60 FL CLC
5	1		*REAR END PANEL	20.00	0.00	*602.10 FL Svc
6	2		*REAR BUMPER SIDE RETIANER - LH/RH	20.00	0.00	*225.40 FL Svc
7	1		*REVERSE SENSOR	0	0.00	*135.70 FS Short
8	1		*REAR BUMPER RUBBER MAT	0	0.00	*50.00 FS nlc

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,365.20
- List Item Discount on L Items (S\$)	435.90
Total Parts (S\$)	1,929.30

ComfortDelGro Engineering Pte Ltd/SHA4583H/26/03/2019 09:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	500.00 200
2	SPRAY PAINTING	New	300.00 200
3	REMOVE/REFIX REVERSE SENSOR	New	80.00 30
4	TUFF KOTE	New	80.00 00
Gross Labour Cost (S\$)			960.00

ComfortDelGro Engineering Pte Ltd/SHA4583H/26/03/2019 09:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.03.2019

Time: 10:13:45

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305280487
REGN NO : SHA4583H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 23.12.2016
DATE/TIME IN : 23.03.2019 13:05
ACCIDENT DATE : 23.03.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0002 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0003 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70		135.70
0004 04-01-0302-1150-G	PRIG4 BUMPER PROTECTOR MA	1	50.00		50.00
0005 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0006 04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10

SUB-TOTAL : 1,199.70

JOB NATURE

0000 PB	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 L	MERIMEN FEE	10.00

SUB-TOTAL : 440.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.03.2019

Time: 10:13:45

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305280487
REGN NO : SHA4583H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 23.12.2016
DATE/TIME IN : 23.03.2019 13:05
ACCIDENT DATE : 23.03.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,639.70

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305280487
Date : 26. Mar. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA4583H

Date of Accident: 23. Mar. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SMC443K
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$1,199.70
(b) Labour Charges	\$440.00
Total for Part-By-Part Repair Cost	\$1,639.70
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 27/3/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19005440/K1SD3N2

Date: 01/04/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT103677
Claimant Vehicle No :	SHA4583H	Insured Vehicle No :	SMC443K
Date of Loss:	23/03/2019	Nature of Claim:	TP
		Claim No:	M1901959

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4583H	Engine No:	2ZRR971576
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU403539136
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	357439 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,929.30	1,199.70	729.60	37.82
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	960.00	430.00	530.00	55.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,899.30	1,639.70	1,259.60	43.44
+ GST 7.00/7.00% (S\$)	202.95	114.78	88.17	43.44
Nett Amount (S\$)	3,102.25	1,754.48	1,347.77	43.44

INSPECTION

Date of Assignment:	26/03/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/03/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 01 Apr 2019)

Parts: 144 **TOYOTA PRIUS 1.8 HYBRID CVT (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA4583H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	458.60 FL	*458.60 FL
2	1		*REAR BUMPER BEAM	Bent	318.80 FL	*318.80 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER UNDERCOVER	Cracked	552.60 FL	*552.60 FL
5	1		*REAR END PANEL	Serviceable	602.10 FL	*- FL
6	2		*REAR BUMPER SIDE RETIANER - LH/RH	Serviceable	225.40 FL	*- FL
7	1		*REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
8	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,365.20	1,537.70
- List Item Discount on L Items 20.00/25.00% (\$\$)	435.90	338.00
Total Parts (\$\$)	1,929.30	1,199.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	TUFF KOTE	New	80.00	0.00
Gross Labour Cost (\$\$)			960.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >