

Hwee Jie

REF: NTUC NS/INC19064x6 13sd 302

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: FBL35267 25/09/2018
Policy No. 5103804516 24/09/2019
Claims No. MT/1036966-002
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
*	

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No. SHC4154C Yr Regn: 29 Nov 2013
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Prin c.c. 1797
Colour: Maroon A/C: Insured / Std / NI / NA
Sp. Reading: 685837 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 3TDKN36U405705957
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / SRim / STD A/Rim or _____
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or chiller
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 20/3/19 D.O.I. 25/3/19
Survey held at Sumit
Des. of Damages : Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC4154C-X
	FBL3526T-X
	03/19/2097
	FBL3526T
	GBF6446C
26/4/19	Confirmed L/s \$1850/- 4days.
	(\$5,442.51 Red - 75%)

RECEIVED 26 APR 2019

Date/Time, File Pass to? 26/04/19
1) Typ 34 ☐ : Preli. Report ☒ : Final Report
Date/Time, File Return to? _____
2) _____
Report Format : _____
Lump Sum / I.B.I. (\$) 1,850/- 4s
Days Of Repair: 4
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)
Survey Fee: 160
Transportation: _____
Photos: _____
Others: _____

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5103804516		NETTO DAMIAN GEORGE	S8741965G	GMC	Third Party	FBL3526T	FBL3526T	25/09/2018	24/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1027118-003	SMRT TAXIS	SHB 1991C	GBG 9343R
2	MT/1036966-002	SMRT TAXIS	SHC 4154C	FBL 3526T
3	MT/1034441-002	SMRT BUS	SG5757E	SJA 4511S
4	MT/1041502-002	COMFORT TRANSPORTATION PTE LTD	SHC 3387D	PA 786X
5	MT/1040396-002	COMFORT TRANSPORTATION PTE LTD	SH7087L	SGR 5464J
6	MT/1041321-002	COMFORT TRANSPORTATION PTE LTD	SHC 3540C	SLC 6469J
7	MT/1041433-002	COMFORT TRANSPORTATION PTE LTD	SHD 4981B	SJU 9496P
8	MT/1041156-002	COMFORT TRANSPORTATION PTE LTD	SHB 4050Z	SLU 2212P
9	MT/1041766-002	COMFORT TRANSPORTATION PTE LTD	SH 9151X	XE 499J
10	MT/1041821-002	COMFORT TRANSPORTATION PTE LTD	SHC 3607U	SLT 2910M

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 26 April 2019 10:02 AM
To: Hwee Jie (LKK Auto)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHC4154C

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Hwee Jie (LKK Auto) [mailto:hweejie@lkkauto.com]
Sent: Friday, 26 April 2019 9:38 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHC4154C

Hi poh suan,

Finalized L/S \$1,850/- 4days.

Best Regards,
Hwee Jie | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 23 April, 2019 11:00 AM
To: Hwee Jie (LKK Auto)
Cc: SUR; CS A Team; 'Leong Chee kwong'; 'EE SIN GUAN'
Subject: SHC4154C

Hi Hwee Jie,

Attached herewith the repair estimate of SHC 4154C having Case No: TAX/03/19/2097.

There is no change to the approved amount of \$1,850 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Tuesday, 23 April 2019 10:45 AM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 15:29
Date Of Accident	20/03/2019 14:10
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4154C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	SHARIFAH RUGAIAH BTE JUNIED AL-JUNIED
NRIC No	S0205602Z
Date Of Birth	10/04/1953
Occupation	OUTDOOR
Date Of Driving Pass	23/05/1979
Driving Experience	39 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : UNKNOWN CHINESE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBANWANG NPC
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190321/2015 ON 20/03/2019 AT ABOUT 1410HRS, I WAS DRIVING MY TAXI, BEARING REGISTRATION SHC4154C, ALONG PIE 11 KM, WHEN I FELT SOMETHING HITTING MY TAXI AND ALSO I HEARD A BANG. AS SUCH, I IMMEDIATELY STOPPED MY TAXI TO MAKE A CHECK. UPON MAKING A CHECK, I DISCOVERED ONE MOTORCYCLE OF UNKNOWN REGISTRATION NUMBER HAD HIT INTO THE LEFT SIDE OF MY TAXI. I APPROACHED THE RIDER TO ASKED WHAT HAPPENED, ONLY TO BE A APPROACHED BY ANOTHER DRIVER WHO INFORMED ME THAT IT WAS NOT THE RIDER'S FAULT. THE DRIVER INFORMED ME THAT THE LORRY, BEARING REGISTRATION NUMBER GBF6446C, HAD ONE OF ITS REAR DOOR OPENED AND AS SUCH, THE MOTORCYCLE WAS EITHER TRYING TO AVOID IT OR WAS HIT BY THE OPENED DOOR. NEITHER MY PASSENGER OR MYSELF SUSTAINED ANY INJURIES. THE DAMAGES TO MY TAXI ARE SCRATCHES AND DENT ON THE REAR LEFT SIDE. THE RIDER WAS CONVEYED TO HOSPITAL. MY TAXI IS FIXED WITH AN IN-CAR CAMERA. I HAD ALREADY HANDED OVER THE MEMORY CARD TO TRAFFIC POLICE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL3526T
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBF6446C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBL3526T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

B 20-3-19
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 20/3/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190321/2015

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20190321/2015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/03/2019 10:04	Vide Report No.: G/20190320/0117	Station Diary No.: 35
--------------------------------------------	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: SHARIFAH RUGAIAH BTE JUNIED AL-JUNIED			Address: APT BLK 424 CANBERRA ROAD #06-461 SINGAPORE 750424	
ID Type / ID No.: NRIC NO / S0205602Z			Contact No.: Home/Office: Mobile: 96807588	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 65	Date of Birth: 10/04/1953	Type of Informant: Driver	
Race: Arab			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2019 14:10	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Towards Tuas, 11km				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF6446C	Lorry	TOYOTA				0
SHC4154C	Taxi	TOYOTA	Prius Hybrid	Maroon	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE
POLICE FORCE**



T/20190321/2015

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

2 of 3

Report No. T/20190321/2015

CONTINUATION OF REPORT

Driver			
Name	SHARIFAH RUGAIAH BTE JUNIED AL-JUNIED		ID No. S0205602Z
Related Vehicle	NIL		Contact No. 96807588
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/03/2019 at about 1410hrs, I was driving my taxi, bearing registration SHC4154C, along PIE 11KM, when I felt something hitting my taxi and also I heard a bang. As such, I immediately stopped my taxi to make a check.

Upon making a check, I discovered one motorcycle of unknown registration number had hit onto the left side of my taxi. I approached the rider to asked what had happened, only to be approached by another driver who informed me that it was not the rider's fault. The driver informed me that the lorry, bearing registration number GBF6446C, had one of its rear door opened and as such, the motorcycle was either trying to avoid it or was hit by the opened door. Neither my passenger or myself sustained any injuries. The damages to my taxi are scratches and dent on the rear left side. The rider was conveyed to hospital.

My taxi is fixed with an in-car camera. I had already handed over the memory card to Traffic Police.



**SINGAPORE
POLICE FORCE**



T/20190321/2015

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20190321/2015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: L / Staff Sgt FATIN AZRIN BINTE AHAD	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/03/2019 10:04
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Contact No.:	
Authentication Stamp NP168	Signature:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4154C
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR1389493
Chassis No.:	JTDKN36U405705957
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	29 Nov 2013
First Registration Date:	29 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2021
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$63,297.00
COE Rebate Amount:	\$21,142.00
Total Rebate Amount:	\$26,999.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Mar 2019

OK



Case Details

Case Reference Number : TAX/03/19/2097
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4154C

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6215-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name :
 Accident Date and Time : 20/03/2019 06:10 AM
 Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair ▾	R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace ▾	BUC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	nec
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair ▾	R
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	R

Total Spare Part Cost 4,494.39

Surveyor Total 865.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,595.51

Final Sur Total 692.22

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾	nee
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾	nee
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▾	12
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▾	nn
Total Spare Part Cost									4,494.39	Surveyor Total		865.28		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,595.51	Final Sur Total		692.22		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	845.00	600	
Total:			845.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
2	Main	TO REPSRAY REAR DOOR LH	378.00	200	
3	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
4	Main	TO RESPRAY REAR FENDER LH	378.00	200	
Total:			1,692.00	700.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,692.00	700.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TRANSFER DOOR MECHANISM	240.00	50	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
4	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0	
5	Main	TO REMOVE / REFIT SEAT	120.00	0	
6	Main	TO REMOVE AND REFIT TYRE	120.00	0	
7	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
8	Main	TO WASH AND VACUUM	60.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			1,160.00	120.00	

Summary

9565.14

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,595.51	692.22
Total Labour Cost	845.00	600.00
Total Spray Painting	1,692.00	700.00
Other	1,160.00	120.00
Overall Total	7,292.51	2,112.22
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	7,300.00	2,100.00
Surveyor Approved Amount		2,100.00

Estimator Assesment(\$)

5

Surveyor Assesment(\$)

4

No of Repair Days*

Remarks

L/S REPAIR, PHOTO AFTER PAINT

Surveyor Name

Hwee jie

Signature

Save Clear

Survey Date

25/03/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4154C
Case Reference Number	TAX/03/19/2097
Registration Date	29/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SHARIFAH RUGAIAH BTE JUNIED AL-JUNIED
Type of Accident	Side Swipe
Accident Date and Time	20/3/2019 2:10 PM
Accident Reported Date and Time	20/3/2019 4:20 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100732
Special Instruction to ARC, if any	TP / NTUC - LKK
Prepared Date and Time	25/3/2019 10:33 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,692.00	\$700.00
Total Spare Part Cost	\$3,595.51	\$865.28
Total Other Cost	\$1,160.00	(\$315.28)
TOTAL COST	\$7,292.51	\$1,850.00 (L/S)
Lump Sum Total	\$7,300.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	25/03/2019 2:20 PM	25/03/2019 2:00 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER PAINT	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0284	Invoice Number	
Quotation Date	22.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,692.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$435.28)
Total Other Costs	\$1,160.00	(\$315.28)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair YL
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X un
		67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given X un
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X un
		67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair R

	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓
		STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	✓
	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X
Total				\$5,808.14		\$865.28			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 865.28 \\
 + 600.00 \\
 + 820.00 \\
 \hline
 2285.28 \\
 - 20\% \\
 \hline
 1828.22 \\
 \hline
 45 \$1850/-
 \end{array}$$

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC19005446/Jsd3e2	
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 08-05-2019	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBL 3526T	Veh. Inspected	SHC 4154C
Policy No.	5103804516	Coverage (\$)	0.00
Claim No.	MT/1036966-002	Excess (\$)	0.00
Assign From		Assign Date	25/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U405705957	Colour	MAROON
Odometer	685837	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	CHILLES	6 mm
L/H Front Tyre	195/65 R15	CHILLES	6 mm
R/H Rear Tyre	195/65 R15	CHILLES	6 mm
L/H Rear Tyre	195/65 R15	CHILLES	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/03/2019	Inspection Date	25/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4154C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR RR/LH (DISC 25%)	BUCKLED	954.50	715.88
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	TYRE	NOT NECESSARY	126.74	-
1	DOOR FRT / LH	NOT NECESSARY	894.40	-
1	STICKER DECAL SMRT (DOOR)	NOT NECESSARY	60.00	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,484.20	-
1	MOULDING BODY, LH	TO REPAIR SEE LABOUR	673.60	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			5,868.14	865.28
<u>LABOUR</u>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC, MOULDING BODY, LH, FENDER RR/LH AND BUMPER REAR.			845.00	600.00
SPRAY PAINT.			1,692.00	700.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO TRANSFER DOOR MECHANISM.			240.00	50.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			200.00	20.00
TO REMOVE & REFIT REAR QUARTER GLASS LH.		NOT NECESSARY	120.00	-
TO REMOVE / REFIT SEAT.		NOT NECESSARY	120.00	-
TO REMOVE AND REFIT TYRE.		NOT NECESSARY	120.00	-
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).			120.00	30.00

Report Ref No. NS/INC19005446/Jsd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,697.00	1,420.00
GRAND TOTAL			9,565.14	2,285.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,850.00

Report Ref No. NS/INC19005446/Jsd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.