



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE19005458/Uha3s2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 23-04-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 664E	Veh. Inspected	SGS 2421Y
Policy No.	8-V0012352-MVA-R003	Coverage (\$)	0.00
Claim No.	VC012439	Excess (\$)	0.00
Assign From	JENNY TOH	Assign Date	27/03/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	GD12383529	Colour	GREY
Odometer	147658	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	MICHELIN	6 mm
L/H Front Tyre	195/55 R15	MICHELIN	6 mm
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/03/2019	Inspection Date	27/03/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------