

INS. CASE OWNER:

CC 3, CTI 1900 5488, P1ha3

LKK:

IDAC:

Surveyor:

Amc

DOI:

ASSIGNMENT

26/3/19

Date / Time:

26/3/19

Registered in Merimen:

Pre-assign / CCU / FTE

SGJ 6065



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A:

26/3/2019

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHD 6676 U



INSRS:

WSP:

Tel :

Liability :

RMKS:

WSP
WSP

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SHD 6676 U - 15/12/18 to 24/12/18; WSP 10/11/18
 - 15/12/18 to 24/12/18; WSP 18/12/18
 SHD 6065 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/HS/TP RES/OD RES/EVA/INV/RV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Insp (\$ _____)

☐ : _____ (\$ _____)

Survey Fee: _____

Transportation: _____

_____ \$ + \$S \$

Photos _____

Other _____

Veh No: SHO 66764 Yr Regn: 9 Apr, 2015

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. R. / Prime Mover /

Truck / Trailer or

Make: Hyundai Z40 C.C. 1600

Colour: Blue A/C: Insured Std / Nil / NA

Sp. Reading: 469534 T/Radio: Insured Std / Nil / NA

Eng/No: _____

C/No: KM HLBKRM F4067952

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Calson

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/3/19 D.O.I. 26/3/19

Survey held at CDGE (Loyang)

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

Pen o/s

The U/C / Chassis frame / Body Structure affected due to collision.

CT2

4.

Member of COMFORTDELGRO

Date/Time: 25.03.2019 16:24 Page : 1


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 3909039 JC NO.: 305280883

MER COMFORT TRANSPORTATION PTE LTD 7010045 MER NO. 383 SIN MING DRIVE SS Singapore SINGAPORE 575717 65508755 R) (O) P) JNT CARD NO.	REGN NO.: SHD6676U	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 24.03.2019 17:50
	YR OF MANU 09.04.2015	TARGET DATE
	CHASSIS CODE RMHLB41UMFU067952	COMPLETION DATE/TIME:

Accident Date: 24.03.2019
NATURE: 3P 24.03.18/B

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
		Towing - Normal



KEYED & PASSED OUT BY: _____

SERVICE ADVISOR _____ CUSTOMER'S SIGNATURE _____

Check-out Slip	Vehicle No.: SHD6676U	Exit Pass
	FZ CHINA	
Signature/Date	Name of Service Advisor	Date
turned to Service Reception upon collection	To be kept by Security Guard	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6676U

DATE 25/3/2019 16:45

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper end cap		\$225	
	Rear Bumper Reinforcement		\$	
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 50.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	Towing Fee (Not Accident Location)			\$ 60.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,320.00
Ka hini LKK 26/3/19 1130hr 2 Days. 4s After Repair photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without prejudice" basis • No illegal modification/repairs allowed • Supplier's liability for workmanship is subject to the approval of the insurance company				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Nett

200

200

X

20

X



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 24/03/19 Time Received: 1750 hrs		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)		4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
2. ☐ New ☐ SPARK Kakis Name of Customer: Lim Yong Seng Contact No.: 93393643 Vehicle No.: SHD 6676 U Make / Model / Colour: 140 Email:		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery		6. Parts Replaced/Remarks: Front Bumper Damaged	
7. Location: 1631 King No 20 KEEF		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi			
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:					

10. Odometer Reading : _____

Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player

☐ OK
☐ Faulty
☐ Not tested

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☒ TZ ☐ YISHUN ☐ OTHERS TOWING


Name of Driver : Nook Ann

Vehicle No. : VN 79114 K

Time Dispatch : 2300 hrs

Time of Arrival : 2310 hrs

Time Completed : _____



: Cracked X : Dented
/ : Scratched O : Missing

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COP

Our Job Ref No : 305280883
Date : 28.03.2019

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHD6676U - CTPL

Fax :
Date of Accident : 24.03.219

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SGJ 606S
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$0.00
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$1250.00


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kalvin
Date : 28/3/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: