

ASS. REC. BY:

REF: CS/C71/19005478/ Ec d302

Special Instruction:

Surveyor: STAVE

merit

ASSIGNMENT (Office)From (Person): Irene Tang Hui Ping of C71Date/Time: 27.3.19 14:01p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 485LInsured: GZ 5017Aat Workshop m/s Platinum WIRK 2of 53 Wai Ave 1 01-205Tel: 67410610/92389179Policy No: DmCVSN18/60318 000Claim No: SNM19D201326C02

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 25.3.2019

CA / REV / REP. / REV 24 HRS

"w"

H.O.D. Endorsement: _____

Date/Time: 27.3.19 4.12p.mPerson Contacted: YSVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SKH 485L - NA/INC	19005315/24
	GZ 5017A - NA/INC	19005315/24
	Diamond: 28/3/2019	
	After repair: 2/4/2019	

D.O.A. - 25.3.2019

D.O.A. - 25.3.2019

Steve

REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SKH 485L** Yr Regn: **11/12/09**
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **BMW 525** CC: **2497**
 Colour: **Black** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **133705** T/Radin: **Insured / Std / NI / NA**

Eng/No: _____
 Ci/No: **W0ANUS290EZ 88623**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **225 / 55 R 17**
 R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Pirelli**

<u>Front</u>		<u>Rear</u>	
R/Bal. 6 mm		R/Bal. 6 mm	
L/Bal. 6 mm		L/Bal. 6 mm	
D.O.I. 25/3/19		D.O.I. 27/3/19	

Survey held at Platinum
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
Rear RH

The U/C / Chassis/frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time / Action / Instruction
 Repair range **6K-7K** ... **6 days**

[Signature]
3/4/2019

Date/Time, File Pass to: : Proll. Report
 : Final Report

Days Of Repair: **6**
 Resurvey No. of Trip: **2**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: **150**
 Transportation
 : S + R: \$
 : Photos
 : Collect.
 : ...
150

Report Format: **PRE**
 Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2019		27 Mar 2019 14:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	NEW STYLE INTERIOR DECORATION , Co. Reg. No.: 52890870K								
Main Claimant:	EAZY RENTALS PTE LTD , Co. Reg. No.: 201723629E								
Vehicle Reg. No.:	SKH485L	Date of Loss:	25/03/2019 10:00 - :59 [111 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201326C02	Policy/Cover Note No.:	DMCVSN18160818000 Coverage: 23/05/2018 - 22/05/2019						
Vehicle Reg. No. (Insured):	GZ5017A	Policy No. (Claimant):	5094576865-01						
		Excess:	\$0.00						
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/04/2019]								
Driver/Custodian (Insured):	HO THIAN FOOK (57 / Male) Email:								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3629E
Vehicle Details	
Vehicle No.:	SKH485L
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	525I A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	70574276N52B25AF
Chassis No.:	WBANU52090CZ88623
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$57,660.00
Original Registration Date:	11 Dec 2009
First Registration Date:	11 Dec 2009
Transfer Count:	3
Actual ARF Paid:	\$57,660.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2019
PARF Rebate Amount:	\$28,830.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,003.00
COE Rebate Amount:	\$1,328.00
Total Rebate Amount:	\$30,158.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 17:35
Date Of Accident	25/03/2019 10:50
Exact Location Of Accident	STANLEY ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH485L
Insured/Policyholder	
Name Of Registered Owner	EAZY RENTALS PTE LTD
Co Reg No	201723629E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	BMW
Model	525I A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5094576865-01
Cover Note Number	

Driver

Name of Driver	SHARIN ARI BIN HANAFI
NRIC No	S9106195C
Date Of Birth	18/02/1991
Occupation	OUTDOOR
Date Of Driving Pass	04/11/2013
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87492116
Fax Number	
Contact Number	OFFICE-87492116
EMail Address	NOEMAIL

Address	BLK 513D YISHUN STREET 51 #08-331
Postcode	764513
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5017A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HO THIAN FOOK
NRIC/Passport Number	S2602400E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SHARIN ARI BIN HANAFI
------	-----------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

BODY

SKH485L

YES

NO

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

ALONG STANLEY S →



VEH A: SHARSL
 VEH B: SE 400
 625017A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Stanley Street and suddenly I felt an impact coming from my right. I was hit by vehicle B that was turning out from a 'small' lane, which was some time. He admitted that he hit me by accident.



DECLARATION

(All declarations and particulars are true in every respect.)

Policyholder's Name:
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Handwritten Signature]

Reporting Officer's Signature
 Name:
 NR/C/P/N No.:

[Handwritten Signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2019		27 Mar 2019 14:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NEW STYLE INTERIOR DECORATION , Co. Reg. No.: 52890870K								
Main Claimant:	EAZY RENTALS PTE LTD , Co. Reg. No.: 201723629E								
Vehicle Reg. No.:	SKH485L	Date of Loss:	25/03/2019 10:00 - :59 [111 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201326C02	Policy/Cover Note No.:	DMCVSN18160818000 Coverage: 23/05/2018 - 22/05/2019						
Vehicle Reg. No. (Insured):	GZ5017A	Policy No. (Claimant):	5094576865-01						
		Excess:	S\$0.00						
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 05/04/2019]								
Driver/Custodian (Insured):	HO THIAN FOOK (57 / Male) Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH485L (SNM19D201326C02)
 [GZ5017A]
 TP
 EAZY RENTALS PTE LTD
 Mar 25 2019 10:00AM
 [NEW STYLE INTERIOR DECORATION]
 Platinum Werkz Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Assessment Reports			1 per page <input type="button" value="v"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail Print
1	25/03/19 17:42	Accident Statement	 Load HTM <input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
2	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
3	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
4	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
5	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
6	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
7	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
8	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
9	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
10	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
11	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
12	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
13	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
14	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
15	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
16	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
17	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
18	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
19	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
20	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
21	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
22	28/03/19 07:52	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>
23	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
24	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
25	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
26	28/03/19 07:52	General View	 Load JPG <input checked="" type="checkbox"/>
27	28/03/19 18:59	Chassis Number	 Load JPG <input checked="" type="checkbox"/>
28	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
29	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
30	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
31	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
32	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
33	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>
34	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG <input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 18:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	03/04/19 17:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/19 14:00	PRS info	Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
2	27/03/19 14:00	Insd GZ5017A GIA report	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/03/19 17:42	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 17:39	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/03/19 17:39	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 17:39	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19005478/ECD3E2**Date:** 04/04/2019REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18160818000
Claimant Vehicle No :	SKH485L	Insured Vehicle No :	GZ5017A
Date of Loss:	25/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201326C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH485L	Engine No:	70574276N52B25AF
Make & Model:	BMW 525I, 2.5 (A)	Chassis No:	WBANU52090CZ88623
Reg. Date:	11/12/2009 (Man. Year: 2008)	Odometer:	133705 km
Colour:	Black		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/03/2019	
Date Inspected:	27/03/2019 Inspected At:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: 143	BMW 525I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH485L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >