

22/03/2002

ASS. REC. BY:

REF: CS3/msg19005500/Ed3024

Special Instruction:

Surveyor: Steve  
Melvin

ASSIGNMENT (Office)

From (Person): Christina Wongof MSGDate/Time: 27.3.2019 17:37 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGH 7495JInsured: SMH 5374at Workshop m/s AMG AutocareTel: 87783636of 36 Toh Guan Road East, #01-36Policy No: A28795104 MCXClaim No: 588618

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.3.2019

(After lunch go)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time: 28.3.19 9:24 AMPerson Contacted: MelvinVehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SGH 7495J - X
	SMH 5374 - X
	Dismantle: 28/3/2019
	After repair: 1/4/2019

Steve

REF: MS19

## ASSIGNMENT

From:

Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH 74954

at Workshop m/s: Ama Autocare

of 36 Toh Guan Road East, #01-36

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: After 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH 74954

Yr Regn:

21/06/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

c.t.

1797

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

380824

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2ME 109309717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GREEN-MAX

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/3/19

D.O.I.

28/3/19

Survey held at

AMA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repa large 25K-35K 4 days

Signature

3/4/2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

4

1)

☐

Final Report

Resurvey No. of Trip:

2

Survey Fee:

120

Date/Time, File Return to?

Transportation

2)

Add Fee:

☐

Site Insp (\$)

) \$ + RS \$

☐

Interview (\$)

) Photos

☐

Tech. Invs (\$)

) Others

☐

Weekend (\$)

)

Report Format:

PRE

Lump Sum / I.B.I. (\$)

TOTAL

130

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2019		27 Mar 2019 17:37 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>				
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N			
Main Claimant:	MOHAMMED SAHERAN BIN SHAM MARICAN, ID: S8530219A			
Vehicle Reg. No.:	SGH7495J	Date of Loss:	23/03/2019 18:00 - :59 [153 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 588618	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2018 - 07/08/2019	
Vehicle Reg. No. (Insured):	SMH537Y	Policy No. (Claimant):	Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/03/2019]			
Driver/Custodian (Insured):	LIAW SOON CHYE (LIAO SHUNCAI) (), NRIC: S7303953C, Tel: +6587686732 Email:			
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE list. Proceed to appoint LKK as the SJE. Contact Person: Mr Melvin / 8778 3636. On WP.			
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>				
There are no mail for this case.				
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div>				
No results.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	0219A
<b>Vehicle Details</b>	
Vehicle No.:	SGH7495J
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	1ZZ2589628
Chassis No.:	ZNE100309717
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,285.00
Original Registration Date:	21 Jun 2006
First Registration Date:	21 Jun 2006
Transfer Count:	2
Actual ARF Paid:	\$21,214.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$33,038.00
<b>Total Rebate Amount:</b>	<b>\$33,038.00</b>

The information contained herein is correct as at 28 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/03/2019 08:50
Date Of Accident	23/03/2019 18:30
Exact Location Of Accident	BLK 694 JURONG WEST CENTRAL 1 RUBBISH CHUTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGH7495J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMMED SAHERAN BIN SHAM MARICAN
NRIC No	S8530219A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81682624
Alternative Phone No	OFFICE-81682624
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S28766517 SMA
Cover Note Number	
<b>Driver</b>	
Name of Driver	MOHAMMED SAHERAN BIN SHAM MARICAN
NRIC No	S8530219A
Date Of Birth	29/08/1985
Occupation	INDOOR
Date Of Driving Pass	12/11/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81682624
Fax Number	
Contact Number	OFFICE-81682624
E-Mail Address	NOEMAIL

Address	BLK 445A BT BATOK WEST AVE 8 #03-427
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : --- GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	MR TANG
Phone Number	96897147
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH537Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIAW SOON CHYE
NRIC/Passport Number	S7303953C
Contact Number	
Address	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 15/03/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAQ BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)



# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened on 23 March 2019 at roughly around 6:30pm, at BLK 694 JURONG WEST CENTRAL 1, rubbish dump area.
Vehicle TOYOTA PRIUS SMH 537 Y reversed onto my vehicle TOYOTA WISH SGH 7495 J while I was reversing to temporarily park my vehicle along the rubbish dump area. The owner of the vehicle was stationary at the rubbish dump area and reversed out onto my vehicle without checking his rear mirror fully. My intention of parking my vehicle temporarily along the rubbish dump area was to offload heavy marketing items.
There was a witness named Mr. Tang, contact number 9689 7147, whom happened to witness the whole incident.
Owner of Toyota Prius : LIAW SOON CHYE
NRIC : S9303953 C

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time: 25/03/2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

(JAL) RUKHT PATOK (VAC)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2019		27 Mar 2019 17:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>SKYWAY MOTOR PTE LTD</b> , Co. Reg. No.: 199904194N									
Main Claimant: <b>MOHAMMED SAHERAN BIN SHAM MARICAN</b> , ID: S8530219A									
Vehicle Reg. No.: <b>SGH7495J</b>		Date of Loss: 23/03/2019 18:00 - :59 [153 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 588618</b>		Policy/Cover Note No.: A28795104MCX (Comprehensive) Coverage: 08/08/2018 - 07/08/2019							
Vehicle Reg. No. (Insured): <b>SMH537Y</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ama Autocare Pte Ltd (HQ)</b> 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Imm.Advice due 28/03/2019]									
Driver/Custodian (Insured): <b>LIAW SOON CHYE (LIAO SHUNCAI)</b> (), NRIC: S7303953C, Tel: +6587686732 Email:									
Adj Asg. Remarks: Liability unclear. TP disagree with our SJE list. Proceed to appoint LKK as the SJE. Contact Person: Mr Melvin / 8778 3636. On WP.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGH7495J (588618)  
[SMH537Y]

TP














MOHAMMED SAHERAN BIN SHAM MARICAN

Mar 23 2019 6:00PM

[SKYWAY MOTOR PTE LTD]

Ama Autocare Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Video</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/03/19 10:52	<b>Video - Accident</b> From:SC - Reg. No: SMH537Y, Claimant: SKYWAY MOTOR PTE LTD		Load MP4	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/03/19 10:52	<b>Accident Statement</b> From:SC - Reg. No: SMH537Y, Claimant: SKYWAY MOTOR PTE LTD		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	28/03/19 18:40	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>
8	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	28/03/19 18:40	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>
14	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	28/03/19 18:40	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
23	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
24	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
25	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
26	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
27	28/03/19 18:40	<b>Dismantled Parts</b>		Load JPG	<input checked="" type="checkbox"/>
28	03/04/19 17:51	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
29	03/04/19 17:51	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
31	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
32	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
33	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/19 10:52	SGH7495J GIA Rpt From: SC - Reg. No: SMH537Y, Claimant: SKYWAY MOTOR PTE LTD	 Load PDF	
2	27/03/19 11:25	Email - PRI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005500/ESD3E2

Date: 04/04/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28795104MCX

Claimant Vehicle No : SGH7495J

Insured Vehicle No : SMH537Y

Date of Loss: 23/03/2019

Nature of Claim: TP

Claim No: 588618

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH7495J**

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2589628

Reg. Date: 21/06/2006 (Man. Year: 2006)

Chassis No: ZNE100309717

Colour: Brown

Odometer: 380824 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: GREEN-MAX 6 mm

Rear Left Side: GREEN-MAX 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 27/03/2019

Date Inspected: 28/03/2019 Inspected At:

Ama Autocare Pte Ltd (HQ)  
36 Toh Guan Road East, #01-36  
Singapore 608580

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,500.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 04 Apr 2019)

**Parts:** M1-MPV      TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGH7495J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >