

ASS. REC. BY:

REF

C23/SPF 19005501/ Jvd 362

Special Instruction:

Surveyor: Hwee Jie

ASSIGNMENT (Office)

From (Person): Frankie Thay

of

SPF

Date/Time

27.3.19 10.01 A.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 4209T

Insured:

TP 1076 D

at Workshop m/s Platinum Werkz

Tel:

67410610

of 53 ubi Avenue 1 # 01-26

Policy No:

Claim No:

AEMD/105/009/2019/010

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 27.3.19

Person Contacted:

Vehicle (IN) OUT

Date/Time

Action/Instruction (X) Estimate

SMH 4209T - X

Upper Range \$4500 - \$5500 (EST)

1/4/19

Submit \$ 4214.80 (OAR)

Repair days: 5 (&gt; weekend) = 7

Do Not Finalise

Surinder Hwee Ho

REF:

SPF.

# ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMH 4209T

at Workshop m/s Platinum Works

of 83 Ubi Ave 1 #01-25.

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SMH4209T Yr Regn: 22 Jan 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit

C.C 1496

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 14117

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GPS1333155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/3/19

D.O.I. 27/3/19

Survey held at

Platinum work 1.10pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

RECEIVED 02 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 2/4 - typist

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

220

220

**Nivitha (LKK Auto)**

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Wednesday, 27 March 2019 10:01 AM  
**To:** Veron Chen (LKKAuto); assignments  
**Cc:** Hafizul Farhan RAHMAT (SPF); Olivia Lau (LKKAuto)  
**Subject:** RE : Pre-repair Inspection for SMH4209T

Your reference: SMH4209T

Our reference: AEMD/105/009/2019/010

Veron,

Please conduct a Pre-Repair Inspection (PRI) for vehicle SMH4209T at following address and contact person for appointment.

Motorcar no. SMH 4209T .

**Address :** Platinum Werkz Pte Ltd  
53 Ubi Avenue 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408934

**Contact :** YS – 67410610

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

Hwee Jie  
no estimate = PRS

**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                  |
|-------------------------------------|----------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                  |
| Owner ID Type:                      | Singapore NRIC                   |
| Owner ID:                           | 2304B                            |
| <b>Vehicle Details</b>              |                                  |
| Vehicle No.:                        | SMH4209T                         |
| Vehicle to be Exported:             | No                               |
| Intended Deregistration Date:       | 28 Mar 2019                      |
| Vehicle Make:                       | HONDA                            |
| Vehicle Model:                      | FIT HYBRID 1.5 AUTO              |
| Primary Colour:                     | Blue                             |
| Manufacturing Year:                 | 2018                             |
| Engine No.:                         | LEB1439733                       |
| Chassis No.:                        | GP51333155                       |
| Maximum Power Output:               | 101.0 kW (135 bhp)               |
| Open Market Value:                  | \$18,417.00                      |
| Original Registration Date:         | 22 Jan 2019                      |
| First Registration Date:            | 22 Jan 2019                      |
| Transfer Count:                     | 0                                |
| Actual ARF Paid:                    | \$8,417.00                       |
| <b>Intended PARF Rebate Details</b> |                                  |
| PARF Eligibility:                   | Yes                              |
| PARF Eligibility Expiry Date:       | 21 Jan 2029                      |
| PARF Rebate Amount:                 | \$6,312.00                       |
| <b>Intended COE Rebate Details</b>  |                                  |
| COE Expiry Date:                    | 21 Jan 2029                      |
| COE Category:                       | E - Open - all except motorcycle |
| COE Period(Years):                  | 10                               |
| QP Paid:                            | \$31,809.00                      |
| COE Rebate Amount:                  | \$30,425.00                      |
| <b>Total Rebate Amount:</b>         | <b>\$36,737.00</b>               |

The information contained herein is correct as at 28 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT         |                                |
|----------------------------|--------------------------------|
| Date Of Report             | 22/03/2019 14:17               |
| Date Of Accident           | 21/03/2019 16:30               |
| Exact Location Of Accident | ALEXANDRA RD TWDS QUEENSWAY RD |
| Country/State of Loss      | SINGAPORE                      |

| DETAILS OF OWN VEHICLE   |  |
|--|--|
| Vehicle Registration Number  | SMH4209T                               |
| <b>Insured/Policyholder</b>  |  |
| Name Of Registered Owner   | ONG CHIN TECK                          |
| NRIC No  | S1622304B                              |
| Email Address  | NOEMAIL                                |
| Mobile Phone No  | (LOCAL) +65-92205995                   |
| Alternative Phone No   | OFFICE-92205995                        |
| <b>Vehicle Particulars</b>   |  |
| Manufacturer   | HONDA                                  |
| Model  | FIT HYBRID 1.5 AUTO                    |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                            |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                                     |
| If No, Please state action to be taken                                       | THIRD PARTY                            |
| Vehicle Category   | PRIVATE HIRE                           |
| <b>Insurance Company</b>   |  |
| Name of Insurance Company  | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage   | COMPREHENSIVE                          |
| Fleet Policy   | NO                                     |
| Policy Number  | 5106957523                             |
| Cover Note Number  |  |
| <b>Driver</b>  |  |
| Name of Driver   | ONG CHIN TECK                          |
| NRIC No  | S1622304B                              |
| Date Of Birth  | 26/12/1963                             |
| Occupation   | OUTDOOR                                |
| Date Of Driving Pass   | 03/06/1982                             |
| Driving Experience   | 36 YEARS AND 9 MONTHS                  |
| Gender   | MALE                                   |
| Mobile Number  | (LOCAL) +65-92205995                   |
| Fax Number   |  |
| Contact Number   | OFFICE-92205995                        |
| Email Address  | NOEMAIL                                |

|   |  |
|---|--|
| Address   | BLK 134 BEDOK RESERVOIR ROAD<br>#05-1239 |
| Postcode  | 470134                                   |
| Was driver an employee of the Insured's Company     | NO                                       |
| If No, Relationship of the Driver with the Insured  | OWNER                                    |
| Vehicle Registration Number of Driver's Own Vehicle | -  |
|   | -  |
|   | -  |
| Insurance Company of Driver's Own Vehicle           | -  |
|   | -  |
|   | -  |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | DRIZZLING                |
| Road Surface       | WET                      |

#### Other Information

|   |                             |
|---|-----------------------------|
| Was any foreign vehicle involved in this accident?  | NO                          |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                           |
| Was any body injured in the Accident?   | YES                         |
| Was any injured conveyed to hospital by ambulance?  | NO                          |
| Was any other material or property damaged?   | YES                         |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                          |
| Number of Passengers (Including Driver)   | 3                           |
| Passenger 1   | NAME: : -<br>GENDER: : MALE |
| Passenger 2   | NAME: : -<br>GENDER: : MALE |

#### Details of Police Action

|   |   |
|---|---|
| Was the accident reported to the police?  | YES   |
| If Yes, Please state which Police Station |   |
| Police Station Name                       | EUNOS NEIGHBOURHOOD POLICE POST   |
| Police Station Address                    | ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE |
| Police Station Contact                    | TEL NO: 1800-4439999 - FAX NO: 62444376   |
| Was notice of intended Prosecution given? | NO  |
| If Yes, against whom?                     |   |

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190321/2133.

#### Attachment(s)

|   |                           |
|---|---------------------------|
| Are accident photos available for attachment? | YES                       |
| Was there any video captured by Car Camera?   | YES                       |
| Remarks/ Reasons:                             | VIDEO FOOTAGE WITH DRIVER |
| Was there any audio recorded?                 | NO                        |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |            |
|-----------------------------|------------|
| Vehicle Registration Number | TP1076D    |
| Vehicle Make/Model/Colour   |            |
| Details Of Properties       |            |
| Vehicle Category            | MOTORCYCLE |

Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

1

#### DETAILS OF INJURED PERSON 1

Name  
ONG CHIN TECK  
Approximate Age  
Injuries Sustain  
BODY  
Injured person in which vehicle?  
SMH4209T  
Were seat belts worn?  
YES  
Was this injured conveyed to hospital by  
ambulance?  
NO  
Address  
Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 7/20190321/2137.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Vehicle No: SMH 4209T

| NAC  | INC    | Item                        | CON | AC    | Qty     |
|------|--------|-----------------------------|-----|-------|---------|
| 1137 | 993626 | Rear Number Plate           |     |       |         |
| 1138 | 993627 | Rear Number Plate Base      |     |       |         |
| 1139 | 993630 | Rear Number Plate Garnish   |     |       |         |
| 1140 | 993632 | Rear Number Plate Lamp      |     |       |         |
| 1141 | 992958 | Rear Bumper                 | DD  | /     | 1 #780  |
| 1142 | 993085 | Rear Bumper Upper           |     |       |         |
| 1143 | 993017 | Rear Bumper Lower           |     |       |         |
| 1144 | 993054 | Rear Bumper Side            |     |       |         |
| 1145 | 993103 | Rear Bumper Tow Cover       |     |       |         |
| 1146 | 992341 | Rear Bumper Clips           | SN  | NEC   | / 6 30  |
| 1147 | 992976 | Rear Bumper Bracket         |     |       |         |
| 1148 | 993068 | Rear Bumper Side Retainer   |     |       |         |
| 1149 | 993045 | Rear Bumper Reinforcement   |     |       |         |
| 1150 | 992970 | Rear Bumper Beam            |     |       |         |
| 1151 | 993077 | Rear Bumper Sponge          |     |       |         |
| 1152 | 992999 | Rear Bumper Damper          |     |       |         |
| 1153 | 993040 | Rear Bumper Protector       |     |       |         |
| 1154 | 993036 | Rear Bumper Pad             |     |       |         |
| 1155 | 993026 | Rear Bumper Moulding        |     |       |         |
| 1156 | 993044 | Rear Bumper Reflector       |     |       |         |
| 1157 | 993023 | Rear Bumper Lower Spoiler   |     |       |         |
| 1158 | 994023 | Reverse Sensor              | SN  | Short | / 200   |
| 1159 | 993327 | Rear End Panel              |     |       |         |
| 1160 | 993339 | Rear End Panel Top Garnish  | DEF | -     | 1 150   |
| 1161 | 993333 | Rear End Panel Inner Trim   |     |       |         |
| 1162 | 990333 | Boot Compartment Inner Trim |     |       |         |
| 1163 | 993851 | Rear LH Taillamp            |     |       |         |
| 1164 | 993853 | Rear LH Taillamp Garnish    |     |       |         |
| 1165 | 993859 | Rear LH Taillamp Panel      |     |       |         |
| 1166 | 995116 | Rear RH Taillamp            |     |       |         |
| 1167 | 993853 | Rear RH Taillamp Garnish    |     |       |         |
| 1168 | 993859 | Rear RH Taillamp Panel      |     |       |         |
| 1169 | 993554 | Rear Apron Panel            |     |       |         |
| 1170 | 992895 | Bootlid                     | BUC | -     | 1 #1000 |
| 1171 | 991328 | Bootlid Emblem              | NEC | /     | 2 144   |
| 1172 | 990356 | Bootlid Handle              |     |       |         |
| 1173 | 995250 | Bootlid Moulding            |     |       |         |
| 1174 | 990376 | Bootlid Reflector           |     |       |         |
| 1175 | 995222 | Bootlid Lamp LH             |     |       |         |
| 1176 | 992899 | Bootlid Lamp RH             |     |       |         |
| 1177 | 995243 | Bootlid Lock                |     |       |         |
| 1178 | 990377 | Bootlid Rubber              | DEF | /     | 1 92    |
| 1179 | 990382 | Bootlid Hinge               |     |       |         |
| 1180 | 993877 | Bootlid Spoiler             |     |       |         |
| 1181 | 994543 | Tailgate                    |     |       |         |
| 1182 | 991328 | Tailgate Emblem             | NLC | /     | 35      |
| 1183 | 994643 | Tailgate Outer Handle       |     |       |         |
| 1184 | 994640 | Tailgate Moulding           | NEC | /     | #70     |
| 1185 | 994545 | Tailgate Garnish            |     |       |         |
| 1186 | 994648 | Tailgate Reflector          |     |       |         |
| 1187 | 994549 | Tailgate Lamp               |     |       |         |
| 1188 | 994646 | Tailgate Protector          |     |       |         |
| 1189 | 994676 | Tailgate Wiper Arm          |     |       |         |
| 1190 | 994677 | Tailgate Wiper Blade        |     |       |         |
| 1191 | 994679 | Tailgate Wiper Nozzle       |     |       |         |
| 1192 | 994555 | Tailgate Wiper Motor        |     |       |         |
| 1193 | 994602 | Tailgate Glass              |     |       |         |
| 1194 | 994606 | Tailgate Glass Rubber       |     |       |         |
| 1195 | 994604 | Tailgate Glass Moulding     | NEC | /     | 70      |
| 1196 | 994607 | Tailgate Glass Sealant      | NEC | /     | 60      |
| 1197 | 994629 | Tailgate Lock               | BT  | /     | 380     |
| 1198 | 994651 | Tailgate Rubber             |     |       |         |
| 1199 | 994611 | Tailgate Hinge              |     |       |         |
| 1200 | 994594 | Tailgate Damper             |     |       |         |
| 1201 | 994613 | Tailgate Inner Board        | CRA | /     | 350     |

| NAC  | INC    | Item                           | CON | AC | Qty   |
|------|--------|--------------------------------|-----|----|-------|
| 1202 | 993784 | Spare Tyre Board               |     |    |       |
| 1203 | 994328 | Spare Tyre Panel               |     |    |       |
| 1204 | 995065 | Spare Tyre                     |     |    |       |
| 1205 | 994326 | Spare Tyre Lock Screw          |     |    |       |
| 1206 | 993787 | Spare Tyre Cover               |     |    |       |
| 1207 | 995323 | Triangle Breakdown Sign        |     |    |       |
| 1208 | 990507 | CD Changer Assy                |     |    |       |
| 1209 | 990164 | Antenna                        |     |    |       |
| 1210 | 990534 | Centre Exhaust Pipe Assy       |     |    |       |
| 1211 | 990532 | Centre Exhaust Mounting        |     |    |       |
| 1212 | 993364 | Rear Exhaust Pipe              |     |    |       |
| 1213 | 993357 | Rear Exhaust Chrome Pipe       |     |    |       |
| 1214 | 993361 | Rear Exhaust Mounting          |     |    |       |
| 1215 | 993358 | Rear Exhaust Heat Shield       |     |    |       |
| 1216 | 995223 | Rear LH Chassis Member         |     |    |       |
| 1217 | 993165 | Rear RH Chassis Member         |     |    |       |
| 1218 | 993436 | Rear LH Fender                 |     |    |       |
| 1219 | 993449 | Rear LH Fender Protector       |     |    |       |
| 1220 | 993420 | Rear LH Fender Inner Panel     |     |    |       |
| 1221 | 993431 | Rear LH Fender Inner Trim      |     |    |       |
| 1222 | 993415 | Rear LH Fender Inner Garnish   |     |    |       |
| 1223 | 993425 | Rear LH Fender Inner Shield    |     |    |       |
| 1224 | 993621 | Rear LH Mudflap                |     |    |       |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |       |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |       |
| 1227 | 995065 | Rear LH Tyre                   |     |    |       |
| 1228 | 993456 | Rear RH Fender                 |     |    |       |
| 1229 | 993450 | Rear RH Fender Protector       |     |    |       |
| 1230 | 993420 | Rear RH Fender Inner Panel     |     |    |       |
| 1231 | 993431 | Rear RH Fender Inner Trim      |     |    |       |
| 1232 | 993415 | Rear RH Fender Inner Garnish   |     |    |       |
| 1233 | 993425 | Rear RH Fender Inner Shield    |     |    |       |
| 1234 | 993622 | Rear RH Mudflap                |     |    |       |
| 1235 | 993934 | Rear RH Wheel Rim              |     |    |       |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |       |
| 1237 | 995065 | Rear RH Tyre                   |     |    |       |
| 1238 | 995162 | Rear Fender Extension Panel LH |     |    |       |
| 1239 | 993401 | Rear Fender Extension Panel RH |     |    |       |
| 1240 | 993430 | Rear Fender Inner Top Garnish  |     |    |       |
| 1241 | 993673 | Rear Fender 1/4 Glass          |     |    |       |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber   |     |    |       |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant  |     |    |       |
| 1244 | 993949 | Rear Windscreen Glass          |     |    |       |
| 1245 | 993976 | Rear Windscreen Rubber         |     |    |       |
| 1246 | 993961 | Rear Windscreen Moulding       |     |    |       |
| 1247 | 993955 | Rear Windscreen Sealant        |     |    |       |
| 1248 | 994729 | Third Brake Light              |     |    |       |
| 1249 | 993385 | Rear Fender Air Grille         |     |    |       |
| 1250 | 992167 | Fuel Lid                       |     |    |       |
| 1251 | 992168 | Fuel Neck                      |     |    |       |
| 1252 | 992179 | Fuel Tank                      |     |    |       |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |       |
| 1254 | 992191 | Fuel Tank Float                |     |    |       |
| 1136 | 990247 | Sticker                        |     |    |       |
|      |        | Smart Buzzer Sensor            | CRA | /  | 1     |
|      |        | Labour                         |     |    | \$700 |
|      |        | Spray Painting                 |     |    | \$600 |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

AUTOMOTIVE ENGINEERING &amp; MGT DIVISION

Ref: CS3/SPF19005501/Jvd3e2

ACCIDENT CLAIM SECTION (SPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD  
POLICE ACADEMYSINGAPORE 298333

Date: 04-04-2019



ATTN : FRANKIE THAY

Code: SPF

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | TP 1076D              | Veh. Inspected | SMH 4209T  |
| Policy No.   |                       | Coverage (\$)  | 0.00       |
| Claim No.    | AEMD/105/009/2019/010 | Excess (\$)    | 0.00       |
| Assign From  | FRANKIE THAY          | Assign Date    | 27/03/2019 |

**2. Vehicle Particulars & Condition**

|              |            |              |            |
|--------------|------------|--------------|------------|
| Make & Model | HONDA FIT  | c.c          | 1496       |
| Engine No.   | HIDDEN     | Year of Reg. | 2019       |
| Chassis No.  | GP51333155 | Colour       | BLACK      |
| Odometer     | 14117 KM   | Steering     | IN ORDER   |
| Brakes       | IN ORDER   | Modification | SPORTS RIM |
| General      | GOOD       |              |            |

**3. Conditions of Tyres**

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| R/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |

**4. Description of Damages**

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

**5. General Information**

|                |   |                     |                         |
|----------------|---|---------------------|-------------------------|
| Accident Date  | 21/03/2019  | Inspect Date / Time | 27/03/2019 ( 01:10 PM ) |
| Survey held at | PLATINUM WERKZ PTE LTD<br>53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE<br>408934 |                     |                         |

**5a. Remarks**

|  |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

**5b. Estimate Days of Repair**

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**OPINION ON REPAIR COST FOR VEHICLE NO. SMH 4209T**

| Qty                                | Description of Parts       | Condition | Recommended (\$) |
|------------------------------------|----------------------------|-----------|------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                            |           |                  |
| 1                                  | REAR BUMPER                | DENTED    | 780.00           |
| 1                                  | REAR END PANEL TOP GARNISH | DEFORMED  | 150.00           |
| 1                                  | BOOTLID                    | BUCKLED   | 1,000.00         |
| 2                                  | BOOTLID EMBLEM             | NECESSARY | 144.00           |
| 1                                  | BOOTLID RUBBER             | DEFORMED  | 92.00            |
| 1                                  | TAILGATE EMBLEM            | NECESSARY | 35.00            |
| 1                                  | TAILGATE MOULDING          | NECESSARY | 70.00            |
| 1                                  | TAILGATE GLASS MOULDING    | NECESSARY | 70.00            |
| 1                                  | TAILGATE GLASS SEALANT     | NECESSARY | 60.00            |
| 1                                  | TAILGATE LOCK              | BENT      | 380.00           |
| 1                                  | TAILGATE INNER BOARD       | CRACKED   | 350.00           |
|                                    | LESS 20% DISCOUNT          |           | -626.20          |
|                                    |                            |           | 2,504.80         |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                            |           |                  |
| 6                                  | REAR BUMPER CLIPS (SN)     | NECESSARY | 30.00            |
| 1                                  | REVERSE SENSOR (SN)        | SHORTED   | 200.00           |
| 1                                  | SMART BUZZER SENSOR (SN)   | CRACKED   | 180.00           |
|                                    |                            |           | 410.00           |
| <b><u>LABOUR</u></b>               |                            |           |                  |
|                                    | LABOUR.                    |           | 700.00           |
|                                    | SPRAY PAINTING.            |           | 600.00           |
|                                    |                            |           | 1,300.00         |
| <b>GRAND TOTAL</b>                 |                            |           | <b>4,214.80</b>  |
| <b>RECOMMENDED COST OF REPAIRS</b> |                            |           | <b>4,214.80</b>  |

Report Ref No. CS3/SPF19005501/Jvd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500

RECOMMENDED REPAIR DAYS : 5

WEEKEND : 2

TOTAL DAYS : 7

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.