

Hwee Jie

REF: NTUC NS/INC19005508/eqd3e2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: YP3690H-
 Policy No: 5081953518-02 (18/7/18-17/7/19)
 Claims No: NT/1036992-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMB1496G Yr Regn: 1304 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Man A22 C.C: 10518
 Colour: Multi Colour A/C: Insured / Std / NI / NA
 Sp. Reading: 385366 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA22229E7002231
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rm / STD A/Rim or _____
 Tyre Size: F: 275/70 R22.5
 R: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 0.5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7/7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7/7</u> mm
D.O.A. <u>20/3/19</u>	D.O.I. <u>27/3/19</u>

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Survey held at Smart
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB1496G - NS/INC18014535/klapn2
	YP3690H - X
23/7/19 @ 10.24am	confirmed with Catherine by \$1200, 0.5 day by email. (Net \$683, 36%)
RECEIVED 23 JUL 2019	

Date/Time. File Pass to? : Preli. Report
 : Final Report
 Date/Time. File Return to?
 Report Format: 7P
 Lump Sum / I.B.I.: 13 (200)

Days Of Repair: 0.5
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Survey Fee: 160
 Transportation: _____
 Photos _____
 Others _____
 TOTAL 160

Shiau Chan (LKKAuto)

From: MTCL@income.com.sg
Sent: Thursday, 18 July 2019 11:37 AM
To: Shiau Chan (LKKAuto)
Subject: RE: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Junainah

Senior Admin Assistant
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 18 July 2019 9:48 AM
To: MTCL@income.com.sg
Subject: RE: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date : 18/07/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	C
1	MT/1036992-002	SMRT BUSES LTD	SMB 1496G	YP 3690H	

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)

[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="20/03/2019 11:57"/>
Vehicle No.(For Motor)	<input type="text" value="YP3690H"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5081953518-02		FANG'S ID PTE LTD	201605165M	GCV	Comprehensive	YP3690H	YP3690H	18/07/2018	17/07/2019

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 23 July 2019 10:24 AM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses)
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); AutoSvs-ARC (Bus); SUR
Subject: RE: KINDLY ADVISE THE STATUS OF SMB 1496G (YOUR REF: BUS/03/19/5044)

Dear Catherine,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,200.00 before GST and 0.5 repair day.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses) <catherineleesc@smrt.com.sg>
Sent: Wednesday, 17 July 2019 9:58 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-ARCBus@smrt.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF SMB 1496G (YOUR REF: BUS/03/19/5044)

Hi Shiau Chan,

Attached herewith our copy of the bus repair estimate for the case.
Our finalised amount is \$1,200/- @ 0.5 working days under lump sum repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: 12 July 2019 16:57
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses) <catherineleesc@smrt.com.sg>
Subject: KINDLY ADVISE THE STATUS OF SMB 1496G (YOUR REF: BUS/03/19/5044)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SMB1496G
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multi-Colour
Manufacturing Year:	2014
Engine No.:	50338151773815
Chassis No.:	WMAA22ZZ9E7002231
Maximum Power Output:	-
Open Market Value:	\$256,071.00
Original Registration Date:	13 Oct 2014
First Registration Date:	13 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2019 15:11
Date Of Accident	20/03/2019 10:15
Exact Location Of Accident	DUNEARN ROAD (BEFORE BS:42049)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1496G
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAN
Model	NL320F (A22)-10.5 D ABS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

Driver

Name of Driver	KHAIRULMAN BIN KASSIM
NRIC No	S7239250G
Date Of Birth	28/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	09/10/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address: 6 ANG MO KIO STREET 62
 Postcode: 569140
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident: SIDE SWIPE
 Weather Conditions: CLEAR
 Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

WHILE TRAVELLING ON THE LEFT MOST LANE OF DUNEARN ROAD, A LORRY (YP3690H) THAT WAS ON THE CENTRE LANE FILTERED LEFT TO ENTER YARWOOD AVENUE. IN THE PROCESS OF FILTERING, THE LORRY'S LEFT REAR PORTION GRAZED THE RIGHT FRONT PORTION OF MY BUS AND DID NOT STOP TO ACKNOWLEDGE THE ACCIDENT. I HORNED AT THE LORRY BUT THE LORRY CONTINUED TO DRIVE OFF. I COULD NOT CHASE AFTER THE LORRY AS SUCH I STOP MY BUS AND CONTACTED BOCC, POLICE AND FIELD TEAM ACTIVATED SHORTLY. WHILE ASSESSING DAMAGES, THE SAME LORRY APPEARED AT THE JUNCTION OF YARWOOD AVENUE AND DUNEARN ROAD. THE TRAFFIC POLICE OFFICER STOPPED THE LORRY DRIVER. WE EXCHANGED PARTICULARS. MY BUS SUSTAINED DAMAGES ON THE RIGHT VIEW MIRROR. NO INJURIES REPORTED. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: PENDING DOWNLOAD
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: YP3690H
 Vehicle Make/Model/Colour
 Details of Properties
 Vehicle Category: COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD


Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. The forms must be **completed by the Policyholder and/or the Authorised Driver**.
- 3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. **Any false reporting may be referred to the Police for investigation.**
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By your submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
- 8. **Consent under the Personal Data Protection Act (PDPA)**
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (ii) Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (v) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud,
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (iii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/03/2019

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB1496G
Case Reference Number	BUS/03/19/5044
Registration Date	10/13/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Khairulman Bin Kassim
Type of Accident	Side Swipe
Accident Date and Time	3/20/2019 10:15 AM
Accident Reported Date and Time	3/21/2019 3:37 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100717
Special Instructions to ARC, if any	SMB1496G - RIGHT FRONT PORTION YP3690H (TP) - INSURED WITH NTUC
Prepared Date and Time	3/22/2019 11:14 AM
Chassis Number	WMAA22ZZ9E7002231
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$865.92	\$974.16
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,395.92	\$1,239.16
Lump Sum Total	\$1,400.00	\$1,250.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted by	Jeong Choon Hwee	Hwee jie
ARC / Surveyor Sign Off Date	22/03/2019 12:18 PM	22/03/2019 2:24 PM
Signature		
Remarks		L/S repair. After repair photo

28/3/19

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 27/03/2019

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPLACE FRONT VIEW MIRROR RH		\$530.00				\$265.00			
Total Labour		\$530.00				\$265.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Part Desc	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011409	BODY LIN		MIRROR VIEW FRONT, R H, MAN A22 'C' SERIES	1.00	\$1,353.00	10.00	\$1,217.70	Replace	Replace
Total					\$1,353.00		\$1,217.70		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Part Desc	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

BR ✓

1883

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1496G
Case Reference Number	BUS/03/19/5044
Registration Date	13/10/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Khairulman Bin Kassim
Type of Accident	Side Swipe
Accident Date and Time	20/3/2019 10:15 AM
Accident Reported Date and Time	21/3/2019 3:37 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100717
Special Instruction to ARC, if any	SMB1496G - RIGHT FRONT PORTION YP3690H (TP) - INSURED WITH NTUC
Prepared Date and Time	22/3/2019 11:14 AM
Chassis Number	WMAA22ZZ9E7002231
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$974.16	\$974.16
Total Other Cost	\$0.00	(\$53.00)
TOTAL COST	\$1,504.16	\$1,186.16
Lump Sum Total	\$1,500.00	\$1,200.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Hwee jie
ARC / Surveyor Sign Off Date	22/03/2019 12:18 PM	22/03/2019 2:24 PM
Signature		
Remarks		L/S repair. After repair photo

checked by Steve 17/7/19

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPLACE FRONT VIEW MIRROR RH	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$53.00)
Total Other Costs	\$0.00	(\$53.00)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011409	BODY RH		MIRROR_VIEW.FRONT_R H,MAN A22 'C' SERIES	1.00	\$1,353.00	10.00	\$1,217.70	Replace	Replace
Total					\$1,353.00		\$1,217.70		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19005508/Eqd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 30-07-2019	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3690H	Veh. Inspected	SMB 1496G
Policy No.	5081953518-02	Coverage (\$)	0.00
Claim No.	MT/1036992-002	Excess (\$)	0.00
Assign From		Assign Date	27/03/2019
2. Vehicle Particulars & Condition			
Make & Model	MAN NL 320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA22ZZ9E7002231	Colour	MULTI COLOUR
Odometer	385366	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	7 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/03/2019	Inspection Date	27/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		0.500 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1496G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	MIRROR,VIEW: FRONT,RH, MAN A22 'C' SERIES LESS 10% DISCOUNT	BROKEN	1,353.00 -	1,353.00 -135.30
			1,353.00	1,217.70
	LABOUR			
	TO REPLACE FRONT VIEW MIRROR RH.		530.00	265.00
			530.00	265.00
	GRAND TOTAL		1,883.00	1,482.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,200.00

Report Ref No. NS/INC19005508/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.