

ASS. REC. BY:

REF: CS/FCI1900SS14/ E9d3m

Special Instruction:

SUPERVISOR: Steve

ASSIGNMENT (Office)

From (Person): May chuan

of FCI

Date/Time: 9:30am 28/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8MF6756C

Insured: SHC 8830H

at Workshop m/s: MOVA

Tel: 6272 3892

of BIK 1008 Bkt Merah Jere 3 #01-04

Policy No:

Claim No: D19002078MFSH

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 23/03/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 10:05am 28/3/19

Person Contacted: Avneel

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|----------------|---|
| | 8MF6756C-X |
| | SHC 8830H-CS3/FCI18020154 / Subs 2 |
| | Sub: 7/11/18 |
| 3/4@5:19pm | Revised via email prev advise. |
| 26/4/19 3:37pm | NATHA said they arrange the vehicle send in next week for repair. |

Barry Stave

REF: FCI

ASSIGNMENT

From:
 Date: 2/4/2019
 Estimated Cost:
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMF 6756S
 at Workshop n/s: Mova Automotive
 of Blk 1005 Blk Merah June 3 #01-04
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: After 10am
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS '05'
 Date: Person Contacted: Vehicle: IN / OUT

| | |
|-----|-----|
| N/S | O/S |
| X | X |

Veh No: SMF 6756C Yr Regn: 21/11/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Tucson c.c. 1591
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 6715 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: KM HJ 3812 VKU 879423
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / Rim / STD A/Rim or
 Tyre Size: F: 225/60R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front R/Bal. 3 mm
 Rear R/Bal. 7 mm
 L/Bal. 7 mm
 L/Bal. 7 mm
 D.O.A. 23/3/19
 D.O.I. 2/4/19
 Survey held at Mova, Blk Merah
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | MV - 10SK Findize Confm \$1399.68, 3 days 24/5/19 (Red \$484.60, 27%) |

RECEIVED 28 MAY 2019

Date/Time, File Pass to? : Preli. Report
 1) 21/5 2019 : Final Report
 Date/Time, File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

| | |
|-----------------|-----|
| Survey Fee: | 100 |
| Transportation: | 50 |
| S + RS, SI | 50 |
| Photos: | 41 |
| Others: | |
| TOTAL | 241 |

Report Format: TP
 Lump Sum / L.B.I: (\$) 1309.68



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002078MFSH

Date: 3/4/2019

Our Ref: CS/FCI19005514/Eqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMF 6756C

Please be informed that we had conducted the inspection of the abovementioned vehicle 2/4/2019 at the premises of M/s Mova have the following to report: -

| | |
|--------------------------|-----------------------|
| Workshop Estimate Amount | : S\$ <u>1,196.16</u> |
| Revised Estimate Amount | : S\$ <u>910.16</u> |
| "Check" Items Amount | : S\$ <u>00.00</u> |
| Market Value | : S\$ _____ |
| LTA Reimbursement Value | : S\$ _____ |
| Nett Value | : S\$ _____ |

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Steve

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|---|--------------------------------------|
| Date | 26-03-2019 | Our Ref No. D19002078MFSH |
| Accident Date | 23-03-2019 | Claim Type. Third Party |
| Insured Vehicle | SHC8830H | Third Party Vehicle. SMF6756C |
| Survey Location | BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 | |
| Contact Person. | NITHA | |
| Contact No. | 62723892/ 0 | Fax No. 62708314 |
| Survey Type | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|-------------------------|--------------------------------|
| Cc : Workshop | MOVA AUTOMOTIVE PTE LTD | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | MAY CHUA | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: Tan Yoong Wei <tanyw@moval.com.sg>
Sent: Friday, May 24, 2019 10:58 AM
To: Steve Chen (LKK Auto)
Subject: RE: FINALISE SMF6756C

close

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Wednesday, 22 May 2019 7:50 PM
To: Tan Yoong Wei
Subject: FINALISE SMF6756C

Dear Ah Wei,

Kindly refer our finalize \$1309.68 (P/P, before GST). 3 days

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei [<mailto:tanyw@moval.com.sg>]
Sent: Wednesday, May 22, 2019 12:44 PM
To: Steve Chen (LKK Auto)
Cc: Veron Chen (LKKAuto); Hsiao Tong (LKKAuto); SUR
Subject: FINALISE SMF6756C

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 3 April 2019 5:19 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; Admin-D (LKKAUTO)
Subject: RE: SURVEY ASSESSMENT - D19002078MFSH/1
Attachments: PRELI ADVISED SMF 6756C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMF 6756C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 28 March, 2019 9:32 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002078MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 6162H |
| Vehicle Details | |
| Vehicle No.: | SMF6756C |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 02 Apr 2019 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | TL TUCSON FL 1.6 GLS T-GDI DCT 2WD SR |
| Primary Colour: | White |
| Manufacturing Year: | 2018 |
| Engine No.: | G4FJJU565010 |
| Chassis No.: | KMHJ3812VKU879423 |
| Maximum Power Output: | 130.0 kW (174 bhp) |
| Open Market Value: | \$23,592.00 |
| Original Registration Date: | 21 Nov 2018 |
| First Registration Date: | 21 Nov 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$25,029.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 20 Nov 2028 |
| PARF Rebate Amount: | \$18,771.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 20 Nov 2028 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$31,302.00 |
| COE Rebate Amount: | \$30,154.00 |
| Total Rebate Amount: | \$48,925.00 |

The information contained herein is correct as at 02 Apr 2019

OK



MOVA Automotive Pte Ltd

Mova Automotive Pte Ltd
BLOCK 1008 BUKIT MERAH LANE 3 #01-04
Singapore 159722

SPARE PARTS

Vehicle No. SMF6756C

Job Order No.

: ATTN: AN KOW

Make / Model TL TUCSON FL 1.6 GLS T-GDI DCT 2WD SR

Branch

: 1008 Bukit Merah Lane 3 #01-04

Year of Mfg 21-Nov-18

Fax No.

: 6270 8314

Chassis KMHJ3812VKU879423

Name

: AH WEI / 9776 2311

DATE

: 22/3/2019



| N | Qty | Description | Cost Price | List Price |
|----|-----|---|------------|-------------------|
| 1 | 1 | Rear Bumper | | 89 TBA |
| 2 | 2 | Rear parking sensor | | TBA |
| 3 | 2 | parking sensor O-Ring | | TBA |
| 4 | | | | |
| 5 | 1 | Rear Bumper lower garnish | | 534.70. |
| 6 | 10 | Bumper cups | | 4.80x10. |
| 7 | | | | |
| 8 | | | | |
| 9 | - | To remove & Replace all accident damage parts. To straighten and re-align | | |
| 10 | | on accident affected areas \$ 350. | | |
| 11 | | | | |
| 12 | - | To spray paint on accident affected areas \$ 300. | | |
| 13 | | | | |
| 14 | - | To remove & Retix Rear parking sensor. \$80. | | |
| 15 | | | | |
| 16 | | | | |
| 17 | | | | |
| 18 | | | | |
| 19 | | | | |
| 20 | | | | |
| 21 | | | | |
| 22 | | | | |
| 23 | | | | |
| 24 | | | | |
| 25 | | | | |
| 26 | | | | |
| 27 | | | | |
| 28 | | | | |
| 29 | | | | |
| 30 | | | | |
| 31 | | | | |
| 32 | | | | |
| 33 | | | | |
| 34 | | | | |
| 35 | | | | |
| 36 | | | | |
| 37 | | | | |
| 38 | | | | |
| 39 | | | | |
| 40 | | | | |

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

John
Steve
W. Pined
2/4/19 11:30 am
2 days
P/P or L/S ?
R. before

Estimate

26/03/2019

MS FIRST CAPITAL INSURANCE LIMITED

 36 Robinson Road
 #16-01 City House
 Singapore 068877.

 Attention :- **XA026**

 Page # :- 1
 Veh # :- SMF6756C
 Veh Model :- HYUNDAI TUCSON
 Estimate# :- CK418918
 Claim # :-
 ACC. Date :- 23/03/19
 Terms :- C.O.D Days
 Remarks :-

| No. | Description | Qty | U.Price | Amounts S\$ |
|--|---|-----|------------------|---------------------|
| LIST ITEMS : | | | | |
| 1. | REAR BUMPER - TBA / <i>DD</i> / <i>BR</i> | 1 | PC <i>529.50</i> | |
| 2. | REAR PARKING SENSOR - TBA / X <i>NAH</i> / <i>CR</i> | 1 | PC <i>209.20</i> | |
| 3. | PARKING SENSOR O-RING - TBA / X <i>NAH</i> / <i>CR</i> | 1 | PC <i>8.40</i> | |
| 4. | REAR BUMPER LOWER GARNISH / <i>CUT</i> | 1 | PC 534.70 | 534.70 |
| 5. | BUMPER CLIPS / <i>MEC</i> | 10 | PC 4.80 | 48.00 |
| LIST TOTAL S\$ | | | | 582.70 |
| 20% DISCOUNT S\$ | | | | -116.54 |
| | | | | 466.16 |
| LABOUR : | | | | |
| TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PART TO STRAIGHTEN AND REALIGN ON ACCIDENT AFFECTED AREAS | | | | <i>290</i> / 350.00 |
| TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS | | | | <i>700</i> / 300.00 |
| TO REMOVE & REFIX REAR PARKING SENSOR | | | | <i>20</i> / 80.00 |
| LABOUR TOTAL S\$ | | | | 730.00 |
| | | | | <i>1993.84</i> |

E. & O.E

| | |
|------------------|----------|
| NON-TAX AMOUNT S | |
| AMOUNT S\$ | 1,196.16 |
| GST @ 7 % | 83.73 |
| AMOUNT DUE S\$ | 1,279.89 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/08/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Store
Wc Repair 2/4/19 11.30am
3 days
P/P or L/S ?
Re bef sy

Estimate

26/03/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1
Veh # :- SMF6756C
Veh Model :- HYUNDAI TUCSON
Estimate# :- CK418918
Claim # :-
ACC. Date :- 23/03/19
Terms :- C.O.D Days
Remarks :-

Attention :- XA026

| No. | Description | Qty | U.Price | Amounts S\$ |
|---------------------|--|-----|---------------------------------------|-------------|
| LIST ITEMS : | | | | |
| 1. | REAR BUMPER - TBA / <i>DD</i> | 1 | PC \$529.50 | |
| 2. | REAR PARKING SENSOR - TBA <i>x NN</i> | 2 | PC \$209.20 | |
| 3. | PARKING SENSOR O-RING - TBA <i>x NN</i> | 2 | PC \$8.40 | |
| 4. | REAR BUMPER LOWER GARNISH <i>- CNT</i> | 1 | PC 334.70 334.70 | 534.70 |
| 5. | BUMPER CLIPS <i>- BEC</i> | 10 | PC 4.80 | 48.00 |
| | LIST TOTAL S\$ | | | 582.70 |
| | 20% DISCOUNT S\$ | | | -116.54 |
| | | | | 466.16 |
| LABOUR : | | | | |
| | TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PART TO STRAIGHTEN AND REALIGN ON ACCIDENT AFFECTED AREAS | | <i>Parts \$1311.80 -20% \$1049.44</i> | |
| | TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS | | <i>Labour \$420</i> | 290 350.00 |
| | TO REMOVE & REFIX REAR PARKING SENSOR | | <i>total P/p \$1469.44 3 DAYS</i> | 200 300.00 |
| | LABOUR TOTAL S\$ | | | 20 80.00 |
| | | | | 730.00 |

E. & O. E

NON-TAX AMOUNT S
AMOUNT S\$ 1,196.16
GST @ 7% 83.73
AMOUNT DUE S\$ 1,279.89

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|-----------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI19005514/Eqd3n2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 29-05-2019 |  |
| | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHC 8830H | Veh. Inspected | SMF 6756C |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | D19002078MFSH | Excess (\$) | 0.00 |
| Assign From | MAY CHUA | Assign Date | 28/03/2019 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HYUNDAI TUCSON | c.c | 1591 |
| Engine No. | HIDDEN | Year of Reg. | 2018 |
| Chassis No. | KMHJ3812VKU879423 | Colour | WHITE |
| Odometer | 6715 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 225/60 R17 | KUMHO | 7 mm |
| L/H Front Tyre | 225/60 R17 | KUMHO | 7 mm |
| R/H Rear Tyre | 225/60 R17 | KUMHO | 7 mm |
| L/H Rear Tyre | 225/60 R17 | KUMHO | 7 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 23/03/2019 | Inspection Date | 02/04/2019 |
| Survey held at | MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722 | | |
| 5a. Remarks | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 6756C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DENTED | 529.50 | 529.50 |
| 1 | REAR PARKING SENSOR | BROKEN | 209.20 | 209.20 |
| 1 | PARKING SENSOR O-RING | BROKEN | 8.40 | 8.40 |
| 1 | REAR BUMPER LOWER GARNISH | CUT | 534.70 | 335.00 |
| 10 | BUMPER CLIPS @\$4.80 | NECESSARY | 48.00 | 30.00 |
| | LESS 20% DISCOUNT | | -265.96 | -222.42 |
| | | | 1,063.84 | 889.68 |
| | LABOUR | | | |
| | TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PART.TO STRAIGHTEN AND REALIGN ON ACCIDENT AFFECTED AREAS. | | 350.00 | 200.00 |
| | TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS. | | 300.00 | 200.00 |
| | TO REMOVE & REFIX REAR PARKING SENSOR. | | 80.00 | 20.00 |
| | | | 730.00 | 420.00 |
| | GRAND TOTAL | | 1,793.84 | 1,309.68 |
| | RECOMMENDED COST OF REPAIRS | | | 1,309.68 |

Report Ref No. CS/FCI19005514/Eqd3n2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.