

ASS. REC. BY:

REF: CS/CTI/19005530/Bcd3d Special Instruction:

Surveyor: Mr hm

ASSIGNMENT (Office)

From (Person): Elaine cheng

of CTI

Date/Time: 27/3/2019 4:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SME 535T

Insured:

SFZ 8299 U

at Workshop in/s:

My Car Consultant

Tel:

8866 8832

of

53 Ubi Ave 1 #01-33

Policy No:

DMPCSN3084781803

Claim No:

8NM19D201283002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:50am 28/3/19

Person Contacted:

Hui Qin

Vehicle: IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SME 535T - NA / MSG19005085 / r3

DOA: 20/3/2019

SFZ 8299U - NA / MSG19005085 / r3

DOA: 20/3/2019

Dismantle: 29/3/2019

REF: CTF

ASSIGNMENT

From: \_\_\_\_\_ Date: 29/3/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 535T

at Workshop m/s: Mycar Consultant

of: 53 Ubi Ave 1 # 01-33

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SME 535T Yr Regn: 6/5/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Audi A6 Avant 2.0 c.c 1984

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 40706 T/Radio: Insured / Std / NI / NA

Eng/No: CDN331992

C/No: WA4ZZZ4G5DN121783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 255/40/19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or \_\_\_\_\_

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>sup</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Front Rear

R/Bal. 7 mm R/Bal. 7 mm


L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 20/3/2019 D.O.I. 29/3/19

Survey held at LK Auto Consultants

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 3,000/- - 4,000/-
	
	3/4/2019
	MV 74,000/-
	PV 63,900/-
	NV 10,100/-
	Tekin Lim
	29/3/19

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: PRS.

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 150

Transportation: \_\_\_\_\_

\$ + RS, SI \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL: 150

## **Nivitha (LKK Auto)**

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Wednesday, 27 March 2019 4:43 PM  
**To:** admin@mycar.sg; 'assignments'  
**Subject:** RE: FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T-PRE-REPAIRINSPECTION FOR SME535T

WITHOUT PREJUDICE

Dear Huiqin,

We refer to your email of 27.03.19.

We regret to inform that we are not agreeable to proposed list of surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** My Car Consultant [mailto:admin@mycar.sg]  
**Sent:** Wednesday, 27 March, 2019 1:53 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Subject:** RE: FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T-PRE-REPAIRINSPECTION FOR SME535T

WITHOUT PREJUDICE

We do not agree to your list of surveyors.

We propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong

- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Winson Goh
- i. Mr Willy Goh
- j. Nicky Seah

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Thanks & Regards,

**Huiqin**

My Car Consultant  
 53 Paya Ubi Industrial Park #01-33 S(408934)  
 Tel: 88668832

---

**From:** "Elaine Cheong" <elaine.cheong@sg.cntaiping.com>  
**Sent:** Wednesday, March 27, 2019 1:29 PM  
**To:** "admin@mycar.sg" <admin@mycar.sg>  
**Subject:** RE: FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T-PRE-REPAIRINSPECTION FOR SME535T

**WITHOUT PREJUDICE**

Dear Huiqin,

We refer to your email of 27.03.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Elaine Cheong**  
 Executive (Motor Claims)  
 Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Angie Foo

**Sent:** Wednesday, 27 March, 2019 1:24 PM

**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; [admin@mycar.sg](mailto:admin@mycar.sg)

**Subject:** FW: FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T -PRE-REPAIRINSPECTION FOR SME535T

Please action- Elaine

**From:** My Car Consultant [<mailto:admin@mycar.sg>]

**Sent:** Wednesday, March 27, 2019 1:08 PM

**To:** Angie Foo

**Subject:** re: FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T -PRE-REPAIRINSPECTION FOR SME535T

WITHOUT PREJUDICE

Hi Angie,

I have tried to call you and Angie but to no avail. Please appoint by latest 1700Hrs as of today 27/03/2019

Thanks & Regards,

**Huiqin**

My Car Consultant

53 Paya Ubi Industrial Park #01-33 S(408934)

Tel: 88668832

---

**From:** "Angie Foo" <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Sent:** Monday, March 25, 2019 2:37 PM

**To:** "[admin@mycar.sg](mailto:admin@mycar.sg)" <[admin@mycar.sg](mailto:admin@mycar.sg)>, "Elaine Cheong" <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>, "Chee So Chow" <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>, "Alfred Toh" <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>

**Subject:** FW: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T -PRE-REPAIRINSPECTION FOR SME535T

Dear Huiqin,

Please contact our claim Executive - ELAINE CHEONG: 6389 6530.

Dear Elaine,

Please look into this PRS since 22.3.2019

Thanks

Angie Foo

**From:** My Car Consultant [<mailto:admin@mycar.sg>]

**Sent:** Monday, March 25, 2019 1:00 PM

**To:** Angie Foo

**Subject:** re: OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T - PRE-REPAIRINSPECTION FOR SME535T

**Importance:** High

WITHOUT PREJUDICE

Hi Angie,

We have yet to receive any survey appointments. Please assist.

Thanks & Regards,

**Huiqin**

My Car Consultant  
53 Paya Ubi Industrial Park #01-33 S(408934)  
Tel: 88668832

---

**From:** "Angie Foo" <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>  
**Sent:** Friday, March 22, 2019 10:50 AM  
**To:** "Elaine Cheong" <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>, "Alfred Toh" <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>, "Chee So Chow" <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>, "admin@mycar.sg" <[admin@mycar.sg](mailto:admin@mycar.sg)>  
**Subject:** OUR REF: SNM19D201283- SFZ8299U & YR REF: SME535T - PRE-REPAIRINSPECTION FOR SME535T

Dear Elaine,

Please conduct PRS soonest possible. SNM19D201283- SFZ8299U

ELAINE CHEONG: 6389 6530.

Best Regards,

**Angie Foo**

Claims Executive  
Claims Department – Motor Division

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6186  
Fax (65) 6224 7175 / 6224 7478  
Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



Disclaimer:

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Claims Dept of CTI  
**Sent:** Friday, 22 March, 2019 8:47 AM  
**To:** Angie Foo  
**Subject:** FW: OUR REF: SME535T YOUR REF: SFZ8299U PRE-REPAIR INSPECTION FOR SME535T

**From:** My Car Consultant [mailto:admin@mycar.sg]  
**Sent:** Thursday, 21 March 2019 5:27 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>  
**Cc:** Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Subject:** OUR REF: SME535T YOUR REF: SFZ8299U PRE-REPAIR INSPECTION FOR SME535T

WITHOUT PREJUDICE

OUR REF: SME535T  
YOUR REF: SFZ8299U  
Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SME535T  
ACCIDENT INVOLVING SME535T AND SFZ8299U

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention. Please let us know within two (2) working days

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Thanks & Regards,

**Huiqin**

My Car Consultant  
53 Paya Ubi Industrial Park #01-33 S(408934)  
Tel: 88668832

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6601G
Vehicle Details	
Vehicle No.:	SME535T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 AVANT 2.0 TFSI MU
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	CDN331992
Chassis No.:	WAUZZZ4G5DN121783
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$40,966.00
Original Registration Date:	06 May 2013
First Registration Date:	06 May 2013
Transfer Count:	1
Actual ARF Paid:	\$35,966.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 May 2023
PARF Rebate Amount:	\$25,176.00
Intended COE Rebate Details	
COE Expiry Date:	05 May 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$92,901.00
COE Rebate Amount:	\$38,085.00
<b>Total Rebate Amount:</b>	<b>\$63,261.00</b>

The information contained herein is correct as at 29 Mar 2019

OK

Avg Dep 13500/2

MV 74,000/2  
 PV 63,900/2  
 NV 10,100/2

hi  
 29/3/19

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/03/2019 16:55
Date Of Accident	20/03/2019 12:20
Exact Location Of Accident	PASIR RIS ST 21 LOYANG POINT CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SME535T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AZMI BIN MOHAMAD YUSOFF
NRIC No	S6826601G
Email Address	AZMI.M.YUSOFF@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97673475
Alternative Phone No	OTHERS-97673475
<b>Vehicle Particulars</b>	
Manufacturer	AUDI
Model	-
Exact Purpose for which vehicle was being used at time of accident	PARKED VEH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80463989 QMX
Cover Note Number	
<b>Driver</b>	
Name of Driver	AZMI BIN MOHAMAD YUSOFF
NRIC No	S6826601G
Date Of Birth	23/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	01/06/2004
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97673475
Fax Number	
Contact Number	OTHERS-97673475
EMail Address	AZMI.M.YUSOFF@GMAIL.COM

Address BLK 672 CHOA CHU KANG CRESCENT  
#09-495  
Postcode 680672  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-

**General Information of the Accident**

Type Of Accident COLLIDED INTO PARKED VEHICLE  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLS REFER TOT HE POLICE REPORT:T/20190320/2091

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SFZ8299U  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

A - SM E535T  
B - SFZ82994

PASIR RIS ST 01  
LOYANG POINT  
CARPARK




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Pls refer to the police report: 9/20190320/2091

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20190320/2091

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

1 of 3

Report No. T/20190320/2091

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2019 13:42	Vide Report No.:	Station Diary No.: 37
--	------------------	--------------------------

### Informant's Particulars

Name of Informant: AZMI BIN MOHAMAD YUSOFF		Address: APT BLK 672 CHOA CHU KANG CRESCENT #09-495 SINGAPORE 680672	
ID Type / ID No.: NRIC NO / S6826601G		Contact No.: Home/Office: Mobile: 97673475	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 23/08/1968	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: TECHNICIAN		Driving Licence Information: Class: Date of Expiry:	

### General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 20/03/2019 12:20	Type of Location: Car Park
Location: Along Road 1 PASIR RIS STREET 21 At the Car Park of Loyang Point				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFZ8299U	Car					0
SME535T	Car	AUDI			Slightly Damaged	0

### Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SME535T	MSIG INSURANCE (SINGAPORE) PTE. LTD.	A80463989QMX	08/11/2018	07/11/2019



**SINGAPORE  
POLICE FORCE**



T/20190320/2091

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

2 of 3

Report No. T/20190320/2091

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	AZMI BIN MOHAMAD YUSOFF	ID No.	S6826601G
Related Vehicle	SME535T (Car)	Contact No.	97673475
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/03/2019 at about 1205hrs, I parked my car SME535T at level 3 of Loyang Point Car Park.

I then alighted from my vehicle and went for lunch.

At 1245hrs after I had my lunch, I then went back to my vehicle. While I was at my vehicle, one male Chinese passer by stop me and informed that earlier he saw someone drove the car registration plate number SFZ8299U hit on my front right portion of my vehicle.

I then take a look at my front portion of my vehicle, I discovered that there is some dented and scratches on my vehicle.

I wish to state that I have in Car Camera.

*[Faint, illegible text and markings, possibly a signature or stamp]*



# SINGAPORE POLICE FORCE



1/20190320/2091

3 of 3

Report No. T/20190320/2091

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

## CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

*[Faint, illegible handwritten notes]*

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
G /  
Staff Sgt IDRIS BIN ROSLI

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
20/03/2019 13:42

Officer In Charge Of Case:  
TP / HRT /  
SI ABDUL KAREEM BIN ABDUL HAGUE  
Contact No.: 65476079

Classification Of Case:

Authentication Stamp  
NP168



# Certificate of Insurance

COPY

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

**MOTOR MAX  
Comprehensive**

Certificate No. A 80463989 QMX

Excess : SGD1,500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
SME535T

2. Name of Policyholder  
AZMI BIN MOHAMAD YUSOFF

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
08/11/2018

4. Date of Expiry of Insurance  
07/11/2019

5. Persons or Classes of Persons entitled to drive\*

AZMI BIN MOHAMAD YUSOFF

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG  
AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.




Signature / Date

Counter-Signatory:

StarBright Auto Pte Ltd

MSIG Insurance (Singapore) Pte. Ltd.  
Approved Insurers



Amy Ler  
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S6826601G



Name  
AZMI BIN MOHAMAD YUSOFF


Race  
MALAY  
Date of Birth: 23-08-1968 Sex: M  
Country of Birth  
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S6826601G  
Name:  
AZMI BIN MOHAMAD YUSOFF

Birth Date: 23 Aug 1968  
Issue Date: 16 Apr 2003



2547255



NRIC No. S6826601G

Blood Group: A+ Date of Issue: 21.12.1994

APT BLK 672 CHOA CHU KANG CRESCENT #09-495  
SINGAPORE 680672  
S6826601G 22/07/2013

Class 2B Motorcycles <= 300 CC 21 Mar 1996  
Class 2A Motorcycles between 301 CC and 400 CC 15 Jul 2003  
Class 2 Motorcycles > 400 CC 24 Jun 2008  
Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg 01 Jun 2004

S6826601G

S / No. 9000087625

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2019		03 Apr 2019 14:50 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>AZMI BIN MOHAMAD YUSOFF</b>								
Vehicle Reg. No.:	<b>SME535T</b>	Date of Loss:	20/03/2019 12:00 - :59 <b>[70 Months and 14 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM19D201283C02</b>	Policy/Cover Note No.:	DMPCSN3084781803						
Vehicle Reg. No. (Insured):	<b>SFZ8299U</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>My Car Consultant Pte Ltd (Ubi)</b> 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 12/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SME535T (SNM19D201283C02)**  
**[SFZ8299U]**  
**TP**  
**AZMI BIN MOHAMAD YUSOFF**  
**Mar 20 2019 12:00PM**  
**[-]**  
**My Car Consultant Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		<b>View</b> View in Browser <input type="button" value="v"/>		
<b>Photos/Images</b>							3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
2	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
3	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
4	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
5	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
6	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
7	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
8	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
9	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
10	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
11	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
12	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
13	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
14	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
15	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
16	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
17	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
18	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
19	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
20	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
21	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
22	04/04/19 11:52	General View		Load JPG	<input checked="" type="checkbox"/>			
23	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
24	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
25	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
26	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
27	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
28	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
29	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
30	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
31	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
32	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
33	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
34	04/04/19 11:52	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
<b>Documentation</b>							1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/19 14:55	PRS - SME535T	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI19005530/BCD3E2

**Date:** 04/04/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3084781803	
Claimant Vehicle No: SME535T	Insured Vehicle No: SFZ8299U	
Date of Loss: 20/03/2019	Nature of Claim: TP	Claim No: SNM19D201283C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME535T		
Make & Model:	AUDI A6, 2.0 (A)	Engine No:	CDN331992
Reg. Date:	06/05/2013 (Man. Year: 2013)	Chassis No:	WAUZZZ4G5DN121783
Colour:	Silver	Odometer:	40706 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	03/04/2019	
Date Inspected:	29/03/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934
Estimated Period of Repair:	3.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
<b>Parts:</b> 143	AUDI A6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME535T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >