



Your Ref: DMPC1800333H

Date: 28<sup>th</sup> March 2019

Our Ref: CS1/ICS19005532/Gsd3s2

**M/s ECICS Ltd**

10 Eunoss Road 8

Singapore Post Centre #09-04A

Singapore 408600

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLB 8543U  
INSURED VEHICLE: SLM 4646A ACCIDENT DATE: 13/08/2018**

We thank you for your instruction on 28/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLB 8543U from M/s Constant Appraiser Services.
- b) Final Repair Bill of SLB 8543U from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SLB 8543U and SLM 4646A.
- d) Colour damaged vehicle photographs of SLB 8543U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLB 8543U
Make & Model	: Nissan Sylphy 1.6
Year of Registration	: 2016
Chassis Number	: MNTBBAB17Z0026892
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.