







<b>INS CASE OWNER:</b>		<u>Richard</u>	<u>CC 4 / AXA 1900 5577 RPKB39</u>	LKK: IDAC:
<b>Surveyor:</b>	<u>Renu</u>	<b>DOI:</b>	<u>21/5/19</u>	<b>Date / Time:</b> <u>21/5/19</u>
<b>Pre-assign / CCU / FTE</b>	<u>FBA 98256</u>			
 Insured Vehicle No.	<u>FATHUL RAHMAN DIR 18011111</u>	Claim No.	<u>Samo/GK4 / 106829</u>	
Name of Insured		Policy No.	<u>VMBR / PIA 8723</u>	
Insured Tel No.		Make / Model	<u>Honda</u>	
Excess Sec II :SS		D.O.A :	<u>4/7/14</u>	
Is driver the owner? ( YES / NO )		Nature of Accident :	<u>Parking K0</u>	
If NO, Driver Name / Age :		OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO		
Driver Tel No. :	(V/L: YES / NO )	Insured Liability :	% Final ? Yes / No	
<u>SKL 9697H</u>				
 INSRs: WSP: <u>performance</u>	 INSRs: WSP:	 INSRs: WSP:	 INSRs: WSP:	 INSRs: WSP:
Tel:	Tel:	Tel:	Tel:	Tel:
Liability :	Liability :	Liability :	Liability :	Liability :
RMKS:	RMKS:	RMKS:	RMKS:	RMKS:
<b>Date/Time</b>	<b>STAGE</b> Non-Reporting Ir (1st) Non-Reporting Ir (2nd) Non-Reporting Ir (Final) Notification Ir (if non-pickup) Call OI After call Ir to OI: <u>o2lotha - vic</u> <b>Documentation Check List:</b> Handler Typist Notification Ir (if non-pickup) <input checked="" type="checkbox"/> <input type="checkbox"/> After call Ir to OI <input checked="" type="checkbox"/> <input type="checkbox"/> Authorisation To Act <input checked="" type="checkbox"/> <input type="checkbox"/> Release Voucher <input checked="" type="checkbox"/> <input type="checkbox"/> Final Repair Bill <input checked="" type="checkbox"/> <input type="checkbox"/> Car Rental Invoice <input type="checkbox"/> <input type="checkbox"/> Towing Invoice <input type="checkbox"/> <input type="checkbox"/> LTA / GIA <input checked="" type="checkbox"/> <input type="checkbox"/> Medical Bill <input type="checkbox"/> <input type="checkbox"/> PIR <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="radio"/> Mandate/Reject Instruction <input checked="" type="checkbox"/> <input type="checkbox"/> LOD <input type="checkbox"/> <input type="checkbox"/> Payment Breakdown Form: <input type="checkbox"/> <input type="checkbox"/> Post-Repair Photos: <input type="checkbox"/> <input type="checkbox"/> Others: <input type="checkbox"/> <input type="checkbox"/>			
<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:		
<b>FINALIZATION</b>	Date/Time:	Confirm with:		
Repair Cost:	\$S	( days ) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/>		
<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with:		
Final Liability:	%	( Agreed / Assigned ) BOLA S/N No. IE		
Repair Cost:	\$S <u>3627.09</u>			
Loss of Rental (LOM):	\$S	( days )		
Loss of Use (LOU):	\$S <u>2400</u>	( \$60 x 4 days )		
Loss of Income (LOI):	\$S	( \$ x days )		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	\$S <u>200</u>			
Medical:	\$S			
Disbursement:	\$S	(e.g. Tow/ Independent)		
Legal Cost:	\$S			
Total:	\$S <u>3899.09</u>	Global Sum SS:		
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:		
Payee 1:	\$S <u>3899.09</u>	Name 1: <u>Performance Motors Ltd</u>		
Payee 2: (Strike if N/A.)	\$S	Name 2:		
Payee 3: (Strike if N/A.)	\$S	Name 3:		

*Ram*

REF: ASM

h

4791F

ASSIGNMENT

From: Date: 21.5.2019

Estimated Cost: A/L 10 am

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 2697H

at Workshop n/s Performa motor

of 303 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Chua Kue sin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 64k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: 4 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"rup"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKL 2697H Yr Regn: 2013 / 04

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 116 I AT cc: 1598

Colour: WHITE A/C Insured / Std / NI / NA

Sp. Reading: 118016 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA1A12000J215020

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 04/03/19 D.O.I: 21/05/19

Survey held at: PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP # 3371.11 (Reel # 4652.99/58%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

) S + RS, SR

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401558W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 155944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

27 MAR 2019

Estimate No. : b1 50622  
Date Estimated : 27/03/2019  
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Au Shao Xian, Harold  
815B UPPER EAST COAST ROAD

SINGAPORE 466610

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

## DESCRIPTION

Replace front bumper, left front door and remove attachment etc include repair on accident damage area

Spray painting left front door and front bumper

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To carry out body cavity preservation.  
(Per panel).

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

Sundries. *See*

## VALUE

1930 1700 2,550.00

1557 1730 1,923.00

135 150 177.00

111 X 118.00

111 X 531.00

80. ? 150.00

Total Labour 1: 5,449.00

## DESCRIPTION

FRT LH DOOR *repair* ?  
FRT LH SIDE PANEL SUPPORT ?  
FRT RH SIDE PANEL SUPPORT ?  
FRT BUMPER LH INSERT ?  
FRT BUMPER RH INSERT ?  
FRT BUMPER PANEL PRIMED (SRA) *repair*  
EMBLEM GROMMET *new*  
FRONT DOOR BRAKE ?  
FRT DOOR JOINT SEAL ?  
Sealing ?  
FRT LH DOOR WINDOW GUIDE ?  
FRT LH DOOR INSIDE CHANNEL SEALING ?  
FRT LH DOOR CHANNEL SEALING ?  
FRT DOOR EDGE PROTECTOR ?  
PLAQUE 82MM *new*

QTY	PRIC	VALUE
1	1,077.40	1,077.40
1	12.50	12.50
1	12.50	12.50
1	7.55	7.55
1	7.60	7.60
1	862.90	862.90
2	0.80	1.60
1	71.00	71.00
1	38.00	38.00
1	21.80	21.80
1	105.85	105.85
1	60.95	60.95
1	71.70	71.70
1	152.50	152.50
1	71.25	71.25

69.11 71.25



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 43190100 (Sales & Admin)  
43190111 (AfterSales)  
Fax. 44747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 43190888 (AfterSales)  
Fax. 43449773

313, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 43190520 (AfterSales)  
43190533/530 (Motorrad)  
Fax. 44796401 (AfterSales)  
44796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 50622  
Date Estimated : 27/03/2019  
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

Total Parts : 2,575.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 21/05/19 @ 1320 Excess S\$ \_\_\_\_\_Surveyor's Name Raghu Sign \_\_\_\_\_Surveyor's Tel 90000068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 4 days

8024.10

Labour 1	:	5,449.00
Parts	:	2,575.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	561.69
Grand Total	:	8,585.79

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## FINAL REPORT

Estimate No. : b1 50622  
Date Estimated : 27/03/2019  
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -  
Au Shao Xian, Harold  
815B UPPER EAST COAST ROAD

- ACCOUNT - 238  
AXA Insurance Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

SINGAPORE 466610

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front LH door, front bumper include replacement of damaged part and knocking out dents caused by the accident	1700.00	10.00	1,530.00
To spray paint front LH door and front bumper	1730.00	10.00	1,557.00
To check electrical wiring systems at the front section for proper function	150.00	10.00	135.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
PLAQUE 82MM	71.25	1.00	3.00	69.11

### # SUPPLEMENTARY ITEMS

Total Labour :	3,302.00
Total Parts :	69.11
Total Labour & Parts :	3,371.11
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,371.11
GST @7%:	235.98
Grand Total :	3,607.09



## Service Request Details

Claim

S9M01GKX

Reference

None

Loss Date

4 March 2019

Report Date

11 Mar 2019 12:00:00 AM

Request Date

28 March 2019

Due Date

28 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*Performance*

### Actions

Next Step

Finish the work

Complete Work

More ▾

### Vehicle Information

Incident Vehicle Registration #

SKL2697H

Make

TPVD BMW

## Service Address

---

...

## Primary Contact/Insured

---

IBRAHIM FATHUL RAHMAN BIN  
BLK 190 #08-26, PASIR RIS ST 12, 510190, Singapore  
96753009  
f1116415@hotmail.com

## Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## Hsiao Tong (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Friday, 5 July 2019 8:42 AM  
**To:** PBSP  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: FINAL REPORT/ SKL2697H

Hi Caroline,

Finalised amount confirmed

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** PBSP [mailto:[pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg)]  
**Sent:** Thursday, 4 July, 2019 6:47 PM  
**To:** Rasul (LKKAUTO); Vic (LKKAUTO)  
**Subject:** FINAL REPORT/ SKL2697H

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,302.00

Total Parts : 69.11

Total Labour & Parts : 3,371.11

Repair days: 4

Thank you.

Regards,  
Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete



all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



**<TP - Mandate IA> - S9M01GKX [ACCIDENT INVOLVING  
FBA 9822G(OI) & SKL 2697H(TP) ON 04/03/2019]**

Type

 Question

Message

Liability: 100%. Insured changed lane and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,914.54(if claim LOU) - \$4,149.54(if claim LOR). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 05 July 2019

Reply



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 05/07/2019

### Survey Details:

Date of loss	4-Mar-19
Date of appointment	28-Mar-19
Date of survey	21-May-19
Location of survey	PERFORMANCE MOTORS LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SKL 2697H
Make and Model	B.M.W. 116i AT ABS D/AIRBAG
Date of registration	22/10/2013
Excess	
Market Value	\$64,000
Part Rebate	\$50,557
Nett Loss	\$13,443

### Repair details:

Initial Estimate	\$ 8,024.10
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 69.11
Check items (estimate)	NIL
Labour	\$ 3,302.00
<b>Total</b>	<b>\$ 3,371.11</b>
Lump Sum(if applicable)	\$ -

Number of days for repair	4
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 3,607.09	\$ 3,607.09
Loss of use (5days x \$60.00)	\$ 300.00	NIL
Loss of rental (5days x \$100.00)(w/GST)	NIL	\$ 535.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
<b>Proposed Total</b>	<b>\$ 3,914.54</b>	<b>\$ 4,149.54</b>



**Re:<TP - Mandate IA> - S9M01GKX [ACCIDENT INVOLVING FBA 9822G(OI) & SKL 2697H(TP) ON 04/03/2019]**

Type

 Question

Message

Hi, pls proceed as per mandate. TY

Reply

## YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.  
All accidents must be reported within 24 hours or the next working day of the incident  
regardless of whether it will lead to a claim.

**POLICY NUMBER** : PNPV2016-00000121-02

### About this policy

Premium paid	: S\$873.63	Coverage start date	: 22/10/2018
(Inclusive of GST)		Coverage end date	: 21/10/2019
Who is insured to drive:	: You and any Authorised Driver		
Policy Type	: CLASSIC		

### About you (As the policyholder)

Your name	: Au Shao Xian Harold		
Address	: 61 Tampines Central 7 #09-23 Citylife @ Tampines Singapore 528595		
Email	: haroldau87@gmail.com		
NRIC/FIN	: S8714791F	Date of birth	: 29/05/1987
Marital status	: Married	Gender	: Male
Current no claims discount	: 50%	Mobile Number	: 96729277
Years of driving experience	: Three or more	Certificate of merit	: Yes

### About your car

Car make and model	: BMW 116I
Year of first registration	: 2013
Car plate number	: SKL2697H
Issued on:	: 04/10/2018



**Abhishek Bhatia**  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions and exclusions of this policy.

Please immediately inform us at +65-6820-8888 or email us to [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details in this Car Insurance Summary need to be changed.



## CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

**POLICY NUMBER: PNPV2016-00000121-02 (Comprehensive - Classic Plan)**

Car plate number: SKL2697H

Your name (As the policyholder): Au Shao Xian Harold

Coverage start date: 22/10/2018

Coverage end date: 21/10/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: UOB Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 04/10/2018

**Abhishek Bhatia**  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888  
or email us at [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details  
in this Certificate of Insurance need to be changed.

The following are maximum limits per Accident as defined in the contract.

Emergency assistance	Yes
Third party liability:	No Limit
Death or injury to a third party	S\$5,000,000
Damage to a third party's property	S\$3,000
Legal costs	
Loss or damage by fire or theft	Market value
Accidental loss or damage to	Market value
Your car	S\$500
Your car's accessories	No
Personal belongings	
Excess	
Standard excess	S\$500
Young driver excess	S\$2,500
Windscreen replacement excess	S\$100
Lifetime NCD guarantee	Yes
Towing	S\$300
Safe travel after an accident	S\$40 per occupant
Daily transport allowance	S\$40 per day for 6 days
Replacement keys and locks	No
Personal accident sum insured	
For the driver	S\$30,000
For each passenger	S\$10,000
Guardian angel benefit	S\$250,000
Extended workmanship guarantee (for repairs done by FWD Premium Workshops)	Yes
New car replacement (if Your Car is written off while less than one year old)	Yes
Car repairs at	
FWD premium workshops	Yes
Your preferred workshop	Yes



**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **S8714791F**  
 Name: **AU SHAO XIAN, HAROLD**  
 Birth Date: **29 May 1967**  
 Issue Date: **24 Jul 2010**

001670256B



**REPUBLIC OF SINGAPORE**  
 IDENTITY CARD NO. **S8714791F**



Name: **AU SHAO XIAN, HAROLD**  
 區紹賢  
 Race: **CHINESE**  
 Date of birth: **29-05-1967** Sex: **M**  
 Country of birth: **SINGAPORE**

S8714791F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

	EFFECTIVE DATE
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 3500kg	28 Jun 2007

Licence No: S8714791F



NP 425A

4615768



S8714791F



Date of issue: **24-07-2010**

61 TAMPINES CENTRAL 7 #09-23  
 SINGAPORE 528595  
 NRIC No: S8714791F Date: 30/10/2016

## Hsiao Tong (LKKAUTO)

---

**From:** PBSP <pml-pbsp@simeдарby.com.sg>  
**Sent:** Tuesday, 27 August 2019 6:26 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** Re: FINAL REPORT/ SKL2697H \*LKK REF: CC4/ASM19005533/R1pb3

Dear Hsiao Tong

We have instructions to accept your offer of settlement.

Please proceed using our Pre-signed dv for payment.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Sent:** Saturday, 17 August 2019 8:42 AM  
**To:** PBSP <pml-pbsp@simeдарby.com.sg>  
**Subject:** RE: FINAL REPORT/ SKL2697H \*LKK REF: CC4/ASM19005533/R1pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,607.09
2. Loss of Use (4days x \$60.00)	\$ 240.00
3. LTA/GIA Search Fee	\$ 2.00
<b>Total</b>	<b>\$ 3,849.09</b>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Sent:** Friday, 5 July 2019 8:42 AM

**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Subject:** RE: FINAL REPORT/ SKL2697H

Hi Caroline,

Finalised amount confirmed


Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** PBSP [<mailto:pml-pbsp@simedarby.com.sg>]  
**Sent:** Thursday, 4 July, 2019 6:47 PM  
**To:** Rasul (LKKAUTO); Vic (LKKAUTO)  
**Subject:** FINAL REPORT/ SKL2697H

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,302.00

Total Parts : 69.11

Total Labour & Parts : 3,371.11

Repair days: 4

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

(Asses Tony)



AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01  
Singapore 068811  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref :

Our Ref :

Date :

15 July 2019

Subject :

**ACCIDENT INVOLVING VEHICLES SKL2697H & FBA9822G ON 04.03.2019**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of Repair	:	S\$	3607.09
Loss of use	:	S\$	320.00 (S\$80.00 x 4 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	3929.09

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Yours sincerely

Cresendo Lagman  
Customer Service Manager, Body & Paint

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)

[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales:  
6319 0527  
Fax 6479 6624

290  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales:  
6319 0888  
Fax 6344 1332

Registration office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401559W



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

02 APRIL 2019

**FATHUL RAHMAN BIN IBRAHIM  
190 PASIR RIS STREET 12  
#08-26  
SINGAPORE 510190**

**By Post & By Email**

Dear Sir/Madam,

**OUR REF : CC4/ASM19005533/hb3  
YOUR REF : FBA 9822G  
ACCIDENT INVOLVING FBA 9822G AND SKL 2697H ALONG ROCHOR ROAD ON  
04.03.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s PERFORMANCE MOTORS LTD acting on behalf of the owner of SKL 2697H against your motor insurance policy.

Based on the accident report and accident, it was reported that your vehicle had collided to the Third Party vehicle SKL 2697H. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

[F1116415@hotmail.com](mailto:F1116415@hotmail.com)  
(Email)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 2 April, 2019 4:59 PM  
**To:** F1116415@hotmail.com  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** YOUR REF: FBA 9822G\_ACCIDENT INVOLVING FBA 9822G AND SKL 2697H ALONG ROCHOR ROAD ON 04.03.2019



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

02 APRIL 2019

**FATHUL RAHMAN BIN IBRAHIM**  
**190 PASIR RIS STREET 12**  
**#08-26**  
**SINGAPORE 510190**

**By Post & By Email**

Dear Sir/Madam,

**OUR REF : CC4/ASM19005533/hb3**

**YOUR REF : FBA 9822G**

**ACCIDENT INVOLVING FBA 9822G AND SKL 2697H ALONG ROCHOR ROAD ON 04.03.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s PERFORMANCE MOTORS LTD acting on behalf of the owner of SKL 2697H against your motor insurance policy.

Based on the accident report and accident, it was reported that your vehicle had collided to the Third Party vehicle SKL 2697H. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKL2697 H & FBA7822 G ON 4/3/2019.

I, Au Shao Xian owner of Vehicle Registration No. SKL2697 H  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment  
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

Name: Harold Au (Date)

NRIC No.: S8714791F 27/3/19

In the presence of:

CHUA KEE SIN  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Name: \_\_\_\_\_ (Date)

NRIC No.: \_\_\_\_\_

27/3/2019  
@ 1116hrs



redefining / insurance

CLAIM REF : S9MUIGRX  
INSURED : Fathul Rahman bin Ibrahim

**DISCHARGE VOUCHER**

We/I Au Shao Xian, NRIC NO. S8714791 E hereby agree to accept the sum of dollars Three Thousand Eight Hundred Forty Nine & Cent Nine Only (\$\$ 3849.09) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. FEA 9822 G as a result of an accident along Road A to RT Tanah A 54 J / Bengawan Street on 4.3.19 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SXL 2677 H.

We/I hereby declare that the said Insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. FEA 9822 G in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. FEA 9822 G.

Dated this 29 day of Aug 2017 19

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

\_\_\_\_\_

Occupation/ Business

\_\_\_\_\_

Address

\_\_\_\_\_

Telephone No.

\_\_\_\_\_

Witness's Name

\_\_\_\_\_

Witness's Signature

\_\_\_\_\_

Witness's NRIC No.

\_\_\_\_\_

CHUA KEE SIN  
Performance Motors Limited  
333 Alexandra Road  
Shin Darby Performance Centre  
Singapore 159941



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Rempang Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63180888 (AfterSales)  
Fax. 63445773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190538 (AfterSales)  
63190533/536 (Motorrad)  
Fax. 6478601 (AfterSales)  
6478624 (Motorrad)

**SERVICE TAX INVOICE**Repair Order No. : **B1 1363358**Date IN : **21/05/2019**Cust. Svc. Advisor: **Chua Kee Sin**Page No. : **1 of 2**Invoice Number : **2121438 / WSB**Invoice Date : **09/07/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng****- CUSTOMER INFORMATION -**

Mr Au Shao Xian, Harold  
815B UPPER EAST COAST ROAD

**SINGAPORE 466610****- INVOICE TO - 238**

AXA Insurance Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

REGN. NO.  
**SKL2697H**

CHASSIS NO.  
**J215020**

REGN. DATE  
**22/10/2013**

MODEL  
**116IA/5**

MILEAGE  
**118016**

**- - - - LABOUR 1 - - - -**

To make good the front left door, front bumper and knock  
out dented area caused by the accident. To remove and  
install body parts in order to carry out painting job.

To respray front left door and front bumper.

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 4.3.2019. 3RD PARTY CAR : FBA9822G.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO  
CONSULTANTS PTE LTD ON 21.5.2019 AT 1.20 PM.  
AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON 2.4.2019  
VIA E-MAIL.

PROPOSE LOSS OF USE = \$80X4. THE AMOUNT IS SUBJECTED  
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

1,700.00

10.00

1,530.00

1,730.00

10.00

1,557.00

150.00

10.00

135.00

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

**Total Labour 1:****3,302.00****- - - - PARTS - - - -**

PLAQUE 82MM

Retail

Qty

Price

DISC%

NETT

1

71.25

3.00

69.11

**Total Parts :****69.11**

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401339W GST Reg. No. M1-0020881-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

288, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/880 (Motorrad)  
Fax. 64796401 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : **B1 1363358**

Date IN : **21/05/2019**

Cust. Svc. Advisor: **Chua Kee Sin**

Page No. : **2 of 2**

Invoice Number : **2121438 / WSB**

Invoice Date : **09/07/2019**

Payment Terms : **30 Days From Invoice**

Invoice By : **Sharon Heng**

Labour Charges : **3,222.00**  
Parts Charges : **69.11**  
Lubricant/Misc : **80.00**

Total Labour & Parts Charges	: S\$	<b>3,371.11</b>
Less Insurance Excess	: S\$	<b>0.00</b>
Invoice Total Amount Exclude GST	: S\$	<b>3,371.11</b>
GST @ 7%	: S\$	<b>235.98</b>
Invoice Total Amount Include GST	: S\$	<b>3,607.09</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,607.09**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-19-047743  
Date of Request: 27/03/2019

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 27/03/2019  
Enquiry By: Melanie Setiawati  
TP Vehicle No: FBA9822G  
Accident Date: 04/03/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FBA9822G	AXA Insurance Pte Ltd	05/06/2018-04/06/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-047743

Date of Request: 27/03/2019

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 27/03/2019  
Enquiry By Melanie Setiawati  
TP Vehicle No. FBA9822G  
Accident Date 04/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBA 9822G (Insd veh)	Model:	B.M.W. 116I AT
	SKL 2697H (TP veh)		
Date of Accident:	04/03/2019		

Global Sum Settlement	: [ ] Yes	: [ X ] No	
Repair Estimate	: \$		8,585.79
Final Repair Cost	: \$		3,607.09
Loss of Use	: \$		240.00
Rental (if any)	: \$		4days at \$60.00 per day
LTA / GIA Search Fee	: \$		2.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	3,849.09

Is Third Party Workshop GIA Registered?		[ X ] YES	[ ] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
		_15_		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks				

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LIMITED	: \$ 3,849.09

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

12/09/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005533/R1pb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:RICHARD

Date : 12-09-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBA 9822G	Veh. Inspected	SKL 2697H
Policy No.	VMZ/P1943733	Coverage (\$)	0.00
Claim No.	S9M01GKX	Excess (\$)	0.00
Assign From		Assign Date	28/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116I AT	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA1A12000J215020	Colour	WHITE
Odometer	118016	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	04/03/2019	Inspection Date	21/05/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 2697H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
1	FRT LH DOOR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,077.40	-
1	FRT LH SIDE PANEL SUPPORT (SN) (CONSISTENT)	NOT NECESSARY	12.50	-
1	FRT RH SIDE PANEL SUPPORT (SN) (CONSISTENT)	NOT NECESSARY	12.50	-
1	FRT BUMPER LH INSERT (SN) (CONSISTENT)	NOT NECESSARY	7.55	-
1	FRT BUMPER LH INSERT (SN) (CONSISTENT)	NOT NECESSARY	7.60	-
1	FRT BUMPER PANEL PRIMED (SRA) (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	862.90	-
2	EMBLEM GROMMET (SN) (CONSISTENT)	NOT NECESSARY	1.60	-
1	FRONT DOOR BRAKE (SN) (CONSISTENT)	NOT NECESSARY	71.00	-
1	FRT DOOR JOINT SEAL (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
1	SEALING (SN) (CONSISTENT)	NOT NECESSARY	21.80	-
1	FRT LH DOOR WINDOW GUIDE (SN) (CONSISTENT)	NOT NECESSARY	105.85	-
1	FRT LH DOOR INSIDE CHANNEL SEALING (SN) (CONSISTENT)	NOT NECESSARY	60.95	-
1	FRT LH DOOR CHANNEL SEALING (SN) (CONSISTENT)	NOT NECESSARY	71.70	-
1	FRT DOOR EDGE PROTECTOR (SN) (CONSISTENT)	NOT NECESSARY	152.50	-
1	PLAQUE 82MM (SN) (CONSISTENT)	NECESSARY	71.25	69.11
			2,725.10	149.11
<b>LABOUR</b>				
REPLACE FRONT BUMPER ,LEFT FRONT DOOR AND REMOVE ATTACHMENT ETC INCLUDE REPAIR ON ACCIDENT DAMAGE AREA.INCLUSIVE OF THE REPAIR OF FRT LH DOOR AND FRT BUMPER PANEL PRIMED (SRA) .			2,550.00	1,530.00
SPRAY PAINTING LEFT FRONT DOOR AND FRONT BUMPER.			1,923.00	1,557.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	135.00
TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		NOT NECESSARY	118.00	-

Report Ref No. CC4/ASM19005533/R1pb3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR).	NOT NECESSARY	531.00	-
			5,299.00	3,222.00
GRAND TOTAL			8,024.10	3,371.11
RECOMMENDED COST OF REPAIRS				3,371.11

Report Ref No. CC4/ASM19005533/R1pb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

« Service Request Details

Claim	SYNDICX
Reference	CC-A/ASM19005533/R1jb3u2 
Loss Date	4 March 2019
Report Date	11 Mar 2019 12:00:00 AM
Request Date	28 March 2019
Due Date	

Vendor Name	LK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

ADD Invoice #

Vehicle Information	
Incident Vehicle Registration #	SKL2697H
Make	TPVD BMW
Model	116i AT ABS D/ARBAG 2WD HID SDR
Service Address	
...	

Primary Contact/Insured
IBRAHIM FATHUL RAHMAN BIN BLK 190 #08-26, PASIR RIS ST 12, 510190, Singapore 96753009 11116415@hotmail.com

Claim Handler
ANG Richard richard.ang@axa.com.sg

Additional Instructions

- 3
- MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	UPLOADED 13 September 2019
LDD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2019
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
TP-Mandate IA del 050719 .pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
TP ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
IA-2697 .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LETTER TO OLP.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	2 April 2019
 Email to OI dtd 020419.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	2 April 2019
 TP PSI EMAIL FROM WORKSHOP WITH ESTIMATE & TP GIA.mig	Letters and Correspondence	Third Party	DHIWAR Namrata	28 March 2019
 FBA962G INSD GIA.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	28 March 2019