

INS. CASE OWNER:

Ins Tan | CC 4, ASM 1900 SS JS, KLEARY

IDAC:

107049

Pre-assign:

DOI:

ASSIGNMENT

29/03/19

Date / Time:

28/3/2019

Registered in Merimen:

Pre-assign / CCU / FTE

PC 6938A

"VIRTUAL"

Insured Vehicle No.:

Claim No.:

9m0179k

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

28/03/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

X616645

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: (NO NEED)

Authorisation To Act:

Release Voucher: DS FORM

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: MZS

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$5650.00

(2 days)

Reduction:

41 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 04-06-19

Confirm with: Susan

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

\$5695.50

2 REPAIR BILLED TO

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5300.00

(\$ 150 x 3 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350

Total:

\$5917.50

Global Sum \$5:

FINAL PAYMENT

Date/Time: 04-06-19

Confirm with: Susan

Email ☒ Call ☐

Payee 1:

\$5917.50

Name 1:

SH SUBS ENGINEERING SERVICES

Payee 2 (Strife / FNA):

\$5

Name 2:

Payee 3 (Strife / FNA):

\$5

Name 3:

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD
41 PANDAN ROAD
SINGAPORE 609283

Attention : Motor Claim Department
Contact : 6349 3836

Estimate : ES002797

Date : 01/04/2019
Vehicle Num. : XE1664S
Make/Model : NISSAN GKB5E-2016
Chassis/Eng# : JNCM1F1AXGU006961/GH11735037
Accident Date : 25/03/2019
Claim No. :
Reference : PC6938A
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	1	NUMBER PLATE BRACKET <i>bt</i>	435	250.00
3.	1	NUMBER PLATE LAMP <i>bro</i>	10%	75.00
4.	1	NUMBER PLATE <i>bt</i>		20.00
	<i>2 pc</i>	REVERSE LAMP <i>mis</i>	90.00	180.00
Nett Total S\$:				525.00
10.00% Discount S\$:				52.50
				472.50

LABOUR :
TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
SPRAY PAINTING
LOSS OF USE : 3 DAY S@ \$ 250/DAY
Labour Total S\$:

450
250
200
450.00
300.00
750.00

Total S\$: 1,222.50

Susan

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 90010068
2 days
45
29/03/19 @ 1710
Resurvey after repair
391.50
450.00
841.50
20%
673.20
45-650
2 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UHI AVE 1, #02-25 PAYA UHI INDUSTRIAL PARK, SINGAPORE 400933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07/05/2019

Survey Details:

Date of loss	25-Mar-19
Date of appointment	28-Mar-19
Date of survey	29-Mar-19
Location of survey	SIN SHENG ENGINEERING SERVICES

Vehicle Details:

Claim Type:	Third party
Vehicle number	XE 1664S
Make and Model	UD TRUCKS
Date of registration	26/4/2016
Excess	
Market Value	\$0
Part Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 1,222.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 391.50
Check items (estimate)	\$ -
Labour	\$ 450.00
Total	\$ 841.50
Lump Sum(if applicable)	\$ 650.00

Number of days for repair	<u>2days</u>
---------------------------	--------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured rear ended third party vehicle.

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	695.50	
Loss of use	\$	600.00	4days x \$150
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	7.49	
Others	\$	-	
Proposed Total	\$	1,302.99	

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 28 March, 2019 3:43 PM
To: assignments
Subject: FW: Accident Involving XE1664S with PC6938A on 25/03/2019
Attachments: XE1664S_PRI.pdf; XE1664S_TP search fee.pdf; GIA REPORT_XE1664S.pdf

Hi team

Kindly assist. TP smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Time: 28.3.2019 3.48pm

Person: AH HO

v : Out

From: sinsheng engineerservices <sinsheng1981@gmail.com>
Sent: Wednesday, 27 March, 2019 12:17 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: Accident Involving XE1664S with PC6938A on 25/03/2019

Dear Officer Incharge,

We are repairer of motor vehicle XE1664S . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

10-May-19

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933

Fax: 6741 4108
Tel: 6256 3561

Our ref: SSES/L2019/0192
Your ref: CC4/ASM19005575/ea3

Attn: Ms Asher

Dear Sir,

VEHICLE: XE1664S (DoA: 25/03/2019)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	695.50
Loss of Use: 4 days @ S\$ 250/day (including 2 day for PRI)	:	1000.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	2.00
Total	:	<u><u>1,697.50</u></u>

Thank You

Yours faithfully

Susan Tan
OPERATIONS EXECUTIVE
Encl

AUTHORIZATION TO ACT

I, C & P LEASING PTE LTD ("The Third Party Claimant") of
41 PANDAN ROAD, SINGAPORE 609283 (address),
being the owner of XE1664S (vehicle no.) hereby authorize
SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me
with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my
vehicle bearing registration no. XE1664S that was damaged pursuant to the accident
which occurred on 25/03/2019 along 2 Woodlands Industrial Park D St 2
involving vehicle's XE1664S / PC6938A ("the
accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem
fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability in so far as the driver/owner/insurers of
the other vehicle is concerned.

Dated this 09 day of MAY (month) 2019 (year)



Signed by "the Third Party claimant"



Signed by "the workshop"



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	PC 6938A	[Insd veh]	Model: UD TRUCKS ESCOT
	XE 1664S	[TP veh]	
Date of Accident/ Time:	25/03/2019 / 08.15		

Repair Estimate	: \$	1308.07	
Final Repair Cost	: \$	695.50	
Loss of Use	: \$	300.00	2 days at \$150.00 per day
Rental (if any)	: \$	-	days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	-	
	: \$		
Final Settlement Sum	: \$	997.50	

Payee Name : SIN SHENG ENGINEERING SERVICES

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

  Signature of workshop representative / Workshop stamp Name of Representative: _____ Date: <u>12/6/19</u>	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: _____ Date: <u>12/6/19</u>
 Signature of AXA's surveyor/representative: Name of AXA's surveyor / Representative: _____ Date: <u>12/6/19</u>	

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD

41 PANDAN ROAD

SINGAPORE 609283

Attention : Motor Claim Department

Contact : 6349 3836

Tax Invoice : TI002797

Date : 10/05/2019

Vehicle Num. : XE1664S

Make/Model : NISSAN GKB5E-2016

Chassis/Eng# : JNCM1F1AXGU006961/GH11735037

Accident Date : 25/03/2019

Claim No. :

Reference : PC6938A

Policy No. :

Amount S\$

ACCIDENT LUMP SUM REPAIRS

650.00



SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Total S\$:	650.00
GST @ 7% S\$:	45.50
Amount Due S\$:	695.50
	=====



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-19-047763

Date of Request: 27/03/2019

Your Ref No: Online Purchase

Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129

Dear Sir/Madam,

XE1664S (DoA:25/03/2019)

Owner : GBL

Enquiry Date 27/03/2019
Enquiry By Wang Sye Yuen
TP Vehicle No. PC6938A
Accident Date 25/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	PC 6938A (Insd veh)	Model:	UD TRUCKS
	XE 1664S (TP veh)		GKB5ELDHNT
Date of Accident:	25/03/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	1,308.07
Final Repair Cost	:	\$	695.50
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	2 days at \$150.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	997.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	SIN SHENG ENGINEERING SERVICES	\$ 997.50

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

19/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19005575/R1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: JAS TAN			Date : 19-06-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6938A	Veh. Inspected	XE 1664S	
Policy No.	VBX/P2120531	Coverage (\$)	0.00	
Claim No.	S9M01I9K	Excess (\$)	0.00	
Assign From		Assign Date	28/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	UD TRUCKS GKB5ELDHNT	c.c	10837	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JNCM1F1AXGU006961	Colour	WHITE	
Odometer	140104	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	KPATOS	8 mm	
L/H Front Tyre	295/80 R22.5	KPATOS	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	KPATOS	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	KPATOS	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2019	Inspection Date	29/03/2019	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1664S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NUMBER PLATE BRACKET (CONSISTENT) (N)	BENT	250.00	250.00
1	NUMBER PLATE LAMP (CONSISTENT) (N)	BROKEN	75.00	75.00
1	NUMBER PLATE (CONSISTENT) (N)	BENT	20.00	20.00
2	REVERSE LAMP @\$90.00 (CONSISTENT) (N)	MISSING (1 PCS ONLY)	180.00	90.00
	LESS 10% DISCOUNT		-52.50	-43.50
			472.50	391.50
LABOUR				
	TO PANEL BEAT /REPAIR REAR BODY.TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS. SPRAY PAINTING.		450.00	250.00
			300.00	200.00
			750.00	450.00
GRAND TOTAL			1,222.50	841.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CC4/ASM19005575/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim

S9M01P9K

Reference

CCA/ASM19005575/R1a2a2

Loss Date

25 March 2019

Report Date

28 Mar 2019 9:41:40 AM

Request Date

28 March 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Send Invoice

Vehicle Information

Incident Vehicle Registration #

XE1664S

Make

THVD UD TRUCKS

Model

ESCOT V-10 B.D GRIBSELDHNT (M)

Service Address

...

Primary Contact/Insured

AMARJIT & SONS COACH SERVICES (PRIVATE LIMITED)
76B PASIR RIS STREET 71, #14-324, S10768, Singapore
63380083
GRACE@VIRTUALINVEST.BIZ

Claim Handler

TAN Jai
6568804844
jai.tan@axa.com.sg

Additional Instructions: default acc Sin Sheng - please do not finalise repair NR-we will send the letter

Messages	Insurites	History	Documents	Assessment	Metrics	Notes
Document Type			Document SubType			
Upload Document						
NAME		TYPE	SUB-TYPE	AUTHOR		DATE UPLOADED
Reports & Statement						
Accident Statement						
Merimen						

