

ASS. REC. BY:

REF: CS/ASM/9005577/ Gsd302 Special Instruction:

Surveyor:

Cid

ASSIGNMENT (Office)

From (Person):

Yvonne ANG

of ASM (AXA)

Date/Time:

28.3.2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 1135J

Insured:

SLE4141G

at Workshop m/s

HS Automotivis Pte Ltd

Tel:

~~67476106~~ 65381368

of

BIR 2 Kaki Bukit Autohub Kaki Bukit Ave 2 #02-25

Policy No:

Claim No:

S9M016P0

Sum Insured:

Excess:

\$400.00

Make of Veh:

(Client's Record)

D.O.A.

07.03.2019

CA / REV

REP. / REV 24 HRS

29/3/19

H.O.D. Endorsement:

Date/Time:

28.3.19.

Person Contacted:

ALEX

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJV 1135J - X
02/04/19	@ 10:09 a.m. revised & revert authorize request to Yvonne via email claim.
02/04/19	@ 10:13 a.m. authorize approved by Yvonne.
02/04/19	@ 10:25 a.m. revert authorize repair to Alex (operator) via email.

60

REF: ASMCA(A)

8453B

ASSIGNMENT

(-2019)

From: _____ Date: 29/3/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU1135Y
 at Workshop m/s: H.S. Automotive
 of: 2 kaki Bukit Ave 2 #02-25

Insured: _____

Policy No: 8338 3328

Claims No: _____

Sum Insured: _____ Excess: \$400.00
 (Client's Record)

Make of Veh: Connie @ 96835528

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$33k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJU1135J Yr Regn: 18 Nov 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW S25i c.c. 2497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 216427 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPBANU 520 48 C 229202

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R17
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or


Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm

D.O.A. _____ D.O.I. 29-03-19

Survey held at: W/S 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
01/4	Finalised \$4600 with Bess Alex
	(S 11,264.00 Red - 71%)

RECEIVED 04 APR 2019

Date/Time, File Pass to? 04/04/19

1) Typist : Preli. Report : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$) 4,600/- HS)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 250

Transportation: _____

S + RS: \$ _____

Photos: _____

Others: _____

TOTAL: 250

Add Fee: Site Insp (\$ _____) Interview (\$ _____) Tech. Invs (\$ _____) Weekend (\$ _____)

 **Service Request Details**

Claim

S9M01GFO

Reference

None 

Loss Date

March 7, 2019

Report Date

Mar 11, 2019 10:45:00 AM

Request Date

March 28, 2019

Due Date

April 4, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SJU1135J

Model
525 I

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

A SANGARALINGAM SHANTI D/O
82EDGEDALE PLAINS, #05-08 THE TERRACE, 828736, Singapore
82687914

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
EXCESS \$400 PEND ESTIMATE CONTACT : HAN 83383328

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

▾ ▾

[+ Upload Documents](#)

NAME	 EMAIL.msg
TYPE	Letters and Correspondence
SUB-TYPE	Workshop
AUTHOR	KUMAR Shailendra
DATE UPLOADED	March 28, 2019

NAME	 EMAIL.msg
TYPE	Letters and Correspondence

AUTHOR RATAN BHOSALE Pragati

DATE UPLOADED March 26, 2019

NAME  SLE4141G TP GIA.PDF

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR NIKAM Santosh Pandurang

DATE UPLOADED March 11, 2019

NAME  SJU1135J INSD GIA.pdf

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR NIKAM Santosh Pandurang

DATE UPLOADED March 11, 2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8453B
Vehicle Details	
Vehicle No.:	SJU1135J
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	525I XL
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	07047238N52B25AF
Chassis No.:	WBANU52040C229202
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$53,322.00
Original Registration Date:	18 Nov 2009
First Registration Date:	18 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$53,322.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2019
PARF Rebate Amount:	\$26,661.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,000.00
COE Rebate Amount:	\$1,169.00
Total Rebate Amount:	\$27,830.00

The information contained herein is correct as at 29 Mar 2019

OK

▶ **bmw 525i Used Vehicle List (5 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW 5 Series 525i XL	\$31,000	\$7,560 /yr	28-Oct-2009	2,497 cc	-	G2 Auto	Availal

Front Tyre, Air Con Compressor And Alternator Just Changed. Fast Sale!

Office No. - -

Edwin Tan - 92957799

BMW 5 Series 525i XL	\$32,500	-	29-Sep-2009	2,497 cc	-	Auto Zoom Enterprise Pte Ltd	Availal
-----------------------------	-----------------	---	-------------	----------	---	------------------------------	----------------

Guaranteed Buy Back Body At \$1200 When Coe Ended, Road Tax 28/9/2019, Parf \$26558 Plus \$1200! Cheaper Than Renting A Car! Neat/Clean/Stock Condition, Engine And Gearbox In Tip Top Condition, Perfect U...

Office No. - 63421000

Robin - 97603335 | Jeffrey - 90041167 | Stanley Chua - 96813489

BMW 5 Series 525i XL	\$35,800	\$9,490 /yr	23-Dec-2009	2,497 cc	136,000 km	AA Trust Automotive	Availal
-----------------------------	-----------------	-------------	-------------	----------	------------	---------------------	----------------

Optional: 5/ 10 Years Coe Available. AA Trust Certified Quality Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner Only! Premium Black Paintwork Coupled With Black Leather Interior! Quiet ...

Office No. - 63450381

Clement - 93365036 | Willey - 91692071 | Dave - 98500051

BMW 5 Series 525i XL (New 10-yr COE)	\$65,800	\$6,570 /yr	28-Apr-2009	2,497 cc	-	QiFei Auto Pte Ltd	Availal
---	-----------------	-------------	-------------	----------	---	--------------------	----------------

New Front Set Of Tyres, New Front 2 Lower And 2 Upper Arm, New Front Absorber, New Mounting, New Eccentric Shaft Sensor, Replaced N Gasket Cover, New Ignition Coil, All Receipt Available.

Office No. - 69083777

Jonas Lim - 90086231 | Jason Chew - 93897284 | Xavier Ng - 96369494

BMW 5 Series 525i (New 10-yr COE)	\$68,800	\$6,870 /yr	23-Nov-2009	2,497 cc	168,538 km	BCC Auto Credit	Availal
--	-----------------	-------------	-------------	----------	------------	-----------------	----------------

Full Loan Available! Options To Renew For 5 Or 10 Years COE! \$53k For 5 Years COE, No Repairs Needed! In-house Workshop Assurance.

Office No. - 65525588

Francis Lim - 91685588

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 2 April 2019 10:25 AM
To: hsautomotivespl@gmail.com
Cc: SUR
Subject: SJU 1135J OD (AXA) DOA - 07/03/2019

Dear Alex,

As instructed by our client, please proceed at repair cost not exceeding \$4,600.00 (inclusive supplementary) to repair the insured vehicle **SJU 1135J (Excess \$ 400/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTH

Type

🔗 Question

Message

Hi Shirley, as spoken please proceed to authorize repair

Reply



IA - SJU 1135J

Type

🔗 Question

Message

Hi Yvonne, IA uploaded. Damages consistent, repair cost economical. We have not authorize repair. Thanks.

From : Shirley

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/04/2019

Survey Details:

Date of loss	7-Mar-19
Date of appointment	28-Mar-19
Date of survey	29-Mar-19
Location of survey	2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJU 1135J
Make and Model	B.M.W. 525I XL
Date of registration	18-Nov-09
Excess	\$400
Market Value	\$33,000
Parf Rebate	\$27,830
Nett Loss	\$5,170

Repair details:

Initial Estimate	15,864.00
------------------	-----------

Proposed/Revised repair cost:

Parts	\$4,408.44
Check items (estimate)	\$0.00
Labour	\$1,430.00
Total	\$5,838.44
Lump Sum(if applicable)	\$4,600.00 (estimate)

Number of days for repair	5 DAYS
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE
HAVE NOT AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%
Proposed repair cost	\$
Loss of use	\$ no. of days
Loss of rental	\$ no. of days
Loss of income	\$ no. of days
LTA search fees	\$
Others	\$
Proposed Total	#VALUE!

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2019 17:05
Date Of Accident	07/03/2019 20:30
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU1135J
Insured/Policyholder	
Name Of Registered Owner	SHANTI D/O A SANGARALINGAM
NRIC No	S7728453B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82687914
Alternative Phone No	OFFICE-82687914

Vehicle Particulars

Manufacturer	BMW
Model	525I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA140843
Cover Note Number	

Driver

Name of Driver	RAMASAMY MAHADEVAN
NRIC No	S7015463C
Date Of Birth	06/05/1970
Occupation	INDOOR
Date Of Driving Pass	28/11/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82687914
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	82 EDGEDALE PLAINS #05-08
Postcode	828736
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SHANTI D/O A SANGARALINGAM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

BEFORE CHANGING LANE, I SIGNALLED LEFT FOR SOME TIME. ROAD WAS CLEAR. I PROCEED TO CHANGE LANE. OUT OF SUDDEN, VEHICLE B HIT ONTO MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE4141G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



redefining / insurance



AXA INSURANCE SINGAPORE PTE LTD
☎ 1800-880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6338 2522
🌐 www.axa.com.sg

Letter of Authorisation for Lump Sum Repair

1. I, [Name] [NRIC] SHANTI D/O A SANGARALINGAM ST728453 B, the owner of vehicle [no.] SJU1135J ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorisation for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Singapore Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorised.

Signed and acknowledged by:

Shanti

Signature of policyholder

Date:



Conner Chan

Name and signature of workshop personnel including workshop stamp

Date: 2.4.19



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

6746 50127
ROC: 201907812C

Vehicle No : 5JW1135J
 Make/Model : Bmw 525i
 CHASSIS NO : WBAWU52040C229202
 Accident Date : _____
 Remarks : _____

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

WORK SHOP REPAIRER ESTIMATES

Date: _____

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARKS

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARKS
1	1	LH FRONT FENDER X Repair.		\$ -	\$ 900 -	X
2	1	LH FRONT FENDER INNER SHIELD - Re.		\$ -	\$ 167 -	/
3	1	LH FRONT FENDER INNER SHIELD CLIP - SET / MC.		\$ -	\$ 45 -	/
4	1	LH FRONT FENDER SIGNAL LAMP - Sur.		\$ -	\$ 68 -	/
5	1	LH SIDE SKIRT / TN		\$ -	\$ 432 -	/
6	1	LH FRONT DOOR / buc		\$ -	\$ 1805 -	/
7	1	LH FRONT DOOR OUTER HANDLE X		\$ -	\$ 469 -	X
8	1	LH FRONT DOOR OUTER HANDLE CAP X		\$ -	\$ 354 -	X
9	1	LH FRONT DOOR WINDOW LOWER CHROME Moulding X		\$ -	\$ 227 -	X
10	1	LH FRONT DOOR WINDOW UPPER CHROME Moulding X		\$ -	\$ 139 -	X
11	1	LH FRONT DOOR WINDOW OUTER VERTICAL GARNISH - Re		\$ -	\$ 71 -	/
12	1	LH FRONT DOOR LOCK X		\$ -	\$ 310 -	X
13	1	LH FRONT DOOR LOCK STRICER X		\$ -	\$ 59 -	X
14	2	LH FRONT DOOR HINGE X		\$ 64	\$ 128 -	X
15	1	LH FRONT DOOR CENTRE CHECKER X		\$ -	\$ 89 -	X
16	1	LH FRONT DOOR INNER TRIM BOARD R / CRA		\$ -	\$ 1938 -	1711.2
17	1	LH FRONT DOOR INNER TRIM BOARD CLIP - SET / MC.		\$ -	\$ 60 -	/
18	1	LH FRONT DOOR SPEAKER ASSY X		\$ -	\$ 34 -	X
19	1	LH FRONT DOOR POWER WINDOW REGULATOR R		\$ -	\$ 391 -	X
20	1	LH FRONT DOOR POWER WINDOW REGULATOR MOTOR X		\$ -	\$ 343 -	X
21	1	LH FRONT DOOR WEATHERSTRIP R / TN		\$ -	\$ 176 -	/
22	1	LH FRONT TYRE X NN		\$ -	\$ -	X
23	1	LH FRONT TYRE RIM (old repair) - \$100. / cut		\$ -	\$ -	100 (cut)
24	1	LH FRONT SHOCK ABSORBER X		\$ -	\$ 640 -	X
25	1	LH FRONT SHOCK ABSORBER TOP MOUNTING X		\$ -	\$ 137 -	X
26	1	LH FRONT STABILISER LINKAGE ROD X		\$ -	\$ 118 -	X
27	1	LH FRONT WHEEL BEARING X		\$ -	\$ 519 -	X
28	1	LH FRONT KNUCKLE ARM X		\$ -	\$ 650 -	X
29	1	LH FRONT LOWER ARM X		\$ -	\$ 400 -	X
30	1	LH FRONT STEERING TIE ROD X		\$ -	\$ 369 -	X

REMARKS:

NO OF DAYS:		4535.2
AGREED FIGURE/LUMP SUM:	\$ -	5% 4308.44
SURVEYOR NAME		CONTACT:
EMAIL ADD:		



HS AUTOMOTIVES PTE LTD

Bik 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No : SSU11353
 Make/Model : Bmw 525i
 CHASSIS NO : WBAWU52040C229202
 Accident Date : _____
 Remarks : _____

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

WORK SHOP REPAIRER ESTIMATES

Date: _____

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARKS

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARKS
1	1	LH FRONT CONTROL ARM	X	\$ -	\$ 412 -	} NW
2	1	LH FRONT ABS SENSOR	X	\$ -	\$ 214 -	
3				\$ -	\$ -	
4				\$ -	\$ -	
5				\$ -	\$ -	
6				\$ -	\$ -	
7				\$ -	\$ -	
8				\$ -	\$ -	
9				\$ -	\$ -	
10				\$ -	\$ -	
11				\$ -	\$ -	
12				\$ -	\$ -	
13				\$ -	\$ -	
14				\$ -	\$ -	
15				\$ -	\$ -	
16				\$ -	\$ -	
17				\$ -	\$ -	
18				\$ -	\$ -	
19				\$ -	\$ -	
20				\$ -	\$ -	
21				\$ -	\$ -	
22				\$ -	\$ -	
23				\$ -	\$ -	
24				\$ -	\$ -	
25				\$ -	\$ -	
26				\$ -	\$ -	
27				\$ -	\$ -	
28				\$ -	\$ -	
29				\$ -	\$ -	
30				\$ -	\$ -	

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HS AUTOMOTIVES PTE LTD

Bik 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

Vehicle No : 53U11353
 Make/Model : Bmw 525i
 CHASSIS NO : WBAWU52040C229202
 Accident Date : _____
 Remarks : _____

WORK SHOP REPAIRER ESTIMATES

Date: _____

Estimate cost of repair to the above mentioned

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARKS
1		LABOUR TO DAMEL BEAT AND REPLACE PARTS		\$ -	\$ 1,800 -	600
2				\$ -	\$ -	
3		TO PUTTY, RESPRAY AND POLISH AFFECTED PORTION		\$ -	\$ 1,800 -	600
4				\$ -	\$ -	700
5		CHECK AND RECTIFY WIRING SYSTEM		\$ -	\$ 120 -	30
6				\$ -	\$ -	
7		REMOVE AND INSTALL FRONT DOOR COMPONENT		\$ -	\$ 150 -	60
8				\$ -	\$ -	
9		REMOVE AND INSTALL FRONT UNDERCARRIAGE		\$ -	\$ 150 -	XNN
10				\$ -	\$ -	
11		RUSTPROOF AFFECTED PORTION		\$ -	\$ 80 -	40
12				\$ -	\$ -	
13				\$ -	\$ -	1430
14				\$ -	\$ -	
15				\$ -	\$ -	
16				\$ -	\$ -	
17				\$ -	\$ -	
18				\$ -	\$ -	
19				\$ -	\$ -	
20				\$ -	\$ -	
21				\$ -	\$ -	
22				\$ -	\$ -	
23				\$ -	\$ -	
24				\$ -	\$ -	
25				\$ -	\$ -	
26				\$ -	\$ -	
27				\$ -	\$ -	
28				\$ -	\$ -	
29				\$ -	\$ -	
30				\$ -	\$ -	

5 Days. *[Signature]* 24/19. 15864/-
 Excess \$400.
 Not Authorised
 Guro Qial - 82880282
 29/3/19.
 wrap up repair.
 After repair photos.

LKK Auto Consulting hence notify the Repairer of the following:

- To resurvey before/after spray painting -
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: \$ -
 Signature: \$ - \$ -
 Date: \$ - \$ -

REMARKS:	
NO OF DAYS:	5838.44
AGREED FIGURE/LUMP SUM:	\$ - 20% = 4600
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

15864



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.
TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM ROC

INVOICE: 19-01001

DATED: 2/4/2019

ATTENTION TO : MOTOR CLAIM DEPARTMENT

AXA INSURANCE PTE LTD

Address: 8 SHENTON WAY #24-01
AXA TOWER SINGAPORE 068811.

Incharge by :

Vehicle No: **SJU1135J**
Make/Model : BMW 525I
CHASIS NO WBANU52040C229202

Workshop add: : Blk 2 Kaki Bukit Ave 2
#01-15 Autohub@Kaki Bukit Ave 2
Singapore 417921

Accident Date : 7/3/2019

Owner: SHANTI D/O A SANGARALINGAM
Policy number: VA1/GA140843

REFERENCE:LUMP SUM

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	LUMP SUM REPAIR FOR VEHICLE MENTIONED ABOVE		L.S \$	4,600.00

TOTAL SUM	\$	4,600.00
LESS EXCESS	\$	-400.00
TOTAL	\$	4,200.00

CLAIMING THIS AMOUNT

Alexlee

AUTHORISED SIGNATURE



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

SATISFACTION VOUCHER

REFER: VEHICLE NO SJU1135J ACCIDENT DATED ON 7/3/2019

I, SHANTI D/O A SANGARALINGAM, HEREBY CONFIRM THAT, HS AUTOMOTIVES PTE LTD, REPAIRED OUR VEHICLE NO SJU1135J TO OUR SATISFACTION AND WE HAVE COLLECTED OUR VEHICLE ON 2/4/2019.

SIGNATURE (& COMPANY STAMP)

A handwritten signature in black ink, appearing to read 'Shanti', is written over a horizontal line. The signature is fluid and cursive.

OWNER: SHANTI D/O A SANGARALINGAM
