

REPAIR ESTIMATE*

VEHICLE NO : SH 7100G

DATE 28/3/2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Replaced</i>			\$ 2,265.90
	Bonnet Lock <i>X su</i>			\$ 36.90
	Radiator Grille <i>ra</i>			\$ 251.00
	Radiator Grille H Emblem <i>ra</i>			\$ 27.50
	Front Bumper Cover <i>ra</i>			\$ 544.50
	Front Bumper Sponge <i>bm</i>			\$ 99.20
	Front Bumper Reinforcement <i>Repl</i>			\$ 402.10
	Front Bumper Grille (LH) <i>ra</i>			\$ 41.60
	Front Bumper Centre Grille <i>ra</i>			\$ 178.60
	Front Bumper Lip <i>ra</i>			\$ 54.90
	Front Bumper Bracket Top (LH/RH) <i>LH - RA X su</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>LH - RA X su</i>		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover <i>X su</i>			\$ 222.60
	Headlamp Support Panel Assy <i>ra</i>			\$ 907.40
	Headlamp (LH/RH) <i>LH - ra RH X su</i>		\$ 1,388.00	\$ 2,776.00
	Radiator <i>X su</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>X su</i>			\$ 792.95
	Radiator Bracket (RH/LH) <i>X su</i>		\$ 6.50	\$ 13.00
	Radiator Guard <i>X su</i>		\$ 20.00	\$ 40.00
	Horn Unit (LH/RH) <i>X su</i>		\$ 73.80	\$ 147.60
	Horn Wire <i>X su</i>			\$ 156.50
	Aircon Condenser <i>X su</i>			\$ 927.50
	Inter Cooler <i>X su</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>X su</i>			\$ 25.90
	Front LH Fender <i>Replaced</i>		\$ 566.30	
	Front LH Fender Liner <i>bm</i>		\$ 175.90	
	Front Bonnet LH/RH Hinges <i>Repl</i>		\$ 91.30	
	SUB TOTAL			\$ 11,736.45
	LESS 20%			\$ 2,347.29
	DISCOUNTED TOTAL			\$ 9,389.16
	Front Number Plate <i>newly</i>			\$ 25.00
	Front No Plate Trim Cover <i>newly</i>			\$ 30.00
	Labour Charge			\$ 55.00
	Panel Beating-Repair Fender			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,950.00
	ESTIMATE TOTAL			\$ 11,394.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

AXA-4S

TS

1630

Acknowledged by Repairer
 Signature: *Ka...*
 Date: *29/3/19*
1030 hrs.
3 Days
4/5
After Repair photo

Nett
 Nett

600
 600
 20
 20
 60

COMFORT DELGRO ENGINEERING

VEHICLE : SH 7100G TYPE OF CLAIM : TP
MODEL : I-40 SURVEY BY : LKK-KALVIN
JOB NO : 305282288 DATE : 29.03.19

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	FRT FENDER LH	1	566.30	
2	FRT FENDER SHIELD LH	1	175.90	
3	BONNET HINGE RH/LH	2	91.30	each
	* Last Entry *			