

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC3/MSG19005587/Urdd3n2  
MSG

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLQ395fk*

at Workshop m/s

of

Insured:

Policy No. *29090793*Claims No. *589034*

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: *35'*IDAC Accident Rpt: *2*

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: *3*

days

Res.: Yes or No

Lum Sum: *20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *SLQ395fk* Yr Regn: *1110*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Nissan 370Z* c.c. *3696*Colour: *silver*

A/C: Insured / Std / NI / NA

Sp. Reading: *127853*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JN16AA23420600046*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/40 ZR19*R: *275/35 ZR19*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *28/3/19*D.O.I. *28/3/19*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*O/S Rear*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Sub. Rep 14 sport in 1925.10 - (D0300-16C4A)**29/3/19 Email GIA to Margaret*

RECEIVED 12 APR 2019

*11/4/19 confirmed 2/5 @ 1800 with Abu. (Reel 5426.20, 7510)*

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *3*

1)

☐ : Final ReportResurvey No. of Trip: *1*

Date/Time, File Return to?

2) *12/4 - typist*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format: *merimen*Lump Sum / I.B.I. (\$) *1800/2*150  
10

160

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Apr 2019		12 Apr 2019 08:34 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N			
Main Claimant:	WENDY PHUA POH LIAN, ID: S84209088			
Vehicle Reg. No.:	SLQ3958K	Date of Loss:	28/03/2019 08:00 - :59 [110 Months and 19 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 589034	Policy/Cover Note No.:	29090793 (Third Party Only) Coverage: 01/09/2018 - 31/08/2019	
Vehicle Reg. No. (Insured):	GBF5624L	Policy No. (Claimant):		
		Excess:		
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/04/2019]			
Driver/Custodian (Insured):	ZHU JIA YONG (), NRIC: G2413066K, Tel: +6584250246 Email:			
Adj Asg. Remarks:	Direct survey done.			

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

**ALL ASSOCIATED TASKS** 
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>  
**Sent:** Friday, 12 April 2019 8:34 AM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 28/3/2019, SLQ 3958K (TP VEHICLE), GBF 5624L (OI VEHICLE)

Hi Veron,

Claim created in merimen, ref: 589034.

Have a great week ahead!

**Nabilah Rasol (Ms)**  
Admin Officer, Claims Services (Motor)  
Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Margaret Loh  
**Sent:** Thursday, 11 April, 2019 3:31 PM  
**To:** Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>  
**Cc:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 28/3/2019, SLQ 3958K (TP VEHICLE), GBF 5624L (OI VEHICLE)

Hi Nabilah,

FYNA.

Thanks.

Best Regards

**Margaret Loh**  
Admin Officer, Claims Services  
Direct line +65 6594 2553 | Direct fax +65 6225 7402 | [margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)



Insurer Claims  
Team of the Year  
2016



---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Thursday, 11 April 2019 2:54 PM  
**To:** Margaret Loh <[margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 28/3/2019, SLQ 3958K (TP VEHICLE), GBF 5624L (OI VEHICLE)

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Margaret,

Kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 29 March 2019 11:07 AM  
**To:** Margaret Loh ([margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)) <[margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)>  
**Cc:** KKLau <[kklau@lkkauto.com](mailto:kklau@lkkauto.com)>; Accounts (LKKAuto) <[account@lkkauto.com](mailto:account@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 28/3/2019, SLQ 3958K (TP VEHICLE), GBF 5624L (OI VEHICLE)

Dear Margaret,

Please be informed that we had inspected the vehicle SLQ 3958K at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 28/3/2019.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 29 March 2019 11:07 AM  
**To:** Margaret Loh (margaret\_loh@sg.msig-asia.com)  
**Cc:** KKLau; Accounts (LKKAuto); SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 28/3/2019, SLQ 3958K (TP VEHICLE), GBF 5624L (OI VEHICLE)  
**Attachments:** GIA.pdf

Dear Margaret,

Please be informed that we had inspected the vehicle SLQ 3958K at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 28/3/2019.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

# CHEAPEST CAR INSURANCE RENEWAL

Compare  
10+ Insurers

GET A CHEAPER QUOTE NOW!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88% P.A Low Interest@Gv  
Finance. 2 Years Warranty.  
\$2000 Down Monthly From \$56  
GV Credit Pte Ltd StarAd

**HIN LUNG AUTO**  
Ho Bee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars  
30 years of car sale

Browse by Category Sort by Date Posted  20 results/page 

2 vehicles

nissan 370

Advanced Search  Submit 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	nissan 370		Any	Any	2011	Any	Any	Any	Available
	Nissan	Fairlady 370Z Roadster	\$69,800	\$15,740 /yr	13-Dec-2011	3,696 cc	44,500 km	Sports	Available
Rare Gem! Nissan's Legendary Z Roadster! Agent Tan Chong Unit, Ultra-Low Mileage, Fully Stock Condition In Titanium Grey. Careful Expat Ownership Shelter Park Only. All-Time Old-School Favourite 6 Spe...									
Posted: 27-Mar-2019 Tags: 2011 Nissan Fairlady, 2011 nissan fairlady, Nissan Fairlady, nissan fairlady, Nissan, Fairlady, fairlady, Used Nissan									
	Nissan	Fairlady 370Z	\$61,888	\$15,930 /yr	19-Jul-2011	3,696 cc	118,000 km	Sports	Available
Genuine 19" Full Forged Volks TE37 Double Black Rims, KW V3 Coilovers (Less Than 3 Months Old), SPL Front And Rear Camber Arms, Z1 Intake Manifold, Z1 Testpipe, Still Gen 3 Ultra Long Tube Dual Inta...									
Posted: 15-Mar-2019 Tags: 2011 Nissan Fairlady, 2011 nissan fairlady, Nissan Fairlady, nissan fairlady, Nissan, Fairlady, fairlady, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used nissan 370, nissan 370 Singapore, used nissan 370 Singapore, used nissan 370, used vehicles Singapore or even buy used nissan 370 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 0908B

### Vehicle Details

Vehicle No.: SLQ3958K  
Vehicle to be Exported: No  
Intended Deregistration Date: 28 Mar 2019  
Vehicle Make: NISSAN  
Vehicle Model: 370Z 3.7L SMT ABS D/AB HID 2WD 2DR  
Primary Colour: Silver  
Manufacturing Year: 2009  
Engine No.: VQ37075400A  
Chassis No.: JN1GAAZ34Z0600046  
Maximum Power Output: 245.0 kW (328 bhp)  
Open Market Value: \$51,927.00  
Original Registration Date: 09 Jan 2010  
First Registration Date: 09 Jan 2010  
Transfer Count: 2  
Actual ARF Paid: \$51,927.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 08 Jan 2020  
PARF Rebate Amount: \$25,963.00

### Intended COE Rebate Details

COE Expiry Date: 08 Jan 2020  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$21,301.00  
COE Rebate Amount: \$1,411.00  
**Total Rebate Amount: \$27,374.00**

The information contained herein is correct as at 28 Mar 2019

OK



Date of Accident : 23/3/19 Accident Time: 8.24am (24-HR-Format)  
 Accident Place : Synagogue street  
 Vehicle. No. (Car Plate No.) : SLA 3958K Make/Model: \_\_\_\_\_  
 Insurance Company : Etiga Policy No: MOU9700  
 Owner or Company Name /IC No. : Wendy Phua Poh Lian / 584209088  
 Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp 96199614 Company Tel \_\_\_\_\_  
 DRIVER'S Name / IC No. : as above  
 DRIVER'S Date Of Birth : 23/7/1984 DRIVER'S License Pass Date 6/11/2007  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
 DRIVER'S Address : 36 Cactus Road 5809595  
 DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) \_\_\_\_\_  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : wendy-phua@gmail.com  
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): 1 Driver  
 Was there any video Captured by car camera: YES \ NO  
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
 Any Injury (If YES, Pls state): NO

**Other Party Driver's Particular (if any)**

Vehicle. No: <u>GBF 5624L (ms16)</u>	Vehicle. No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: <u>zhu Jia Yong</u>	Name Driver: _____
IC No. Driver/Contact: <u>G2413066K</u>	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:

witness - Eric tan  
 Eric tan - 98268145

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time, I was driving my vehicle A along synagogue street, when I was turning into the OLBC center carpark, suddenly vehicle B reversed and hit on my RH side rear portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/03/2019 11:43
Date Of Accident	28/03/2019 08:25
Exact Location Of Accident	AT SYNAGOGUE STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3958K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WENDY PHUA POH LIAN
NRIC No	S8420908B
Email Address	WENDY.PHUA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96199614
Alternative Phone No	OFFICE-96199614

### Vehicle Particulars

Manufacturer	NISSAN
Model	370Z-3.7 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0009700
Cover Note Number	09/01/2019 - 08/01/2020

### Driver

Name of Driver	WENDY PHUA POH LIAN
NRIC No	S8420908B
Date Of Birth	23/07/1984
Occupation	INDOOR
Date Of Driving Pass	05/11/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96199614
Fax Number	
Contact Number	OFFICE-96199614
Email Address	WENDY.PHUA@GMAIL.COM

Address	36 CACTUS ROAD
Postcode	S809595
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	ERIC TAN
Phone Number	98268145
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF5624L
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHU JIA YONG
NRIC/Passport Number	G2413066K
Contact Number	NA
	NA
Address	NA
	NA
Postcode	NA
Insurance Company Name	

Nature Of Damage

NA

No. Of Passenger (Including Driver)



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

28/3/19

11:45AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

28/3/19 11:35AM

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time, I was driving my vehicle A along synagogue street, when I was turning into the OCRC center carpark, suddenly vehicle B reversed and hit on my RH side near partition.

Insurance Co.	Etisia
Vehicle No.	56Q3958K
Date of Accident	28/3/2017
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

28/3/2017 11:35AM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/3/2017 11:41AM

Reporting Centre Personnel's Signature

Name:

Report Centre



not allowed  
back  
2/55 1800  
3 day.  
The ph. After repair  
28/3/19

QTY	PARTICULAR
1 PCS	TAILLAMP O/S
1 PCS	REAR BUMPER 763.60
1 PCS	REAR BUMPER SIDE RETAINER O/S
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER INNER SPLASH SHIELD O/S
1 PCS	REAR SPORT RIM O/S
1 PCS	REAR LOWER ARM O/S
1 PCS	REAR KNUCKLE ARM O/S
1 PCS	REAR KNUCKLE ARM BEARING O/S

De 17	\$866.00	X
De 17	\$1,650.00	✓
De 17	\$48.50	✓
De 17	\$35.00	✓
De 17	\$105.00	✓
De 17	\$1,800.00	✓
De 17	\$455.20	X
De 17	\$566.50	X
De 17	\$250.00	X
	\$5,776.20	

LABOUR CHARGES:  
TO CHECK WIRING  
TO DISMANTLE & REFIX REVERSE SENSOR  
TO CONDUCT WHEEL ALIGNMENT  
TO DISMANTE & REFIX REAR UNDERCARRIAGE  
TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$80.00	50
	\$120.00	60
11	\$150.00	X
11	\$50.00	X
	\$500.00	200
	\$500.00	300
TO	\$7,226.20	

$$\begin{array}{r} 1.256-8 \\ 20 \\ \hline 856.88 \\ 2286.88 \end{array}$$

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19005587/UV3D3N2

Date: 15/04/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29090793
Claimant Vehicle No :	SLQ3958K	Insured Vehicle No :	GBF5624L
Date of Loss:	28/03/2019	Nature of Claim:	TP
		Claim No:	589034

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLQ3958K	Engine No:	VQ37075400A
Make & Model:	NISSAN 370Z, 3.7 (A)	Chassis No:	JN1GAAZ34Z0600046
Reg. Date:	09/01/2010 (Man. Year: 2009)	Odometer:	127853 km
Colour:	Silver		
Engine Capacity:	3696 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/40ZR19	Rear Tyre Size:	275/35ZR19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,776.20	1,656.89	4,119.31	71.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	630.00	820.00	56.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,226.20</b>	<b>2,286.89</b>	<b>4,939.31</b>	<b>68.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>(S\$)</b>	7,226.20	1,800.00	5,426.20	75.09
<b>+ GST 7.00/7.00% (S\$)</b>	505.83	126.00	379.83	75.09
<b>Nett Amount (S\$)</b>	<b>7,732.03</b>	<b>1,926.00</b>	<b>5,806.03</b>	<b>75.09</b>

## INSPECTION

Date of Assignment:	12/04/2019	
Date Inspected:	28/03/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2019)
<b>Parts:</b> M1-COUPE	NISSAN 370Z 3.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLQ3958K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP O/S	Not Necessary	866.00 F	*- FL
2	1		*REAR BUMPER	Deformed/Torn	1,650.00 F	*763.60 FL
3	1		*REAR BUMPER SIDE RETAINER O/S	Bent	48.50 F	*48.50 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
5	1		*REAR BUMPER INNER SPLASH SHIELD O/S	Torn	105.00 F	*105.00 FL
6	1		*REAR LOWER ARM O/S	Not Necessary	455.20 F	*- FL
7	1		*REAR KNUCKLE ARM O/S	Not Necessary	566.50 F	*- FL
8	1		*REAR KNUCKLE ARM BEARING O/S	Not Necessary	250.00 F	*- FL
9	1		*REAR SPORT RIM O/S	Dented	1,800.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,776.20</b>	<b>1,752.10</b>
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	95.21

<b>Total Parts (S\$)</b>	<b>5,776.20</b>	<b>1,656.89</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	150.00	0.00
5	TO SPRAY RUST PROOFING	New	50.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	500.00	200.00
7	TO PUTTY & SPRAY PAINTING	New	500.00	300.00
Gross Labour Cost (\$\$)			1,450.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >