

ASSIGNMENT

Store

REF:

ASSIGNMENT

56J 5594

From
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No:
at Workshop m/s
of
Insured
Policy No.
Claims No
Sum Insured:
(Client's Record)
Make of Veh:

Date:

Veh No: ~~56J 55894~~
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW 3201 GT
Colour: Blue
Sp. Reading: 61634
Eng/No:
C/No: WBA3X1234 00 735338
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R18
R: "

Yr Regn. 26/12/14

CC 1997.

A/C Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or cinurato

Front
R/Bal. 7 mm
L/Bal. 7 mm
D.O.A. 23/3/19
Rear
R/Bal. 7 mm
L/Bal. 7 mm
D.O.I. 2/4/19

Survey held at Vintage
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 90,000
PV - 77,517
NV - 12,483

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + R\$ 51

) Photos

) Other

)

FORM

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$