

22/03/2002

ASS. REC. BY:

REF: CS/FCI 19005603/Jt d3n2 Special Instruction:

Surveyor: HW/2 JIA

ASSIGNMENT (Office)

(WS)

From (Person):

May chua

of

FCI

Date/Time:

28.3.2019 4.58 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL2 FHUJ

Insured:

SHA 60602

at Workshop m/s

Hua Hong Private

Tel:

66619688 98164151.
66619690

of 25 D Sungai Kadut Street 1

Policy No:

Claim No:

D19002112 MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"W"

H.O.D. Endorsement:

Date/Time:

29.3.19 11.50 a.m

Person Contacted:

ms Tan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SL2 FHUJ -X

SHA 60602 -X

24/4@10:33am revised preli advise via email

Confirm with ashley part by part \$2,039.77 (Red: 1925.03, 48%)

Springer Hwee Jie

ASSIGNMENT

From:

Date:

22/4

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLZ7710J

at Workshop m/s

Hua Hong

of

JSD Sungei Kadut St. 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLZ7710J

Yr Regn: 17 May 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota CHR

C.C. 1797

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading:

62741

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZYX102119074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/3/19

D.O.I.

22/4/19

Survey held at

Hua Hong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Waiting for workshop to agree with finalization amount.

RECEIVED 29 JUL 2019

Date/Time, File Pass to?



Preli. Report

1) 26/7 Typist



Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I: (\$)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

130

50

50

26

256



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002112MFSH

Date: 24/4/2019

Our Ref: CS/FCI19005603/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 7710J

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/4/2019 at the premises of M/s Hua Hong have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,964.80</u>
Revised Estimate Amount	: S\$ <u>1,850.64</u>
"Check" Items Amount	: S\$ <u>755.84</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-03-2019	Our Ref No. D19002112MFSH
Accident Date	27-03-2019	Claim Type. Third Party
Insured Vehicle	SHA6060L	Third Party Vehicle. SLZ7710J
Survey Location	25D SUNGEI KADUT STREET 1	
Contact Person.	YVONNE TOH	
Contact No.	66619688/ 0	Fax No. 66619699
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

*T: 11-500-0000
 m/s: Tan
 v: 000*

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HONG PRIVATE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Friday, 26 July 2019 3:23 PM
To: Denise Tay (LKKAUTO)
Subject: RE: Finalisation for Vehicle No. SLZ7710J

Dear Denise

Confirmed COR \$2039.77

Will forward LOD to First Cap, thanks!

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg
   

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 17 July 2019 3:05 PM
To: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>; Ashley Tan <ashley@huahong.com.sg>
Subject: RE: Finalisation for Vehicle No. SLZ7710J

Dear Ashley,

Please call me, Can confirm this case.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hwee Jie (LKK Auto)
Sent: Monday, 1 July 2019 3:22 PM
To: Ashley Tan <ashley@huahong.com.sg>
Cc: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: Finalisation for Vehicle No. SLZ7710J

Hi Ashley,

Please confirm so I can proceed with finalization, thank you.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 24 April 2019 10:33 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002112MFSH/1
Attachments: PRELI ADVISED SLZ 7710J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLZ 7710J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 29 March 2019 12:07 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002112MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 28 March, 2019 4:58 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002112MFSH/1

Dear Sir/Mdm,

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0309M
Vehicle Details	
Vehicle No.:	SLZ7710J
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	2ZR8433231
Chassis No.:	ZYX102119074
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,984.00
Original Registration Date:	17 May 2018
First Registration Date:	17 May 2018
Transfer Count:	0
Actual ARF Paid:	\$9,778.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2028
PARF Rebate Amount:	\$7,333.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$35,343.00
Total Rebate Amount:	\$42,676.00

The information contained herein is correct as at 23 Apr 2019

OK



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

10 April 2019

QUOT201904-000005

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ7710J, SHA6060L & SJD8833X ON 27/03/2019 ALONG KPE TUNNEL AT ABOUT 0750 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SLZ7710J
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No. : ZYX102119074
Policy No. : 5087272209-03
Date of Accident : 27/03/2019

LKK Auto Consultants hereby notify

- To resurvey the damaged parts during resurvey
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper DEF		\$ 508.00
2	10	Rear Bumper Clip nec	\$ 2.50	\$ 25.00
3	1	Rear Bumper Lower DEF		\$ 357.70
4	1	Rear Bumper Lower Cover (Center) SCR		\$ 66.90
5	1	Rear Bumper Lower Clip nec		\$ 10.50
6	2	Rear Bumper Retainer (LH/RH) na x	\$ 97.80	\$ 195.60
7	1	Rear Bumper Tow Cover mis		\$ 32.70
8	2	Rear Bumper Reflector Cover (LH/RH) na x	\$ 107.40	\$ 214.80
9	1	Rear Reinforcement 2 BT		\$ 318.90
10	1	Rear End Panel 1 na x		\$ 625.90
				25% \$ 2,356.00
				Less 20% \$ 471.20
				\$ 1,884.80

11 1 Reverse Sensor Shorted NETT \$ 200.00 ✓

To dismantle, cut & weld rear panel, change rear bumper, rear lower bumper, rear reinforcement, knocking & pull straight rear tyre floor panel and all area affected by accident. \$ 900.00 400

To perform wire checking. \$ 20.00 ✓

To dismantle & refit rear bumper sensor. \$ 60.00 30

To spray rear bumper, rear reinforcement, rear end panel and rear tyre floor panel. \$ 900.00 400



Signature

CONTINUE NEXT PAGE

24/4/19
22/4/19
P/P 3 days
7% GST \$ 3,964.80
Total \$ 277.54
Total \$ 4,242.34



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19005603/Etd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6060L	Veh. Inspected	SLZ 7710J
Policy No.		Coverage (\$)	0.00
Claim No.	D19002112MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	28/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZYX102119074	Colour	BROWN
Odometer	62741	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	DUNLOP	6 mm
L/H Front Tyre	215/60 R17	DUNLOP	6 mm
R/H Rear Tyre	215/60 R17	DUNLOP	6 mm
L/H Rear Tyre	215/60 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/03/2019	Inspection Date	22/04/2019
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 7710J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	508.00	508.00
10	REAR BUMPER CLIP @\$2.50	NECESSARY	25.00	25.00
1	REAR BUMPER LOWER	DEFORMED	357.70	357.70
1	REAR BUMPER LOWER COVER (CENTER)	SCRATCHED	66.90	66.90
1	REAR BUMPER LOWER CLIP	NECESSARY	10.50	10.50
2	REAR BUMPER RETAINER (LH/RH) @\$97.80	NOT NECESSARY	195.60	-
1	REAR BUMPER TOW COVER	MISSING	32.70	32.70
2	REAR BUMPER REFLECTOR COVER (LH/RH) @\$107.40	NOT NECESSARY	214.80	-
1	REAR REINFORCEMENT	BENT	318.90	318.90
1	REAR END PANEL	NOT NECESSARY	625.90	-
	LESS 20% DISCOUNT		-471.20	-
	LESS 25% DISCOUNT		-	-329.93
			1,884.80	989.77
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	TO DISMANTLE,CUT & WELD REAR PANEL,CHANGE REAR BUMPER,REAR LOWER BUMPER,REAR REINFORCEMENT,KNOCKING & PULL STRAIGHT REAR TYRE FLOOR PANEL AND ALL AREA AFFECTED BY ACCIDENT.		900.00	400.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT REAR BUMPER SENSOR.		60.00	30.00
	TO SPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL AND REAR TYRE FLOOR PANEL.		900.00	400.00
	-		-	-
	-		-	-
	-		-	-
	-		-	-
			1,880.00	850.00

Report Ref No. CS/FCI19005603/Etd3n2



GRAND TOTAL		3,964.80	2,039.77
RECOMMENDED COST OF REPAIRS			2,039.77

Report Ref No. CS/FC119005603/Etd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.