Surveyor Hwae sie	ASSIGNM	ENT (Office)		9	-
From (Person); Clara Milah	420 of ms	19	I	Date/Time: 29.3.19	13.19 p.m
Estimated Cost:		Bill to:			
OD) TP / WS / TP RES / OD F	RES/EVA/INV/MV/	CS		Shave	
To Inspect Vehicle No: WC4	641K		Insured:	97432262	
at Workshop m/s YLW TO	2 Automobile	Tech.	Tal	67622081	686148
of BIK 6 WO	odlanda Door	1 399 4	_ 101	0,100	
Policy No: 329088 + 96 1	NKF				621058
		Claim No:			9825
Sum Insured:		Excess: 4	1500.00		
Make of Veh: (Client's Record)			D	O.O.A. 19.3. 2014	1
CA / REV) REP. / REV 24	HRS			1. Apr. 20	
CA / REV) REP. / REV 24	HRS Person Contacted:	winnie		1. Apr. 20	
CA / (REV)/ REP. / REV 24 Date/Time: 24.3.19 2.13	Person Contacted;			1. Apr. 20	
Date/Time Action/Instruction	Person Contacted:			1. Apr. 20	
CA / (REV)/ REP. / REV 24 Date/Time: 24.3.19 2.13	Person Contacted:			1. Apr. 20	
Date/Time Action/Instruction	Person Contacted:	2 .	Ve	H.O.D. Endorsement:	
Date/Time Action/Instruction W CHOULT Change	Person Contacted: n () Estimate MOVCENOD to	Trianali	Ve	H.O.D. Endorsement:	
Date/Time Action/Instruction W (444) t Change 440 7:201 ceek	Person Contacted: n () Estimate workshop to	Triangle	Ve R awto	H.O.D. Endorsement: hicle_IN (OUT))19
Date/Time Action/Instruction W (444) t Change 440 7:201 ceek	Person Contacted: n () Estimate workshop to	Triangle	Ve R awto	H.O.D. Endorsement: hicle_IN (OUT))19
Date/Time Action/Instruction W CHOCH CNOWN	Person Contacted: n () Estimate workshop to	Triangle	Ve R awto	H.O.D. Endorsement: hicle_IN (OUT))19

REF:	MS	(

ASSIGNMENT

From: Date: 1/4/2019	Veh No. WC 4641K	Yr Regn: 17 Oct 2011
Estimated Cost	Type: M.Car / M.Cycle / Bus / Van / L	orry / Taxi / Prime Mover /
OD TP WE/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or	
To Inspect Vehicle No: WC 4641K	Make: (SUZU CYH.	528s c.c 15681
at Workshop m/s You Tee Automobile	Colour white	A/C: Insured / Std / NI / NA
To Inspect Vehicle No: WC 4641K at Workshop m/s Yew 7ee Automobile of Blk 6 woodland 5 Rd 399 F. Yw	Tee Inc Sp. Reading 201585	T/Radio: Insured / Std / NI / NA
Insured: Est.	Eng/No:	
Policy No.	C/No: JALCYHS2S	SB 7000167
Claims No.	Gen. Cond: Good / Fair / Poor / Burn	t s
Sum Insured: Excess: \$1,50	0.00 Steering: Ingred / Jammed / Leaked	/ Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked	/ Burnt or
Make of Veh: After gam.	Modi: Nil / (Rim / STD A/Rim o	r
Aller Janes	Tyre Size: F: 295/80 A	22.5
(Policy Condition)	R: - · ·	
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA	/ MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Indfo	162
Bal. or Market Value:	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	. R/Bal. & mm	R/Bal. 8/8 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 8 mm	L/Bal. 8/8 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 19/3/19	DOL (4/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Yew	tee Auto
Carround	Des. of Damages : Fig / Rear / O/S	
CA I REV / REP. / 24 HRS		
Date: Person Contacted:		ly Structure affected due to collision.
Date / Time Action / Instruction		\\\ \\ \\ \\
MV-\$48000		Mounte
PV-48095	D 4 9 ANG 2019	1 1 2 2
NU-\$39905 RECE	EIVED 1 3 AUG 2019	N (3) 8/301
Sent email confirm	Us \$23.0007- CRed: 2	9,913.20:56%
	N. P.	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	
1) BA TUPISF : Final Report	Resurvey No. of Trip: 2	Survey Fee: 300
DaterTime, File Return to?	dd Fee: Site Insp (\$	Transportation.)S+RS,Si
2)	Interview (\$) Photos
Down to Company	Tech. Invs (\$) Others N
Report Format:		7 50003
Lump@um / I.B.I: (\$ 23,000 -	Weekend (\$	211
		TOTAL - 311

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	28 Mar 2019 16:00 Sendback Est	28 Mar 2019 16:05 S\$52,913.20	29 Mar 2019 13:19 Assign	2019 19		THE HEATT CO.	New Assignment Cancel Case		
Main		Referen	nce	Claim Deta	ails	Documents		Show All	
CLAIM SU	JBFOLDER DETAI	LS		The second second					
Insured:		YU CHAN T	RANSPORT, Co.	Reg. No.: -, T	el: +6596520779				
Vehicle Reg. No.:		WC4641			Date of Loss:		19/03/2019 04:00 - :59 [89 Months and 2 Days From LTA Reg Date (Man Yr)]		
Claim Type:		OD / 5884	138	Policy/Cover Note No.:		B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019			
		Describer.		Excess:		S\$1,500.0	S\$1,500.00		
Repairer:		Yew Tee Au Woodlands -	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081						
Handling Ir	nsurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Clara Milah Yeo]						
Adjuster:		LKK Auto C	onsultants Pte Lt	d (HO) - Tel: 6	256-3561 [Imn	Advice due	30/03/201	an reoj	
Driver/Cust	todian:	HAN YU CHA	N (55) , NRIC: S	2696146G, Te	el: +6596520779 En	nail:	30/03/201	2]	
Adj Asg. Re	emarks:	Only LKK car after 9am.	n survey for this in	sured's portfolio	. Please revert. Estir	mate: \$52,913. (Car in on 01/0	04/2019	
ASSOCIAT	TED MAIL RECEIV	/ED				View All	Compose C	ase Mail	
There are n	o mail for this case						compose c	asc man	
B									
ALL ASSO	CIATED TASKS			View /	All Search Tasks	Create N		Complete	

View Received Message

This mail is associated with:

WC4641K (588438)

OD
Mar 19 2019 4:00AM
[YU CHAN TRANSPORT]
Yew Tee Automobile Tech Pte Ltd

From	MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 05/04/2019 10:58 AM.
To	LKK_HQ
Subject	Alert - Adj Mandate Approved (\$\$23000.00) - WC4641K - Claim Handler: Clara Milah Yeo

DOCUMENTS	SUMMARY
-----------	---------

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Business	
Owner ID: Vehicle Details	5192B	
Vehicle No.:	WC4641K	
Vehicle to be Exported:	No	
Intended Deregistration Date:	02 Apr 2019	
Vehicle Make:	ISUZU	
Vehicle Model:	CYH52S	
Primary Colour:	White	
Manufacturing Year:	2011	
Engine No.:	6WG1415361	
Chassis No.:	JALCYH52SB7000167	
Maximum Power Output:		
Open Market Value:	\$139,262.00	
Original Registration Date:	17 Oct 2011	
First Registration Date:	17 Oct 2011	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$6,964.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	16 Oct 2021	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
QP Paid:	\$31,900.00	
COE Rebate Amount:	\$8,095.00	
Total Rebate Amount:	\$8,095.00	
	7-,	

The information contained herein is correct as at 02 Apr 2019

ОК

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



New 5 Years Coe Renewal Toyota Altis 1.6A

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login Ways of Selling 2.88%p.a Low Interest@Gv Finance.2 Years Warranty. \$2000 Down Monthly From \$568 GV Credit Pte Ltd StarAd



Browse by Category

Post an Ad

2 vehicles

Isuzu CYH52S

Model

Price

Anv

\$53,888

Depreciation Any

\$7,180 /yr

Reg Date Eng Cap

Mileage

Veh Type

Truck

Status

Available

DIRECT OWNER

Search Selection

Isuzu CYH52S

•

Make

Isuzu CYH52S (COE till

\$60,800

18-Sep-2007

15,681 cc

Any

Any

Sort by Date Posted

Advanced Search

Απν Available

▼ 40 results/page

09/2027) Fuel Type: Diesel

Well Kept Condition, In-House Finance Is Available, Call Now For Viewing.

Tags: 2007 Isuzu CYH52S, 2007 isuzu cyh52s, Isuzu CYH52S, isuzu cyh52s, Isuzu, CYH52S, cyh52s, Used Posted: 29-Mar-2019

09-Dec-2011

15,681 cc

Truck Available

Isuzu CYH52S

Posted: 17-Mar-2019

Fuel Type: Diesel

Tags: 2011 Isuzu CYH52S, 2011 isuzu cyh52s, Isuzu CYH52S, isuzu cyh52s, Isuzu, CYH52S, cyh52s, Used

\$20,050 /yr

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

▼ results/page 40

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu CYH52S, Isuzu CYH52S Singapore, used Isuzu CYH52S, used vehicles Singapore or even buy used Isuzu CYH52S Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Clara Milah Yeo

Date:

04 Apr 2019

Preliminary Advice

Vehicle No

: WC4641K

Accident Date

: 19/03/2019

Make

: ISUZU CYH52S

Policy No.

: B29088496MKF

Assignment Date

:S\$

: 29/03/2019

Excess

: S\$1,500.00

Date of Inspection

: 01/04/2019

Est. Duration of Repair

: 14.00

Inspection At

: YEW TEE AUTOMOBILE TECH PTE LTD (HQ)

BLK 6 WOODLANDS ROAD 399F,, YEW TEE IND ESTATE

SINGAPORE 678006

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,913.20
Revised Amount	:S\$	14.397.00
Check Items (Estimated)	:S\$	35,879.00
Total	:S\$	50,276.00

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	8,095.00
Salvage Value	:S\$	

39,905.00 :S\$ Margin for Repair

Remarks

(х)	The vehicle	is	economical	for	repair.

The above survey was conducted on a 'without prejudice' basis.

(x) Repairer is asking on all in lump sum \$23,000/-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Clara Milah Yeo

Date:

04 Apr 2019

Preliminary Advice

Vehicle No

: WC4641K

Accident Date

: 19/03/2019

Make

: ISUZU CYH52S

Policy No.

: B29088496MKF

Assignment Date

: 29/03/2019

Excess

: S\$1,500.00

Date of Inspection

: 01/04/2019

Est. Duration of Repair

: 14.00

Inspection At

: YEW TEE AUTOMOBILE TECH PTE LTD (HQ)

BLK 6 WOODLANDS ROAD 399F,, YEW TEE IND ESTATE

SINGAPORE 678006

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

nate (Gross) :S\$ 52,913.20	
t :S\$ 14.397.00	0
stimated) :S\$ 33,679.00	35879
:S\$ 48,076.00	3/1505
:S\$ 48,076.00	203

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	8,095.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,905.00

Remarks

(x)	The vehicle is economical for repair.
()	The above survey was conducted on a 'without prejudice' basis.

(x) Repairer is asking on all in lump sum \$23,000/-





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

为是表现,然后是自由的主义	ACCIDENT STATEMENT
Date Of Report	19/03/2019 14:06
Date Of Accident	19/03/2019 04:00
Exact Location Of Accident	MARINA MALL TO MARINA GROVE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	WC4641K
Insured/Policyholder	
Name Of Registered Owner	HAN YU CHAN
NRIC No	S2696146G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96520779
Alternative Phone No	OFFICE-96520779
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	GOODS VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29088496 MKF
Cover Note Number	
Driver	
Name of Driver	HAN YU CHAN
NRIC No	S2696146G
Date Of Birth	08/04/1963
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1993
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96520779
Fax Number	
Contact Number	OFFICE-96520779

NOEMAIL

Address BLK 510B WELLINGTON CIRCLE #02-75 Postcode 752510 Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured OWNER Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLIDED INTO PROPERTY Weather Conditions CLEAR DRY Road Surface Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) 1 involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by ambulance? NO Was any other material or property damaged? I have been approached by unknown person(s) YES soliciting/offering accident claims assistance. Number of Passengers (Including Driver) 1 **Details of Police Action** Was the accident reported to the police? NO If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? Circumstances of Accident REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

0.4

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

, , j. 17.

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by the or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law forms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by the:
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal information may can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
 - (e) the information to collected under (d) above may be shared / disclosed;
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agancies as reasonably required for the purposes stated, or

for complying with requirements under any regulations, lane or court orders.

TRA

Policyholder's Signature Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

District

NRIC/FIN NA

Sketch Plan #2

	1 22 2	(X 10 H) X/4	10 20 3		*** 00000	1 E
Para sa	80 H		0.			1000 1000 1000 II
3.4		STEEL		15-11-11-1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	(808) (80)	* 1000 crass of 1
- 9	A	10	<u> </u>		1 23	
1	317	-V			****	
	tilly a second	** (**********************************				
	E CIRCUMSTA	NCES OF THE A	ACCIDENT		53 x 11,000 bes	
-	White	-f w	as dovo	y rehide	WC 4647	K 9/019
	-			101104	100 7011	1
Ma	ring gl	we, do	g ny au	t on the	milen	Mad
74	J	osf osf	control	- 1 has	on the	stool Ito
quo	1 /	1031	Control	and bang	on the	efeel bin
The	at is	all frum	me			
1			•			
	ECLARA FION	Averaging and				
	Co. Fing. No.	0	lars are true in ever	y *espect		
Ŋ	Co. Fing. No.	PO	lars are true in ever	A setbect		h

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006) TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg ON BEHALF OF OWNER:

Policy Particulars: - OWN DAMAGED CLAIM

Insured veh.

WC4641K

Excess.

\$ 1,500.00

Policy No.

erik .

B 29088496 MKF

Coverage. Comprehensive

Claiming Against.

MSIG

Insured Under.

MSIG

Vehicle Particulars & Condition

Make & Model

Isuzu CYH52S

Engine No.

6WG1415361

Chassis No.

JALCYH52SB7000167

Odometer

Engine CC.

Year Of Reg.

2011

Colour.

WHITE

Parf/COE Rebate.

Conditions Of Tyres

Size

Make

R/H Front Tyre L/H Front Tyre

R/H Rear Tyre

L/H Rear Tyre

Description Of Damages

Front portion, L/H side damaged.

General Information

Accident Date.

19/3/2019

Survey held at

Yew Tee Automobile Tech Pte Ltd

MEGA@Woodlands, 39 Woodlands Close #01-12, Singapore 737856

Remarks

KINDLY LET US HAVE THE APPROVAL SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006) TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Front bumper DEF /	\$ 1,300.00 /
1	Front bumper bracket LH BT -	\$ 200.00 /
1	Front bumper grille	\$ 170.00 ×
1	Front headlamp LH CRA/	\$ 550.00
1	Front headlamp wire harness LH CUT /	\$ 2,400.00
1	Front side lamp LH SCR /	\$ 170.00/
1	Front signal lamp LH CRA /	\$ 80.00/
1	Front panel Repair x	\$ 1,700.00 \(\)
1	Front panel damper LH ?	\$ 250.00 X
1	Front panel damper RH ?	\$ 250.00 X
2	Front panel lock ?	\$ 400.00 ×
2	Front panel lock catch ?	\$ 300.00 ×
1	Front corner panel LH CRA /	\$ 110.00/
1	Front side mirror top LH SCR	\$ 200.00 /
1	Front side mirror arm LH .	\$ 300.00 /
1	Front windscreen glass CFA	\$ 1,600.00
1	Front windscreen rubber Nec /	\$ 200.00 /
1	Front windscreen pillar inner garnish LH ?	\$ 310.00 X
1	Front windscreen pillar inner panel LH	\$ 920.00 X
1	Front door LH Buc	\$ 1,300.00 /
1	Front door glass LH ? X	\$ 400.00 X
1	Front door glass regulator motor I H	\$ 300.00 /
1	Front door glass regulator motor En	\$ 520.00 X
1	Front door rubber LH !	\$ 220.00 /
1	Front door inner rubber LH ? 00	\$ 290.00
1	Front door pillar En	\$ 1,100.00
1	Front door pillar inner panel LH	\$ 1,900.00
1	Front door top hinges LH	\$ 100.00
1	Front door bottom hinges LH	\$ 100.00
1	Front door glass outer moulding LH DEF /	\$ 170.00 /
1	Front door outer protector LH CRA	\$ 350.00
1	Front door side lamp LH M (5 / CRU	\$ 80.00 /
1	The state of the s	\$ 180.00 /
1	Front door top step LH ? X	\$ 200.00 X
1	Front door lower step LH CRA	\$ 200.00 /
1	Front door lower step support LH BT	\$ 380.00 /
1	Front door lower protector LH CRA/	\$ 460.00
1	Front door lower protector inner shield LH ? X	\$ 400.00 X

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006) TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	<u>Description Of Parts</u>		Pricing
1	Front door lock LH ? / 8T		\$ 480.00
1	Front door lock catch LH 7 ×		\$ 40.00 X
1	Front door inner board LH ? / CRV		\$ 600.00 /
1	Front door inner handle LH 7 X		\$ 80.00 X
1	Front door wheel arch inner protector LH ? X		\$ 350.00 X
1	Front cabin side panel LH BUC/		\$ 2,500.00
1	Front cabin side panel glass LH		\$ 400.00 X
1	Front cabin side panel glass rubber LH Nec/		\$ 150.00 /
1	Front cabin side panel step LH BUC /		\$ 250.00 /
1	Front cabin side panel outer protector LH ? / MIS		\$ 350.00
1	Front cabin rooftop lining ?		\$ 800.00 ×
1	Front cabin top dashboard 1 X		\$ 1,100.00 X
1	Front cabin top dashboard glove cover LH ?		\$ 440.00 X
1	Front cabin bottom dashboard 7 X		\$ 700.00 ×
1	Front cabin bottom dashboard glove cover LH ? X		\$ 330.00 ×
1	Front cabin instrument cluster ? X		\$ 700.00 X
1	Front cabin dashboard reinforcement ? / IT		\$ 2,000.00
1	Front cabin side inner trim LH ?		\$ 280.00 ×
1	Front cabin rear inner trim ? ×		\$ 480.00 ×
1	Front cabin floor panel ? / 00		\$ 4,000.00
2	Front cabin front mounting ? X		\$ 200.00 X
1	Front condenser LH ? 20		\$ 700.00
1	Front condenser bracket LH		\$ 180.00 /
1	Front condenser fan cowling LH ?		\$ 300.00
1	Front condenser fan motor LH ? ×		\$ 320.00 ×
1	Front condenser fan blade LH ? X		\$ 200.00 X
1	Air con suction pipe ? X		\$ 310.00 X
1	Air con return pipe		\$ 290.00 ×
1	Air con discharge pipe		\$ 320.00 ×
		Subtotal	\$ 38,910.00
		Add 10%	\$ 3,891.00
			\$ 42,801.00
1	ERP bracket		\$ 12.00
1	Front door inner board clips .		\$ 45.00 15/
1	Front door lower inner shield clips LH 🕺		\$ 45.00 15/
			\$ 102.00

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006) TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts		Pr	ricing	6	
LABOUR						
	nd reconnect, check electrical wiring harness wire, edamaged parts.		\$	80	100.00	/
	Terostat Sealant On The Cutting Areas.		\$		60.00	/
To Dismantle a	nd Refit Front Windscreen Glass.		\$		100.00	1
To Remove & R	efit air-con compressor, air-con motor, condenser, pipes		\$	100	180.00	1
& vacuum, incli	iding refilling of gas.					
To Transfer Do	or		\$	80	100.00	!
To Computer R	eset and Re-program all fault code.			100 /		
To Dismantle &	Refit Front Dashboard & related wire harness & related parts.		\$	209/	550.00	?
Towing fees			\$		350.00	!)
To dismantle ar	nd refit rear fender glass		\$	50	60,00	1
To remove & re	place the above damaged parts, straighten, knock out,		\$	5	,000.00	
	inculding cut & weld body panels. To re-adjust to the using power tools.			250	0/	
To spray painti	ng on the replaced & repair parts, prepare spray such as		\$	3	,000.00	7
masking tape tl	ne unaffected areas with papers, cleaning & sanding of olising & waxing are also available.			1000	/	
surfaces, illiar p	olishig & waxing are also available.	LABOUR	\$	10	,000.00	-
		Sub Total.	\$	52	,903.00	
	- 70	7% GSt	\$	3	,703.21	
	4279	Grand Total	\$	56	,606.21	_

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

Hure Jie - LKK 1/4/19 L/Seff 14days. Not Authorise Excess: \$1500/-

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRACK	ING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	1	Adj Submitte	d Ins Auth	'ed	Status	
Main	28 Mar 2019 16:00 Sendback Est	28 Mar 2019 16:05 \$\$52,913.20	29 Mar 2019 13:19 Edit Adj Rpt	S\$23,00 Edit Est		5\$23,000.0 View Rpt	0		Pending 1 Report Cancel Ca	or Survey
	Main	Refere	ence	Clair	n Details		Docume	ents	٦.	Show All
CLAIM SU	BFOLDER DETA	ILS								
Insured:	YU CHAN TR	ANSPORT, Co. Re	eg. No.: -, Tel:	+659652077	9					
Vehicle Reg No.:	WC4641K			Da	te of Loss:		9 04:00 - :59 s and 2 Days F	rom LTA R	eg Date (M	lan Yr)]
Claim Type	OD / 58843	38			licy/Cover te No.:		MKF (Compre 01/07/2018 -		9	
				Ex	cess:	S\$1,500.00)			
Repairer:	Yew Tee Aut	omobile Tech Pte	Ltd (HQ) Blk 6 \	Woodlands R	oad 399F,,	Yew Tee Ind	Estate, 67800	6 Woodlan	ds - Tel: 6	7622081
Handling Insurer:	MSIG Insura	ince (Singapore)	Pte. Ltd. (HQ) -	Tel: +65 682	27 7888	[Handled by	Clara Milah \	reo]		
Adjuster:	LKK Auto Co	nsultants Pte Ltd	(HQ) - Tel: 6256	-3561 [Ha	andled by C	HEN TSUE	YEE] [Fina	I Rpt du	e 28/04/	2019]
Driver/Cust dian:	0	(55), NRIC: S2								
Adj Asg. Remarks:	Only LKK can	survey for this insu	red's portfolio. Ple	ease revert.	Estimate: \$	52,913. Car	in on 01/04/2	019 after 9	am.	
ASSOCIAT	ED MAIL RECE	IVED						View All	Compose	Case Mail
		Alert - Adj Manda Please submit pre			- WC4641	K - Claim H	andler: Clara	Milah		
• 14310_3						View All 5	Search Tasks	Create N		
XW.3556-5	CIATED TASKS					VIEW AII	search rasks	Create N	ew Task	Complete

Claim Documents

WC4641K (588438)
OD
Mar 19 2019 4:00AM
[YU CHAN TRANSPORT]
Yew Tee Automobile Tech Pte Ltd

Ass	essment Reports		1 per page	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbna	il Prin
1	28/03/19 16:05	Repairer Estimates	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	-
1	04/04/19 17:19	Adjuster Immediate Advice	■ Load HTM	
Pho	otos/Images		3 per page ✓	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbna	_
1	28/03/19 16:07	Accident Photo	6 Load JPG	~
2	28/03/19 16:07	Accident Photo	 Load JPG 	V
3	28/03/19 16:07	Accident Photo	1 Load JPG	V
4	28/03/19 16:07	Accident Photo	■ Load JPG	V
5	28/03/19 16:07	Accident Photo	1 Load JPG	V
6	28/03/19 16:07	Accident Photo	⑥ Load JPG	V
7	28/03/19 16:07	Accident Photo	1 Load JPG	V
8	28/03/19 16:07	Accident Photo	1 Load JPG	V
9	28/03/19 16:07	Accident Photo	■ Load JPG	V
10	28/03/19 16:07	Accident Photo	1 Load JPG	V
11	28/03/19 16:07	Accident Photo	1 Load JPG	V
12	28/03/19 16:07	Accident Photo	■ Load JPG	V
13	28/03/19 16:07	Accident Photo	Load JPG	V
14	28/03/19 16:07	Accident Photo	1 Load JPG	V
15	28/03/19 16:07	Accident Photo	1 Load JPG	V
16	28/03/19 16:07	Accident Photo	Load JPG	V
17	28/03/19 16:07	Accident Photo	■ Load JPG	V
18	28/03/19 16:07	Accident Photo	■ Load JPG	V
19	28/03/19 16:07	Accident Photo	Load JPG	
20	28/03/19 16:07	Accident Photo	Load JPG	-
21	28/03/19 16:07	Accident Photo	■ Load JPG	
22	28/03/19 16:07	Accident Photo	Load JPG	V
23	28/03/19 16:07	Accident Photo	Load JPG	V
24	28/03/19 16:07	Accident Photo	Load JPG	
25	28/03/19 16:07	Accident Photo	Load JPG	-
26	28/03/19 16:07	Accident Photo	Load JPG	
27	28/03/19 16:07	Accident Photo	Load JPG	V
28	28/03/19 16:07	Accident Photo	■ Load JPG	-
29	28/03/19 16:07	Accident Photo	1 Load JPG	
30	28/03/19 16:07	Accident Photo	■ Load JPG	-
31	28/03/19 16:07	Accident Photo	■ Load JPG	
32	28/03/19 16:07	Accident Photo	Load JPG	-
33	28/03/19 16:07	Accident Photo	■ Load JPG	

Merimen e-Claims Page 2 of 4

Ass	essment Reports		1 per page	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbna	
			0	₹
35	28/03/19 16:07	Accident Photo	1 Load JPG	▼
36	28/03/19 16:07	Accident Photo	1 Load JPG	₹ 2
37	28/03/19 16:07	Accident Photo	1 Load JPG	· •
38	28/03/19 16:07	Accident Photo	1 Load JPG	₹ 🗸
39	28/03/19 16:07	Accident Photo	1 Load JPG	· •
40	28/03/19 16:07	Front View Left	€ Load JPG	· •
41	28/03/19 16:07	Accident Photo	■ Load JPG	
42	28/03/19 16:07	Accident Photo	■ Load JPG	
43	28/03/19 16:07	Accident Photo	1 Load JPG	· •
44	28/03/19 16:07	Accident Photo	■ Load JPG	-
45	28/03/19 16:07	Accident Photo	1 Load JPG	-
46	28/03/19 16:07	Accident Photo	1 Load JPG	
		Accident Photo	1 Load JPG	-
47	28/03/19 16:07		1 Load JPG	100
48	28/03/19 16:07	Accident Photo		_
49	28/03/19 16:07	Accident Photo	Load JPG	_
50	28/03/19 16:07	Accident Photo LKK Auto Consultants Pte Ltd (HQ)	Load JPG Thumbna	-
No 1	04/04/19 17:27	General View	1 Load JPG	
2	04/04/19 17:27	General View	1 Load JPG	-
		See CAME		
3	04/04/19 17:27	General View		_
1	04/04/19 17:27	General View	D Load JPG	_
5	04/04/19 17:27	General View	1 Load JPG	
6	04/04/19 17:27	General View	1 Load JPG	-
7	04/04/19 17:27	General View	1 Load JPC	_
8	04/04/19 17:27	General View	1 Load JPG	_
9	04/04/19 17:27	General View	1 Load JPG	_
10	04/04/19 17:27	General View	1 Load JPG	
11	04/04/19 17:27	General View	1 Load JPG	5 Z
12	04/04/19 17:27	General View	1 Load JPG	5 \
13	04/04/19 17:27	General View	1 Load JPG	i 🔽
14	04/04/19 17:27	General View	1 Load JPG	5 •
15	04/04/19 17:27	General View	1 Load JPG	5 2
16	04/04/19 17:27	General View	1 Load JPG	5 V
17	04/04/19 17:27	General View	1 Load JPG	3 •
18	04/04/19 17:27	General View	1 Load JPG	5 Z
19	04/04/19 17:27	General View	1 Load JPG	5 E
20	04/04/19 17:27	General View	1 Load JPG	5 Z
21	04/04/19 17:27	General View	1 Load JPG	-
22	04/04/19 17:27	General View	1 Load JPG	-
23	04/04/19 17:27	General View	■ Load JPG	T =
24	04/04/19 17:27	General View	1 Load JPG	-
25	04/04/19 17:27	General View	1 Load JPG	-
26	04/04/19 17:27	General View	1 Load JPG	-
27	04/04/19 17:27	General View	1 Load JPG	-
		General View	1 Load JPC	-
28	04/04/19 17:27	ASS COMME		
29	04/04/19 17:27	General View	1 Load JPC	_
30	04/04/19 17:27	General View	1 Load JPC	_
31	04/04/19 17:27	General View	1 Load JPC	
32	04/04/19 17:27	General View	1 Load JPG	3

Merimen e-Claims Page 3 of 4

Ass	essment Reports		1 per p	age 🗸	4
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)		Thumbnail	_
33	04/04/19 17:27	General View	0	Load JPG	~
34	04/04/19 17:27	General View	0	Load JPG	✓
35	04/04/19 17:27	General View	0	Load JPG	✓
36	04/04/19 17:27	General View	0	Load JPG	~
37	04/04/19 17:27	General View	0	Load JPG	V
38	04/04/19 17:27	General View	0	Load JPG	✓
39	04/04/19 17:27	General View	0	Load JPG	V
40	04/04/19 17:27	General View	0	Load JPG	V
41	04/04/19 17:27	General View	0	Load JPG	V
42	04/04/19 17:27	General View	0	Load JPG	V
43	04/04/19 17:27	General View	0	Load JPG	V
44	04/04/19 17:27	General View	0	Load JPG	V
45	04/04/19 17:27	General View	0	Load JPG	~
46	04/04/19 17:27	General View	0	Load JPG	V
47	04/04/19 17:27	General View	0	Load JPG	V
48	17/04/19 09:49	Dismantled Parts	0	Load JPG	<u> </u>
19	17/04/19 09:49	Dismantled Parts	0	Load JPG	2
HITES.		Dismantled Parts		100000000000000000000000000000000000000	-
50	17/04/19 09:49	1000 100 W S	0	Load JPG	<u>-</u>
51	17/04/19 09:49	Dismantled Parts	0	Load JPG	9
52	17/04/19 09:49	Dismantled Parts	0	Load JPG	2
53	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
4	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
55	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
56	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
57	17/04/19 09:49	Dismantled Parts	0	Load JPG	-
58	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
59	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
50	17/04/19 09:49	Dismantled Parts	0	Load JPG	-
51	17/04/19 09:49	Dismantled Parts	0	Load JPG	-
52	17/04/19 09:49	Dismantled Parts	0	Load JPG	-
53	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
54	17/04/19 09:49	Dismantled Parts	0	Load JPG	
55	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
66	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
57	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
68	17/04/19 09:49	Dismantled Parts	0	Load JPG	5
59		Dismantled Parts	0	Load JPG	2
	17/04/19 09:49	Dismantled Parts	0		Z
70	17/04/19 09:49		0	Load JPG	
1	23/04/19 10:22	Dismantled Parts		Load JPG	5
2	23/04/19 10:22	Dismantled Parts	0	Load JPG	<u>-</u>
'3	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
4	23/04/19 10:22	Dismantled Parts	0	Load JPG	-
75	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
76	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
7	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
8	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
79	23/04/19 10:22	Dismantled Parts	0	Load JPG	6
30	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
31	23/04/19 10:22	Dismantled Parts	0	Load JPG	5
82	23/04/19 10:22	Dismantled Parts	0	Load JPG	V

Ass	sessment Reports			ge 🔻	V
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	1	humbnail	Print
83	23/04/19 10:22	Dismantled Parts	0	Load JPG	V
84	23/04/19 10:22	Dismantled Parts	0	Load JPG	V
85	23/04/19 10:22	Dismantled Parts	0	Load JPG	V
86	23/04/19 10:22	Dismantled Parts	Ð	Load JPG	✓
87	14/05/19 09:02	Dismantled Parts	0	Load JPG	V
88	14/05/19 09:02	Dismantled Parts	0	Load JPG	V
89	14/05/19 09:02	Dismantled Parts	0	Load JPG	V
90	14/05/19 09:02	Dismantled Parts	0	Load JPG	☑
91	14/05/19 09:03	Photo After Spray	0	Load JPG	V
92	14/05/19 09:03	Photo After Spray	0	Load JPG	V
93	14/05/19 09:03	Photo After Spray	0	Load JPG	✓
94	14/05/19 09:03	Photo After Spray	0	Load JPG	V
95	14/05/19 09:03	Photo After Spray	0	Load JPG	✓
96	14/05/19 09:03	Photo After Spray	0	Load JPG	V
Dod	cumentation		1 per pa	ge 🔻	V
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	1	Thumbnail	Print
1	28/03/19 16:06	E-filed GIA report	0	Load PDF	
2	28/03/19 16:09	Repair Estimates	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/19 09:14	ESTIMATE	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG19005605/ETD3E2

Date:

15/08/2019

REFERENCE

Date of Loss:

Insured/Claimant:

YU CHAN TRANSPORT

19/03/2019

Policy No:

Nature of Claim:

B29088496MKF

Engine No:

Chassis No:

Odometer:

OD

No

Claim No: 588438

JALCYH52SB7000167

6WG1415361

301585 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

WC4641K

Make & Model:

ISUZU CYH52S, 15.7 D (M)

17/10/2011 (Man. Year: 2011)

White

Colour: Engine Capacity:

15681 cc

Market Value/New Car Price: S\$48,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

Front Left Side:

295/80 R22.5

Indforce 8 mm

Rear Tyre Size: Rear Left Side:

295/80 R22.5 (D) Indforce 8/8 mm

Front Right Side:

Indforce 8 mm

Rear Right Side:

Indforce 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,913.20	32,637.00	20,276.20	38.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,913.20	32,637.00	20,276.20	38.32
Approved Total (Overridden) (S\$)		23,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	51,413.20	21,500.00	29,913.20	58.18
+ GST 7.00/7.00% (S\$)	3,598.92	1,505.00	2,093.92	58.18
Nett Amount (S\$)	55,012.12	23,005.00	32,007.12	58.18

INSPECTION

Date Inspected:

Date of Assignment:

29/03/2019 Present Location:

01/04/2019 Inspected At:

Yew Tee Automobile Tech Pte Ltd (HQ)

Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee

Ind Estate

Singapore 678006

Estimated Period of Repair:

14.0 days

Adjuster: CHEN TSUE YEE Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen Part Source		(Last Synchronised: 15 Aug 2019)		
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for WC4641K)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*TOTAL PARTS		42,913.20 F	*28,367.00 F
2	2 1 *TOTAL LABOUR AND PAINT			10,000.00 F	*4,270.00 F
F=Fra	anchise part.		Total Parts (S\$)	52,913.20	32,637.00
		Report was unsubmitte	ed during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >