

22/03/2002

ASS. REC. BY:

REF: CS/Smo 19005612/Ktd 302

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

min min

From (Person): Gnoh Pau Loong

of SMO

Date/Time: 29.3.19 14:32 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 2441C

Insured:

at Workshop m/s Chung Hoe Motor

Tel: 67556142

of Blk 109 # 01-3741382 Yishun Industrial Park A.

Policy No: D18MTPV 01014776

Claim No: CMTD 1901566

Sum Insured:

Excess: TBA \$0.00

Make of Veh:

(Client's Record)

D.O.A. 28-3-19

CA / REV / REP. / REV 24 HRS

"W1"

H.O.D. Endorsement:

Date/Time: 29.3.19

Person Contacted: Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 2441C - X
114 -	Revert via menmen.
114 @ 17:20pm	authorise by Gnoh Pau Loong
114 @ 5:33pm	inform Eefeeda authorise repair excess \$0

ASS. REC. BY:

REF: SMO /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8102k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJ 2441C Yr Regn: 11, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Audi A4 c.c. 1399

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 47491 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF4711A037200

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 6 mm

L/Bal. 7 mm L/Bal. 6 mm

D.O.A. 28/3/19 D.O.I. 29/3/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

Part by Part 7753.20 (Red, 737.90 '8%)

RECEIVED 11 SEP 2019

10/9/2019

Date/Time, File Pass to?

1) 11/9/2019

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: OD

Lump Sum / (B.I.) (\$

7753.20

250

11

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2019 Sendback Est	29 Mar 2019 14:05 S\$8,358.00	29 Mar 2019 14:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LI JUN, ID: S7161783A, Tel: +6591866439, Email: junli55@yahoo.com.sg		
Vehicle Reg. No.:	SLJ2441C	Date of Loss:	28/03/2019 13:00 - :59 [27 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901566	Policy/Cover Note No.:	D18MTPV01018776 (Comprehensive)
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/04/2019]		
Driver/Custodian:	LI JUN (47 / Male), NRIC: S7161783A, Tel: +6591866439 Email: junli55@yahoo.com.sg		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SLJ2441C (CMTD1901566)

OD

Mar 28 2019 1:00PM

[LI JUN]

Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 01/04/2019 17:20 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6907.30) - SLJ2441C - Claim Handler: GNOH PAU LOONG

Approved:6907.30.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 01 Apr 2019

Preliminary Advice

Vehicle No	: SLJ2441C	Accident Date	: 28/03/2019
Make	: AUDI A4	Policy No.	: D18MTPV01018776
Assignment Date	: 29/03/2019	Excess	: S\$0.00
Date of Inspection	: 29/03/2019	Est. Duration of Repair	: 5.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,358.00
Revised Amount	:S\$	6,538.80
Check Items (Estimated)	:S\$	368.50
Total	:S\$	6,907.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	60,970.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,937.30

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repair on part by part

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1783A
Vehicle Details	
Vehicle No.:	SLJ2441C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CVN022013
Chassis No.:	WAUZZZF47HA057200
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,212.00
Original Registration Date:	30 Nov 2016
First Registration Date:	30 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$27,097.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2026
PARF Rebate Amount:	\$20,322.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$40,648.00
Total Rebate Amount:	\$60,970.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/03/2019 17:05
Date Of Accident	28/03/2019 13:50
Exact Location Of Accident	JALAN SENANG TWDS JALAN CRESC
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLJ2441C
Insured/Policyholder	
Name Of Registered Owner	LI JUN
NRIC No	S7161783A
Email Address	JUNLI55@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91866439
Alternative Phone No	OTHERS-91866439
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 1.4 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01018776
Cover Note Number	30/11/18 - 29/11/19
Driver	
Name of Driver	LI JUN
NRIC No	S7161783A
Date Of Birth	10/06/1971
Occupation	INDOOR
Date Of Driving Pass	19/01/2007
Driving Experience	12 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91866439
Fax Number	
Contact Number	
Email Address	JUNLI55@YAHOO.COM.SG

Address	31 ROSEWOOD DRIVE #04-30
Postcode	737922
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I stopped my car and confirmed that traffic was clear so I started to move forward. In the mid juncture, vehicle B appeared at my left and crashed onto the front left of my car. Ambulance and traffic police came to the scene and I was told by police officer that I don't have to file police report as case consider non injury, rider not convey to hospital.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC4248L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MOHD AZHARI BIN TEMON
NRIC/Passport Number	G6624361W
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN






DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped my car and confirmed that traffic was clear so I started to move forward. In the mid juncture, vehicle B appeared at my left and crashed onto the front left of my car. Ambulance and traffic police came to the scene and I was told by police officer that I don't have to file police report as case consider non injury, rider not convey to hospital.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Personnel's Signature Name: (KS) NRIC/FIN No.:
GIARMC SketchPlanForm_V3 <input checked="" type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Reporting Only <input type="checkbox"/> Claim OD/TP at other workshop ()		

SKETCH PLAN


VEHICLE NO.: SLJ 2441C
INSURER : Sompo
DATE & TIME: 28/3/19 @ 13:50

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (Ys)
NRIC/FIN No.:



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/SOMPO
Policy No:	D18MTPV01018776	Date of Loss:	28/03/2019
Vehicle Reg. No.:	SLJ2441C	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LI JUN	Contact No:	+6591866439
Driver:	LI JUN		
Make/Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Vehicle Reg. Date:	30/11/2016
Vehicle Colour:	WHITE		
Engine No:	CVN022013	Chassis No:	WAUZZZF47HA057200
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

Description of Accident/Loss: I STOPPED MY CAR AND CONFIRMED THAT TRAFFIC WAS CLEAR SO I STARTED TO MOVE FORWARD. IN THE MID JUNCTURE, VEHICLE B APPEARED AT MY LEFT AND CRASHED ONTO THE FRONT LEFT OF MY CAR. AMBULANCE AND TRAFFIC POLICE CAME TO THE SCENE AND I WAS TOLD BY POLICE OFFICER THAT I DON'T HAVE TO FILE POLICE REPORT AS CASE CONSIDER NON INJURY, RIDER NOT CONVEY TO HOSPITAL.

Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS	Amount
Parts	6,798.00
Miscellaneous Items	0.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,358.00
+ GST 7.00% (S\$)	585.06
Nett Amount (S\$)	8,943.06

This claim is handled by: **SHARON CHIONG BENG CHOON**

- LKK Auto Consultancy hereby certifies the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS		SLJ2441C
Reference		bd/sompo
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	0.00	0.00	*700.00 F
2	1		*1 pc frt bumper LH fog lamp garnish	0.00	0.00	*45.00 F
3	1		*1 pc frt LH side retainer	0.00	0.00	*16.00 F
4	1		*1 pc frt bumper reinforcement	0.00	0.00	*265.00 F
5	1		*1 pc frt bumper lower cover	0.00	0.00	*70.00 F
6	1		*1 pc frt LH fender	0.00	0.00	*254.00 F
7	1		*1 pc frt LH fender inner shield	0.00	0.00	*80.00 F
8	1		*1 pc LH headlamp	0.00	0.00	*3,080.00 F
9	1		*1 pc LH headlamp wiper nozzle	0.00	0.00	*90.00 F
10	1		*1 pc bonnet	0.00	0.00	*930.00 F
11	1		*1 pc frt LH sport rim	0.00	0.00	*650.00 F
Sub Total (S\$)						6,180.00
+ Margin on L,N Items 10.00% (S\$)						618.00
Total Parts (S\$)						6,798.00

Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05. Not valid without Reference section.	
Generated using Merimen e-Claims IEAS	

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & refix frt bumper,grille,headlamp,reinforcement,nozzles,frt LH fender,knock & repair bonnet & realign the same	New	600.00
2	Putty & respray bonnet,frt LH fender,frt bumper (pearl white)	New	800.00
3	Remove & refix frt LH sport rim,tyre,repair & balancing,putty & respray	New	100.00
4	To conduct frt LH under carriage and conduct computerized wheel alignment	New	60.00
Gross Labour Cost (S\$)			1,560.00

Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05. Not valid without Reference section.	
Generated using Merimen e-Claims IEAS	

< END OF ESTIMATES >

Allen Kenneth

UR

SLJ2441C

OD/SOMPO

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 29 Mar 2019)
Parts: 143 **AUDI A4 1.4 TFSI S TRONIC (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Q7753.20 ✓ OK

b4p

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	0.00	0.00 ✓	*700.00 F
2	1		*1 pc frt bumper LH fog lamp garnish	0.00	0.00 ✓	*45.00 F
3	1		*1 pc frt LH side retainer	0.00	0.00 ✓	*16.00 F
4	1		*1 pc frt bumper reinforcement	0.00	0.00 ✓	*265.00 F
5	1		*1 pc frt bumper lower cover	0.00	0.00 ✓	*70.00 F
6	1		*1 pc frt LH fender	0.00	0.00 ✓	*254.00 F
7	1		*1 pc frt LH fender inner shield	0.00	0.00 ✓	*80.00 F
8	1		*1 pc LH headlamp	0.00	0.00 ✓	*3,080.00 F
9	1		*1 pc LH headlamp wiper nozzle	0.00	0.00 ✓	*90.00 F
10	1		*1 pc bonnet	0.00	0.00 ✓	*930.00 F
11	1		*1 pc frt LH sport rim	0.00	0.00 ✓	*650.00 F

F=Franchise part.

Sub Total (S\$) 6,180.00
+ Margin on L,N Items 10.00% (S\$) 618.00
Total Parts (S\$) 6,798.00

Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & refix frt bumper,grille,headlamp,reinforcement,nozzles,frt LH fender,knock & repair bonnet & realign the same	New	500.00
2	Putty & respray bonnet,frt LH fender,frt bumper (pearl white)	New	800.00
3	Remove & refix frt LH sport rim,tyre,repair & balancing,putty & respray	New	100.00
4	To conduct frt LH under carriage and conduct computerized wheel alignment	New	60.00
Gross Labour Cost (S\$)			1,560.00

Cheng Hoe Motor Pte Ltd/SLJ2441C/29/03/2019 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SLJ2441C

SUPP 1

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Apr 2019)
Parts: 143 **AUDI A4 1.4 TFSI S TRONIC (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SLJ2441C/03/04/2019 15:24
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc frt bumper inner sponge	0.00	0.00	CN *54.00 F	✓
2	1		*1 pc frt LH fender inner top garnish	0.00	0.00	CN *17.00 F	✓
3	1		*1 pc engine LH under cover	0.00	0.00	BZ *32.00 F	✓
4	1		*1 pc engine LH under cover extension	0.00	0.00	GA *18.00 F	X
						Sub Total (S\$)	121.00
						+ Margin on L,N Items 10.00% (S\$)	12.10
						Total Parts (S\$)	133.10

Cheng Hoe Motor Pte Ltd/SLJ2441C/03/04/2019 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SLJ2441C/03/04/2019 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parts \$ 5809.
Supp item \$ 103
 \$ 5912
Add 10% \$ 591.20
Labour \$ 1250
 \$ 7753.20

Confirm
Kenneth
24/8/19



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No:200106569G



Customer: CHENG HOE MOTOR PTE LTD

Address: 1A

BLK 1019 YISHUN IND PK A, #01-374/382
SINGAPORE 768761

SLJ2441C

WAUZZZ7HA057200

Tax Invoice No: SRI2700663

Date: 02/04/2019

Area Code: 1A DELIVER

Credit Terms: 30Days

Kian Hua Sales: LOONG

No.	Description	Qty	Unit Price	Amount
1	BUMPER AUDI A4 16> FRT +h/lampwash	1	700.00	700.00
2	H/LAMP AUDI A4 16> LED LH	1	3,080.00	3,080.00
3	AUDI A4 RIM	1	650.00	650.00

Products received and checked to be in good condition Sub-Total: SGD 4,430.00
G.S.T(7%): 310.10
Total : SGD 4,740.10

Customer's Signature / Company Stamp

Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

SEAH - 02/04/2019 3:10:53 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM

新中汽配有限公司 KINZHONG AUTOPARTS LLP

IQ : 33 Tyrwhitt Road Singapore 207535
el : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052
Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800
el : (65) 3157 2377 Fax : (65) 6702 3855
E-mail : info@kinzhongautoparts.com
Website : http://www.kinzhongautoparts.com

ILKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR & VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

CUSTOMER'S COPY

CR301594 - 199896
02-04-2019

Tax Invoice No. :
Date :
Your Reference No. :
Payment Term :
Currency :
Page No. :
SGD
1/1

GST Registration No.: M90361482G

TAX INVOICE

Customer

Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind. Park A
#01-374/382
Singapore 768761

Delivery Address

Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind. Park A
#01-374/382
Singapore 768761
CHOP & SIGN

ITEM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
1	8W0807681B9B9+	GRILL	GW B2-G1-CTN	1 PCS	45.00	45.00
2	8W0807611+	PLATE	GW B2-K2	1 PCS	70.00	70.00
3	8W0821105A+	FENDER 3000908	GW B1-C1	1 PCS	254.00	254.00
4	8W0821171A+	WHEEL HOUS	GW A1-PLT	1 PCS	80.00	80.00
5	8W0823029A+	HOOD	GW B1-D1	1 PCS	930.00	930.00

Remarks: 2441

Vehicle No. : SLJ2441C
Chassis No. : WAUZZZF47HA057200
Ordered By :
Salesperson : Tan
Time : 02-04-2019 15:08 PM
Zone Code : NORTH

Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD

Name

Date & Time

XG Planner

Bank Details:

Bank Name: United Overseas Bank Limited
Account Number:
UOB, Singapore 379 301 364 5 (SGD)
UOB, Singapore 379 900 273 4 (EUR)
UOB, Singapore 379 900 040 5 (USD)
SWIFT UOVBGSGG

SUB-TOTAL	:	1,379.00
GST	:	96.53
TOTAL	:	1,475.53

checked and Received By
Goods sold are not refundable for cash.
Special Indent & Electrical Parts cannot be returned.

For and On Behalf of
XINZHONG AUTOPARTS LLP
Co. UEN: T08LL0804C

新中汽配有限公司 XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road Singapore 207535
 Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052
 Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800
 Tel : (65) 3157 2377 Fax : (65) 6702 3855
 E-mail : info@xinzhongautoparts.com
 Website : http://www.xinzhongautoparts.com

VOLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR & VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

CUSTOMER'S COPY

CR301599 - 199901
 02-04-2019

Tax Invoice No. :
 Date :
 Your Reference No. :
 Payment Term : SGD
 Currency : 1/1
 Page No. :
 GST Registration No.: M90361482G

TAX INVOICE

Customer

Cheng Hoe Motor Pte Ltd
 Blk 1019 Yishun Ind. Park A
 #01-374/382
 Singapore 768761

Delivery Address

Cheng Hoe Motor Pte Ltd
 Blk 1019 Yishun Ind. Park A
 #01-374/382
 Singapore 768761
 CHOP & SIGN

EM NO.	PART NO.	DESCRIPTION	LOC	QTY	UNIT PRICE	AMOUNT
1	8W0820581C	COVER	XZ SALES	1 PCS	17.00	17.00
2	8W0853887A	SPOILER	XZ SALES	1 PCS	32.00	32.00
3	8W0807550A	FOAM INSER	XZ SALES	1 PCS	54.00	54.00

Supp item

Remarks:

Vehicle No. : SLJ2441C
 Chassis No. :
 Ordered By :
 Salesperson : Tan
 Time : 02/04/2019 15:21 PM
 Zone Code : NORTH

Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD _____

Name _____

Date & Time _____

XG Planner

Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT UOVBSGSG

SUB-TOTAL	:	103.00
GST	:	7.21
TOTAL	:	110.21

Checked and Received By

Goods sold are not refundable for cash.

Special Indent & Electrical Parts cannot be returned.

For and On Behalf of
 XINZHONG AUTOPARTS LLP

Co. UEN: T08LL0804C

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2019 Sendback Est	29 Mar 2019 14:05 S\$8,358.00	29 Mar 2019 14:32 Edit Adj Rpt	S\$7,753.20 Edit Estimates	S\$7,753.20 View Rpt		Pending for Survey Report Cancel Case
Supp #1	03 Apr 2019 15:22	03 Apr 2019 15:24 S\$133.10	03 Apr 2019 15:24			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LI JUN, ID: S7161783A, Tel: +6591866439, Email: junli55@yahoo.com.sg		
Vehicle Reg. No.:	SLJ2441C	Date of Loss:	28/03/2019 13:00 - :59 [27 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901566	Policy/Cover Note No.:	D18MTPV01018776 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/04/2019]		
Driver/Custodian:	LI JUN (47 / Male) , NRIC: S7161783A, Tel: +6591866439 Email: junli55@yahoo.com.sg		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- SOMPO_SG (10/09/2019): Alert - Adj Mandate Approved (S\$7753.20) - SLJ2441C - Claim Handler: GNOH PAU LO...
- SOMPO_SG (01/04/2019): Alert - Adj Mandate Approved (S\$6907.30) - SLJ2441C - Claim Handler: GNOH PAU LO...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLJ2441C (CMTD1901566)

OD

Mar 28 2019 1:00PM

[LI JUN]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page 1	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print		
1	28/03/19 17:31	Accident Statement		Load HTM			
2	29/03/19 14:05	Repairer Estimates		Load HTM			
3	03/04/19 15:24	Repairer Estimates Suppl. #1		Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/04/19 14:26	Adjuster Immediate Advice		Load HTM			
2	10/09/19 11:16	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page 3	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
2	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
3	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
4	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
5	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
6	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
7	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
8	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
9	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
10	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
11	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
12	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
13	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
14	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
15	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
16	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
17	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
18	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
19	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
20	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
21	01/04/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>		
22	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
23	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
24	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
25	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
26	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
27	10/09/19 11:19	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
28	10/09/19 11:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
29	10/09/19 11:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
30	10/09/19 11:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/04/19 14:15	ESTIMATE		Load PDF			
2	10/09/19 11:10	SUPPLEMENTARY		Load PDF			

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
1	28/03/19 17:31	Accident Statement		Load HTM	<input type="checkbox"/>
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
2	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
3	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
4	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
5	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
6	28/03/19 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
7	28/03/19 17:30	SCENE	Load JPG	<input checked="" type="checkbox"/>	
8	28/03/19 17:30	SCENE	Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	28/03/19 17:29	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>	
2	28/03/19 17:29	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>	
3	28/03/19 17:29	IC & DL	Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; height: 40px; margin-top: 10px;"></div>			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 10px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19005612/KTD3E2

Date: 17/09/2019

REFERENCE

Insured/Claimant: LI JUN Policy No: D18MTPV01018776
Date of Loss: 28/03/2019 Nature of Claim: OD Claim No: CMTD1901566

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ2441C**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN022013
Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: WAUZZZF47HA057200
Colour: Metallic Pearl White Odometer: 47491 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 7 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,931.10	6,503.20	427.90	6.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,250.00	310.00	19.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,491.10	7,753.20	737.90	8.69
+ GST 7.00/7.00% (S\$)	594.38	542.72	51.66	8.69
Nett Amount (S\$)	9,085.48	8,295.92	789.56	8.69

INSPECTION

Date of Assignment: 29/03/2019 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 29/03/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ2441C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc frt bumper (WCP)	Buckled	700.00 F	*700.00 F
2	1		*1 pc frt bumper LH fog lamp garnish (WCP)	Cracked	45.00 F	*45.00 F
3	1		*1 pc frt LH side retainer (WCP)	Serviceable	16.00 F	*- F
4	1		*1 pc frt bumper reinforcement (WCP)	Repair	265.00 F	*- F
5	1		*1 pc frt bumper lower cover (WCP)	Cracked	70.00 F	*70.00 F
6	1		*1 pc frt LH fender (WCP)	Bent	254.00 F	*254.00 F
7	1		*1 pc frt LH fender inner shield (WCP)	Cracked	80.00 F	*80.00 F
8	1		*1 pc LH headlamp (WCP)	Cut	3,080.00 F	*3,080.00 F
9	1		*1 pc LH headlamp wiper nozzle (WCP)	Serviceable	90.00 F	*- F
10	1		*1 pc bonnet (WCP)	Bent	930.00 F	*930.00 F
11	1		*1 pc frt LH sport rim (WCP)	Dented	650.00 F	*650.00 F
Supplementary #1						
12	1		*1 pc frt bumper inner sponge (WCP)	Cracked	54.00 F	*54.00 F
13	1		*1 pc frt LH fender inner top garnish (WCP)	Cracked	17.00 F	*17.00 F
14	1		*1 pc engine LH under cover (WCP)	Broken	32.00 F	*32.00 F
15	1		*1 pc engine LH under cover extension (WCP)	Serviceable	18.00 F	*- F
					Sub Total (\$\$)	6,301.00 5,912.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	630.10 591.20
					Total Parts (\$\$)	6,931.10 6,503.20

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & refix frt bumper,grille,headlamp,reinforcement,nozzles,frt LH fender,knock & repair bonnet & realign the same	New	600.00	500.00
2	Putty & respray bonnet,frt LH fender,frt bumper (pearl white)	New	800.00	660.00
3	Remove & refix frt LH sport rim,tyre,repair & balancing,putty & respray	New	100.00	30.00
4	To conduct frt LH under carriage and conduct computerized wheel alignment	New	60.00	60.00
Gross Labour Cost (S\$)			1,560.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >