

ASS. REC. BY:

REF: ~~CS~~ A2619005613/Ecd302

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

mumun

From (Person):

Chin Lee Yung

of

AIG

Date/Time:

2/13/19 @ 11:24am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS1691E

Insured:

SKV 2480M

at Workshop m/s

Hong Hwa Motor

Tel:

84983980

of

5033 Amk Ind. park 2 # 01-261

Policy No:

Claim No:

791941236686

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:49am 29/3/19

Person Contacted:

Mr. Ang

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJS1691E - NA / MS914001558/m2

D.O.A - 30/11/2013

SFV 2480M - X

Steve

REF:

ASSIGNMENT

From _____ Date: _____
Estimated Cost _____
QD / TP / WS / TP RES / QD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of _____
Insured _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJS 1691 E Yt Regn: 30/7/09
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Latio

CC: 1.5

Colour: White

A/C Insured / Std / NI / NA

Sp. Reading: 201924

T/Ratio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: JN1B AAC 112 0021248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NR / S/Rim / STD A/Rim or

Tyre Size: F: _____

185 / 65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/3/19

D.O.I. 29/3/19

Survey held at Heng Hwa

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

Date/Time, File Pass to?

☐ : Prol. Report

4)

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + R + SI

) Photos

) Other

Report Format : DAR


Lump Sum / I.B.I. (\$

180

10

190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 29/3/2019 11:29:22 AM
Attachments:  Heng Huat Motor - Pre-Repair Notice (AIG)(SJS1691E).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

not yet do in m-r-n

- no wksp address

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.HHM (SJS1691E)
Your Ref: SKV2480M

29 March 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6835 7416 & EMAIL

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: CHEONG LIMOUSINE
TRAFFIC ACCIDENT ON 27 MARCH 2019 AT 08:40 HRS ALONG WEST COAST HIGHWAY
INVOLVING VEHICLES NO. SJS1691E & SKV2480M & SLZ7804Y

We are instructed by Cheong Limousine to notify you of a road accident on 27 March 2019 at about 08:40 hrs along West Coast Highway involving our clients' vehicle registration number SJS1691E and vehicle registration number SKV2480M driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Heng Huat Motor Repair Workshop
Address: 5033 Ang Mo Kio Industrial Park 2
#01-261 Ang Mo Kio Industrial Park 2
Singapore 569536
Contact: Mr Ang (8498 3980)

Please liaise with the above workshop directly.

Yours faithfully

CrossBorders LLC
CrossBorders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee			
Vehicle Details			
Vehicle No. :	SJS1691E		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	LATIO CVT 1.5L ABS D/AIRBAG 2WD 4DR		
Chassis No. :	JN1BAAC11Z0021248		
Propellant :	Petrol		
Engine No. :	HR15090122B		
Engine Capacity :	1498 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1450 kg		
Unladen Weight :	1130 kg		
Year Of Manufacture :	2008		
Original Registration Date :	30 Jul 2009		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$9,889.00		
COE Expiry Date :	29 Jul 2019		
Road Tax Expiry Date :	29 Jul 2019		
PARF Eligibility Expiry Date :	29 Jul 2019		
Inspection Due Date :	29 Jul 2020		
Intended Transfer Date :	01 Apr 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4086A
Vehicle Details	
Vehicle No.:	SJS1691E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO CVT 1.5L ABS D/AIRBAG 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	HR15090122B
Chassis No.:	JN1BAAC11Z0021248
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$20,149.00
Original Registration Date:	30 Jul 2009
First Registration Date:	30 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$20,149.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2019
PARF Rebate Amount:	\$10,074.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$9,889.00
COE Rebate Amount:	\$321.00
Total Rebate Amount:	\$10,395.00

The information contained herein is correct as at 01 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/03/2019 10:59
Date Of Accident	27/03/2019 08:40
Exact Location Of Accident	WEST COAST HIGHWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS1691E
Insured/Policyholder	
Name Of Registered Owner	CHEONG LIMOUSINE
Co Reg No	53334086A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84983980
Alternative Phone No	OFFICE-84983980
Vehicle Particulars	
Manufacturer	NISSAN
Model	LATIO SEDAN
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107830932
Cover Note Number	
Driver	
Name of Driver	CHIA TECK MENG
NRIC No	S7203367A
Date Of Birth	27/01/1972
Occupation	OUTDOOR
Date Of Driving Pass	05/04/1994
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90668538
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 282A SENGKANG EAST AVENUE #07-591
Postcode	541282
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV2480M
Vehicle Make/Model/Colour	MITSUBISHI LANCER / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG YONG YEE
NRIC/Passport Number	S8376492I
Contact Number	93868667
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLZ7804Y
Vehicle Make/Model/Colour MAZDA 2 / BLACK
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SUN YAOKUN
NRIC/Passport Number S8973406A
Contact Number 91993977

Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHIA TECK MENG
Approximate Age 47
Injuries Sustain PAIN ON NECK AND SHOULDER AREA
Injured person in which vehicle? SJS1691E
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLK 282A SENGKANG EAST AVENUE #07-591
Postcode 541282

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

28 MAR 2019

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature


NO-WING KIN JAMES

NRIC/FIN No.:

admin.vac@vicom.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
Police
Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:
28 MAR 2019


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/FIN No.:
admin.vac@vicom.com.sg



**SINGAPORE
POLICE FORCE**



T/20190327/2103

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 4

Report No. T/20190327/2103

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/03/2019 15:08		Vide Report No.:		Station Diary No.: 70	
Informant's Particulars					
Name of Informant: CHIA TECK MENG			Address: APT BLK 282A SENGKANG EAST AVENUE #07-591 SINGAPORE 541282		
ID Type / ID No.: NRIC NO / S7203367A			Contact No.: Home/Office: Mobile: 90668538		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 27/01/1972	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/03/2019 08:40	Type of Location:
Location: Along Road 1 WEST COAST HIGHWAY				
Towards Tuas				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS1691E	Car	NISSAN	LATIO	White	Slightly Damaged	1
SKV2480M	Car	MITSUBISHI	LANCER	Black		0
SLZ7804Y	Car	MAZDA	2	Black		1



**SINGAPORE
POLICE FORCE**



T/20190327/2103

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 4

Report No. T/20190327/2103

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHIA TECK MENG	ID No.	S7203367A
Related Vehicle	SJS1691E (Car)	Contact No.	90668538
Hospital/Clinic	NEO MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	27/03/2019	Date Discharge	27/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	WONG YONG YEE	ID No.	S8376492I
Related Vehicle	SKV2480M (Car)	Contact No.	93868667
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SUN YAOKUN	ID No.	S8973406A
Related Vehicle	SLZ7804Y (Car)	Contact No.	91993977
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/03/2019 at about 0840hrs, I was driving my vehicle (SJS1691E - V1) along West Coast Highway (towards direction of Tuas) on right most lane. Somewhere before exit of Telok Blangah Road, the vehicle ahead of me had came to a stop due to heavy traffic. Thus I then slowed down and came to a stop as well. Shortly after, I felt an Impact coming from the rear. Upon making a check, I discovered that a vehicle (SKV2480M - V2) had collided onto my vehicle's rear.

There was also another vehicle (SLZ7804Y - V3) that had collided onto V2's rear. Upon making further checks with V2's driver, he informed that when my vehicle had came to a stop, he had managed to stop



**SINGAPORE
POLICE FORCE**



T/20190327/2103

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 4

Report No. T/20190327/2103

CONTINUATION OF REPORT

his vehicle as well. However, his vehicle was then hit by V3 from behind. The impact had caused it to surge forward and hit my vehicle. Due to the collision, I felt some pain on my neck and shoulder area. I have since sought medical treatment and was given 3 days of MC. There is CCTV in my vehicle. However it is only forward-facing.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999



T/20190327/2103

4 of 4

Report No. T/20190327/2103

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD KHAIRUL AZIZ BIN A GHAFAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 27/03/2019 15:08
Officer In Charge Of Case: TP / GIT / Sr-Staff Sgt RAZIZ-BIN-TAHAR Contact No.: 65476200 SN 005	Classification Of Case:
Authentication Stamp NP168 signature Singapore Police Force	

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (0)
 (4) Not Consistent (NC)


Aug 2005

Rear Portion

Vehicle No: **SJS 1691E**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DU	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	GR	✓ 2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	DU	✓	
1158	994023	Reverse Sensor	SPAT	✓	
1159	993327	Rear End Panel	DU	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim	GR	✓	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	RA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	RA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem	NEC	2	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	KT	✓	
1178	990377	Bootlid Rubber	TA	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			


 3/4/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019 Edit Reg		29 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Gerardin (Xu JingLing) Koh Ching-Lin , ID: S7822823G								
Main Claimant:	CHEONG LIMOUSINE , Co. Reg. No.: 53334086A								
Vehicle Reg. No.:	SJS1691E	Date of Loss:	27/03/2019 08:00 - :59 [115 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7919412366SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKV2480M	Policy No. (Claimant):							
		Excess:							
Repairer:	Heng Huat Motor (HQ) BLOCK 5033 AMK INDUSTRIAL PARK 2 # 01-261, 569536 Ang Mo Kio - Tel: 84983980								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 10/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (02/04/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS1691E (7919412366SG)
[SKV2480M]
TP
CHEONG LIMOUSINE
Mar 27 2019 8:00AM
[Gerardin (Xu JingLing) Koh Ching-Lin]
Heng Huat Motor

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
17	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
18	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
19	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
20	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
21	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
22	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
23	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
24	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
25	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
26	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
27	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
28	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
29	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
30	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
31	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
32	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
33	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
34	04/04/19 12:50	General View											Load JPG	<input checked="" type="checkbox"/>
35	04/04/19 12:51	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
36	04/04/19 12:51	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
37	04/04/19 12:51	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	04/04/19 12:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/04/19 13:49	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005613/ECD3E2

Date: 04/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle
No: SJS1691E

Insured Vehicle No: SKV2480M

Date of Loss: 27/03/2019

Nature of Claim: TP

Claim No: 7919412366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS1691E

Make & Model: NISSAN LATIO, 1.5 (A)

Reg. Date: 30/07/2009 (Man. Year: 2008)

Colour: White

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: HR15090122B

Chassis No: JN1BAAC11Z0021248

Odometer: 201924 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/03/2019

Date Inspected: 29/03/2019 Inspected At:

Heng Huat Motor (HQ)
BLOCK 5033 AMK INDUSTRIAL PARK 2
01-261
Singapore 569536

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REAR BUMPER LOWER SPOILER	Dented	0.00 F	*- F
5	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*REAR END PANEL INNER TRIM	Broken	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*BOOTLID	Repair	0.00 F	*- F
11	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Bent	0.00 F	*- F
13	1		*BOOTLID RUBBER	Torn	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >