



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/04/2019

User ID : CatherineLee

Poh Kin

Section A - Accident Details

Registration Number	SMB133K
Case Reference Number	BUS/03/19/5055
Registration Date	1/10/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Shamsun Bin Selamat
Type of Accident	Side Swipe
Accident Date and Time	8/3/2019 11:00 AM
Accident Reported Date and Time	28/3/2019 11:22 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100831
Special Instruction to ARC, if any	SMB133K - LEFT FRONT PORTION GBD5298E (TP) - INSURED WITH AXA
Prepared Date and Time	28/3/2019 5:10 PM
Chassis Number	WEB63442021000263
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,000.00	\$530.00
Total Spray Cost	\$616.00	\$448.00
Total Spare Part Cost	\$887.48	\$887.48
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,563.48	\$1,863.48
Lump Sum Total	\$0.00	\$1,850.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Cheon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	28/03/2019 5:17 PM	30/03/2019 11:48 AM
Signature		
Remarks		US repair. After paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
90 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/04/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL REPLACE ITEM & REPAIR LEFT SIDE PORTION	\$1,060.00	\$530.00
Total Labour	\$1,060.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$616.00	\$446.00
Total Spray Painting & Panel Beating	\$616.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009352	GLASS		WINDSCREEN FRT LH F OR MB OC500 BUS	1.00	\$931.50	10.00	\$838.35	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE DIRECT GLAZING	3.00	\$37.00	0.00	\$111.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
Total					\$1,128.50		\$1,109.35		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

U/s \$1850/- 2 days.