

22/03/2002

ASS. REC. BY:

REF: CS/III 19005630 / As d302

Special Instruction:

Survivor  
men

Adnan

ASSIGNMENT (Office)

From (Person):

Gabriel

Wee

of

III

Date/Time:

29/3/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 7813D

Insured:

SHA 7384X

at Workshop m/s

Ace Automation

Tel:

68441184

of

13 Kaki Bukit Road 4 # 03-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27.3.2019

1. Apr. 2019

CA / REV / REP. / REV 24 HRS

"W1"

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Anna

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SJJ 7813D - X
	SHA 7984X - X

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJJ7813D Yr Regn: 2008 / SeptType: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Delica c.c 2360Colour silver A/C: Insured / Std / NI / NASp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMYLTCVSW7J000111Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 01/04/19Survey held at Ace AntolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP111COE Expiry: 24/09/23.MV: 25k (Depreciation 5.5k x 4.5 year = 25k).PV: 14.9k.Nett: 10.1k.

24/07/19 Confirmed L/S \$6,600/- @ 7 days with Adrian.  
(\$15,771.70 Red - 71%)  
Resurvey No. of Trip - 1

RECEIVED 23 JUL 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 24/07/19  
Typ 4

2)

3)

4)

5)

6)

Prel. Report:

Final Report: \$6,600/- L/S

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

1190111161

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Friday, 29 March 2019 2:46 PM  
**To:** Weng Kit; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** 'Jerone'; danny.teo@advlawllc.com  
**Subject:** RE: Our Ref: SJJ 7813D (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJJ 7813D & SHA 7384X ALONG BLK 85A WHAMPOA DRIVE MSCP ON 27 MARCH 2019  
**Attachments:** 20190328181803857.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJJ 7813D and let us have your report urgently.

This claim will be handled by Daniel.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

Anna:  
✓ in  
E: ✓

---

**From:** Weng Kit [mailto:wengkit@chiaarul.com]  
**Sent:** 29 March, 2019 1:04 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** 'Jerone' <jerone@chiaarul.com>  
**Subject:** RE: Our Ref: SJJ 7813D (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJJ 7813D & SHA 7384X ALONG BLK 85A WHAMPOA DRIVE MSCP ON 27 MARCH 2019

Dear Sirs,

We refer to your email below.

Our client is agreeable to appoint **Mr. Marcus Chua from LKK Auto Consultants Pte Ltd** as the mutual surveyor for the above matter.

Please let us have your confirmation on the same.

Best Regards,

**Weng Kit (Mr.)**  
Paralegal

M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Friday, March 29, 2019 9:29 AM

**To:** Weng Kit

**Cc:** 'Jerone'

**Subject:** RE: Our Ref: SJJ 7813D (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJJ 7813D & SHA 7384X ALONG BLK 85A WHAMPOA DRIVE MSCP ON 27 MARCH 2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Weng Kit [<mailto:wengkit@chiaarul.com>]

**Sent:** 28 March, 2019 6:19 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Cc:** 'Jerone' <[jerone@chiaarul.com](mailto:jerone@chiaarul.com)>

**Subject:** Our Ref: SJJ 7813D (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJJ 7813D & SHA 7384X ALONG BLK 85A WHAMPOA DRIVE MSCP ON 27 MARCH 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 28 March 2019 for your attention.

Best Regards,

**Weng Kit (Mr.)**

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

**CHIA S ARUL LLC**  
**ADVOCATES & SOLICITORS**  
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS

Our Ref : SJJ 7813D (wk)

Your Ref : To be advised

28 March 2019

India International Insurance Pte Ltd

BY EMAIL

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : MUHAMMAD AIZAT BIN ABDUL HISHAM**  
**ACCIDENT INVOLVING SJJ 7813D & SHA 7384X ALONG BLK 85A WHAMPOA**  
**DRIVE MSCP ON 27 MARCH 2019**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for Muhammad Aizat Bin Abdul Hisham, the owner of motor vehicle no. SJJ 7813D which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SHA 7384X for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7203A
Vehicle Details	
Vehicle No.:	SJJ7813D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Apr 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	DELICA 2.4L CVT
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	4B12AT0792
Chassis No.:	JMYLTCV5W7J000111
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,580.00
Original Registration Date:	25 Sep 2008
First Registration Date:	25 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$29,580.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,689.00
COE Rebate Amount:	\$14,927.00
Total Rebate Amount:	\$14,927.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Apr 2019

OK



## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the indgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 01/04/2019 17:09  
Date Of Accident 27/03/2019 23:30  
Exact Location Of Accident BLK 85A WHOMPA DRIVE MSCP DECK 2  
Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SJJ7813D  
Insured/Policyholder  
Name Of Registered Owner MUHAMMAD AIZAT BIN ABDUL HISHAM  
NRIC No S8327203A  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-90304420  
Alternative Phone No OFFICE-90304420

## Vehicle Particulars

Manufacturer MITSUBISHI  
Model DELICA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.  
Type Of Coverage THIRD PARTY  
Fleet Policy NO  
Policy Number P10094024R00  
Cover Note Number

## Driver

Name of Driver MUHAMMAD AIZAT BIN ABDUL HISHAM  
NRIC No S8327203A  
Date Of Birth 19/08/1983  
Occupation INDOOR  
Date Of Driving Pass 22/12/2010  
Driving Experience 8 YEARS AND 3 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-90304420  
Fax Number  
Contact Number OFFICE-90304420  
Email Address NOEMAIL

Address	BLK 83 WHAMPOA DRIVE #16-294
Postcode	320083
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

**General Information of the Accident**

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO

Number of Passengers (Including Driver)	1
---	---

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG JAVA NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2959999 - FAX NO: 63918499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO POLICE REPORT: T/20190328/2015.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SHA7384X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

18/04/19:17:55  
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKB362P

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


## Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

ACE AUTO  
1

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20190328/2015.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

X *[Signature]*

Policyholder's Signature  
Date & Time:

X *[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

11/4/19 3.25pm *[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
Singapore 417807  
Tel:6702 4282 Fax:6702 4202

JMYLTCVSW7J00011

TP 111  
Swirley

Page No. 1

Vehicle No. SJJ7813D MITSUBISHI DELICA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	REAR BUMPER LH <i>turn</i>		410.00	✓
1	REAR BUMPER CENTER <i>new</i>		320.00	+
1	REAR BUMPER REFLECTOR LH <i>new</i>		215.00	+
1	REAR BUMPER CORNER PANEL LH <i>new</i>		110.00	+
1	REAR MUD <del>FLAP</del> LH <i>turn</i>		120.00	✓
1	REAR FENDER LH <i>Distorted</i>		<del>2110.00</del>	1380
1	REAR FENDER FUEL COVER LH <i>Dented</i>		210.00	✓
1	REAR FENDER FUEL COVER CABLE LH <i>new</i>		135.00	X
1	REAR FENDER FUEL PUMP <i>new</i>		1510.00	+
1	REAR FENDER SIDE RETAINER LH <i>new</i>		48.00	✓
1	REAR FENDER DOOR SLIGHTLY GRILLE LH <i>new</i>		489.00	X
1	REAR FENDER INNER SHEILD LH <i>turn</i>		259.00	✓
1	REAR AIR VENT LH <i>excluded</i>		115.00	✓
1	REAR DOOR LH <i>Repair</i>		1980.00	X
1	REAR DOOR LOCK LH <i>new</i>		650.00	X
1	REAR KNUCKLE ARM LH <i>Bent</i>		<del>810.00</del>	580
1	REAR BEARING WITH HUB LH <i>Damaged</i>		<del>660.00</del>	355
1	REAR UPPER ARM LH <i>Bent</i>		155.00	✓
1	REAR CENTRE ARM LH <i>Bent</i>		210.00	✓
1	REAR LOWER ARM LH <i>Bent</i>		240.00	✓
1	REAR EXHAUST PIPE <i>new</i>		930.00	X
1	REAR FENDER RH <i>Repair</i>		2110.00	X
1	REAR KNUCKLE ARM RH		810.00	+
1	REAR BEARING WITH HUB RH		660.00	+
1	REAR UPPER ARM RH		160.00	+
1	REAR CENTRE ARM RH		210.00	+
1	REAR LOWER ARM RH		255.00	+
	<i>Reas Fender Inner Shield RH turn</i>	259 ✓	15891.00	
	<i>Sliding Door Rail Bent</i>	358 ✓ less	1589.10	10%
	<i>Fuel Pipe Bent</i>	205 ✓	14301.90	
<b>SPECIAL ITEMS</b>				
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	30
1 SET	REAR FENDER SEALANT <i>new</i>		100.00	40
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	200
1	REAR RIM RH <i>cut</i>		550.00	✓
1	REAR RIM LH <i>cut</i>		550.00	✓
1	REAR TYRE LH <i>new</i>		790.00	+
1	REAR TYRE RH <i>new</i>		790.00	+
Total Parts			17441.90	

Reas Fender Glass Sealant *new*

60 ✓





**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SJJ7813D MITSUBISHI DELICA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	<del>1600.00</del>	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	<del>1200.00</del>	1000
3	To remove and refix wiring at damaged areas	<del>180.00</del>	30.
4	To perform anti rust treatment on affected areas	<del>150.00</del>	60
6	To remove & replace undercarriage part	<del>350.00</del>	220
7	To conduct full computerised wheel alignment	<del>150.00</del>	80.
8	To remove and refix rear <del>exhaust pipe</del> <sup>fuel tank</sup>	<del>200.00</del>	80
Labour Total :		3830.00	
TOTAL (PARTS & LABOUR) :		21271.90	22371.70

To remove and refix upholstery. ~~100~~ 120

To remove rear fender glass ~~100~~ 120

2690

total: 8344.60

L/S: 66K

07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and sent to final approval from Insurance Company

Repairer



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019 <a href="#">Edit Reg</a>		29 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>MUHAMMAD AIZAT BIN ABDUL HISHAM</b> , ID: S8327203A								
Vehicle Reg. No.:	<b>SJJ7813D</b>	Date of Loss:	27/03/2019 00:00 - :59 [126 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT19030729</b>	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>SHA7384X</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ace Autolution (HQ)</b> 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Pooi Chin Han Daniel</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 09/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJJ7813D (MCT19030729)

[SHA7384X]






































TP



















































MUHAMMAD AIZAT BIN ABDUL HISHAM

Mar 27 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Ace Autolution

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/07/19 11:38	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
81	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
82	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
83	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
84	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/07/19 11:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
89	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
90	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
91	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
92	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
93	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
94	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
95	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
96	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
97	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
98	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
99	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
100	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
101	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
102	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
103	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
104	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
105	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
106	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
107	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
108	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
109	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
110	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
111	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
112	26/07/19 11:38	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/04/19 09:13	Singapore Accident Statement	Load PDF	<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19005630/ASD3E2

Date: 29/07/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant Vehicle No :** SJJ7813D **Insured Vehicle No :** SHA7384X  
 Date of Loss: 27/03/2019 Nature of Claim: TP Claim No: MCT19030729

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJJ7813D**  
 Make & Model: MITSUBISHI DELICA, 2.4 CVT (A) Engine No: 4B12AT0792  
 Reg. Date: 25/09/2008 (Man. Year: 2007) Chassis No: JMYLTCV5W7J000111  
 Colour: Silver Odometer: 0 km  
 Engine Capacity: 2360 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,241.70	5,843.60	12,398.10	67.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	2,690.00	1,440.00	34.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,371.70</b>	<b>8,533.60</b>	<b>13,838.10</b>	<b>61.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>22,371.70</b>	<b>6,600.00</b>	<b>15,771.70</b>	<b>70.50</b>

## INSPECTION

Date of Assignment: 29/03/2019  
 Date Inspected: 01/04/2019 Inspected At: Ace Autolution (HQ)  
 13 KAKI BUKIT ROAD 4, #03-29 Bartley  
 Biz Centre  
 Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)	
<b>Parts:</b> M1-MPV	MITSUBISHI DELICA 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ7813D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LH	Torn	410.00 FL	*410.00 FL
2	1		*REAR BUMPER CENTER	Not Necessary	320.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	215.00 FL	*- FL
4	1		*REAR BUMPER CORNER PANEL LH	Not Necessary	110.00 FL	*- FL
5	1		*REAR MUD FLAP LH	Torn	120.00 FL	*120.00 FL
6	1		*REAR FENDER LH	Distorted	2,110.00 FL	*1,380.00 FL
7	1		*REAR FENDER FUEL COVER LH	Dented	210.00 FL	*210.00 FL
8	1		*REAR FENDER FUEL COVER CABLE LH	Not Necessary	135.00 FL	*- FL
9	1		*REAR FENDER FUEL PUMP	Not Necessary	1,510.00 FL	*- FL
10	1		*REAR FENDER SIDE RETAINER LH	Necessary	48.00 FL	*48.00 FL
11	1		*REAR FENDER DOOR SLIGHTLY GRILLE LH	Not Necessary	489.00 FL	*- FL
12	1		*REAR FENDER INNER SHIELD LH	Torn	259.00 FL	*259.00 FL
13	1		*REAR AIR VENT LH	Cracked	115.00 FL	*115.00 FL
14	1		*REAR DOOR LH	Repair	1,980.00 FL	*- FL
15	1		*REAR DOOR LOCK LH	Not Necessary	650.00 FL	*- FL
16	1		*REAR KNUCKLE ARM LH	Bent	810.00 FL	*580.00 FL
17	1		*REAR BEARING WITH HUB LH	Damaged	660.00 FL	*355.00 FL
18	1		*REAR UPPER ARM LH	Bent	155.00 FL	*155.00 FL
19	1		*REAR SHOCK ABSORBER	Bent	210.00 FL	*210.00 FL
20	1		*REAR LOWER ARM LH	Bent	240.00 FL	*240.00 FL
21	1		*REAR EXHAUST PIPE	Not Necessary	930.00 FL	*- FL
22	1		*REAR FENDER RH	Repair	2,110.00 FL	*- FL
23	1		*REAR KNUCKLE ARM RH	Not Necessary	810.00 FL	*- FL
24	1		*REAR BEARING WITH HUB RH	Not Necessary	660.00 FL	*- FL
25	1		*REAR UPPER ARM RH	Not Necessary	160.00 FL	*- FL
26	1		*REAR CENTRE ARM RH	Not Necessary	210.00 FL	*- FL
27	1		*REAR LOWER ARM RH	Not Necessary	255.00 FL	*- FL
28	1		*REAR FENDER INNER SHIELD RH	Torn	259.00 FL	*259.00 FL
29	1		*SLIDING DOOR RAIL	Bent	358.00 FL	*358.00 FL
30	1		*FUEL PIPE	Bent	205.00 FL	*205.00 FL
31	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
32	1		*SET REAR FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
34	1		*REAR RIM RH	Cut	550.00 FS	*550.00 FS
35	1		*REAR RIM LH	Cut	550.00 FS	*550.00 FS
36	1		*REAR TYRE LH	Not Necessary	790.00 FS	*- FS
37	1		*REAR TYRE RH	Not Necessary	790.00 FS	*- FS
38	1		*REAR FENDER GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	19,913.00	6,334.00
				- List Item Discount on L Items 10.00/10.00% (S\$)	1,671.30	490.40
				Total Parts (S\$)	18,241.70	5,843.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	1,000.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,000.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
5	TO REMOVE & REPLACE UNDERCARRIAGE PART	New	350.00	220.00
6	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT	New	150.00	80.00
7	TO REMOVE AND REFIX REAR FUEL TANK	New	200.00	80.00
8	TO REMOVE AND REFIX UPHOLSTERY	New	150.00	120.00
9	TO REMOVE REAR FENDER GLASS	New	150.00	100.00
Gross Labour Cost (S\$)			<b>4,130.00</b>	<b>2,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >