

ASS. REC. BY:

REF: CS 3/1CS/9005631/ R/cd30

Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

From (Person):

Crystabnu Tan

of

ECICS

Date/Time:

28.2.19 5.11pm

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FT 1237 B

Insured:

6BG 7614Y

at Workshop m/s

ong motor

Tel:

83802233

of

464 Macpherson Road Singapore

Policy No:

Claim No:

DMCV 19000154 / CT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

1. Apr. 2019

Date/Time:

29.3.19 4.13pm

Person Contacted:

Jacky Siah

Vehicle:

IN OUT

Date/Time	Action/Instruction (X) Estimate	
	FT 1237 B - NA / INC 19005241 / 24	D.O.A - 20/3/2019
	6BG 7614Y - NA / INC 19005241 / 24	D.O.A - 20/3/2019
	Dismantle part : 08/04/2019	

Surveyor

*Paul*

REF:

ICS

PRS

ASSIGNMENT

From:

Date:

1/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FT 1237 B

at Workshop m/s

Org Motor

of

464 Macpherson Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

jecky @ 8386 2233

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FT 1237 B

Yr Regn:

Feb / 01

Type:

Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA RXZ

C.C

133

Colour

MULTI

A/C:

Insured / Std / NI / NA

Sp.Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZMC258049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

2.50-18

R:

2.50-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

U.I.V.A

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/03/19

D.O.I.

01/04/19

Survey held at

ORG MOTOR

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$3,000 - \$3,500

*John*  
15/5/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

100

100

200

Report Format :

PRG

Lump Sum / I.B.I. (\$) )

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		29 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by adjuster]</b>	
Insured:				
Main Claimant: <b>MUHAMMAD FAUZI BIN SAFRI</b> , ID: S9606911A				
Vehicle Reg. No.:	<b>FT1237B</b>	Date of Loss:	20/03/2019 16:00 - :59	
Claim Type:	<b>TP / DMCV1900015H/CT</b>	Policy/Cover Note No.:	(Comprehensive)	
Vehicle Reg. No. (Insured):	<b>GBG7614Y</b>	Policy No. (Claimant):		
		Excess:		
Repairer: <b>Ong Motors (HQ)</b> 464 Macpherson, 368182 Macpherson - Tel:				
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Crystabelle Tan</b> - 6303 0190]				
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 09/04/2019]</b>				
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>	
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

## Nivitha (LKK Auto)

---

**From:** Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle\_Tan@ecics.com.sg>  
**Sent:** Thursday, 28 March 2019 5:21 PM  
**To:** assignments  
**Subject:** RE: Our Ref: FT 1237B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO AVENUE 3 ON 20 MARCH 2019 - Our Ref : DMCV1900015H/02/CT  
**Attachments:** 20190328111203041.pdf; SAS2572031 (1).PDF; SAS2572793.PDF

Dear LKK

Enclosed the documents.

Please upload the above attachments in merimen.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

E.Y  
v:in  
4.13 pm

---

**From:** Crystabelle Tan Gek Peng (ECICS, Claims)  
**Sent:** Thursday, 28 March, 2019 5:13 PM  
**To:** 'Weng Kit'; assignments  
**Cc:** 'Jerone'; ECICS Claims  
**Subject:** RE: Our Ref: FT 1237B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO AVENUE 3 ON 20 MARCH 2019 - Our Ref : DMCV1900015H/02/CT

WITHOUT PREJUDICE

Dear Weng Kit

Thank you for your email.

We are not agreeable with your surveyor list and we will appoint LKK for the SJE.

Aside to LKK

Please assist to arrange survey for TPV.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Weng Kit [<mailto:wengkit@chiaarul.com>]

**Sent:** Thursday, 28 March, 2019 4:46 PM

**To:** Crystabelle Tan Gek Peng (ECICS, Claims)

**Cc:** 'Jerone'; ECICS Claims

**Subject:** RE: Our Ref: FT 1237B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO AVENUE 3 ON 20 MARCH 2019 - Our Ref : DMCV1900015H/02/CT

Dear Crystabelle,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

S/N	Surveyor	Surveyor Firm
1.	Mr. Sebastian Lim Yong Tian	Constant Appraiser Services
2.	Mr. B J Loi	Par Automotive Consultancy
3.	Mr. Patrick Ng	CarLink Consultancy
4.	Mr. How Andrew	Prominent Appraiser Services
5.	Mr. Ong Ah Heng Kent	KTO Automobile Assessors
6.	Mr. Phillip Foo	Precision Appraisal Services
7.	Mr. Lee Kok Weng	Lee Automobile Appraiser Services
8.	Mr. Danny Ho Joo Loong	HJL Auto Appraiser Services
9.	Mr. Thor Teck Soon David	JAS Appraisal Services
10.	Mr. Dave Chang Fuh Keong	Sincere Appraisal Services

Best Regards,

**Weng Kit (Mr.)**

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Crystabelle Tan Gek Peng (ECICS, Claims) [[mailto:Crystabelle\\_Tan@ecics.com.sg](mailto:Crystabelle_Tan@ecics.com.sg)]

**Sent:** Thursday, March 28, 2019 4:44 PM

**To:** Weng Kit

**Cc:** 'Jerone'; ECICS Claims

**Subject:** RE: Our Ref: FT 1237B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO AVENUE 3 ON 20 MARCH 2019 - Our Ref : DMCV1900015H/02/CT

WITHOUT PREJUDICE

Dear Weng Kit

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Weng Kit [<mailto:wengkit@chiaarul.com>]

**Sent:** Thursday, 28 March, 2019 11:12 AM

**To:** ECICS Claims

**Cc:** 'Jerone'

**Subject:** Our Ref: FT 1237B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO AVENUE 3 ON 20 MARCH 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 28 March 2019 for your attention.

Best Regards,

**Weng Kit (Mr.)**

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS

Our Ref : FT 1237B (wk)

Your Ref : To be advised

28 March 2019

ECICS Limited

BY EMAIL

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : MUHAMMAD FAUZI BIN SAFRI**  
**ACCIDENT INVOLVING FT 1237B & GBG 7614Y ALONG ANG MO KIO**  
**AVENUE 3 ON 20 MARCH 2019**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for Muhammad Fauzi Bin Safri, the owner of motor cycle no. FT 1237B, which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. GBG 7614Y for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor cycle at:

Address	464 Macpherson Road Singapore 368182
Contact Person	Mr. Jacky Siah (8380 2233)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6911A
<b>Vehicle Details</b>	
Vehicle No.:	FT1237B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	White
Manufacturing Year:	2000
Engine No.:	3B5258049
Chassis No.:	ZMC258049
Maximum Power Output:	-
Open Market Value:	\$3,605.00
Original Registration Date:	19 Feb 2001
First Registration Date:	19 Feb 2001
Transfer Count:	6
Actual ARF Paid:	\$541.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Feb 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,567.00
COE Rebate Amount:	\$300.00
<b>Total Rebate Amount:</b>	<b>\$300.00</b>
<b>Message</b>	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit <a href="http://www.nea.gov.sg/mtc incentive">http://www.nea.gov.sg/mtc incentive</a> or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 16 May 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FT1237B		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	RXZ		
Chassis No. :	ZMC258049		
Propellant :	Petrol		
Engine No. :	3BS258049		
Engine Capacity :	133 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	-		
Year Of Manufacture :	2000		
Original Registration Date :	19 Feb 2001		
Lifespan Expiry Date :	30 Jun 2028		
COE Category :	D - Motorcycle		
PQP Paid :	\$1,567.00		
COE Expiry Date :	18 Feb 2021		
Road Tax Expiry Date :	25 Oct 2019		
Inspection Due Date :	25 Apr 2020		
Intended Transfer Date :	16 May 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.			
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.			
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.			
For more information, please visit <a href="http://www.nea.gov.sg/mtcincentive">http://www.nea.gov.sg/mtcincentive</a> or contact NEA at 1800-2255-632.			

You may print this page for reference.

OK      Print

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019 15:11 <a href="#">Edit Reg</a>		28 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by adjuster]</a></span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>MUHAMMAD FAUZI BIN SAFRI</b> , ID: S9606911A									
Vehicle Reg. No.: <b>FT1237B</b>		Date of Loss: 20/03/2019 16:00 - :59 <b>[217 Months and 1 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / DMCV1900015H/CT</b>		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): <b>GBG7614Y</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ong Motors (HQ)</b> 464 Macpherson, 368182 Macpherson - Tel:									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Crystabelle Tan</b> - 6303 0190]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 09/04/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FT1237B (DMCV1900015H/CT)  
[GBG7614Y]  
TP  
MUHAMMAD FAUZI BIN SAFRI  
Mar 20 2019 4:00PM  
[-]  
Ong Motors

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
2	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
3	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
4	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
5	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
6	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
7	16/05/19 10:10	General View								Load JPG	<input checked="" type="checkbox"/>	
8	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
9	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
10	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
11	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
12	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
13	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
14	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
15	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
16	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
17	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
18	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
19	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
20	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
21	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
22	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
23	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
24	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
25	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
26	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
27	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
28	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
29	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
30	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
31	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
32	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
33	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
34	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
35	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
36	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	
37	16/05/19 10:11	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	16/05/19 10:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS19005631/R1CD3E2

Date: 24/05/2019

### REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : FT1237B

Insured Vehicle No : GBG7614Y

Date of Loss: 20/03/2019

Nature of Claim: TP

Claim No: DMCV1900015H/CT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FT1237B

Make &amp; Model: YAMAHA RXZ, 133cc (M)

Engine No: 3BS258049

Reg. Date: 19/02/2001 (Man. Year: 2000)

Chassis No: ZMC258049

Colour: Multi-colour

Odometer: 0 km

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 2.50-18 Rear Tyre Size: 2.50-18

Front Left Side: Viva 3 mm Rear Left Side: Viva 3 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 28/03/2019

Date Inspected: 01/04/2019

Inspected At:

Ong Motors (HQ)  
464 Macpherson  
Singapore 368182

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$3,500.00

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 24 May 2019)
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FT1237B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >