



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHEN XINYOU			Ref: CC4/ASM19005691/Jgs3q2 Date: 15/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 1066B	Veh. Inspected	SFH 8333Z	
Policy No.	P2031117	Coverage (\$)	0.00	
Claim No.	S9M01BR1	Excess (\$)	0.00	
Assign From		Assign Date	01/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X1	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBAJG12080EG23842	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/01/2019	Inspection Date	08/04/2019	
Survey held at	CARZ AUTO SERVICES PTE LTD 1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	