

27/03/2019

ASS. PFC. BY

SMA Vey/01

Rasul

REF

CS3/ASM 19005704/Rld302

Ref Instruction

ASSIGNMENT (Office)

From (Person)

of

ASM (AXA)

Date/Time

1/4/19 @ 2.01pm

Estimate / Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No.

SMA 9411D

Insured

SMA 9039X

at Workshop m/s

Innu Auto

Tel.

63851171

of

Blk 5 Defu Lane 10 # 01-574

Policy No.

Claim No.

S9M01191

Sum Insured

Excess:

Make of Veh.

D.O.A.

27/03/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

3.00pm @ 1/4/19

Person Contacted:

Irene

Vehicle

IN/OUT

Date/Time

Action/Instruction (X)

Estimate

Insp: GMS : Gekaki Bukit Ave 6 #04-11

SMA 9411D-X

SMA 9039X-X

Dismantle: 2/4/2019



Service Request Details

Claim

S9M01I9I

Reference

CS3/ASM19005709/R1cd3 

Loss Date

March 27, 2019

Report Date

Mar 28, 2019 9:34:39 AM

Request Date

April 1, 2019

Due Date

April 1, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▼

Vehicle Information

Incident Vehicle Registration #

SMA9411D

INNO AUTO PTE LTD

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171 FAX: 6385 1141

Co. Regn. No. 201118053M

Date: 27/3/2019

To AXA Insurance Singapore P/L
Motor Claims Department

8 Shenton Way

#24-01 AXA Tower

Singapore 068811

By fax only

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT


Please be informed that an accident involving my/our vehicle no. SMA 9411D and vehicle(s) no. SMA 9039X had taken place at / along Tampines Ave 5 on date 27/03/2019 at time 8:37 hrs

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Ms Tan at 98388224 to arrange.

Yours sincerely,



PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

Best Regards,
Irene Tan
Inno Auto Pte Ltd
Tel: 6385 1171

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8075G
Vehicle Details	
Vehicle No.:	SMA9411D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	LEB5601610
Chassis No.:	GB71068163
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,508.00
Original Registration Date:	22 Jun 2018
First Registration Date:	22 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$17,712.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2028
PARF Rebate Amount:	\$13,284.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$34,343.00
Total Rebate Amount:	\$47,627.00

The information contained herein is correct as at 09 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/03/2019 16:08
Date Of Accident	27/03/2019 08:40
Exact Location Of Accident	TAMPINES AVE 5
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMA9411D
Insured/Policyholder	
Name Of Registered Owner	SOH CHUN BENG (SU JUNMING)
NRIC No	S7818075G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81189362
Alternative Phone No	OFFICE-81189362
Vehicle Particulars	
Manufacturer	HONDA
Model	FREED
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA368553
Cover Note Number	
Driver	
Name of Driver	NG YEONG HUA EILEEN
NRIC No	S8121974E
Date Of Birth	23/07/1981
Occupation	INDOOR
Date Of Driving Pass	21/01/2003
Driving Experience	16 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81189362
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	74 UPPER SERANGOON VIEW #11-52
Postcode	S533881
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TAMPINES AVE 5 ON 27/03/2019 AT ABOUT 8.37AM. I STOPPED MY VEHICLE TO LET THE ONCOMING VEHICLE TO CLEAR. SUDDENLY THE VEHICLE SMA9039X HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA9039X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SMA 9411D

SM A 9039X

Tampines Ave 5

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Tampines Ave 5
on 27/3/2019 @ abt 8:37 am.

I stopped my vehicle to let the oncoming vehicle to clear, suddenly, the vehicle SMA9039X hit onto my vehicle rear portion

That's all

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured the vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19005709/R1cd3e2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 22-04-2019		
ATTN: LYNN KHONG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMA 9039X	Veh. Inspected	SMA 9411D	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M0119I	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	01/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GB71068163	Colour	BLUE	
Odometer	13319 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	27/03/2019	Inspect Date / Time	01/04/2019 (04:09 PM)	
Survey held at	GMS-68 KB AVE 6#04-11			
Repairer	INNO AUTO PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

Report Ref No. CS3/ASM19005709/R1cd3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.